

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 173/IC/TC/HO/2018
DATE : 15-AUG-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : LEE CHAY ENG
ADDRESS : BLK 119 LORONG 1 TOA PAYOH
#05-437
S(310119)
TELEPHONE NO : 94888375

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : AXA 3RD PARTY DIRECT SETTLEMEN
VEHICLE NO : SLZ3218R
MODEL CODE : BDTARCZB17EWA---K
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2017
ENGINE NO : HR16926384C
CHASSIS NO : MNTBBAB17Z0032024
MILEAGE : 1 KM
DATE IN : 15/08/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 13/08/2018

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

NAZ LKK
17/8/18 1220

4 DAYS -
PIE
Before paint photo
67418434

Na2@lkkauto.com

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLZ321BR

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-REAR	50.00	30
2	RPJ	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL @\$120.00/PORTION X 2 PORTION	240.00	100
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	20
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @\$100.00/PORTION X 2PORTIONS	200.00	100
5	ZZ/001	REMOVE/INSTALL REAR BUMPER,END PANEL,TRUNK LID AND AFFECTED PORTION.REPAIR LHR FENDER AND RHR FENDER	1250.00	600
6	ZZ/002	RESPRAY PAINT REAR BUMPER,END PANEL,TRUNK FLOOR PANEL,TRUNK LID,LH REAR FENDER AND RH REAR FENDER	1400.00	600
7	ZZ/003	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR	240.00	50
8	ZZ/004	CHECK REAR LIGHTINGS AND WIRING SYSTEM	20.00	/nrc
9	ZZ/005	SEARCH FEE	2.00	/nrc
10	ZZ/006	TOWING AND RECOVERY CHARGES FOR DIRECT SETTLEMENT CLAIMS	80.00	60
TOTAL LABOUR CHARGES			3547.00	

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLZ3218R

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/RETT REMARKS
1	CARPET-LUGGAGE FLOOR	84902-3SB0A	411.20	?
2	PLATE-LUGGAGE, REAR	84921-3SD0A	93.80	?
3	DUCT-DRAFTER	76805-2DR0A	50.30	?
4	W/STRIP-TRUNK LID	84830-3SB3J	87.20	✓
5	HINGE ASSY-TRUNK LID @\$58.40EACH X2PCS	H4400-3RAMA	116.80	DEFORMED X SVC
6	LOCK ASSY-TRUNK LID	84630-3AW0A	64.50	✓ not working
7	BUMPER RUBBER-TRUNK LID @\$4.50EACH X2PCS	01658-0209J	9.00	✓ deformed
8	EMBLEM-REAR	90892-BG00A	59.70	✓ KLC
9	EMBLEM-REAR	84890-3RA1B	90.50	✓ KLC
10	EMBLEM-REAR	84890-3RA0B	47.90	✓ KLC
11	FINISHER ASSY-TRUNK LID	84810-3ST1A	189.90	?
12	TRUNK LID	H430M-3SBMA	1190.50	X R
13	SENSOR-REVERSE	SENSOR		200.00 X SVC
14	RH REAR BUMPER STAY	85212-EE530	44.90	?
15	LH REAR BUMPER STAY	85213-EE530	42.40	?
16	ENERGY ABSORBER-REAR BUMPER, RH	85092-3ST0A	87.00	?
17	ENERGY ABSORBER-REAR BUMPER, CENTER	85090-3ST0A	34.70	?
18	ENERGY ABSORBER-REAR BUMPER, LH	85093-3ST0A	130.70	?
19	RH REAR BUMPER SIDE BRACKET	85226-3ST1A	34.30	?
20	LH REAR BUMPER SIDE BRACKET	85227-3ST1A	34.30	?
21	REAR BUMPER CLIP @\$1.20EACH X4PCS	01553-10501	4.80	?
22	REAR BUMPER FASCIA	85022-3ST4H	620.90	✓ DD
23	REAR END PANEL	G9110-3SBMA	438.20	✓ BT
24	LAMP ASSY-REAR COMBI, RH TRUNK	26550-3SB3A	144.80	?
25	LAMP ASSY-REAR COMBI, LH TRUNK	26555-3SB3A	144.80	?

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLZ3218R

DAMAGED PARTS & PRICES				
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26 LAMP ASSY-REAR COMBI,RH	26550-35B00	380.40	?	
27 LAMP ASSY-REAR COMBI,LH	26555-35B00	380.40	?	
SUB TOTAL		4933.90	0.00	200.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		986.78	0.00	0.00
GRAND TOTAL		3947.12	0.00	200.00
OVERALL TOTAL		4147.12		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLZ3218R

TOTAL LABOUR CHARGES	3547.00
TOTAL SPARE PARTS CHARGES	4147.12

GRAND TOTAL	7694.12 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.