

22/03/2018

ASS. REC. BY:

REF: CS/FCU18014872/Klvbn2

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person): CWS Joanne Tong of FCL Date/Time: 15082018 523pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1038 U Insured: SH 6607T

at Workshop m/s Premier Tel: 65446689

of 23 Changi South Ave 2 #03-02.

Policy No: Claim No: D18006127MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 14082018
(Client's Record)

CA / REV / REP. / REV 24 HRS '08'

16082018

H.O.D. Endorsement:

Date/Time: 15082018 533pm Person Contacted: Vincent Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 1038 U - CS/TP 14018350 / Tlgm3d1 DA: 23092014
	SH 6607T - CS/FCU17022271 / Utbnk DA: 20112017
17/8/18	Email preli revised to FCJ

(08/11/13)

Bureau: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No _____

Claims No _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 10384 Yr Regn: 22 Dec 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/C / Prime Mover /

Truck / Trailer or

Make: ICIA optima C.C. 1680Colour: Silver A/C: Insured / Std / Nil / NASp. Reading: 361459 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: ICNAH M44MF5627928

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 14/8/18 D.O.I. 16/8/18Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

MS B.L.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/9/18 Completed 4/5 \$5400/ 5 days. (Recd 3759.40, 419) FCI

RECEIVED 21 SEP 2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 2019 - typistReport Format: awsLump Sum / I.B.I. (\$) 5400/2Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

170

50

50

60

330



LKK Auto Consultants Pte Ltd
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
 TEL: 6256 3561 FAX: 6256 4315
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014872/K1vb	
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877			Date : 15-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6607T	Veh. Inspected	SHD 1038U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006127MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	15/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/08/2018	Inspection Date	16/08/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18006127MFSH

Our ref: CS/FCI18014872/K1vb

DATE: 17/8/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1038U


We thank you for your instruction on 15/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/8/2018 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$7,632.10
Revised Estimate Amount	: S\$5,225.60
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kalvin Ang

Technical Investigator

Technical Investigation & Reconstructionist (SAE-A)

MOTOR SURVEY ASSIGNMENT

Date	15-08-2018	Our Ref No. D18006127MFSH
Accident Date	14-08-2018	Claim Type. Third Party
Insured Vehicle	SH6607T	Third Party Vehicle. SHD1038U
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 17 August 2018 11:16 AM
To: 'Claim Workflow System'
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006127MFSH/1, SHD 1038U
Attachments: SHD 1038U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 1038U
Date of survey: 16/8/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 15 August 2018 5:33 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006127MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 15 August, 2018 5:23 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006127MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	22 Dec 2015 / 09:09:12	Receipt No.:	AACCK001-AX239-151222-000014
Asset Type:	Vehicle	Transaction Amount:	\$68,909.00
Asset ID:	SHD1038U	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151222090912509742		
Vehicle No.:	SHD1038U		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	22 Dec 2015		
Original Registration Date:	22 Dec 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5657928		
Engine No.:	D4FDFH314500		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$22,359.00		
Minimum PARF Benefit:	\$13,981.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	22 Dec 2015 09:09:12		
COE No.:	2015122201003537W		
COE Expiry Date:	21 Dec 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$45,466.00		
Lifespan Expiry Date:	21 Dec 2023		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

16-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1038 U

1 pc	n/s head lamp @ \$1028.00	✓	\$	1,028.00
1 pc	Front bumper	Rebrand	\$	531.00
1 pc	Front bumper emblem	✓	\$	44.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	n/s ✓ o/s x 2	\$	32.00
1 pc	Front bumper n/s protector @ \$51.00	✓	\$	51.00
1 pc	Front bumper n/s fog lamp cover @ \$66.00	✓	\$	66.00
1 pc	Front n/s fender	✓	\$	384.00
1 pc	Front n/s fender inner shield	X 2	\$	120.00
2 pc	Front n/s wheel cover	2 Rear wheel cover - X 2 brushed	\$	116.00 X 2 = 232
1 pc	n/s mirror assy	Broken	\$	590.00
1 pc	Front n/s door	X repair	\$	761.00
2 pcs	Front n/s door hinges @ \$34.00	X 2	\$	68.00
1 pc	Front n/s door glass @ \$322.00	✓	\$	322.00
	n/s Door weatherstrips	✓	\$	4,113.00
	Front Bonnet	✓	\$	411.30
	Front Support Panel	✓	\$	3,701.70
		\$ 73		
		\$ 979		
		\$ 645	Less 10%	

S/NETT

1 set	Front bumper clips	✓	\$	48.00
1 pc	Front n/s fender sticker	X 2	\$	30.00
1 set	Front n/s fender inner shield clips	X 2	\$	28.00
1 set	n/s door stickers	✓	\$	100.00
1 pc	Rear n/s fender sticker	✓	\$	60.00
	Sundry		\$	50.00 20 nec
	To check front n/s wheel alignment		\$	80.00 X 2
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 50
	To dismantle / refit inner components of the front n/s door into new shell door		\$	150.00 50
	To dismantle / refit new front n/s door glass onto new shell door		\$	150.00 X 2
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the bonnet, rear n/s door, rear n/s fender, etc.		\$	1,200.00 600
	To putty and spray painting on bonnet, front bumper, front n/s fender, n/s side mirror, front n/s door, rear n/s door, n/s rocker panel garnish, rear n/s fender,		\$	1,600.00 1310
	To apply rustproofing on the repaired and replaced panels.		\$	150.00 50
			\$	7,527.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

9159.40

-7633.10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014872/K1vbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6607T	Veh. Inspected	SHD 1038U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006127MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	15/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5657928	Colour	SILVER	
Odometer	361459	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/08/2018	Inspection Date	16/08/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1038U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	N/S HEAD LAMP	CRACKED	1,028.00	1,028.00
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
2	FRONT BUMPER N/S & O/S SIDE RETAINER @\$16.00	N/S CRACKED / O/S SERVICEABLE	32.00	16.00
1	FRONT BUMPER N/S PROTECTOR	CUT	51.00	51.00
1	FRONT BUMPER N/S FOG LAMP COVER	CUT	66.00	66.00
1	FRONT N/S FENDER	DENTED	384.00	384.00
1	FRONT N/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
2	FRONT N/S WHEEL COVER & REAR WHEEL COVER @\$116.00	GRAZED	232.00	232.00
1	N/S MIRROR ASSY	BROKEN	590.00	590.00
1	FRONT N/S DOOR	TO REPAIR SEE LABOUR	761.00	-
2	FRONT N/S DOOR HINGES @\$34.00	SERVICEABLE	68.00	-
1	FRONT N/S DOOR GLASS	CUT	322.00	322.00
1	N/S DOOR WEATHERSTRIP	CUT	73.00	73.00
1	FRONT BONNET	DENTED	979.00	979.00
1	FRONT SUPPORT PANEL	BENT	645.00	645.00
	LESS 10% DISCOUNT		-592.60	-496.10
			5,333.40	4,464.90
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT N/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SET N/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			316.00	228.00
LABOUR				
	TO CHECK FRONT N/S WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-

Report Ref No. CS/FCI18014872/K1vbn2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	50.00
	TO DISMANTLE/REFIT INNER COMPONENTS OF THE FRONT N/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO DISMANTLE/REFIT NEW FRONT N/S DOOR GLASS ONTO NEW SHELL DOOR.		150.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE BONNET, REAR N/S DOOR, REAR N/S FENDER, ETC. INCLUSIVE OF THE REPAIR OF FRONT N/S DOOR.		1,200.00	600.00
	TO PUTTY AND SPRAY PAINTING ON BONNET, FRONT BUMPER, FRONT N/S FENDER, N/S SIDE MIRROR, FRONT N/S DOOR, REAR N/S DOOR, N/S ROCKER PANEL GARNISH, REAR N/S FENDER.		1,600.00	1,310.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
			3,510.00	2,060.00
GRAND TOTAL			9,159.40	6,752.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,400.00

Report Ref No. CS/FCI18014872/K1vbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING**B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.