

22/03/2002

ASS. REC. BY:

REF: CS/CTI18014873/ Dcd3m2 Special Instruction:

Surveyor:

Mentimen

From (Person):

Irene Tay

ASSIGNMENT (Office)

etf

Date/Time:

15/8/18 @ 11:22am.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 4997R

Insured:

GV 51074

at Workshop m/s

EM-1 Auto

Tel:

6452 3298

of

Blk 8 Jln Ming Ind. Est & C #01-68

Policy No:

DMCV 8N1713991801

Claim No:

8NM18D0389702

Sum Insured:

Excess:

Make of Veh:

D.O.A. 10/08/2018

(Client's Record)

16/8/18

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

12.51pm @ 14/8/18

Person Contacted:

Annie

Vehicle: IN/OUT

Date/Time

Action/Instruction (☒) Estimate

SLQ 4997R - CCG LCR 18005446 / Upb3

DOA: 18/3/18

GV 51074-X


Surveyor

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 9 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ 4997R Yr Regn: 2017, July
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Opel Mokka c.c. 1598
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp. Reading: 5792 T/Radio: Insured / Std / NI / NA
 Eng/No: A2170185GU7X0563
 C/No: W0LJD7EC2HB181508
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/65 R18
 R: ---

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>10/08/2018</u>	D.O.I. <u>16/08/2018</u>

Survey held at BM2 Sin Ming
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or.
N/S Body y N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>China Taping GV5107U</u>
	<u>Pending part prices.</u>
	<u>Repair cost exceed 10K</u>
<u>11/12/18</u>	<u>Finalised at 2/5 12,500/- with 9 days 7 (Red. 12,986.04, 50%)</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

☐ : S + RS, ☐ : SI

☐ : Photos

☐ : Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 12,500/-)

220

RECEIVED 11 DEC 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI18014873/Drd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 15-08-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GV 5107U	Veh. Inspected	SLQ 4997R	
Policy No.	DMCVSN1713991801	Coverage (\$)	0.00	
Claim No.	SNM18D03897C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	15/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/08/2018	Inspection Date	16/08/2018	
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Aug 2018		15 Aug 2018 11:22 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TH HARDWARE & SCRAP METAL TRADING, Co. Reg. No.: -		
Main Claimant:	EDWIN YEO, Co. Reg. No.: 53364148M		
Vehicle Reg. No.:	SLQ4997R	Date of Loss:	10/08/2018 10:00 - :59
Claim Type:	TP / SNM18D03897C02	Policy/Cover Note No.:	DMCVSN1713991801 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	GV5107U	Policy No. (Claimant):	5092465190-01
		Excess:	S\$0.00
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/08/2018]		
Driver/Custodian (Insured):	YAP CHI SENG (69 / Male), NRIC: S0957103E, Tel: +6597350501		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4148M
Vehicle Details	
Vehicle No.:	SLQ4997R
Vehicle to be Exported:	No
Intended De-registration Date:	12 Aug 2018
Vehicle Make:	OPEL
Vehicle Model:	MOKKA X 1.6 CDTI 6AT
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	A2170185GU7X0563
Chassis No.:	W0LJD7EC2HB181508
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,749.00
Original Registration Date:	13 Jul 2017
First Registration Date:	13 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$16,049.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jul 2027
PARF Rebate Amount:	\$12,036.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$42,355.00
Total Rebate Amount:	\$54,391.00

The information contained herein is correct as at 11 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/08/2018 15:38
Date Of Accident	10/08/2018 10:30
Exact Location Of Accident	BEDOK NORTH AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ4997R
Insured/Policyholder	
Name Of Registered Owner	EDWIN YEO
Co Reg No	53364148M
Email Address	EDWINEYOYONGXIANG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-81287546
Alternative Phone No	OFFICE-81287546

Vehicle Particulars

Manufacturer	OPEL
Model	MOKKA X-1.6 CDTI 6AT (LED) (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092465190-01
Cover Note Number	19/07/2018 - 18/07/2019

Driver

Name of Driver	EDWIN YEO YONG XIANG
NRIC No	S9326545I
Date Of Birth	20/07/1993
Occupation	INDOOR
Date Of Driving Pass	08/10/2015
Driving Experience	2 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81287546
Fax Number	
Contact Number	
E Mail Address	EDWINEYOYONGXIANG@HOTMAIL.COM

Address	BLK 108 WOODLANDS ST 13 #13-160
Postcode	730108
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS TRAVELLING ON THE RIGHT LANE OF BEDOK NORTH AVE 4. VEHICLE B WAS ON THE LEFT LANE. VEHICLE B WAS UNABLE TO MAKE UP HIS MIND AND SWERVING LEFT AND RIGHT ON THE LEFT AND ABIT ON THE RIGHT LANE. I PROCEED TO GO STRAIGHT. SUDDENLY, VEHICLE B MADE A SUDDEN RIGHT TURN (ILLEGAL U-TURN) AND HIT ONTO MY VEHICLE LEFT PORTION. AFTER THE ACCIDENT, WE STOPPED ON THE OPPOSITE EMPTY SPACE TO EXCHANGE PARTICULARS AND TAKE PHOTO. VEHICLE B DRIVER ADMITTED HIS FAULT AND SIGNED ON CONFESSION NOTE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GV5107U
Vehicle Make/Model/Colour	LORRY
Details Of Properties	FRONT RIGHT PORTION
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	YAP CHI SENG
NRIC/Passport Number	S0957103E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: : PASSENGER

GENDER: : FEMALE

DETAILS OF INJURED PERSON 1

Name	EDWIN YEO YONG XIANG
Approximate Age	
Injuries Sustain	BACK
Injured person in which vehicle?	SLQ4997R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 108 WOODLANDS ST 13 #13-160
Postcode	730108

Sketch Plan Pg. 1

NTUC Income Motor Service Centre

Report No. M1

D.O.A

Vehicle No

Make Model:

Report Date: 8/10/2018 Start Time: 3:54 PM

Reporting Type: 7P End Time:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, law or court orders.


8/10/2018 15:54
Policyholder's Signature
Date & Time:

EDWIN YEO
Co Reg No: 53364148M/2018 15:54
Driver's Signature (If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Chen Junliang
NTUC Fin No: S990765

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY VEHICLE WAS TRAVELLING ON THE RIGHT LANE OF BEDOK NORTH AVE 4. VEHICLE B WAS ON THE LEFT LANE. VEHICLE B WAS UNABLE TO MAKE UP HIS MIND AND SWERVING LEFT AND RIGHT ON THE LEFT AND ABIT ON THE RIGHT LANE. I PROCEED TO GO STRAIGHT. SUDDENLY, VEHICLE B MADE A SUDDEN RIGHT TURN (ILLEGAL U-TURN) AND HIT ONTO MY VEHICLE LEFT PORTION. AFTER THE ACCIDENT, WE STOPPED ON THE OPPOSITE EMPTY SPACE TO EXCHANGE PARTICULARS AND TAKE PHOTO. VEHICLE B DRIVER ADMITTED HIS FAULT AND SIGNED ON CONFESSION NOTE.


DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 8/10/2018 15:54

EDWIN YEO
 Co Reg No: 53364148M
 8/10/2018 15:54

 Driver's Signature (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: Chen JunLiang
 NRIC/ Fin No: S990765

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLQ 4997R
Vehicle Model : OPEL MOKKA
Accident Date : 10.08.2018
Original Reg Date : 13.07.2017

Date : 13.08.2018
Chassis : W0LJD7EC2HB181508
TP Ins. CHINA

Alignment Paper Require

ESTIMATE

1	1 pc	Front Door LH	✓	
2	1 pc	Front Door Glass LH	✓	
3	1 pc	Front Door Quarter Glass LH	X	
4	1 pc	Front Door Quarter Glass Rubber LH	✓	
5	1 pc	Front Door Black Sticker LH (Big)	✓	
6	1 pc	Front Door Black Sticker LH (Small)	✓	
7	1 pc	Front Door Outer Chrome Moulding RH	✓	
8	1 pc	Front Door Inner Frame Garnish LH	X	
9	1 pc	Front Door Wing Mirror LH	X	
10	1 pc	Front Door Outer Handle LH	✓	
11	1 pc	Front Door Outer Handle Joint LH	✓	
12	1 pc	Front Door Inner Lock LH	✓	
13	1 pc	Front Door Lock Catch LH	X	
14	1 pc	Front Door Weatherstrip LH	✓	
15	2 pcs	Front Door Hinge LH	X	
16	1 pc	Front Door Checker LH	X	
17	1 pc	Front Door Bottom Protector LH	✓	
18	1 pc	Front Door Channel LH	✓	
19	1 pc	Front Door Channel Seal LH	✓	
20	1 pc	Front Door Regulator Motor LH	X	
21	1 pc	Front Door Regulator Gear LH	✓	
22	1 pc	Front Door Inner Trim LH	✓	
23	1 set	Front Door Inner Trim Clip LH	✓	
24	1 pc	Front Door Speaker LH	X	
25	1 pc	Rear Door LH	✓	
26	1 pc	Rear Door Black Sticker LH	✓	
27	1 pc	Rear Door Outer Chrome Moulding LH	✓	
28	1 pc	Rear Door Inner Frame Garnish LH	X	
29	1 pc	Rear Door Outer Handle LH	X	
30	1 pc	Rear Door Outer Handle Joint LH	X	
31	1 pc	Rear Door Inner Lock LH	X	
32	1 pc	Rear Door Lock Catch LH	X	
33	1 pc	Rear Door Weatherstrip LH	✓	

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLQ 4997R

B/F

1	2 pcs	Rear Door Hinge LH	2 St	2 L	
2	1 pc	Rear Door Checker LH	2 distal	2 L	
3	1 pc	Rear Door Bottom Protector LH	St	✓	
4	1 pc	Rear Door Channel LH	St	2 L	
5	1 pc	Rear Door Channel Seal LH	HL	✓	
6	1 pc	Rear Door Glass	HL	X	
7	1 pc	Rear Door Quarter Glass Rubber	N/C	✓	
8	1 pc	Rear Door Quarter Glass Chrome Moulding	N/C	✓	
9	1 pc	Rear Door Regulator Motor LH	2 HL	2 X	
10	1 pc	Rear Door Regulator Gear LH	2 St	2 L	
11	1 pc	Rear Door Inner Trim LH	2 money grade	2 L	
12	1 set	Rear Door Inner Trim Clip LH	2 N/C	2 L	
13	1 pc	Rear Door Speaker LH	N/C	X	
14	1 pc	Center Door Pillar LH	N/C	X	
15	1 pc	Rocker Panel Side Skirt	2 money grade	2 L	
16	1 set	Rocker Panel Side Skirt Clips	2 N/C	2 L	
17	1 pc	Rear Fender Arch Garnish LH	N/C	✓	
18	1 set	Rear Fender Arch Garnish Clip	N/C	✓	
19	1 pc	Rear Fender Inner Shield RH	SV	X	
20	1 set	Rear Fender Inner Shield Clip RH	SV	X	
21	1 pc	Taillamp LH	SV	X	
22	1 pc	Taillamp Inner Sealer LH	HL	X	
23	1 set	Taillamp Clip LH	HL	X	
24	1 pc	Rear Bumper	N/C	✓	
25	2 pcs	Rear Bumper Side Retainer	SV 2/1	X	
26	1 set	Rear Bumper Clip	N/C	✓	
27	1 pc	Rear Bumper Lower Skirt	2 money grade	2 L	
28	1 pc	Rear Absorber LH	2 distal	2 L	
29	1 pc	Rear Wheel Bearing LH	2 Don	2 L	
30	1 pc	Rear Axle Beam	2 HL	X	
31	1 pc	Rear Sport Rim 18" (Original) LH	N/C	✓	

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLQ 4997R

B/F

1	1 pc	Rear Tyre 18" LH	out 500.00	480.00	SN
---	------	------------------	------------	--------	----

Labour charge

Panel Beating	1,800.00	1200/-
Spray painting	1,800.00	1200/-
Anti rust	180.00	60/-
Check Wiring	100.00	30/-
Remove and install front and rear door part.	180.00	120/-
Remove and install carpet and seat.	180.00	60/-
Remove and install rear under carriage.	350.00	150/-
To check four wheel alignment	90.00	60/-
To reset and check fault code	350.00	120/-

16/08/2018 @ 1130am

NA declined

1/5m

1/5m

2/5m

Photo after work

Check part price

31/08/2018

1/5m

2/5m

9 to 12 Day

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLQ 4997R

Date : 31.08.2018

Vehicle Model : OPEL MOKKA

Chassis : W0LJD7EC2HB181508

Accident Date : 18.03.2018

TP Ins. AIG

Original Reg Date : 13.07.2017

SUPPLEMENTARY

1	1 pc	Front Door Outer Handle Inner Base	Broken		✓
---	------	------------------------------------	--------	--	---

Eng
2KE Auto

R

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLQ 4997R
Vehicle Model : OPEL MOKKA
Accident Date : 10.08.2018
Original Reg Date : 13.07.2017

Date : 13.08.2018
Chassis : W0LJD7EC2HB181508
TP Ins. CHINA

ESTIMATE

1	1 pc	Front Door LH <i>Bnc</i>	1,495.50
2	1 pc	Front Door Glass LH <i>Scratched</i>	569.00
3	1 pc	Front Door Quarter Glass LH <i>NH</i>	269.30
4	1 pc	Front Door Quarter Glass Rubber LH <i>Nec</i>	132.20
5	1 pc	Front Door Black Sticker LH (Big) <i>Cut</i>	79.20
6	1 pc	Front Door Black Sticker LH (Small) <i>Nec</i>	56.20
7	1 pc	Front Door Outer Chrome Moulding RH <i>St</i>	163.20
8	1 pc	Front Door Inner Frame Garnish LH <i>NH</i>	192.10
9	1 pc	Front Door Wing Mirror LH <i>regrw</i>	856.00
10	1 pc	Front Door Outer Handle LH <i>Cut</i>	96.00
11	1 pc	Front Door Outer Handle Joint LH <i>Nec</i>	52.00
12	1 pc	Front Door Inner Lock LH <i>Dem</i>	492.50
13	1 pc	Front Door Lock Catch LH <i>regrw</i>	58.20
14	1 pc	Front Door Weatherstrip LH <i>Nec</i>	195.00
15	2 pcs	Front Door Hinge LH <i>regrw</i>	164.00
16	1 pc	Front Door Checker LH <i>regrw</i>	106.00
17	1 pc	Front Door Bottom Protector LH <i>St</i>	186.20
18	1 pc	Front Door Channel LH <i>St</i>	159.20
19	1 pc	Front Door Channel Seal LH <i>Nec</i>	96.10
20	1 pc	Front Door Regulator Motor LH <i>NH</i>	592.00
21	1 pc	Front Door Regulator Gear LH <i>St</i>	326.30
22	1 pc	Front Door Inner Trim LH <i>broken mounting</i>	752.10
23	1 set	Front Door Inner Trim Clip LH <i>Nec</i>	40.00
24	1 pc	Front Door Speaker LH <i>NH</i>	180.00
25	1 pc	Rear Door LH <i>Bnc</i>	1,395.50
26	1 pc	Rear Door Black Sticker LH <i>Cut</i>	79.20
27	1 pc	Rear Door Outer Chrome Moulding LH <i>Nec</i>	163.20
28	1 pc	Rear Door Inner Frame Garnish LH <i>NH</i>	192.10
29	1 pc	Rear Door Outer Handle LH <i>NH</i>	96.00
30	1 pc	Rear Door Outer Handle Joint LH <i>NH</i>	52.00
31	1 pc	Rear Door Inner Lock LH <i>NH</i>	419.20
32	1 pc	Rear Door Lock Catch LH <i>NH</i>	58.20
33	1 pc	Rear Door Weatherstrip LH <i>Nec</i>	195.00

C/F

9,958.70

6723.60

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLQ 4997R

B/F

9,958.70

1	2 pcs	Rear Door Hinge LH <i>bt</i>	82.00	164.00	✓
2	1 pc	Rear Door Checker LH <i>distorted</i>		106.00	✓
3	1 pc	Rear Door Bottom Protector LH <i>bt</i>		169.50	✓
4	1 pc	Rear Door Channel LH <i>bt</i>		146.20	✓
5	1 pc	Rear Door Channel Seal LH <i>hlc</i>		96.10	✓
6	1 pc	Rear Door Glass <i>HN</i>		490.20	X
7	1 pc	Rear Door Quarter Glass Rubber <i>hlc</i>		172.90	✓
8	1 pc	Rear Door Quarter Glass Chrome Moulding <i>hlc</i>		212.00	✓
9	1 pc	Rear Door Regulator Motor LH <i>HN</i>		592.00	X
10	1 pc	Rear Door Regulator Gear LH <i>bt</i>		326.30	✓
11	1 pc	Rear Door Inner Trim LH <i>mounting crack</i>		695.00	✓
12	1 set	Rear Door Inner Trim Clip LH <i>hlc</i>		40.00	✓
13	1 pc	Rear Door Speaker LH <i>HN</i>		180.00	X
14	1 pc	Center Door Pillar LH <i>repair</i>		891.50	X
15	1 pc	Rocker Panel Side Skirt <i>mounting crack</i>		752.00	✓
16	1 set	Rocker Panel Side Skirt Clips <i>hlc</i>		40.00	✓
17	1 pc	Rear Fender Arch Garnish LH <i>cut</i>		173.20	✓
18	1 set	Rear Fender Arch Garnish Clip <i>hlc</i>		40.00	✓
19	1 pc	Rear Fender Inner Shield RH <i>svc</i>		79.00	X
20	1 set	Rear Fender Inner Shield Clip RH <i>HN</i>		25.00	X
21	1 pc	Taillamp LH <i>HN</i>		395.00	X
22	1 pc	Taillamp Inner Sealer LH <i>HN</i>		38.00	X
23	1 set	Taillamp Clip LH <i>HN</i>		25.00	X
24	1 pc	Rear Bumper <i>cut</i>		1,450.00	✓
25	2 pcs	Rear Bumper Side Retainer <i>svc</i>		138.00	X
26	1 set	Rear Bumper Clip <i>hlc</i>		50.00	✓
27	1 pc	Rear Bumper Lower Skirt <i>mounting crack</i>		600.00	✓
28	1 pc	Rear Absorber LH <i>distorted</i>	7164.20	415.00	✓
29	1 pc	Rear Wheel Bearing LH <i>Dom</i>		536.00	✓
30	1 pc	Rear Axle Beam <i>HN</i>		2,219.00	X
31	1 pc	Rear Sport Rim 18" (Original) LH <i>cut</i>		980.00	✓

22,195.60

Less 10%

2,219.56

C/D

19,976.04

13887.80

12499.02

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLQ 4997R

B/F

19,976.04

1	1 pc	Rear Tyre 18" LH cut 50% degradation	480.00	SN ✓
			240.00	

Labour charge

Panel Beating	1,800.00	1200/-
Spray painting	1,800.00	1200/-
Anti rust	180.00	60/-
Check Wiring	100.00	30/-
Remove and install front and rear door part.	180.00	120/-
Remove and install carpet and seat.	180.00	60/-
Remove and install rear under carriage.	2880.00	150/-
To check four wheel alignment	90.00	60/-
To reset and check fault code	350.00	40/-

25,486.04

Less 20% 5,097.21

Lump sum \$ 20,388.83

16/08/2018 @ 1130hrs

WIA Antirust

L/Sun

Ryan

LKK Auto

9 days.

15619.02

Supp 98.10

15717.12

L/S 12500/-

25584.14.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Photo after repair
Check Part Prices.

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLQ 4997R

Date : 31.08.2018

Vehicle Model : OPEL MOKKA

Chassis : W0LJD7EC2HB181508

Accident Date : 10.08.2018

TP Ins. *AIG China Teiping*

Original Reg Date : 13.07.2017

SUPPLEMENTARY

1	1 pc	Front Door Outer Handle Inner Base <i>broken</i>	109.00	✓
---	------	--	--------	---

10% 98.10

S. Ryan

2kk Auto

8

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118014873/DCD3N2

Date: 17/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1713991801
Claimant Vehicle No :	SLQ4997R	Insured Vehicle No :	GV5107U
Date of Loss:	10/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D03897C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ4997R	Engine No:	A2170185GU7X0563
Make & Model:	OPEL MOKKA X, 1.6 CDTI 6AT (LED) (A)	Chassis No:	W0LJD7EC2HB181508
Reg. Date:	13/07/2017 (Man. Year: 2017)	Odometer:	85792 km
Colour:	Brown		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R18	Rear Tyre Size:	215/65R18
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	20,554.14	12,837.12	7,717.02	37.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,030.00	2,880.00	2,150.00	42.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,584.14	15,717.12	9,867.02	38.57
Approved Total (Overridden) (S\$)		12,500.00		
(S\$)	25,584.14	12,500.00	13,084.14	51.14
+ GST 7.00/7.00% (S\$)	1,790.89	875.00	915.89	51.14
Nett Amount (S\$)	27,375.03	13,375.00	14,000.03	51.14

INSPECTION

Date of Assignment:	15/08/2018	
Date Inspected:	16/08/2018 Inspected At:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68 Singapore 575643
Estimated Period of Repair:	9.0 days	

Adjuster: BRYAN TANI

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2018)
Parts: 143	OPEL MOKKA X 1.6 CDTI 6AT (LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ4997R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Buckled	1,495.50 FL	*1,495.50 FL
2	1		*FRONT DOOR GLASS LH	Scratched	569.00 FL	*569.00 FL
3	1		*FRONT DOOR QUARTER GLASS LH	Not Necessary	269.30 FL	*- FL
4	1		*FRONT DOOR QUARTER GLASS RUBBER LH	Necessary	132.20 FL	*132.20 FL
5	1		*FRONT DOOR BLACK STICKER LH (BIG)	Cut	79.20 FL	*79.20 FL
6	1		*FRONT DOOR BLACK STICKER LH (SMALL)	Necessary	56.20 FL	*56.20 FL
7	1		*FRONT DOOR OUTER CHROME MOULDING RH	Bent	163.20 FL	*163.20 FL
8	1		*FRONT DOOR INNER FRAME GARNISH LH	Not Necessary	192.10 FL	*- FL
9	1		*FRONT DOOR WING MIRROR LH	Repair	856.00 FL	*- FL
10	1		*FRONT DOOR OUTER HANDLE LH	Cut	96.00 FL	*96.00 FL
11	1		*FRONT DOOR OUTER HANDLE JOINT LH	Necessary	52.00 FL	*52.00 FL
12	1		*FRONT DOOR INNER LOCK LH	Damaged	492.50 FL	*492.50 FL
13	1		*FRONT DOOR LOCK CATCH LH	Repair	58.20 FL	*- FL
14	1		*FRONT DOOR WEATHERSTRIP LH	Necessary	195.00 FL	*195.00 FL
15	2		*FRONT DOOR HINGE LH	Repair	164.00 FL	*- FL
16	1		*FRONT DOOR CHECKER LH	Repair	106.00 FL	*- FL
17	1		*FRONT DOOR BOTTOM PROTECTOR LH	Bent	186.20 FL	*186.20 FL
18	1		*FRONT DOOR CHANNEL LH	Bent	159.20 FL	*159.20 FL
19	1		*FRONT DOOR CHANNEL SEAL LH	Necessary	96.10 FL	*96.10 FL
20	1		*FRONT DOOR REGULATOR MOTOR LH	Not Necessary	592.00 FL	*- FL
21	1		*FRONT DOOR REGULATOR GEAR LH	Bent	326.30 FL	*326.30 FL
22	1		*FRONT DOOR INNER TRIM LH	Mounting Broken	752.10 FL	*752.10 FL
23	1		*FRONT DOOR INNER TRIM CLIP LH (SET)	Necessary	40.00 FL	*40.00 FL
24	1		*FRONT DOOR SPEAKER LH	Not Necessary	180.00 FL	*- FL
25	1		*REAR DOOR LH	Buckled	1,395.50 FL	*1,395.50 FL
26	1		*REAR DOOR BLACK STICKER LH	Cut	79.20 FL	*79.20 FL
27	1		*REAR DOOR OUTER CHROME MOULDING LH	Necessary	163.20 FL	*163.20 FL
28	1		*REAR DOOR INNER FRAME GARNISH LH	Not Necessary	192.10 FL	*- FL
29	1		*REAR DOOR OUTER HANDLE LH	Not Necessary	96.00 FL	*- FL
30	1		*REAR DOOR OUTER HANDLE JOINT LH	Not Necessary	52.00 FL	*- FL
31	1		*REAR DOOR INNER LOCK LH	Not Necessary	419.20 FL	*- FL
32	1		*REAR DOOR LOCK CATCH LH	Not Necessary	58.20 FL	*- FL
33	1		*REAR DOOR WEATHERSTRIP LH	Necessary	195.00 FL	*195.00 FL
34	2		*REAR DOOR HINGE LH	Bent	164.00 FL	*164.00 FL
35	1		*REAR DORO CHECKER LH	Distorted	106.00 FL	*106.00 FL
36	1		*REAR DOOR BOTTOM PROTECTOR LH	Bent	169.50 FL	*169.50 FL
37	1		*REAR DOOR CHANNEL LH	Bent	146.20 FL	*146.20 FL
38	1		*REAR DOOR CHANNEL SEAL LH	Necessary	96.10 FL	*96.10 FL
39	1		*REAR DOOR GLASS	Not Necessary	490.20 FL	*- FL
40	1		*REAR DOOR QUARTER GLASS RUBBER	Necessary	172.90 FL	*172.90 FL
41	1		*REAR DOOR QUARTER GLASS CHROME MOULDING	Necessary	212.00 FL	*212.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*REAR DOOR REGULATOR MOTOR LH	Not Necessary	592.00 FL	*- FL
43	1		*REAR DOOR REGULATOR GEAR LH	Bent	326.30 FL	*326.30 FL
44	1		*REAR DOOR INNER TRIM LH	Mounting Cracked	695.00 FL	*695.00 FL
45	1		*SET REAR DOOR INNER TRIM CLIP LH	Necessary	40.00 FL	*40.00 FL
46	1		*REAR DOOR SPEAKER LH	Not Necessary	180.00 FL	*- FL
47	1		*CENTER DOOR PILLAR LH	Repair	891.50 FL	*- FL
48	1		*ROCKER PANEL SIDE SKIRT	Mounting Cracked	752.00 FL	*752.00 FL
49	1		*SET ROCKER PANEL SIDE SKIRT CLIPS	Necessary	40.00 FL	*40.00 FL
50	1		*REAR FENDER ARCH GARNISH LH	Cut	173.20 FL	*173.20 FL
51	1		*SET REAR FENDER ARCH GARNISH CLIP	Necessary	40.00 FL	*40.00 FL
52	1		*REAR FENDER INNER SHIELD RH	Serviceable	79.00 FL	*- FL
53	1		*SET REAR FENDER INNER SHIELD CLIP RH	Not Necessary	25.00 FL	*- FL
54	1		*TAILLAMP LH	Not Necessary	395.00 FL	*- FL
55	1		*TAILLAMP INNER SEALER LH	Not Necessary	38.00 FL	*- FL
56	1		*SET TAILLAMP CLIP LH	Not Necessary	25.00 FL	*- FL
57	1		*REAR BUMPER	Cut	1,450.00 FL	*1,450.00 FL
58	2		*REAR BUMPER SIDE RETAINER	Serviceable	138.00 FL	*- FL
59	1		*SET REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
60	1		*REAR BUMPER LOWER SKIRT	Mounting Cracked	600.00 FL	*600.00 FL
61	1		*REAR ABSORBER LH	Distorted	415.00 FL	*415.00 FL
62	1		*REAR WHEEL BEARING LH	Damaged	536.00 FL	*536.00 FL
63	1		*REAR AXLE BEAM	Not Necessary	2,219.00 FL	*- FL
64	1		*REAR SPORT RIM 18 (ORIGINAL) LH	Cut	980.00 FL	*980.00 FL
65	1		*FRONT DOOR OUTER HANDLE INNER BASE	Broken	109.00 FL	*109.00 FL
66	1		*REAR TYRE 18 LH (50)(DEPRECIATION)	Cut	480.00 FS	*240.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	22,784.60	14,236.80
- List Item Discount on L Items 10.00/10.00% (S\$)	2,230.46	1,399.68
Total Parts (S\$)	20,554.14	12,837.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,200.00
2	SPRAY PAINTING	New	1,800.00	1,200.00
3	ANTI RUST	New	180.00	60.00
4	CHECK WIRING	New	100.00	30.00
5	REMOVE AND INSTALL FRONT AND REAR DOOR PART	New	180.00	120.00
6	REMOVE AND INSTALL CARPET AND SEAT	New	180.00	60.00
7	REMOVE AND INSTALL REAR UNDER CARRIAGE	New	350.00	150.00
8	TO CHECK FOUR WHEEL ALIGNMENT	New	90.00	60.00
9	TO RESET AND CHECK FAULT CODE	New	350.00	-
Gross Labour Cost (S\$)			5,030.00	2,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >