

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/LAW/0344/2018  
DATE : 14-AUG-2018

MS FIRST CAPITAL INSURANCE LIMITED  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
S(068877)  
TEL : 65073848  
FAX :  
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR CHEN TONGYU  
ADDRESS : BLK 307B ANG MO KIO AVENUE 1  
#12-431  
S(562307)  
TELEPHONE NO : 90235746

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TP-SHA3279T  
VEHICLE NO : SKU5779M  
MODEL CODE : FRLARBZJ11UEA---A--  
MODEL/YEAR : NISSAN QASHQAI 1.2  
ENGINE NO : HRA2168676A  
CHASSIS NO : SJNFEAJ11U1437257  
MILEAGE : 1 KM  
DATE IN : 14/08/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : LAWRENCE  
ACCIDENT DATE : 02/08/2018

pls

Lawrence

CLIC

Revised  
\$100 x 03

= \$300 + GST

= \$321/-

## TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKU5779M  
-----

| S/NO                 | JOB CODE | NATURE OF JOB                                                         | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATION |
|----------------------|----------|-----------------------------------------------------------------------|----------------------|------------------------------|
| 1                    | RPI      | PERFORM RUST PROOFING & TREATMENT FOR AFFECTED<br>PANEL               | 120.00               | .00                          |
| 2                    | RS       | SUPPLY & INSTALL REVERSE SENSOR                                       | 110.00               | 110.00                       |
| 3                    | SEALI    | APPLY SEALANT TO ALL AFFECTED PANEL JOINTS &<br>RESEAL NECESSARY AREA | 100.00               | 100.00                       |
| 4                    | ZZ/001   | REPAIR END PANEL AND RENEW REAR BUMPER                                | 800.00               | 390.00                       |
| 5                    | ZZ/002   | S/PAINT REAR BUMPER (2 TONE) AND END PANEL                            | 1000.00              | 350.00                       |
| TOTAL LABOUR CHARGES |          |                                                                       | 2130.00              | 950.00                       |

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKU5779M

| S/NO                                                  | PARTS DESCRIPTION             | PARTS NUMBER  | DAMAGED PARTS & PRICES |      |        | REMARKS |
|-------------------------------------------------------|-------------------------------|---------------|------------------------|------|--------|---------|
|                                                       |                               |               | NETT                   | LIST | S/NETT |         |
| 1                                                     | GROMMET BUMPER \$2.20 EA X 02 | 01281-00111   |                        |      | 4.40   | OK      |
| 2                                                     | CLIP BUMPER \$7.40 EA X 03    | 85284-JD00A   | 22.20                  |      |        | OK      |
| 3                                                     | CLIP BUMPER \$1.20 EA X 04    | 01553-05933   | 4.80                   |      |        | OK      |
| 4                                                     | RETAINER-BUMPER RH            | 79184-4EA0A   | 23.80                  |      |        | X       |
| 5                                                     | GROMMET BUMPER \$2.50 EA X 04 | 63846-5V000   | 10.00                  |      |        | OK      |
| 6                                                     | BRACKET-BUMPER RH             | 85220-4EA0A   | 35.90                  |      |        | X       |
| 7                                                     | FINISHER-REAR BUMPER TOW      | 85071-4EA0A   | 16.80                  |      |        | OK      |
| 8                                                     | FASCIA-RR BUMP                | 85022-4EA0H   | 717.00                 |      |        | OK      |
| 9                                                     | SUNDRIES                      | NPN           |                        |      | 100.00 | X       |
| 10                                                    | REVERSE SENSOR(J11 & T32)     | SENSOR-TE5140 |                        |      | 210.00 | X       |
| SUB TOTAL                                             |                               |               | 770.80                 | 0.00 | 4.40   |         |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |                               |               | 154.16                 | 0.00 | 0.00   |         |
| GRAND TOTAL                                           |                               |               | 616.64                 | 0.00 | 4.40   |         |
| OVERALL TOTAL                                         |                               |               | 621.04                 |      |        |         |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKU5779M

|                           |         |
|---------------------------|---------|
| NETT ITEM                 | 770.80  |
| LESS 20.00%)              | -154.16 |
| NETT AMOUNT               | 616.64  |
| LIST ITEM                 | 0.00    |
| LESS 30.00%)              | 0.00    |
| LIST AMOUNT               | 0.00    |
| SPECIAL NETT ITEM         | 4.40    |
| LESS .00%)                | 0.00    |
| SPECIAL NETT AMOUNT       | 4.40    |
| TOTAL LABOUR CHARGES      | 950.00  |
| TOTAL SPARE PARTS CHARGES | 621.04  |
|                           | -----   |
| TOTAL CHARGES             | 1571.04 |
| ADD 7 % GST               | 109.97  |
|                           | -----   |
| GRAND TOTAL               | 1681.01 |
|                           | -----   |