

2-09/2001

SS REC BY:

REF: CS/FCI18014875/TI v03 n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Genee Jer

of

FCI

Date/Time:

14/8/18 @ 6.28pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 5779M

Insured:

8HA 3279T

at Workshop m/s

Tan chong motor

Tel:

6469 4091

of

913 Bkt timah Rd

Policy No:

Claim No:

D18005927MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 02/08/2018

30/8/18 @ 10am.

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(DS)

Date/Time:

934am @ 15/8/18

Person Contacted:

Lawrence

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	SKU 5779M-x
	8HA 3279T-NS/INC16011420/HT vbn2 DOA: 16/6/16
3/9/18	Email preli revised to FCI
21/9/18	@ 448pm Sipah will check
24/9/18	Check with Taufik again, Apply Sealant OK

Tanflin

REF:

FCI

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD (TP) WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK45779M Yr Regn: 295 July
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Nissan Qashqar 1.2 1197
Colour: Blue A/C Insured / Std / NI / NA
Sp. Reading: 65138 T/Radio: Insured / Std / NI / NA
Eng/No: 3JNFEA J1141437257
C/No: _____
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/60R17
R: _____
BS / DUN / ~~EXX~~ / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: 6 Rear: 6
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A. 34/8/18 elow
Survey held at: TC Bkt Tind
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

24/9/18 Final fig \$ 1571.04 Confirmed by email (Ref 1537.76, 499)

RECEIVED 24 SEP 2018

Copy/Time: File Pass to? ☐ Prel. Report
☐ Final Report

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee
Transportation

Date/Time: File Return to? 24/9- typist

Add Fee: ☐ Site Insp. \$
☐ Interview \$
☐ Tech. Insp. \$
☐ Workshop \$

Report Format: CWS
Lump Sum / LB \$ 1571.04

130
50
16
196



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005927MFSH

Our ref: CS/FCI18014875/T1vd3

Date: 3/9/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKU 5779M


We thank you for your instruction on 14/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/8/2018 at the premises of M/s TAN CHONG MOTOR SALES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,108.80
Revised Estimate Amount	: S\$1,471.04
"Check" Items Amount	: S\$357.76
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-08-2018	Our Ref No. D18005927MFSH
Accident Date	02-08-2018	Claim Type. Third Party
Insured Vehicle	SHA3279T	Third Party Vehicle. SKU5779M
Survey Location	911 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE	
Contact Person.	LAWRENCE TEO	
Contact No.	64694091/ 67038914	Fax No. 64697472
Survey Type	DIRECT SETTLEMENT: EST. COR - \$3,108.80	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN CHONG MOTOR SALES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Norsipah <norsipah@tanchong.com>
Sent: Tuesday, 11 September 2018 12:03 PM
To: Veron Chen (LKKAUTO); Lawrence Teo
Subject: Re: SKU 5779M-DOA: 2/8/2018

Hi Veron,

Vehicle just in today for repair. Will finalize once completed. Thank you.

Best Regards,

Sipah
Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
D: +6567038915
E: norsipah@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Tuesday, September 11, 2018 11:46 AM
To: Lawrence Teo; Norsipah
Subject: SKU 5779M-DOA: 2/8/2018

Dear Sipah/Lawrence,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 3 September 2018 2:02 PM
To: 'Claim Workflow System'
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005927MFSH/1, SKU 5779M
Attachments: SKU 5779M PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKU 5779M
Date of survey: 30/8/2018
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 15 August 2018 9:38 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005927MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 14 August 2018 6:27 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005927MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 24 September 2018 11:48 AM
To: 'Lawrence Teo'; Norsipah
Cc: SUR
Subject: RE: COR Finalization SKU5779M doa 02.08.2018

Dear Lawrence,

WITHOUT PREJUDICE

Confirmed amount \$1571.04 before GST @ 3 working days.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lawrence Teo <lawrenceteo@tanchong.com>
Sent: Monday, 24 September 2018 11:25 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Norsipah <norsipah@tanchong.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: COR Finalization SKU5779M doa 02.08.2018

Dear Veron,

Is Necessary

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472
Email: lawrenceteo@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: 24 September 2018 10:50
To: Norsipah <norsipah@tanchong.com>
Cc: Lawrence Teo <lawrenceteo@tanchong.com>; SUR <sur@lkkauto.com>
Subject: FW: COR Finalization SKU5779M doa 02.08.2018

Dear Sipah,

WITHOUT PREJUDICE

The below labour is not allow.

Please close at \$1471.04 before GST @ 3 working days.

Kindly check and confirm.

APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	100.00
---	--------	--------

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norsipah <norsipah@tanchong.com>

Sent: Friday, 21 September 2018 4:53 PM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: COR Finalization SKU5779M doa 02.08.2018

Hi

Please refer attach for finalization.

Thank you.

Best Regards,

Sipah

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

E: norsipah@tanchong.com D:+6567038915

Website: www.tanchong.com :: www.nissan.com.sg

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg
reg no. 1978-00490-N



CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION)

(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 EDITION (REPUBLIC OF SINGAPORE)

OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

**PRIVATE CAR
Comprehensive**

Certificate No. : DMPPHQ18-005098

1. Index Mark and Registration Number of Vehicles

SKU5779M

2. Name of Policyholder

CHEN TONGYU

3. Effective Date of the Commencement of Insurance for the purpose of the Act

31/07/2018

4. Date of Expiry of Insurance

30/07/2019

5. Person or Classes of persons entitled to drive*

(a) The Policyholder

(b) Any other person who is driving on the Policyholder's order or with his permission permission.

Form: MX2

Excess:

Insured/Named Driver:

S\$500.00

Unnamed Drivers:

S\$1,000.00

YEID Additional:

S\$3,000.00

EQ Insurance-MARS Motor
Accident Help Center

6311 3211



* Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitation as to use*

Use for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover :

(a) use for hire or reward

(b) use for racing, pace-making, reliability trials or speed testing

(c) use for the carriage of goods (other than samples) in connection with any trade or business

(d) use for any purpose in connection with the Motor Trade

*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

Hire Purchase :

b000074/MoneySmart Financial Pte Ltd
Date of Issue : 19/07/2018 15:16

Authorised Signatory
EQ Insurance Company Limited

Exp No. : DMPPHQ17-003735

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8423920H



Name

CHEN TONGYU

陈 通 煜

Race

CHINESE

Date of birth

18-08-1984

Sex

M

S8423920H

Country/Place of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE




Licence Number: S8423920H

Name

CHEN TONGYU

Birth Date: 18 Aug 1984

Issue Date: 06 Sep 2004



001282398K

Driving License

5415306



NRIC No. S8423920H



Date of issue

23-01-2015

Address

APT BLK 307B ANG MO KIO AVENUE 1
#12-431
SINGAPORE 562307

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CL

PASS D

Class 3

Motor Cars of unladen weight not exceeding
3000 kg with not more than 7 passengers,
exclusive of the driver, and Motor Tractors
and other Motor Vehicles of unladen weight
not exceeding 2500 kg

06 Sep 2011

NP 428A



License No. S8423920H

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0344/2018
DATE : 14-AUG-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN: MOTOR CLAIM DEPT

OWNER'S NAME : MR CHEN TONGYU
ADDRESS : BLK 307B ANG MO KIO AVENUE 1
#12-431
S(562307)
TELEPHONE NO : 90235746

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHA3279T
VEHICLE NO : SKU5779M
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2168676A
CHASSIS NO : SJNFEAJ11U1437257
MILEAGE : 1 KM
DATE IN : 14/08/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 02/08/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT ~~WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

Tanpin 97445749
- WP
30/8/18 @ 1030
03 days
Resurvey before paint
sur @ Inkan to - w.m.

3/9/18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKU5779M

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X mm
2	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	✓ ✓
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X ✓
4	22/001	REPAIR END PANEL AND RENEW REAR BUMPER	800.00	390 ✓
5	22/002	S/PAINT REAR BUMPER (2 TONE) AND END PANEL	1000.00	250 350 ✓
TOTAL LABOUR CHARGES			2130.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKU5779M

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40 <i>per ✓</i>
2 CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20	<i>rec ✓</i>	
3 CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80	<i>rec ✓</i>	
4 RETAINER-BUMPER RH	79184-4EA0A	23.80	<i>? X nn</i>	
5 GROMMET BUMPER \$2.50 EA X 04	63846-5V000	10.00	<i>rec ✓</i>	
6 BRACKET-BUMPER RH	85220-4EA0A	35.90	<i>? X nn</i>	
7 FINISHER-REAR BUMPER TOW	85071-4EA0A	16.80	<i>de ✓</i>	
8 FASCIA-RR BUMP	85022-4EA0H	717.00	<i>de ✓</i>	
9 SUNDRIES	NPN			100.00 <i>? X nn</i>
10 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00 <i>? X nn</i>
SUB TOTAL		830.50	0.00	314.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		166.10	0.00	0.00
GRAND TOTAL		664.40	0.00	314.40
OVERALL TOTAL		978.80		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKU5779M

TOTAL LABOUR CHARGES	2130.00
TOTAL SPARE PARTS CHARGES	978.80
GRAND TOTAL	3108.80 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0344/2018
DATE : 14-AUG-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR CHEN TONGYU
ADDRESS : BLK 307B ANG MO KIO AVENUE 1
#12-431
S(562307)
TELEPHONE NO : 90235746

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHA3279T
VEHICLE NO : SKU5779M
MODEL CODE : FRLARBEJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2168676A
CHASSIS NO : SJNFEAJ11U1437257
MILEAGE : 1 KM
DATE IN : 14/08/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 02/08/2018

OLB

TRAFIC

CLIC

RMK
#100 x 03

= #300 + GST

= #321/-

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKU5779M

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	.00
2 RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	110.00
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	100.00
4 ZZ/001	REPAIR END PANEL AND RENEW REAR BUMPER	800.00	390.00
5 ZZ/002	S/PAINT REAR BUMPER (2 TONE) AND END PANEL	1000.00	350.00
	TOTAL LABOUR CHARGES	2130.00	950.00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKU5779M

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40	OK
2 CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20			OK
3 CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80			OK
4 RETAINER-BUMPER RH	79184-4EA0A	23.80			X
5 GROMMET BUMPER \$2.50 EA X 04	63846-5V000	10.00			OK
6 BRACKET-BUMPER RH	85220-4EA0A	35.90			X
7 FINISHER-REAR BUMPER TOW	85071-4EA0A	16.80			OK
8 FASCIA-RR BUMP	85022-4EA0H	717.00			OK
9 SUNDRIES	NPN			100.00	X
10 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00	X
SUB TOTAL		770.80	0.00	4.40	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		154.16	0.00	0.00	
GRAND TOTAL		616.64	0.00	4.40	
OVERALL TOTAL		621.04			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKU5779M

NETT ITEM	770.80
LESS 20.00%)	-154.16
NETT AMOUNT	616.64

LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	4.40
LESS .00%)	0.00
SPECIAL NETT AMOUNT	4.40

TOTAL LABOUR CHARGES	950.00
TOTAL SPARE PARTS CHARGES	621.04

TOTAL CHARGES	1571.04
ADD 7 % GST	109.97

GRAND TOTAL	1681.01
-------------	---------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014875/T1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3279T	Veh. Inspected	SKU 5779M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005927MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	14/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI 1.2	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	SJNFEAJ11U1437257	Colour	BLUE	
Odometer	65138	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/60 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/60 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/60 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/08/2018	Inspection Date	30/08/2018	
Survey held at	TAN CHONG MOTOR SALES PTE LTD 913, BUKIT TIMAH RD, SINGAPORE 589623.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 5779M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
3	CLIP BUMPER @\$7.40 (N)	NECESSARY	22.20	22.20
4	CLIP BUMPER @\$1.20 (N)	NECESSARY	4.80	4.80
1	RETAINER-BUMPER RH (N)	NOT NECESSARY	23.80	-
4	GROMMET BUMPER @\$2.50 (N)	NECESSARY	10.00	10.00
1	BRACKET-BUMPER RH (N)	NOT NECESSARY	35.90	-
1	FINISHER-REAR BUMPER TOW (N)	DEFORMED	16.80	16.80
1	FASCIA-RR BUMP (N)	DEFORMED	717.00	717.00
	LESS 20% DISCOUNT		-166.10	-154.16
			664.40	616.64
SPECIAL NETT ITEMS				
2	GROMMET BUMPER @\$2.20 (SN)	NECESSARY	4.40	4.40
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
1	REVERSE SENSOR (J11 & T32)(SN)	NOT NECESSARY	210.00	-
			314.40	4.40
LABOUR				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	NOT NECESSARY	120.00	-
	SUPPLY & INSTALL REVERSE SENSOR.		110.00	110.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		100.00	100.00
	REPAIR END PANEL AND RENEW REAR BUMPER.		800.00	390.00
	S/PAINT REAR BUMPER (2 TONE) AND END PANEL.		1,000.00	350.00
			2,130.00	950.00
GRAND TOTAL			3,108.80	1,571.04
RECOMMENDED COST OF REPAIRS				1,571.04

Report Ref No. CS/FCI18014875/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.