

ASS. REC. BY:

REF

CS3/AWA 18014883/G24d3k2

Special Instruction:

Surveyor

GQ

ASSIGNMENT (Office)

From (Person):

Hew Lee Fong

of

AWAC

Date/Time:

15/8/18 @ 11:08am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 470B

Insured:

GBH 5943E

at Workshop in/s:

SLK Auto

Tel:

9123 7949

of

8 Kaki Bkt Ave 4 # 03-21

Policy No:

AVCP8009242/800

Claim No:

GBH 5943E / KW

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/08/2018

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

12:46pm @ 15/8/18

Person Contacted:

Mr. GUO

Vehicle-IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLK 470B - X

GBH 5943E - X

1/8/11/13) wef
ASS. REC. BY:

PRS
XML

REF: AWAC

25/2E ✓

ASSIGNMENT

From: _____ Date: 16/8/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 470 B

at Workshop m/s SLK Auto

of 8 kaki Bkt Ave 4 # 03-21

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record) After 10am.

Make of Veh: Mr. GUO @ 9123 79 49

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLK 470 B Yr Regn: 03 Jan 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 2.4

Make: Honda odyssey c.c 2356

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 40978 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHM RC 1890 GC 207864

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55 R17

R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 16-08-18

12:15 pm

Date / Time Action / Instruction

\$ 3000 - \$ 4000

18/8/18 Submit PRS Report

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: 100

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

100

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Catherine Chong (LKK Auto)

From: Hew, LeeFong <LeeFong.Hew@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Wednesday, 15 August, 2018 11:08 AM
To: 'assignments'
Cc: SUR; 'accident@kscgp.com'; 'jiapei@kscgp.com'
Subject: TP Survey assignment for SLK 470B - DOA: 08/08/2018 Our ref: GBH 5943E/KW

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do not** have consensus in the appointment of the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SLK 470 B
Insured Vehicle	:	GBH 5943 E (Accident not Reported)
Policy Number	:	AVCPSB0092421800
Name of Workshop	:	STK Auto (S) Pte Ltd
Contact Number	:	9123 7949
Person to Contact	:	Guohua
Estimated Cost of repairs	:	\$ NA

Regards,
Claims Division

Copy to KSCGP Juris LLP (Your Ref: SLK470B/STK/jp/mf) via Email

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail

in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS3/AWA18014883/Gz4d3

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 15-08-2018



Code : AWA

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBH 5943E	Veh. Inspected	SLK 470B
Policy No.	AVCPSB0092421800	Coverage (\$)	0.00
Claim No.	GBH5943E/KW	Excess (\$)	0.00
Assign From		Assign Date	15/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	08/08/2018	Inspection Date	16/08/2018
Survey held at	STK AUTO (S) PTE LTD 8 KAKI BUKIT AVE 4 #03-21 PREMIER@KAKI BUKIT SSINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2512E
Vehicle Details	
Vehicle No.:	SLK470B
Vehicle to be Exported:	No
Intended De-registration Date:	17 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	K24W72013389
Chassis No.:	JHMRC1890GC207864
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$32,861.00
Original Registration Date:	03 Jan 2017
First Registration Date:	03 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$38,006.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jan 2027
PARF Rebate Amount:	\$28,504.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jan 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,340.00
COE Rebate Amount:	\$47,192.00
Total Rebate Amount:	\$75,696.00

The information contained herein is correct as at 17 Aug 2018

OK


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLE TREE ANSON S 079914		Ref: CS3/AWA18014883/Gz4d3e2 Date: 21-08-2018	
		Code: AWA	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBH 5943E	Veh. Inspected	SLK 470B
Policy No.	AVCPSP0092421800	Coverage (\$)	0.00
Claim No.	GBH5943E/KW	Excess (\$)	0.00
Assign From		Assign Date	15/08/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA ODYSSEY 2.4	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMRC1890GC207864	Colour	WHITE
Odometer	40978 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.			
5. General Information			
Accident Date	08/08/2018	Inspect Date / Time	16/08/2018 (12:15 PM)
Survey held at	STK AUTO (S) PTE LTD 8 KAKI BUKIT AVE 4 #03-21 PREMIER@KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/AWA18014883/Gz4d3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.