

**Trans-cab Auto Services Pte Ltd**

AAD1808-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5059M**

*Not Authorised*  
*11 Lny @ 3350/h*

Vehicle No.:	<b>SHC 5059M</b>
Chassis No.:	VF1ABL15AUC276084
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	10.8.2018
Third Party Insurer :	<b>TOKIO MARINE</b>

<b>PART</b>		<b>LIST</b>	
1	1 BUMPER COVER REAR	\$	<i>Buolnd</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Pollem</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>cm</i> 43.61 ✓
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1 BOOT REAR	\$	<i>R</i> 2,872.68
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36
19	1 BOOT BADGE	\$	<i>na</i> 225.36
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81

} X

**Trans-cab Auto Services Pte Ltd**

**AAD1808-061**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5059M**

30	1 FENDER PANEL REAR LH	\$	R	3,299.13
31	1 WHEELARCH REAR LH	\$	Sm	543.47
32	1 FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45
33	1 FENDER PANEL REAR RH	\$	R	3,299.13
34	1 WHEELARCH REAR RH	\$	Sm	543.47
35	1 TAILLAMP RH	\$	Sm	552.55
36	1 TAILLAMP PANEL RH	\$	R	986.70
37	1 TAILLAMP LH	\$	Sm	552.55
38	1 TAILLAMP PANEL LH	\$	R	986.70
39	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sm	404.56
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88
42	1 SPARE WHEEL PANEL TRIM	\$	Sm	612.21
43	1 EXHAUST REAR	\$	R	7,489.05
44	1 EXHAUST CAP REAR	\$	R	230.49
45	1 CHASSIS PANEL REAR RH	\$	R	3,766.43
46	1 KUCKLE ARM REAR RH L70Y	\$	Sm	736.67
47	1 BRAKE DISC REAR L70Y	\$	Sm	525.91
48	1 WHEEL HUB NUT L70Y	\$	Sm	51.11
49	1 WHEEL HUB CAP L70Y	\$	Sm	57.82
50	1 ABS SENSOR REAR RH L70Y	\$	Sm	255.75
51	1 REAR AXLE L70Y	\$	Sm	4,167.03
52	1 AXLE ARM RH L70Y	\$	Sm	117.22
53	1 LOWER ARM REAR RH L70Y	\$	Sm	905.99
54	1 ABSORBER REAR	\$	Sm	389.75
55	1 STABILIZER BAR REAR RH	\$	Sm	604.65
56	1 BRAKE CALIPER REAR RH	\$	Sm	1,300.67
57	1 WHEEL HOUSING PANEL REAR RH	\$	R	4,682.09
58	1 CHASSIS PANEL REAR RH	\$	R	3,766.43

} X

<b>TOTAL</b>	<b>\$</b>	<b>56,525.01</b>
<b>10%</b>	<b>\$</b>	<b>5,652.50</b>
	<b>\$</b>	<b>50,872.51</b>

**Special Nett**

1 1SET PARKING AID	\$	Short 700.00	600.00
2 1SET REAR BUMPER CLIP	\$	nc 66.00	—
3 1SET BUMPER BRACKET CTR CLIP	\$	nc 33.00	—
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nc 10.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD1808-061**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5059M**

5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	sc	17.82	} X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
19	1 TAILLAMP CLIP RH	\$	na	5.00	
20	1 TAILLAMP CLIP LH	\$	na	5.00	
21	2 REAR WINDSCREEN SELANT	\$	na	80.00	
22	1 WINDSCREEN MOULDING	\$	na	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sc	385.00	
25	1 SPARE TYRE	\$	sc	330.00	
26	1 RIGHT REAR TYRE	\$	sc	330.00	
27	1 RIGHT REAR TYRE RIM	\$	sc	380.00	

**TOTAL \$ 2,935.02**

**TOTAL PARTS \$ 53,807.53**

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	3001
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X

**Trans-cab Auto Services Pte Ltd**

**AAD1808-061**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5059M**

To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X

**TOTAL \$ 12,540.00**

**Over All Total \$ 66,347.53**

**(LUMP SUM)**

**Repair Days**

~~20 DAYS~~  
*2 1/2 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: