



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TOKIO MARINE INSURANCE SINGAPORE LTD		Ref : CC3/TMI18014907/Kvd3	
20 MCCALLUM STREET #09-01 TOKIO MARINE CENTRESINGAPORE 069046		Date : 16-08-2018	
Code : TMI			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLU 8229C	Veh. Inspected	SHC 5059M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/08/2018	Inspection Date	15/08/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

Pre-Repair Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		17 Aug 2018 11:10 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	A&G , Co. Reg. No.: 53343696J								
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHC5059M	Date of Loss:	10/08/2018 00:00 - :59						
Claim Type:	TP / M1803984	Policy/Cover Note No.:	MI001810 (Comprehensive) Coverage: 08/12/2017 - 08/12/2018						
Vehicle Reg. No. (Insured):	SLU8229C	Policy No. (Claimant):	VPX/P1680520						
		Excess:	S\$2,000.00						
Repairer:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/08/2018]								
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 16 August 2018 2:51 PM
To: motorclaims@tokiomarine.com.sg
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD,DOA: 10/8/2018, SHC 5059M (TP VEHICLE), SLU 8229C (OI VEHICLE)
Attachments: EST.pdf; GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5059M, M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 ON 15/8/2018.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/08/2018 09:49
Date Of Accident	10/08/2018 01:00
Exact Location Of Accident	TAMPINES AVENUE 9
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHC5059M
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	TEO SENG HUAT
NRIC No	S1471873G
Date Of Birth	11/05/1961
Occupation	OUTDOOR
Date Of Driving Pass	19/03/1979
Driving Experience	39 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97519801
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 239 BISHAN STREET 22 #21-202
Postcode	670239
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 10/8/18 at about 0100 hours, I was travelling straight on the extreme left lane along Tampines Avenue 9 when I saw a passenger flag my taxi, I slow down and made a stop. Suddenly, I felt an impact. Vehicle B (SLU8229C) had hit onto my taxi rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE IS TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU8229C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

AAD1808-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5059M

Not Authorised
11 Sep @ 3350/h

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5059M
VF1ABL15AUC276084
RENAULT
LATITUDE
10.8.2018
TOKIO MARINE

PART

LIST

PART	LIST
1 1 BUMPER COVER REAR	\$ <i>Burland</i> 1,108.46 ✓
2 1 BUMPER LOWER REAR	\$ <i>Pulliam</i> 768.84 ✓
3 1 BUMPER BRACKET CTR REAR	\$ <i>SL</i> 113.47 X
4 1 BUMPER BRACKET SIDE RH REAR	\$ <i>SL</i> 135.97 X
5 1 BUMPER RETAINER RH REAR	\$ <i>SL</i> 44.99 X
6 1 BUMPER REFLECTOR RH	\$ <i>CM</i> 43.61 ✓
7 1 BUMPER BRACKET SIDE LH REAR	\$ <i>SL</i> 135.97 X
8 1 BUMPER RETAINER LH REAR	\$ <i>SL</i> 44.99 X
9 1 BUMPER REFLECTOR LH	\$ <i>SL</i> 43.61 X
10 1 BUMPER BEAM REAR	\$ <i>B</i> 777.52 ✓
11 1 BUMPER BEAM BRACKET LH REAR	\$ <i>B</i> 225.95 ✓
12 1 BUMPER BEAM BRACKET RH REAR	\$ <i>R</i> 225.95 X
13 1 BOOT REAR	\$ <i>R</i> 2,872.68
14 1 BOOT FINISHER	\$ <i>SL</i> 470.06
15 1 BOOT WHEATERSTRIP	\$ <i>SL</i> 323.05
16 1 BOOT REFLECTOR LAMP LH	\$ <i>SL</i> 493.35
17 1 BOOT REFLECTOR LAMP RH	\$ <i>SL</i> 493.35
18 1 BOOT BADGE 'RENAULT'	\$ <i>na</i> 225.36
19 1 BOOT BADGE	\$ <i>na</i> 225.36
20 1 BOOT STRUT LH	\$ <i>SL</i> 276.08
21 1 BOOT STRUT RH	\$ <i>SL</i> 276.08
22 1 BOOT HINGE LH	\$ <i>R</i> 367.84
23 1 BOOT HINGE RH	\$ <i>R</i> 367.84
24 1 BOOT INNER TRIM	\$ <i>SL</i> 586.45
25 1 BOOT SWITCH	\$ <i>SL</i> 168.13
26 1 BOOT LOCK	\$ <i>R</i> 202.67
27 1 BOOT LOCK CATCH	\$ <i>R</i> 74.40
28 2 LICENCE PLATE LAMP	\$ <i>SL</i> 50.52
29 2 BOOT RUBBER PLUG	\$ <i>SL</i> 221.81

X

Trans-cab Auto Services Pte Ltd

AAD1808-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5059M

30	1 FENDER PANEL REAR LH	\$	R 3,299.13
31	1 WHEELARCH REAR LH	\$	Sm 543.47
32	1 FENDER PANEL INNER TRIM REAR RH	\$	Sm 671.45
33	1 FENDER PANEL REAR RH	\$	R 3,299.13
34	1 WHEELARCH REAR RH	\$	Sm 543.47
35	1 TAILLAMP RH	\$	Sm 552.55
36	1 TAILLAMP PANEL RH	\$	R 986.70
37	1 TAILLAMP LH	\$	Sm 552.55
38	1 TAILLAMP PANEL LH	\$	R 986.70
39	1 OUTER PANEL REAR (End Panel)	\$	R 1,471.77
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sm 404.56
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 2,189.88
42	1 SPARE WHEEL PANEL TRIM	\$	Sm 612.21
43	1 EXHAUST REAR	\$	R 7,489.05
44	1 EXHAUST CAP REAR	\$	R 230.49
45	1 CHASSIS PANEL REAR RH	\$	R 3,766.43
46	1 KUCKLE ARM REAR RH L70Y	\$	Sm 736.67
47	1 BRAKE DISC REAR L70Y	\$	Sm 525.91
48	1 WHEEL HUB NUT L70Y	\$	Sm 51.11
49	1 WHEEL HUB CAP L70Y	\$	Sm 57.82
50	1 ABS SENSOR REAR RH L70Y	\$	Sm 255.75
51	1 REAR AXLE L70Y	\$	Sm 4,167.03
52	1 AXLE ARM RH L70Y	\$	Sm 117.22
53	1 LOWER ARM REAR RH L70Y	\$	Sm 905.99
54	1 ABSORBER REAR	\$	Sm 389.75
55	1 STABILIZER BAR REAR RH	\$	Sm 604.65
56	1 BRAKE CALIPER REAR RH	\$	Sm 1,300.67
57	1 WHEEL HOUSING PANEL REAR RH	\$	R 4,682.09
58	1 CHASSIS PANEL REAR RH	\$	R 3,766.43
TOTAL		\$	56,525.01
10%		\$	5,652.50
		\$	50,872.51

} X

Special Nett

1	1SET PARKING AID	\$	Short 700.00 600sm
2	1SET REAR BUMPER CLIP	\$	nc 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	nc 33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nc 10.00 X

Trans-cab Auto Services Pte Ltd

AAD1808-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5059M

5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	sa	17.82	} X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
19	1 TAILLAMP CLIP RH	\$	na	5.00	
20	1 TAILLAMP CLIP LH	\$	na	5.00	
21	2 REAR WINDSCREEN SELANT	\$	na	80.00	
22	1 WINDSCREEN MOULDING	\$	na	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sa	385.00	
25	1 SPARE TYRE	\$	sa	330.00	
26	1 RIGHT REAR TYRE	\$	sa	330.00	
27	1 RIGHT REAR TYRE RIM	\$	sa	380.00	

TOTAL \$ 2,935.02

TOTAL PARTS \$ 53,807.53

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	3001
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1808-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5059M

To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X

TOTAL \$ 12,540.00

Over All Total \$ 66,347.53

66727.51.

(LUMP SUM)

Repair Days

-20 DAYS

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18014907/KVD3N2
Date: 27/08/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI001810
Claimant Vehicle No :	SHC5059M	Insured Vehicle No :	SLU8229C
Date of Loss:	10/08/2018	Nature of Claim:	TP
		Claim No:	M1803984

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5059M	Engine No:	M9R8839C000767
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC276084
Reg. Date:	02/12/2013 (Man. Year: 2013)	Odometer:	235746 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	53,807.51	3,396.94	50,410.57	93.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,920.00	800.00	12,120.00	93.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	66,727.51	4,196.94	62,530.57	93.71
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	66,727.51	3,350.00	63,377.51	94.98
+ GST 7.00/7.00% (S\$)	4,670.93	234.50	4,436.43	94.98
Nett Amount (S\$)	71,398.44	3,584.50	67,813.94	94.98

INSPECTION

Date of Assignment:	17/08/2018	
Date Inspected:	15/08/2018 Inspected At:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	2.5 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Aug 2018)
Parts: 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC5059M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Buckled/Dented	1,108.46 FL	*1,108.46 FL
2	1	*BUMPER LOWER REAR	Dented/Cracked	768.84 FL	*768.84 FL
3	1	*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1	*BUMPER REFLECTOR RH	Cracked	43.61 FL	*43.61 FL
7	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1	*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1	*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1	*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1	*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1	*BOOT REAR	Repair	2,872.68 FL	*- FL
14	1	*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1	*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1	*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1	*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1	*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
19	1	*BOOT BADGE	Not Necessary	225.36 FL	*- FL
20	1	*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1	*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1	*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1	*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1	*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1	*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1	*BOOT LOCK	Repair	202.67 FL	*- FL
27	1	*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2	*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2	*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
31	1	*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
32	1	*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
33	1	*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
34	1	*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
35	1	*TAILLAMP RH	Serviceable	552.55 FL	*- FL
36	1	*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
37	1	*TAILLAMP LH	Serviceable	552.55 FL	*- FL
38	1	*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
39	1	*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
40	1	*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
41	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
42	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
43	1	*EXHAUST REAR	Repair	7,489.05 FL	*- FL
44	1	*EXHAUST CAP REAR	Repair	230.49 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*CHASSIS PANEL REAR RH	Repair	3,766.43 FL	*-FL
46	1	*KUCKLE ARM REAR RH L70Y	Serviceable	736.67 FL	*-FL
47	1	*BRAKE DISC REAR L70Y	Serviceable	525.91 FL	*-FL
48	1	*WHEEL HUB NUT L70Y	Serviceable	51.11 FL	*-FL
49	1	*WHEEL HUB CAP L70Y	Serviceable	57.82 FL	*-FL
50	1	*ABS SENSOR REAR RH L70Y	Serviceable	255.75 FL	*-FL
51	1	*REAR AXLE L70Y	Serviceable	4,167.03 FL	*-FL
52	1	*AXLE ARM RH L70Y	Serviceable	117.22 FL	*-FL
53	1	*LOWER ARM REAR RH L70Y	Serviceable	905.99 FL	*-FL
54	1	*ABSORBER REAR	Serviceable	389.75 FL	*-FL
55	1	*STABILIZER BAR REAR RH	Serviceable	604.65 FL	*-FL
56	1	*BRAKE CALIPER REAR RH	Serviceable	1,300.67 FL	*-FL
57	1	*WHEEL HOUSING PANEL REAR RH	Repair	4,682.09 FL	*-FL
58	1	*CHASSIS PANEL REAR RH	Repair	3,766.43 FL	*-FL
59	1	*SET PARKING AID	Shorted	700.00 FS	*600.00 FS
60	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
61	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
62	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
63	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
64	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
65	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
66	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
67	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
68	1	*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*-FS
69	1	*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS
70	1	*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*-FS
71	1	*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*-FS
72	1	*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
73	1	*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*-FS
74	1	*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*-FS
75	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*-FS
76	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*-FS
77	1	*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
78	1	*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS
79	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
80	1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
81	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
82	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*-FS
83	1	*SPARE TYRE	Serviceable	330.00 FS	*-FS
84	1	*RIGHT REAR TYRE	Serviceable	330.00 FS	*-FS
85	1	*RIGHT REAR TYRE RIM	Serviceable	380.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	59,460.01	3,689.38
- List Item Discount on L Items 10.00/10.00% (\$\$)	5,652.50	292.44
Total Parts (\$\$)	53,807.51	3,396.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	300.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	-
11	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
14	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
Gross Labour Cost (\$\$)			12,920.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >