

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/04/2017 16:01
Date Of Accident	18/04/2017 11:00
Exact Location Of Accident	MACPHERSON TO PIE (TUAS)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY5601T
Insured/Policyholder	
Name Of Registered Owner	S K SHAMINI TRADING
Co Reg No	53050956C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90090965

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MCV16A00046000
Cover Note Number	

Driver

Name of Driver	SHANMUGAM KALEESWARAN
NRIC No	S7260589F
Date Of Birth	12/07/1972
Occupation	INDOOR
Date Of Driving Pass	20/01/1996
Driving Experience	21 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90090965
Fax Number	
Contact Number	
Email Address	SHAMKSN@YAHOO.COM.SG

Address BLK 426 WOODLANDS STREET 41 #06-204
 Postcode 730426
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION- HEAD TO REAR (INSURED HIT TP)
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

VEHICLE B SUDDENLY JAM BRAKE. I COULDN'T STOP IN TIME AND HIT ONTO VEHICLE B REAR.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJY5289B
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claim process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate police liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand and acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/ are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurer/lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;
- investigating the accident and/or my claims;
- (iii) carrying out and/ or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers/lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

K SHAMINI TRADING
JLX 426 WOODLANDS STREET 41
#06-204 SINGAPORE 730426
CONTACT : SHAM 90090965

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder)/ Date & Time

Witnessed by Reporting Centre Personal

Sketch Plan

Describe Circumstances of the Accident

VEHICLE B SUDDENLY JAM BRAKE, I WON'T STOP
IN TIME AND HIT ONTO VEHICLE B REAR.

Declaration

I/We declare the foregoing particulars are true in every respect.

S K SHAMINI TRADING
BLK 426 WOODLANDS STREET 41
#06-204 SINGAPORE 730426
CONTACT : SHAM 90090965

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personal

Insurance Co. ECICO
Vehicle No. BY56017 Date of accident 18/04/2017
 Reporting Only
 Own Damage Claim
 Third Party Claim

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190688 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

20 APR 2017

E S T I M A T E

Estimate No. : b1 42392
Date Estimated : 19/04/2017
Prepared By : Han Kwan Yong

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -

Wilmar Sugar Pte Ltd
56 Neil Road

Singapore 088830

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY5289B	LL57581	13/09/2010	X5 xDRIVE35i	0

DESCRIPTIONVALUE

To replace rear bumper & attachments, boot lid, tail gate including to knock out tail panel and dented area caused by the accident

✓ 4250 5,950.00

To respray rear bumper, boot lid, tail gate, tail panel and rear right fender

✓ 4142 4,602.00

To carry out body cavity preservation (2X).

✓ 200 236.00

To replace rear windscreen including to conduct water leak test.

✓ ✓ 649.00

To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function.

X *451 531.00

To transfer lock mechanism from old to new tail gate include conducting checks on new tail gate central locking system for proper function.

✓ ✓451 531.00

To replace Front center exhaust silencer including to align system and check for leak.

MAX 531.00

To replace Rear exhaust silencer including to align system and check for leak.

✓ ✓ 531.00

To replace both engine mounting including re-alignment and fixing engine in installation position.

ANX 679.00

To replace both gearbox mountings including re-alignment gearbox to cross member and propeller shaft system.

MAX 679.00

To remove old PDC assembly, replace damaged parts and PDC sensors include reconnecting to new bumper and conducting checks for proper function.

✓ 150 177.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 42392
Date Estimated : 19/04/2017
Prepared By : Han Kwan Yong

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY5289B	LL57581	13/09/2010	X5 xDRIVE35i	0

DESCRIPTION

To check electrical wiring sys tem and lighting of the rear s
ection for proper function.

300 VALUE
177.00

Sundries.

not ✓ / 150.00

Total Labour 1: 15,423.00

DESCRIPTION

RUBBER MOUNTING
CLAMPING BUSH
TAILPIPE TIP CHROME
Exhaust pipe, Front
REAR SILENCER WITH EXHAUST F
ENGINE MOUNTING
RUBBER MOUNTING
GEARBOX MOUNTING
BOOTLID BOTTOM
HINGE, TRUNK LID LOWER PART
TRUNK LID TOP
EXPANDING NUT (13 pcs)
RR BUMPER CARRIER
MOUNT RR BUMPER LH CORNER
MOUNT REAR BUMPER RH CORNER
LH SUPPORT
RH SUPPORT
MOUNT BUMPER RR CENTRE
MOUNT BUMPER RR LH
MOUNT BUMPER RR RH
TRIM PANEL BUMPER RR BOTTOM
RR BUMPER PRIMED
UNDERRIDE PROTECTION (ALU MATT/AHV)
TRIM PANEL BUMPER BOTTOM LH
TRIM PANEL BUMPER BOTTOM RH
SET TRIMS TOWING LUG PRIMED
EMBLEM GROMMET
EMBLEM REAR
EMBLEM X5 ADHERED
PLASTIC NUT
SPINDLE DRIVE LH
BOOTLID PUSH BUTTON
SUPPORT TRUNK LID BOTTOM
TRUNK LID LOCK BOTTOM RIGHT
TRUNK LID LH STOP
TRUNK LID RH STOP
LOCK PANEL
LOCK TRUNK LID
RH SPINDLE DRIVE
RR W/SCREEN

QTY	PRIC	VALUE
1/3	32.85	de 32.85 98.55 ✓
1	113.10	bt 113.10 ✓
2	118.70	wt 237.40 ✓
1	628.50	pm X 628.50 ✓
1	2,326.40	bt 2,326.40 ✓
1	265.60	nt X 265.60 ✓
1	193.70	X 193.70 ✓
1	193.70	X 193.70 ✓
1	1,649.35	de 1,649.35 ✓
2	69.55	nn X 139.10 ✓
1	2,820.85	ht 2,820.85 ✓
10	1.10	ne 11.00 ✓
1	689.85	bt 689.85 ✓
1	71.95	de 71.95 ✓
1	71.95	nn X 71.95 ✓
1	25.50	nn X 25.50 ✓
1	25.50	de 25.50 ✓
1	197.45	de 197.45 ✓
1	141.65	nn 141.65 ✓
1	141.65	de 141.65 ✓
1	254.55	de 254.55 ✓
1	1,471.55	de 1,471.55 ✓
1	152.80	dis 152.80 ✓
1	115.45	nn X 115.45 ✓
1	115.45	de 115.45 ✓
1	58.40	de 58.40 ✓
2	0.80	nn 1.60 ✓
1	67.80	nn 67.80 ✓
1	61.05	nn 61.05 ✓
8	0.85	6.80 ✓
1	552.55	552.55 ✓
1	46.05	46.05 ✓
2	99.05	198.10 ✓
1	99.05	99.05 ✓
1	57.25	57.25 ✓
1	57.25	57.25 ✓
1	10.00	10.00 ✓
1	149.55	149.55 ✓
1	592.10	592.10 ✓
1	1,087.80	1,087.80 ✓

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401555M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 42392	Page No. : 3 of 3
Date Estimated : 19/04/2017	
Prepared By : Han Kwan Yong	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY5289B	LL57581	13/09/2010	X5 xDRIVE35i	0

DESCRIPTION	QTY	PRIC	VALUE
# HEAT INSULATOR REAR SILENCER	1	256.80	256.80
# SEAL TRUNK LID CENTER	1	187.50	187.50
# TRUNK LID GASKET	1	263.85	263.85
EXPANDING RIVET	30	1.35	40.50
# RR BUMPER LH REFLECTOR	1	33.35	33.35
RR BUMPER RH REFLECTOR	1	33.35	33.35
# REAR LIGHT IN THE SIDE PANEL	1	463.95	463.95
# REAR LIGHT IN TRUNK LID RH	1	310.85	310.85
# THIRD STOP LAMP	1	168.55	168.55
# REGISTRATION PLATE LAMP	1/2	18.10	9.05
DECOUPLING RING PDC TORQUE CONVERTE	4	4.95	19.80
# PDC sensor	2	363.05	726.10
BUMPER PDC SENSOR - ELBOW	1/2	231.10	115.55
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
Total Parts :			18,515.70

38,074.55

Labour 1	:	15,423.00
Parts	:	18,515.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,375.71
Grand Total	:	36,314.41

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

34064.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 42392
Date Estimated : 19/04/2017
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Wilmar Sugar Pte Ltd
56 Neil Road

- ACCOUNT - 144674
ECICS Limited
7 Temasek Boulevard, #10-03 Suntec Tower C
Singapore 038987

Singapore 088830

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE	
SJY5289B	LL57581	13/09/2010	X5 xDRIVE35i	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
* To replace rear bumper and attachments, trunk lid top, boot lid bottom, underide protection include making good the tail end panel, rear RH fender and knocking out dents caused by the accident	4250.00		4,250.00		
* To respray rear bumper, boot lid, tail gate, tail end panel and rear RH fender	4142.00		4,142.00		
To carry out body cavity preservation (2x)	200.00		200.00		
To remove and install rear windscreen to facilitate repairs include conducting water leak tests	649.00		649.00		
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00	X	451.00		
To transfer lock mechanism from old to new tail gate include conducting checks on new tail gate central locking system for proper function	451.00		451.00		
* To replace rear silencer with exhaust flap, rubber mounting, clamping bush, tailpipe tip chrome, heat insulator include alignment and conducting checks for leak	531.00		531.00		
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00		(A)
# To replace rear RH light in side panel, rear RH light in trunk lid, registration plate lamp include conducting checks for proper function	150.00		150.00		(A)
To remove old PDC assembly, replace damaged parts and reconnect to new bumper include conducting checks for proper function	150.00		150.00		
* To reconnect electrical components and wirings at the rear section include conducting checks for proper function	300.00		300.00		

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

To tow accident vehicle to PML workshop (See owner's receipts)		300.00		300.00	(A)
Sundries		150.00		150.00	
To supply number plate		83.00		BT 83.00	(A)
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
# COVER *	13.30	1.00		13.30	(A)
RUBBER MOUNTING	32.85	1.00		32.85	
CLAMPING BUSH	113.10	1.00		113.10	
TAILPIPE TIP CHROME	118.70	2.00		237.40	
# REAR SILENCER WITH EXHAUST FLAP *	2,326.40	1.00		2,326.40	
# COMPRESSION STRUT RR RH *	66.65	1.00		66.65	(A)
BOOTLID BOTTOM	1,649.35	1.00		1,649.35	
TRUNK LID TOP	2,820.85	1.00		2,820.85	
EXPANDING NUT	1.00	3.00		3.00	
EXPANDING NUT	1.10	10.00		11.00	
RR BUMPER CARRIER	689.85	1.00		689.85	
MOUNT REAR BUMPER RH CORNER	71.95	1.00		71.95	
RH SUPPORT	25.50	1.00		25.50	
MOUNT BUMPER RR CENTRE	197.45	1.00		197.45	
MOUNT BUMPER RR RH	141.65	1.00		141.65	
# TRIM PANEL BUMPER RR BOTTOM (PDC) *	254.55	1.00		254.55	
RR BUMPER PRIMED	1,471.55	1.00		1,471.55	
UNDERRIDE PROTECTION (ALU MATT/AHV)	152.80	1.00		152.80	
# TRIM PANEL BUMPER BOTTOM RH (SCHWAR *	115.45	1.00		115.45	
SET TRIMS TOWING LUG PRIMED	58.40	1.00		58.40	
EMBLEM GROMMET	0.80	2.00		1.60	
EMBLEM REAR	67.80	1.00		67.80	
EMBLEM X5 ADHERED	61.05	1.00		61.05	
HEAT INSULATOR REAR SILENCER	256.80	1.00		256.80	
TRUNK LID GASKET	263.85	1.00		263.85	
EXPANDING RIVET	1.35	30.00		40.50	
# PIN TERMINAL 6 POL Z CODE *	5.55	1.00		5.55	(A)
RR BUMPER RH REFLECTOR	33.35	1.00		33.35	
# REAR LIGHT IN THE SIDE PANEL RH *	463.95	1.00		463.95	
REAR LIGHT IN TRUNK LID RH	310.85	1.00		310.85	
REGISTRATION PLATE LAMP	18.10	1.00		18.10	
DECOUPLING RING PDC TORQUE CONVERTE	4.95	4.00		19.80	
BUMPER PDC SENSOR - ELBOW	231.10	1.00		231.10	
(DG) CLEANER R1 (100ML)	23.85	1.00		23.85	
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00		263.10	
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85	

SUPPLEMENTARY ITEMS

Total Labour :	12,038.00
Total Parts :	12,542.15
Total Labour & Parts :	24,580.15
Deduction for Excess :	0.00
Total Repair Costs less Excess:	24,580.15
GST @7%:	1,720.61
Grand Total :	26,300.76

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 42392
Date Estimated : 19/04/2017
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Wilmar Sugar Pte Ltd
56 Neil Road

- ACCOUNT - 144674
ECICS Limited
7 Temasek Boulevard, #10-03 Suntec Tower 1
Singapore 038987

Singapore 088830

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJY5289B	LL57581	13/09/2010	X5 xDRIVE35i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00 ✓
# To replace rear RH light in side panel, rear RH light in trunk lid, registration plate lamp include conducting checks for proper function	150.00		150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR SILENCER WITH EXHAUST FLAP *	2,326.40	1.00		2,326.40 Rept
# COMPRESSION STRUT RR RH *	66.65	1.00		66.65 bt ✓
# TRIM PANEL BUMPER RR BOTTOM (PDC) *	254.55	1.00		254.55 Rept
# PIN TERMINAL 6 POL Z CODE *	5.55	1.00		5.55 ne ✓
# TRIM PANEL BUMPER BOTTOM RH (SCHWAR) *	115.45	1.00		115.45 Rept
# COVER *	13.30	1.00		13.30 mis ✓
# REAR LIGHT IN THE SIDE PANEL RH *	463.95	1.00		463.95 Rept

Total Labour :	381.00
Total Parts :	3,245.85
Total Labour & Parts :	3,626.85

CASH SALES / INVOICE

No: 98775265
0004055



James Towing Services

Blk 288 Yishun Ave 6 #07-50 Singapore 760288
James Low HP: ~~9867 4534~~ • 9015 7488



日期 Date: 18/4/17

寶號 Messrs: Cash
車號 Vehicle No: SJY5289B 型號 Model No: BMW X5
由 From: 8 Kaki Bukit ave 4 到 To: 303 Alexandra Rd
時間 (日夜) Time (day / night): 1700 pm to 1800 pm
其他 Other: King RORY
現金 CASH \$ 120.00 支票 CHEQUE:


注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。
NOTES: Vehicle is towed at owner's risk. The company accepts no responsibility for damage or other misdemeanor to your vehicle whilst being towed.

收貨人 Received by: [Signature]

經手人 Issued by: [Signature]

CASH SALES / INVOICE

No: 98775265
0004053



James Towing Services

Blk 288 Yishun Ave 6 #07-50 Singapore 760288
James Low HP: ~~9867 4534~~ • 9015 7488



日期 Date: 18/04/17

寶號 Messrs: Cash
車號 Vehicle No: SJY5289B 型號 Model No: BMW X5
由 From: PIE 到 To: 8 Kaki Bukit
時間 (日夜) Time (day / night): 1235 pm to 1335 pm
其他 Other: King RORY Accident
現金 CASH \$ 180.00 支票 CHEQUE:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。
NOTES: Vehicle is towed at owner's risk. The company accepts no responsibility for damage or other misdemeanor to your vehicle whilst being towed.

收貨人 Received by: [Signature]

經手人 Issued by: [Signature]

Veron Chen (LKKAuto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 27 September 2018 4:24 PM
To: Veron Chen (LKKAuto)
Cc: SUR
Subject: Re: SJY 5289B-DOA: 18/4/2017
Attachments: SKM_558e18092716240.pdf

Dear Veron

As requested, please refer to attach.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, 27 September 2018 4:19:36 PM
To: PBSP
Cc: SUR
Subject: RE: SJY 5289B-DOA: 18/4/2017

Dear Caroline,

Re-forward.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 27 September 2018 4:10 PM
To: Caroline <pml-pbsp@simebarby.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJY 5289B-DOA: 18/4/2017

Dear Caroline,

Please provide us towing receipts.

Best Regards,
Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 27 September 2018 4:07 PM

To: Caroline <pml-pbsp@simebarby.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: SJY 5289B-DOA: 18/4/2017

Dear Caroline,

We refer to the mentioned vehicle.

Please removed-To transfer lock mechanism from old to new boot lid include conduction checks on new boot lid central locking system for proper function.-\$451.00

Final amount \$24,129.15 before GST @ 10 working days.

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Your Ref: DMCV1700042H

Date: 18th October 2018

Our Ref: CS1/ICS18014912/T1vd3s2

M/s ECICS Ltd
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SJY 5289B INSURED VEHICLE: GY 5601T ACCIDENT DATE: 18/04/2017**

We thank you for your instruction on 26/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJY 5289B from M/s Performance Motors Ltd.
- b) Singapore Accident Statement of Vehicles SJY 5289B and GY 5601T.
- c) Colour damaged vehicle photographs of SJY 5289B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJY 5289B
Make & Model	: B.M.W X5 XDRIVE35I
Year of Registration	: 2010
Chassis Number	: WBAZV42080LL57581
Engine Capacity	: 2979 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 5289B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
3	RUBBER MOUNTING (SN)	DEFORMED 1PCS ONLY	98.55	32.85
1	CLAMPING BUSH (SN)	BENT	113.10	113.10
2	TAILPIPE TIP CHROME (SN)	CUT	237.40	237.40
1	EXHAUST PIPE, FRONT (SN)	NOT NECESSARY	628.50	-
1	REAR SILENCER WITH EXHAUST F (SN)	BENT	2,326.40	2,326.40
1	ENGINE MOUNTING (SN)	NOT NECESSARY	265.60	-
1	RUBBER MOUNTING (SN)	NOT NECESSARY	193.70	-
1	GEARBOX MOUNTING (SN)	NOT NECESSARY	193.70	-
1	BOOTLID BOTTOM (SN)	DEFORMED	1,649.35	1,649.35
2	HINGE, TRUNK LID LOWER PART (SN)	NOT NECESSARY	139.10	-
1	TRUNK LID TOP (SN)	BENT	2,820.85	2,820.85
13	EXPANDING NUT (SN)	NECESSARY	14.00	14.00
1	RR BUMPER CARRIER (SN)	BENT	689.85	689.85
1	MOUNT RR BUMPER LH CORNER (SN)	DEFORMED	71.95	71.95
1	MOUNT REAR BUMPER RH CORNER (SN)	NOT NECESSARY	71.95	-
1	LH SUPPORT (SN)	NOT NECESSARY	25.50	-
1	RH SUPPORT (SN)	DEFORMED	25.50	25.50
1	MOUNT BUMPER RR CENTRE (SN)	DEFORMED	197.45	197.45
1	MOUNT BUMPER RR LH (SN)	NOT NECESSARY	141.65	-
1	MOUNT BUMPER RR RH (SN)	DEFORMED	141.65	141.65
1	TRIM PANEL BUMPER BOTTOM (SN)	DEFORMED	254.55	254.55
1	RR BUMPER PRIMED (SN)	DEFORMED	1,471.55	1,471.55
1	UNDERRIDE PROTECTION (ALU MATT/AHV) (SN)	DISTORTED	152.80	152.80
1	TRIM PANEL BUMPER BOTTOM LH (SN)	NOT NECESSARY	115.45	-
1	TRIM PANEL BUMPER BOTTOM RH (SN)	DEFORMED	115.45	115.45
1	SET TRIMS TOWING LUG PRIMED (SN)	DEFORMED	58.40	58.40
2	EMBLEM GROMMET (SN)	NECESSARY	1.60	1.60
1	EMBLEM REAR (SN)	NECESSARY	67.80	67.80
1	EMBLEM X5 ADHERED (SN)	NECESSARY	61.05	61.05
8	PLASTIC NUT (SN)	NOT NECESSARY	6.80	-

Report Ref No. CS1/ICS18014912/T1vd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPINDLE DRIVE LH (SN)	NOT NECESSARY	552.55	-
1	BOOTLID PUSH BUTTON (SN)	NOT NECESSARY	46.05	-
2	SUPPORT TRUNK LID BOTTOM (SN)	NOT NECESSARY	198.10	-
1	TRUNK LID LOCK BOTTOM RIGHT (SN)	NOT NECESSARY	99.05	-
1	TRUNK LID LH STOP (SN)	NOT NECESSARY	57.25	-
1	TRUNK LID RH STOP (SN)	NOT NECESSARY	57.25	-
1	LOCK PANEL (SN)	NOT NECESSARY	10.00	-
1	LOCK TRUNK LID (SN)	NOT NECESSARY	149.55	-
1	RH SPINDLE DRIVE (SN)	NOT NECESSARY	592.10	-
1	RR W/SCREEN (SN)	NOT NECESSARY	1,087.80	-
1	HEAT INSULATOR REAR SILENCER (SN)	BENT	256.80	256.80
1	SEAL TRUNK LID CENTER (SN)	NOT NECESSARY	187.50	-
1	TRUNK LID GASKET (SN)	NECESSARY	263.85	263.85
30	EXPANDING RIVET (SN)	NECESSARY	40.50	40.50
1	RR BUMPER LH REFLECTOR (SN)	NOT NECESSARY	33.35	-
1	RR BUMPER RH REFLECTOR (SN)	CUT	33.35	33.35
1	REAR LIGHT IN THE SIDE PANEL (SN)	CRACKED	463.95	463.95
1	REAR LIGHT IN TRUNK LID RH (SN)	CRACKED	310.85	310.85
1	THIRD STOP LAMP (SN)	NOT NECESSARY	168.55	-
2	REGISTRATION PLATE LAMP (SN)	DISTORTED 1PC ONLY	36.20	18.10
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NECESSARY	19.80	19.80
2	PDC SENSOR (SN)	NOT NECESSARY	726.10	-
2	BUMPER PDC SENSOR - ELBOW (SN)	NOT WORKING 1PCS ONLY	462.20	231.10
1	(DG) CLEANER R1 (100ML) (SN)	NECESSARY	23.85	23.85
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) (SN)	NECESSARY	263.10	263.10
1	(DG/SL) GLASS PRIMER 30ML (VP206) (SN)	NECESSARY	27.85	27.85
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	NUMBER PLATE (SN) (ADDITIONAL)	BENT	83.00	83.00
1	COVER (SN) (ADDITIONAL)	MISSING	13.30	13.30
1	COMPRESSION STRUT RR RH (SN) (ADDITIONAL)	BENT	66.65	66.65
1	PIN TERMINAL 6 POL Z CODE (SN) (ADDITIONAL)	NECESSARY	5.55	5.55

Report Ref No. CS1/ICS18014912/T1vd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SILENCER WITH EXHAUST FLAP (SN) (ADDITIONAL)	REPEATED	2,326.40	-
1	TRIM PANEL BUMPER RR BOTTOM (PDC) (SN) (ADDITIONAL)	REPEATED	254.55	-
1	TRIM PANEL BUMPER BOTTOM RH (SCHWAR) (SN) (ADDITIONAL)	REPEATED	115.45	-
1	REAR LIGHT IN THE SIDE PANEL RH (SN) (ADDITIONAL)	REPEATED	463.95	-
			21,997.55	12,775.15
	LABOUR			
	TO REPLACE REAR BUMPER & ATTACHMENTS, BOOT LID, TAIL GATE INCLUDING TO KNOCK OUT TAIL PANEL AND DENTED AREA CAUSED BY THE ACCIDENT.		5,950.00	4,250.00
	TO RESPRAY REAR BUMPER, BOOT LID, TAIL GATE, TAIL PANEL AND REAR RIGHT FENDER.		4,602.00	4,142.00
	TO CARRY OUT BODY CAVITY PRESERVATION (2X).		236.00	200.00
	TO REPLACE REAR WINDSCREEN INCLUDING TO CONDUCT WATER LEAK TEST.		649.00	649.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOT LID INCLUDE CONDUCTING CHECKS ON NEW BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTIONING.	NOT NECESSARY	531.00	-
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW TAIL GATE INCLUDE CONDUCTING CHECKS ON NEW TAIL GATE CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.		531.00	451.00
	TO REPLACE FRONT CENTER EXHAUST SILENCER INCLUDING TO ALIGN SYSTEM AND CHECK FOR LEAK.	NOT NECESSARY	531.00	-
	TO RELACE REAR EXHAUST SILENCER INCLUDING TO ALIGN SYSTEM AND CHECK FOR LEAK.		531.00	531.00
	TO REPLACE BOTH ENGINE MOUNTING INCLUDING RE-ALIGNMENT AND FIXING ENGINE IN INSTALLATION POSITION.	NOT NECESSARY	679.00	-
	TO REPLACE BOTH GEARBOX MOUNTINGS INCLUDING RE-ALIGNMENT GEARBOX TO CROSS MEMBER AND PROPELLER SHAFT SYSTEM.	NOT NECESSARY	679.00	-
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND PDC SENSORS INCLUDE RECONNECTING NEW BUMPER AND CONDUCTING CHECKS FOR PROPER FUNCTION.		177.00	150.00
	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING OF THE REAR SECTION FOR PROPER FUNCTION.		300.00	300.00

Report Ref No. CS1/ICS18014912/T1vd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS. (ADDITIONAL)		231.00	231.00
	TO REPLACE REAR RH LIGHT IN SIDE PANEL, REAR RH LIGHT IN TRUNK LID, REGISTRATION PLATE LAMP INCLUDE CONDUCTING CHECKS FOR PROPER FUNCTION. (ADDITIONAL)		150.00	150.00
	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP. (ADDITIONAL)		300.00	300.00
			16,077.00	11,354.00
	GRAND TOTAL		38,074.55	24,129.15
RECOMMENDED COST OF REPAIRS				24,129.15

Report Ref No. CS1/ICS18014912/T1vd3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.