

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61

Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

**INSURER : AIG ASIA PACIFIC INSURANCE PTE LTD****PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1808/007
Policy No:	5096183528	Date of Loss:	13/08/2018
Vehicle Reg. No.:	<b>SLL8474H</b>	Driveable?	yes
Driver Age:	08/05/1994	Third Party Vehicle No.:	GBH5208U
Any Injuries?	no	Contact No:	90225444
Insured/Claimant:	DANIEL TAN JIA JUN (CHEN JIAJUN)	Driver:	DANIEL TAN JIA JUN (CHEN JIAJUN)

Make/Model:	Toyota, Wish - ZNE10	Vehicle Reg. Date:	20 Nov 2007
Vehicle Colour:	BLUE	Engine Number:	1ZZ2978992
Chassis No:	ZNE100384130	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss REVERSE HIT  
 Remarks:  
 Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

**COST OF CLAIMS**

	Amount
Parts	412.50
Miscellaneous Items	40.00
Labour	110.00
Paintwork Labour	180.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>742.50</b>
<b>GST 7.00%(S\$):</b>	<b>51.98</b>
<b>Nett Amount(S\$):</b>	<b>794.48</b>

This claim is handled by: Shaun Toh L M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*not allowed  
 or  
 2/3  
 20/8/18  
 the repairer  
 means  
 10/8/18*

**REPAIR DETAILS****Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>no/ae</i>	550.00	550.00	-25.00	412.50
<b>Total Parts (\$)</b>						<b>412.50</b>

**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT NUMBER PATE <i>scr</i>	40.00	40.00	0.00	40.00
<b>Sub Total (\$)</b>						<b>40.00</b>

**Estimates On Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 <i>20</i>
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	80.00	80.00	0.00	80.00 ✓
<b>Gross Labour Cost (\$)</b>						<b>110.00</b>

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	180.00	180.00	0.00	180.00 ✓
<b>Gross Labour Cost (\$)</b>						<b>180.00</b>

**< END OF ESTIMATES >**