

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5021X**AAD1808-100***Not Authored**11 Sep @ 2450h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5021X

VF1ABL15AUC275144

RENAULT

LATITUDE

13.8.2018

AIG

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.47 ✓
2	1 BUMPER LOWER REAR	\$	<i>mulm</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 ✗
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 ✗
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99 ✗
6	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61 ✓
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 ✗
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99 ✗
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 ✗
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95
13	1 BOOT REAR	\$	<i>R</i> 2,872.68
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36
19	1 BOOT BADGE	\$	<i>na</i> 225.36
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81

Trans-cab Auto Services Pte Ltd**AAD1808-100**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5021X

30	1 DOOR PANEL REAR RH	\$	R	2,844.66	}	X
30	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45		
30	1 FENDER PANEL REAR RH	\$	R	3,299.13		
31	1 WHEELARCH REAR RH	\$	Sn	543.47		
32	1 TAILLAMP RH	\$	Sn	552.55		
33	1 TAILLAMP PANEL RH	\$	R	986.70		
34	1 TAILLAMP LH	\$	Sn	552.55		
35	1 TAILLAMP PANEL LH	\$	R	986.70		
36	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77		
37	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56		
38	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	}	
39	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21		
40	1 EXHAUST REAR	\$	R	7,489.05		
41	1 EXHAUST CAP REAR	\$	R	230.49		

TOTAL	\$	34,199.54
10%	\$	3,419.95
	\$	30,779.59

Specical Nett

1	1SET PARKING AID	\$	Sn 700.00	X
2	1SET REAR BUMPER CLIP	\$	na 66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sn 17.82	} X
11	1SET BOOT FINISHER CLIP	\$	na 24.20	
12	1 BOOT STICKER "Trans-cab"	\$	na 30.00	
13	1 BOOT STICKER "6555-3333"	\$	na 30.00	
14	1 BOOT INNER TRIM CLIP	\$	na 45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na 35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	na 28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	na 28.00	

Trans-cab Auto Services Pte Ltd**AAD1808-100**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5021X

19	1 TAILLAMP CLIP RH	\$	nn	5.00	} X
20	1 TAILLAMP CLIP LH	\$	nn	5.00	
21	2 REAR WINDSCREEN SELANT	\$	nn	80.00	
22	1 WINDSCREEN MOULDING	\$	nn	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	
25	1 SPARE TYRE	\$	nn	330.00	

TOTAL \$ 2,225.02**TOTAL PARTS \$ 33,004.61****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,750.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,200.00	2001
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00 X
To repair and realign rear exhaust pipe.	\$	nn	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1808-100**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5021X

To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>

TOTAL \$ 9,290.00**Over All Total \$ 42,294.61****(LUMP SUM)****Repair Days***15 days**2 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: