



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

Claimant Insurer: India International Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	12/08/2018
Vehicle Reg. No.:	SJY9071K	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TANIA SAMANTHA D'CRUZ		
Make/Model:	NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A)	Vehicle Reg. Date:	13/10/2010
Vehicle Colour:	GREY	Chassis No:	JN1BAAG11Z0111180
Engine No:	HR15389070B		
Odometer:	0 KM		
Paint Type:		Nett Item Discount:	10.00 %
List Item Discount:	30.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	-		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	3,871.60
Miscellaneous Items	10.00
Labour	1,720.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,601.60
+ GST 7.00% (S\$)	392.11
Nett Amount (S\$)	5,993.71

This claim is handled by: AH WEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Tanjim 97495249
- WP
20/8/18 @ 420
Recovery after repair
sur@lkhauto.com
4 days

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Aug 2018)
Parts: 143 NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJY9071K)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET - REPAIR	10.00	0.00	-
2	1		*FRONT FENDER RH	10.00	0.00	bt ✓ *672.70 FN
3	1		*FRONT FENDER BRACKET RH	10.00	0.00	? *58.00 FN
4	10		*FRONT COWLING CLIPS	10.00	0.00	nh ✓ *47.00 FN
5	1		*FRONT HEADLAMP RH	10.00	0.00	cm ✓ *638.00 FN
6	1		*FRONT HEADLAMP LOWER BRACKET RH	0	0.00	nh ✓ *39.00 FS
7	1		*FRONT BUMPER RETAINER RH	10.00	0.00	nh ✓ *45.00 FN
8	1		*FRONT BUMPER	10.00	0.00	de ✓ *636.20 FN
9	2		*FRONT BUMPER SIDE CHROME L+R	10.00	0.00	nh ✓ *139.60 FN
10	10		*FRONT BUMPER CLIPS	10.00	0.00	nh ✓ *47.00 FN
11	1		*FRONT TOP GRILLE	10.00	0.00	x *378.40 FN
12	1		*FRONT FOG LAMP RH	0	0.00	x *412.60 FS
13	1		*FOG LAMP GARNISH RH	10.00	0.00	x *139.70 FN
14	1		*FRONT REINFORCEMENT	10.00	0.00	y *643.70 FN
15	1		*SPONGE	10.00	0.00	x *238.00 FN
16	1		*WIPER TANK - CHECK	10.00	0.00	-
17	1		*FRONT RADIATOR TOP GARNISH - CHECK	10.00	0.00	-
18	10		*FRONT RADIATOR TO GARNISH CLIPS	10.00	0.00	x ✓ *47.00 FN
19	1		*FRONT EMBLEM	10.00	0.00	x ✓ *69.70 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	4,251.60
- Nett Item Discount on N Items (S\$)	380.00
Total Parts (S\$)	3,871.60

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO RUST PROOF AFFECTED AREAS	New	60.00
			30
		Gross Labour Cost (\$\$)	60.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REPAIR FRONT HEADLAMP TOP PANEL AND BONNET, SUPPORT PANEL. TO REMOVE & REPLACE ALL ACCIDENT AFFECTED AREAS	New	500 750.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	600 800.00
3	TO TEST FRONT LIGHTING WATER LEAKAGE	New	20 50.00
4	TO DO WHEEL ALIGNMENT	New	1 60.00
5	ALIGNMENT	New	-60.00
Gross Labour Cost (S\$)			1,720.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >