

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 20 Aug 2018

Preliminary Advice

Insured Vehicle No	: SLB1433A		
TP Vehicle No	: SKN6833Y	Accident Date	: 13/08/2018
Make	: TOYOTA COROLLA ALTIS	Assignment Date	: 16/08/2018
Date of Inspection	: 16/08/2018	Est. Duration of Repair	: 4-5/Days
Inspection At	: KANG AUTO ENGINEERING PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...O/S Rear Body.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,428.58
Revised Amount	:S\$	2,128.80
Check Items (Estimated)	:S\$	475.65
Total	:S\$	2,604.45

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :We have not authorized repairs.