

## Vic (LKKAuto)

---

**From:** Vic (LKKAuto)  
**Sent:** Friday, 24 August, 2018 1:35 PM  
**To:** C Meenachi - III  
**Cc:** Admin A; Vic (LKKAuto)  
**Subject:** ACCIDENT INVOLVING VEHICLES SKL 3354R (OI) AND SHB 9602Z(TP) ON 15/08/2018 LKK REF CC4/III18014924/Kha3  
**Attachments:** TP VIDEO.mp4

Your Ref: TBA (SKL 3354R)

Dear Meena,

ACCIDENT INVOLVING VEHICLES SKL 3354R (OI) AND SHB 9602Z(TP) ON 15/08/2018

We refer to the above matter.

As per merimen mandate, we attached a copy of TP video footage as requested.

Based on the footage, TP was within lane when OI vehicle encroached and collided to TP.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.