

**Trans-cab Auto Services Pte Ltd**

AAD1808-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9602Z**

*Not with order  
L1 Sup @ 2750*

Vehicle No.:	<b>SHB 9602Z</b>
Chassis No.:	KL1LA69RJBB122741
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	15.8.2018
Third Party Insurer :	<b>III</b>

<b>PART</b>			<b>LIST</b>
1	1 Front Bumper	\$	<i>Per</i> 1,202.00 ✓
2	1 Front Bumper Lower Absorber	\$	<i>Sm</i> 180.00
3	1 Front Bumper Reinforcement	\$	<i>R</i> 356.00
4	1 Front Bumper Retainer RH	\$	<i>Sm</i> 102.00
5	1 Front Bumper Retainer LH	\$	<i>Sm</i> 102.00
6	1 Front Bumper Lower Grille	\$	<i>Sm</i> 78.00
7	1 Front Bumper Lower Stiffener	\$	<i>R</i> 134.37
8	1 Front Bumper Bracket LH	\$	<i>R</i> 10.00
9	1 Front Bumper Bracket RH	\$	<i>R</i> 10.00
10	1 Bumper Fog Lamp Cover RH	\$	<i>Sm</i> 32.40
11	1 Bumper Fog Lamp Cover LH	\$	<i>Sm</i> 32.40
12	1 Headlamp LH	\$	<i>GA</i> 816.00 ✓
13	1 Headlamp LH inner panel	\$	<i>R</i> 611.16 X
14	1 Front Fender LH	\$	<i>R</i> 837.60 ✓
15	1 Front Fender Liner LH	\$	<i>Sm</i> 47.00
16	1 Front Fender Inner Wheel House Panel LH	\$	<i>R</i> 1,437.00
17	1 Front Shock Absorber Assy LH	\$	<i>Sm</i> 216.17
18	1 Front Shock Absorber Top Mounting LH	\$	<i>Sm</i> 48.32
19	1 Front Lower Arm LH	\$	<i>Sm</i> 283.00
20	1 Front Knuckle Arm LH	\$	<i>Sm</i> 230.00
21	1 Front Door LH	\$	<i>R</i> 1,133.00
22	1 Front Side View Mirror Assy LH	\$	<i>Sm</i> 1,191.00

<b>TOTAL</b>	\$	<b>9,089.42</b>
<b>10%</b>	\$	<b>908.94</b>
	\$	<b>8,180.48</b>

**Trans-cab Auto Services Pte Ltd**

AAD1808-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9602Z****Special Nett**

1 Set Front Bumper Fastener Clip	\$	<i>na</i> 24.00 ✓
1 Set Front licence plate with holder	\$	<i>su</i> 192.00
1 Set Radiator Grille clip	\$	<i>na</i> 35.00
1 Set Front Fender Liner clip	\$	<i>na</i> 30.00
1 Front Fender RR Bracket LH	\$	<i>R</i> 7.10
1 Front Wheel Rim Hub Cap LH	\$	<i>su</i> 166.30
1 Front Tyre LH	\$	<i>su</i> 180.00
1 Front Tyre Rim LH	\$	<i>su</i> 126.00

<b>TOTAL</b>	<b>\$</b>	<b>760.40</b>
--------------	-----------	---------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>8,940.88</b>
--------------------	-----------	-----------------

**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 <i>4000</i>
Putty and spray painting of the affected portion.	\$	4,000.00 <i>4000</i>
Towing Fees.	\$	<i>na</i> 120.00 <i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>na</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 <i>X</i>

**Trans-cab Auto Services Pte Ltd**

AAD1808-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9602Z**

To rust-proofing of the affected areas.	\$	170.00	<i>301</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X

**TOTAL \$ 10,460.00****Over All Total \$ 19,400.88****Repair Days (Lump Sum)***15 days**2 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: