



FALCON-AIR

BUILDING RESOURCES GROUP PTE LTD
31 TUAS AVENUE 8
SINGAPORE 639245

Attention : Motor Claim Department
Contact : 8715311 68617091

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-L

Estimate : ES003232

Date : 19/07/2018
Vehicle Num. : YP7071T
Make/Model : MITSUBISHI FUSO
Chassis/Eng# : FEB21EA21484
Accident Date : 23/06/2018
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	FRONT BUMPER		1,010.33
3.	1	FRONT BUMPER GARNISH		353.11
		FRONT BUMPER BRACKET		187.05
		List Total S\$:		1,550.49
		10.00% Discount S\$:		155.05
				1,395.44
		LABOUR :		
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS		300.00
		TO REPAIR FRONT CHASSIS, FRONT GRILLE INCLUDES KNOCKING & REPLACEMENT OF PARTS		280.00
		Labour Total S\$:		580.00

E. & O.E.

Total S\$: 1,975.44



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Tan Guan 97495749
2 days
Resurvey before paint
surelkkhant.com
'wp' 17/8/18 320p

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg