



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
Mr CHIAN TIAN MING (ZHONG ZHENMING Blk 152 Rivervale Crescent 07-106 Singapore 540152 Contact No Mobile: 98633469	Cust No/Name /Mr Chian Tian Ming (Zhong Zhen
	Reg No/Reg Date SLC9815Z*KC17R(/ 31/05/2016
	Date In/Mileage 15/08/2018/ 0
	Chassis No KNAFX411MG5579476
	Engine No G4FGFH609713
	Make/Model KIA/FORTE K3 1.6 A EX BF4
	Colour/Trim 4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	16/08/2018/ 08:19	DS	218 / MarsLer	63253
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNT88088	REVERSE SENSOR SET				280.00
M SUNDRY	C & C LOGO				50.00
S MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				80.00
S MIPNT88088	TO REMOVE AND RE-INSTALL TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS				600.00
S MIPNT88088	TO TRANSFER REAR BOOT COMPONENT & MECHANISM PARTS				600.00
S MIPNT88088	TO REPLACE REAR BUMPER, REAR BEAM, REAR BOOT, ETC -REPAIR REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				2400.00
S MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL				200.00
S MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				1680.00
M KS 86611 A7 000	COVER - REAR BUMPER	1.00	768.00	0.00	768.00
P KS 86695 A7 000	COVER - REAR BUMPER,	1.00	234.00	0.00	234.00
M KS 92405 A7 000	LHR REFLECTOR REFLEX	1.00	114.00	0.00	114.00
M KS 86613 A7 000	LH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00
M KS 86614 A7 000	RH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00
P KS 0G032 50 037A	CLIP - BUMPER	10.00	2.00	0.00	20.00
P KS 86631 A7 000	BEAM-RR BUMPER	1.00	365.00	0.00	365.00
M KS 86636 A7 000	BRACKET - REAR BEAM	2.00	5.00	0.00	10.00
M KS 86635 A7 000	BRACKET - REAR BEAM	1.00	5.00	0.00	5.00
M KS 86641 A7 000	LH STAY - REAR BUMPE	1.00	75.00	0.00	75.00
M KS 86642 A7 000	RH STAY - REAR BUMPE	1.00	75.00	0.00	75.00
M KS 69200 A7 070	PANEL ASSY - TRUNK L	1.00	1491.00	0.00	1491.00
P KS 86310 A7 050	KIA LOGO ASSY	1.00	37.00	0.00	37.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
Mr CHIAN TIAN MING (ZHONG ZHENMING Blk 152 Rivervale Crescent 07-106 Singapore 540152 Contact No Mobile: 98633469	Cust No/Name /Mr Chian Tian Ming (Zhong Zhen
	Reg No/Reg Date SLC9815Z*KC1/ 31/05/2016
	Date In/Mileage 15/08/2018/ 0
	Chassis No KNAFX411MG5579476
	Engine No G4FGFH609713
	Make/Model KIA/FORTE K3 1.6 A EX BF4
	Colour/Trim 4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	16/08/2018/ 08:19	DS	218 / MarsLer	63253

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
P WFFORTE FORTE EMBLEM <i>mer</i>	1.00	40.00	0.00	40.00 ✓
P WFEMBLEMK3 EMBLEM K3 <i>mer</i>	1.00	15.00	0.00	15.00 ✓
Z NOTES ACCIDENT ON 13/08/2018 ALONG JUNC B/W UPP SERANGOON RD & HOUGANG AVE 4 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # SLU4693X TP INS : I.I.I				

Estimate

Not Authorised
h/ku

Tel: 62563561

Take photo before pa.ing.

23/8/18

4 day.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Parts	3,315.00
Labour	0.00
Standard Menu	0.00
Specialist Job	5,840.00
Others(Lub,etc)	0.00
Sundry	50.00
Total(w/o GST)	9,205.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.