INS. CASE OWNER STANDS CC /AIC	31801 YAYY,	U HA / LIKE	
Surveyor: DOI: _	ASSIGNMENT 24 108 118	_ Date / Time : L/J [8/4
Pre-assign / CCU / FTE SUU 16867 Insured Vehicle No. Thin Unit Will Insured Tel No. HP: D.O.A : 146 Is driver the owner? (YES / NO.) Nature of Accident	Claim No. Policy No. Make / Mod Place of Acc	all had	764
If NO, Driver Nance / Age : Driver Tel No. : (V/L_ YE		ORT: YES / NO : TP GIA REPORT: ility: % Final? Yes /?	
INSRS: VAN INSRS: WSP: Tel: Liability: RMKS: RMKS:	INSRS: WSP: Tel: Liability: RMKS:	INSRS. WSP: Tel: Liability RMKS:	1
Date/Time	WW T		DATE/PIC
no of GIA ISENT ON	T us letter	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Vinal): Notification ltr (if non-pickup): Call OI:	0- 1Y
OI REVERSING.		Documentation Check List: Handle	
		Natification ltr (if nan-pickup) After call ltr to OE	\dashv
		Authorisation To Act:	
16. CHAR SHERM WHOLDE	MYL TAN	Release Voscher:	
17 7 14 9 14 1. 001 11.	IL IVE	Final Repair Bill	
NO VIDEO,		Car Rental Invoice Towing Invoice	
TELOBIA - TO WHATEKAWA CI MIN		LTA/GIA:	= =
10/00/19 - TO WHYDRAWN CLAW	BUILT IND GOT MY	Medical Bill	-
-to close.	and welcht	PIR	=
0 000		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
UKLIMINARY ADVICE Date/Time: Sent By:		Post-Repair Photos	
		Others:	
NALIZATION Date/Time: Confirm	with	Confirm by:	
pair Cost: \$\$ (days) Reductio	E %	Email Ca	11
NAL SETTLEMENT Date/Time: Confirm with		Email Cal	
ual Liability: % (Agreed / Assessed) BOLA Si	/N No. :	If NO or B 28. Ass. Lin:	
pair Cost S5 —	COMMY.		
ss of Rental (LOR): SS - (days)	14/	A TO WHENDER	WW
ss of Use (LOU): SS — (S a days)	6.1.	CLANIN	
ss of Income (LOI): S\$ (\$ x days)			
	[Tick only one]		
A/LTA Search SS -			
edical: S5 —	NI SOUR BURNES III	1) Claim status: Normal/Reject/Priv	
	/ Independent)	2) Report Format. WP Que	
gal Cost SS -		3) Survey fee: 9 39	0000
tal: SS — Global Sum SS:			
NAL PAYMENT Date/Time: Confirm with:		Email Cal	
yee 1; S\$ - Name 1:	-		
yee 2: (Strike if N.A.) SS Name 2:	₹8		
and the first of the term of t			

* .4	i i	_
(0917/13) Wef	REF: AIG	Δ.
AS REC BY:	AS	SIGNMENT
9	malalia	Veh No: 68760736 Yr Regn: 31 05
From:	Date. 25 8 11 8	Type: M.Car / M.Cycle / Bus / Van / Lerry / Taxi / Prime Mover /
Estimated Cost:		Truck / Trailer of M
ON WS / TP RES / OD RES		1200
	78D 6073E	Make: Toyoto Dyng at 1983
at Workshop m/s	fan lim Motor	- Contrary
51 Def	a tene 10	
Insured		Eng/No:
Policy No.	522/6861	CNO: JTF4F344003010387
Clams No.		Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured	Excess	Steering: Ingredic / Jammed / Leaked / Burnt or
(Client's Record)	llamo	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	ower wuiting	Modi: (NID / S/Rim / STD A/Rim or
		Tyre Size: F: IFS NIX
(Policy Condition)		R: 15-5-12
Remark: The veh had commend	ced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of in	ispection.	TOYOTYOKO OF Delium
Bail. or Market Value:	124.	Front Rear
IBAC Accident Rougt	Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA PR Seep	Consistent? : Yes or No	L/Bal. 6, mm L/Bal. 6 mm
	lys Res.: Yes or No	D.O.A. 14/0/18 D.O.I. 24/8/18
Lum Sum: %	3 Val.: Yes or No	Survey hold at
arm/south or	1 -2 Call 13	2007/03/4 (2009) 1900
CA / REV / REP. / 24 HI	Vehicle: IN/OU	// / /
Date: Person Co	ontacted: / /	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruc	tion 29/3/2020	The did t distant time t dody distant
47 A SEY		
1000	7 ,4,1	
	He \$1,150.00	
	CRUBO: 9 2,0	62.95 (64%)
Date/Time, File Pass-to?	Preli. Report	Days Of Repair:
	Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?		Transportation:
	Add Fe	100000000000000000000000000000000000000
		100000000000000000000000000000000000000
		ee: : Site Insp (\$) _s+Rssi .
Date/Time, File Return to? Report Format : Lump Sum / I.B.J: (\$		ee: Site Insp (\$) _s-Rs_si Interview (\$) Pholis

ŝ



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Annated to rederation inte	rnationale Des Experts En Autor	il Como	
AIG	ASIA PACIFIC INS	SURANCE PTE LTD	Ref : CC6/AIG18014	4947/jb3	
CHA	SHENTON WAY #0 ARTIS BUILDING GAPORE 079120	8-16	Date : 16-08-2018 Code : AIG		
1.		Policy Particu	lars :- THIRD PARTY CLA	IM	
_	Insured Veh.	SLL 1686J	Veh. Inspected	GBD 6073E	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From		Assign Date	16/08/2018	
2.		Vehicle F	Particulars & Condition		
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	1/2/	Steering		
	Brakes		Modification		
	General				
3.		Co	nditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.		Desc	ription of Damages		
5.		Ge	neral Information	- LIF - P - L	
	Accident Date	14/08/2018	Inspection Date		
	Survey held at	TAN LIM MOTOR PTE LTD)		
		51 DEFU LANE 10 SINGAPORE 539216			
5a.			Remarks		

Not Albert

4/5 8 2 dy.



51 Defu Lane 10 Singapore 539216 Tel: 68585151 (24 Hours) Fax: 68580877

_ GST Regn. No. : M2-8922054-2

Messrs Yuan Li Electrical Engineering Pte Ltd

AlGAsia Insured's Veh No : SLL1686J

Date of Accident: 14 August 2018

Date: 15 August 2018

Estimate To Repair GBD6073E - Toyota Dyna 150 (D)

Chassis No: JTFUF34Y003010387

24/08/1	80	15 15 C9	80 h
		Amount	
	s	279.30	×

	Quantity	Description			Amount
		LIST ITEMS			
)1	1 pc	right front corne	r panel 20 1 (C	\$	279.30
)2	1 pc	right headlamp	SCA	\$	882.50
)3	1 pc	right headlamp	lower fininsher 🚜 ។	\$	22.00
4	1 pc	front bumper	By	\$	398.50
)5	1 pc	right front door	step garnish 7	\$	376.00
6	1 pc	front centre grill		S	445.60
				\$	2,403.90
		Less 25 %		\$	600.98
				\$	1,802.93
		SPECIAL NETT	ITEMS		
07	1 pc	right front door	corporate address sticker	\$	50.00
				s	50.00
		LABOUR & MIS	SC. CHARGES		
31		To check electr	ical lighting concerned.	\$	60.00
2		To rust-proofing	of the affected areas.	\$	44 50.00
3			knocking and straighten the necessary portion,	S	550.00
			newal of parts, adjust and realign the same.		700.00
)4		Putty and spray	painting of the affected portion.	\$	700.00
				\$	1,360.00
		Total	this is a new table to the control of the following:	\$	3,212.93
			 To server increasing spray painting 		
			Lotary legad partial during reservey In one legad partial during reservey		
			at way is on a "Wilmost Projudice" basis		
			Tip vitro if I no reation (s) in inflowed		
			a livered and permitting to resurveyed and		
	1		a subject it it all approval from Insurance Company		
			:Acknowledge::Ty Repairer		
			:Acknowledgestry Repeirer Signatures		

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered V	/ehicle
Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5194D
Vehicle Details	
Vehicle No.:	GBD6073E
Vehicle to be Exported:	No
Intended De-registration Date:	15 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	Blue
Manufacturing Year:	2005
Engine No.:	5L5575867
Chassis No.:	JTFUF34Y003010387
Maximum Power Output:	
Open Market Value:	\$23,690.00
Original Registration Date:	30 Mar 2005
First Registration Date:	30 Mar 2005
Transfer Count:	2
Actual ARF Paid:	\$1.185.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	2
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$27,286.00
COE Rebate Amount:	\$8,845.00
Total Rebate Amount:	\$8,845.00
Message	

The information contained herein is correct as at 15 Aug 2018

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the



Joy Irene (LKKAuto)

From:

Joy Irene (LKKAuto)

Sent:

Monday, 8 October 2018 10:47 AM

To:

'darryltan@gmail.com'

Cc:

Admin A

Subject:

ACCIDENT INVOLVING SLL 1686J AND GBD 6073E ON 14/08/2018

OUR REF: CC6/AIG18014947/Ujb3

TAN CHEE WEE

Policy Holder

Dear Sir,

ACCIDENT INVOLVING SLL 1686J AND GBD 6073E ON 14/08/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further gueries.

Best Regards, Joy Irene | Case Handler LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com| Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Vic (LKKAuto)

From:

Vic (LKKAuto)

Sent:

Tuesday, 18 June, 2019 3:57 PM

To:

Foo, Chityan

Cc:

Admin A; Vic (LKKAuto)

Subject:

Your Ref. 6453933103SG_ACCIDENT INVOLVING VEHICLES SLL 1686J AND GBD

6073E ON 14/08/2018 LKK REF CC6/AIG18014947/Uhb3

Attachments:

Email from TP dd 220519.pdf

Your Ref: 6453933103SG

Dear Jimmy,

We refer to the subject matter.

Please be informed that TP repairer had withdrawn the claim (see attached email).

As such, will submit our WP report and will close file in our end.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IKK Save the Earth Print only when necessary

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Vic (LKKAuto)

From:

Sam <sam@tlmotor.com.sg>

Sent:

Wednesday, 22 May, 2019 8:27 AM

To:

Joy Irene (LKKAuto); Admin A

Subject:

RE: Check Liability - TLM Ref. TP013082018; LKK Ref. TBA; Accident involving

GBD6073E (TLM) & SLL1686J (AIG) on 14.08.2018

Without prejudice

Dear Joy,

The owner of GBD6073E has withdraw third-party claim at our end.

Thank you & regards Sam

From: Joy Irene (LKKAuto) [mailto:JoyIrene@lkkauto.com]

Sent: Wednesday, 15 May 2019 3:25 PM

To: Sam <sam@tlmotor.com.sg>; Admin A <admin-a@lkkauto.com>

Subject: RE: Check Liability - TLM Ref: TP013082018; LKK Ref: TBA; Accident involving GBD6073E (TLM) & SLL1686J

(AIG) on 14.08.2018

WITHOUT PREJUDICE

Dear Sam,

We refer to the subject.

Please be informed that solely basing on the accident statements submitted by parties involved, the liability is clear.

Kindly note on the following:

- The final repair cost is subject to the consistency of the damages according to the nature of the accident and approval of our principal insurer;
- The days for losses(use/income/rental) will be based on the number of days of repair recommended by our surveyor and our principal's approval;
- Our insured reserved their rights to dispute on damage consistency and liability;
- Contents herein should not be construed as an admission of any liability, confirmation of damages whatsoever to the insured/insurer's part;
- This e-mail is on without prejudice basis and does not amount to an authorisation of repair to your client's vehicle; and
- 6) This e-mail should not be regarded as a waiver by AIG of their rights to repudiate the claim should there be future discovery of any breach of policy terms and conditions committed by their driver or insured.

Thank you

Best Regards, Joy Irene | Case Handler LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com| Fax: 6741-4108

...CLAIM SUBFOLDER...(Pending for Survey Report) Revoked / No settlement

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	1840	Submitted	Ins Auth'ed	Status	_	
Main	16 Aug 2018 Edit Reg	Est Submitted	24 Aug 2018 00:00 Edit Adj Rpt	S\$1,150.00 Edit Estima	5\$1	1,150.00 lew Rpt	and notified	Pending f Report	Pending for Survey	
	Main) R	eference	Clair	n Details		Document	ıs]	Show All	
CLAIM SU	BFOLDER DE	TAILS				[Created b	by adjuster]			
nsured:	TAN CHE	WEE, ID: 5723	35568G							
Main Claimant:	YUAN LI	ELECTRICAL ENG	GINEERING PE LTD	, Co. Reg. N	o.: 201215	194D				
Vehicle Reg No.:	GBD607	GBD6073E					09:00 - :59 s and 15 Days !	From LTA Reg Di	te (Man Yr))	
Claim Type	pe: TP / 6453933103SG Policy/Cover Note No.: 2100500833-01 (Comprehension Note No.: 210050083-01 (Comprehension Note No.: 210050083-01 (Comprehension Note No.: 210050083-01 (Comprehension Note No.: 210050083-01 (Comprehension No.: 210050080-01 (Comprehension No.: 210050080-01 (Comprehension No.: 210050080-01 (Comprehension No.: 210050080					nsive)				
Vehicle Reg No. (Insured):	SLL16863 POLICY NO. MT002030									
				Ex	cess:					
Repairer:	Tan Lim F	dotor Pte Ltd (D	efu) 1 Defu Lane 6,	539365 Defu L	ane - Tel:	6858 5151				
dandling insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expres	s) - Tel: 65-64	19-3000	[Handled b	y Foo, Chit Yan] Chityan.Foo@a	ig.com	
Claimant's Insurer:	Tokio Ma	rine Insurance S	ingapore Ltd (HQ)	- Tel: 6221 61	111					
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 625	56-3561 [H	endled by P	MARCUS CHU	IA] [Final R	pt due 28/08	/2018]	
ASSOCIAT	ED MAIL RE	CEIVED					Vi	ew All Comp	ose Case Mail	
AlG_SG	(17/08/2018)	No OI GIA Rep	ort (SLL1686) VS (GBD6073E)						
ALL ASSO	CIATED TAS	ks⊟			1.0	View All S	earch Tasks	Create New Task	Complete	
Due Date	Priority	Type Task	Group Subject	Handler	Assign	ned By	Completed On		n Done	

Claim Documents

*GBD6073E (6453933103SG) [SLL1686J] TP YUAN LI ELECTRICAL ENGINEERING PE LTD Aug 14 2018 9:00AM [TAN CHEE WEE] Tan Lim Motor Pte Ltd

Lit	pload Documents Up	oad Photos Compose New Letter Upload Video Upload Audio	View	View in Brown	ser v
Ass	essment Reports		1 per	page 🔻	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Prin
1	04/09/18 09:47 Accident Statement From: SC - Reg. No: SLL16863, Claimant: TAN CHEE WEE		0	Load HTM	
Pho	otos/Images		3 per p	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	24/08/18 17:13	Chassis Number	0	Load JPG	V
2	24/08/18 17:14	Odometer Reading	0	Load JPG	V
3	24/08/18 17:14	eneral View		Load JPG	V
4	24/08/18 17:14	General View	0	Load JPG	V
5	24/08/18 17:14	General View	0	Load 3PG	V
6	24/08/18 17:14	General View	0	Load JPG	120
7	24/08/18 17:14	ieneral View		Load JPG	12
8	24/08/18 17:14	General View		Load JPG	V
9	24/08/18 17:14	General View	0	Load JPG	V
10	24/08/18 17:14	General View	0	Load JPG	V
11	24/38/18 17:14	General View	0	Load JPG	W
12	24/08/18 17:14	General View	0	Load JPG	V
13	24/08/18 17:14	General View	0	Load 3PG	V
14	24/08/18 17:14	General View	0	Load JPG	120
15	24/08/18 17:14	General View	0	Load JPG	V
16	24/08/18 17:14	General View	0	Load JPG	V
17	24/08/18 17:14	General View	0	Load JPG	V
18	24/08/18 17:14	General View	0	Load JPG	12
19	24/08/18 17:14	General View	0	Load JPG	1
20	24/08/18 17:14	General View	0	Load JPG	V
21	24/08/18 17:14	General View	0	Load JPG	150
22	24/08/18 17:14	General View	0	Load 3PG	V
23	24/08/18 17:14	General View	0	Load JPG	V
Doc	umentation		1 per s	age 🔽	V
Nο	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/08/18 16:54	TP EST & GIA REPORT	0	Load PDF	
2	21/08/18 09:20	NON REPORTING LETTER	0	Load PDF	
3	27/08/18 19:13	TP ESTIMATE- MARKED	0	Load PDF	
4	18/06/19 15:55	EMAIL FROM TP	0	Load PDF	
5	18/06/19 15:58	EMAIL TO AIG	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co Reg. No. 189807 198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/AIG18014947/UHB3Q2

Date:

25/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100500833-01

Claimant Vehicle GBD6073E No:

Insured Vehicle No: SLL1686J

Date of Loss:

14/08/2018

Nature of Claim:

TP

Claim No: 6453933103SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

GBD6073E

Make & Model:

TOYOTA DYNA 100, 3.0 D (M)

Engine No:

5L5575867

Reg. Date: Colour

30/03/2005 (Man. Year: 2005)

Chassis No: Odometer:

JTFUF34Y003010387 418242 km

Engine Capacity: 2986 cc

Market Value/New Car Price: N/A

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Sum Insured (S\$):

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

185 R14

Rear Tyre Size:

155 R12

Front Left Side: Front Right Side: Delium 6 mm

Rear Left Side: Rear Right Side: Delium 6 mm Delium 6 mm

Delium 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,852.92	960.75	892.17	48.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	520.00	840.00	61.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,212.92	1,480.75	1,732.17	53.91
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	3,212.92	1,150.00	2,062.92	64.21
+ GST 7.00/7.00% (S\$)	224.90	80.50	144.40	64.21
Nett Amount (S\$)	3,437.82	1,230.50	2,207.32	64.21
Global Sum S	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment:

24/08/2018

Date Inspected:

24/08/2018

Inspected At:

TAN LIM MOTOR PTE LTD

51 DEFU LANE 10 SINGAPORE 539216

Estimated Period of Repair:

2.0 days

Adjuster: MARCUS CHUA Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT FRONT CORNER PANEL (DENTED)	Not Consistent With The Impact	279.30 FL	*-FL
2	1		*RIGHT HEADLAMP	Scratched	882.50 FL	*882.50 FL
3	1		*RIGHT HEADLAMP LOWER FINISHER	Not Necessary	22.00 FL	*-FL
4	1		*FRONT BUMPER	Bent	398.50 FL	*398.50 FL
5	1		*RIGHT FRONT DOOR STEP GARNISH	Not Necessary	376.00 FL	*-FL
6	1		*FRONT CENTRE GRILLE	Repair	445.60 FL	*-FL
7	1		*RIGHT FRONT DOOR CORPORATE ADDRESS STICKER	Not Necessary	50.00 FS	*-FS
F=Fn	inchise	part. S=8	SpcNett. L=ListItemDisc List Item Discount or	Sub Total (S\$)		1,281.00 320.25
			3,400,000	Total Parts (S\$)	A202-2819-20	960.75

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
2	TO RUST -PROOFING OF THE AFFECTED AREAS	New	50.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	550.00	200.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	700.00	300.00
	Gross Labour Cost (S\$)		1,360.00	520.00
	Report was unsubmitted during	Mester Mest	1,500.00	520.00

< END OF ESTIMATES >