

AIGAsia Insured's Veh No : SLL1686J

Date of Accident : 14 August 2018

Not Authorized
LKK
1/58
2 day.
24/8/18
Whaphi Attorney -



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Yuan Li Electrical Engineering Pte Ltd

Date : 15 August 2018

Estimate To Repair GBD6073E - Toyota Dyna 150 (D)

Chassis No : JTFUF34Y003010387

LKK - Marcos
24/08/18 C 10930h

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	right front corner panel 20 n/c	\$ 279.30 X
02	1 pc	right headlamp 5 n/c	\$ 882.50 X
03	1 pc	right headlamp lower finisher 11	\$ 22.00 X
04	1 pc	front bumper 34	\$ 398.50 X
05	1 pc	right front door step garnish 11	\$ 376.00 X
06	1 pc	front centre grille 2	\$ 445.60 X
			\$ 2,403.90
		Less 25 %	\$ 600.98
			\$ 1,802.93
<u>SPECIAL NETT ITEMS</u>			
07	1 pc	right front door corporate address sticker 11	\$ 50.00 X
			\$ 50.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 60.00 20
02		To rust-proofing of the affected areas.	\$ 11 50.00 X
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 550.00 200
04		Putty and spray painting of the affected portion.	\$ 700.00 300
			\$ 1,360.00
		Total	\$ 3,212.93

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- To survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: