Person) furthe fun of	NT (Office) Date	Time: 16/8/188 9-420m
WS/TP RES/OD RES/EVA/ENV/MV/CS		1
cshop m/s Imperium Au	129	34c 0695) 9748 9940
25 Kelli 8kt RJ 4 # 01-	49	
sured:	Claim No: 018000	5093MFSH
f Veh: Record)	Sec. 2007.	A. 10 06/2018
REV / REP. / REV 24 HRS		O.D. Endorsement:
me: 11. 28am@16 8 18 Person Contacted	Shawn Vehicle	INDOUT
me Action/Instruction () Estimate		
8/M 6642 X - NA INC 180	14699/14	DOA: 10/8/18
1801 Sha WWS 1 1 - NATING 18014	699/h4	DOA: 1018/18
a comment of where of	y enal.	
BCISEM revised to humene b	y emoil.	

OB/11/13) Wef ASS. REC. BY: MOVELS	re./		
3	ASSIGNMENT	-1	
	Veh No: SJM 6642	Vyr Regn: 13/1	109
rom: Date:	Type/ M.Car / M.Cycle / Bus / Van / L		er l
stimated Cost:	Truck / Trailer or A		
D /TP / WS / TP RES / OD RES / EVA / INV / MV			1980
o Inspect Vehicle No: 50M 6642/	Make: Logo to Ar	A/C: Insured / St	MINIMA
t Workshop m/s /njerium	Colour School)	
1	Sp.Reading 2003	T/Radio: Insured / S	ta / NI / NA
nsured:	Eng/No:	22/212	2/20
Policy No.	C/No: JTGGH	2313 6:000	2641
Claims No.	Gen. Cond: Good / Fair / Poor / Burn	t	92
Sum Insured: Excess:	Steering: Inorder/ Jammed / Leaked	/ Burnt or	
Sull modicu.	Brake: Norder/Jammed / Leaked	/ Burnt or	
(Client's Record) Make of Veh:	Modi: Nil / SIRim LSTD A/Rim o	or	
	Tyre Size: F:		
	R: 245	160216	<
(Policy Condition) N/S N/S			SUMI/
Remark. The ventilad commences its	1 (1)	() mile / Office / incre	
repair at the time of inspection.	TOYO / KOKO of		/
Bal. or Market Value:	Front /	Rear	,
IDAC Accident Rport: Consistent? : Yes or No	R/Bal mm	R/Bal.	mm
GIAL PR Seen: Consistent? : Yes or No	L/Bal. mm	L/Bal.	// mm
Est. Repairs: days Res.: Yes or No	D.O.A. 10/8/18	D.O.I. 20/	8/15
Lum Sum: % 3 Val.: Yes or No	Survey held at		770
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S	I N/S / U/C / Roofto	p or
Vehicle	: IN/OUT Rec		
Date:Person Contacted:	The U/C / Chassis frame / Bo	dy Structure affected de	ue to collision.
Date / Time Action / Instruction			
1 5 mglh , nett, 462)	3- 101		
9/0/18 confind 2/5 \$	3200 with Slown		
110,0 CRed 0 5794.45, 64°/	•)		
DECENT.	ED 3 1 AUS 2010		
RECEIV	ED 3 1 A00 20.0		
Date/Time, File Pass to? : Preli. Report	Days Of Repair:		
	Resurvey No. of Trip:	Survey Fee:	160
1318 MGG : Final Report	Resultey No. of Trip.	Transportation:	50
Date/Time, File Return to?	Add Fee: Site Insp (\$)S+RS,SI	50
2)	: Interview (\$) Photos	62
70) Others	
Report Format :	: Tech. Invs (\$	Julias	
Lump Sum / J.B.I: (\$ 3200)	: Weekend (\$)	
5.00 St		TOTAL	322




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter	nationale Des Experts En Auton	nobile
FIRS	ST CAPITAL INSUI	RANCE LTD	Ref : CS/FCI180149	48/Uqd3
	ROBINSON ROAD -01 CITY HOUSES	INGAPORE 068877	Date: 16-08-2018 Code: FCI2	
1.		Policy Particul	ars :- THIRD PARTY CLA	IM
	Insured Veh.	SHC 695J	Veh. Inspected	SJM 6642X
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18006093MFSH	Excess (\$)	0.00
11100	Assign From	CWS (LURENE JAW)	Assign Date	16/08/2018
2.		Vehicle P	articulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	摄	Steering	
	Brakes		Modification	
	General			
3.		Cor	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Descr	ription of Damages	
5.		Ger	neral Information	
	Accident Date	10/08/2018	Inspection Date	16/08/2018
	Survey held at	IMPERIUM AUTOMOTIVE	The state of the s	1 x x x x x x x x x x x x x x x x x x x
	100 A 01 A 0 A 0 A 0 A 0 A 0 A 0 A 0 A 0	25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		
5a.			Remarks	
			"WITHOUT PREJUDICE" BAS S, WE HAVE NOT AUTHORIS	



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18006093MFSH

Date: 21 July 2018

Our Ref: CS/FCI18014948/Uqd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJM 6642X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/08/2018 at the premises of M/s IMPERIUM AUTOMOTIVE. and have the following to report:-

Workshop Estimate Amount	: S\$	8,994.45	
Revised Estimate Amount	: S\$	4,001.18	
"Check" Items Amount	: <u>S</u> \$		
Market Value	: S\$	4	
LTA Reimbursement Value	: <u>S</u> \$	-	
Nett Value	: S\$	-	

Description of Damage: <u>The vehicle sustained damages</u> at the rear portion.



Yours faithfully

CHUA KANG SENG Licensed Appraiser



MS First Capital Insurance Limited to Rea No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

14-08-2018

Our Ref No. D18006093MFSH

Accident Date

10-08-2018

Claim Type. Third Party

Insured Vehicle

SHC0695J

Third Party Vehicle. SJM6642X

Survey Location

25 KAKI BUKIT ROAD 4 #01-49 SYNERGY@KB

Contact Person.

SHAWN TAN

Contact No.

97489940/97489940

Fax No. 63467213

Survey Type

WITHOUT PREJUDICE:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

IMPERIUM AUTOMOTIVE

Attention, NIL

Cc : TP Solicitor

JUSEQUITY LAW

CORPORATION

TP Solicitor Fax No. NA

Officer Incharge

LURENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Tuesday, 21 August 2018 1:56 PM

To:

'Claim Workflow System'; assignments

Cc:

LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR

Subject:

RE: SURVEY ASSESSMENT - D18006093MFSH/1

Attachments:

CSFCI18014948Uqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SJM 6642X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 16 August 2018 11:31 AM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18006093MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 16 August 2018 9:41 AM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18006093MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey. Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards, Admin Team Claim Workflow System

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

SELL YOUR CAR YOURSEL

Get listed until it's sold + we will handle all the paperwork!



POST AN AD NOW!

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! BMW 730Li At \$93K. Low Mileage Of 90000km.



All Wear And Tear Done Up With Full Records And Receipts From Reputable Workshop Direct Owner StarAd



Browse by Category 9 vehicles

Post an Ad

Toyota Picnic

Model

Ways of Selling

Price

Depreciation

Reg Date

Eng Cap

Mileage

Sort by Date Posted

Advanced Search

Any

Veh Type

Submit I

Status

✓ 20 results/page ✓

Search Selection

Toyota Picnic

Advertiser Login

V

Make

MPV

Available

Available

Toyota Picnic 2.0A (New 5-vr COE)

\$69,800

\$13,950 /yr

24-Jun-2009

2009

1,998 cc

80,000 km

100% Accident Free. Fuel Efficient Family Car, Excellent Unit, Full Borneo Maintained. Both Bank And In House Loan Is Available, Low Interest Rate. Cheapest In The Market. High Trade In Is Available. .

Posted: 16-Aug-2018 Tags: 2009 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota



Toyota Picnic 2.0A

\$25,800

\$10,840 /yr

25-Nov-2009

1,998 cc

131,000 km

MPV

Available

Very Well Maintained, Beautiful Red On Beige Interior, Regularly Serviced! Please Call To View/Test Drive Today!

SKL Automobile Pte Ltd

Posted: 13-Aug-2018 Tags: 2009 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota



Toyota Picnic 2.0A

\$24,800

\$12,490 /yr

27-Aug-2009

1,998 cc

MPV

Available

Well Maintained By Owner. Please Call Our Sales Consultant For The Viewing Arrangement And Best Offer.

Posted: 13-Aug-2018 Tags: 2009 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota



Toyota Picnic 2.0A (New 5-yr

\$40,800

\$8,160 /yr

11-Feb-2009

1,998 cc

93,000 km

Available

AA Trust Certified Quality 1 Owner Vehicle! Extremely Well Maintained By 1 Owner Only! Perfect Looking Silver On Beige Interior To Portray A Classic Look! Tip Top Condition! Popular And Spacious MPV F...

AA Trust Automotive

Posted: 04-Aug-2018 Tags: 2009 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Buy Tyres Online! Calast Special Offers from Tyrepac!



Toyota Picnic 2.0A (New 10-yr COE

\$5,780 /yr

19-Feb-2009

1,998 cc

120,000 km

MPV

Available

Monthly Only \$510! Option To Renew Syrs COE At \$39800! Option Selling Without COE At \$18800. Good Condition, Accident Free, No Repair Needed, Bank Loan In House Loan Available, Trade In Welcome.

Posted: 04-Aug-2018 Tags: 2009 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota



Toyota Picnic 2.0A

\$18,080 /yr

02-1un-2009

1,998 cc

Available

Elegant Blue MPV, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In House Loan Packages Available.

Prime Motor & Leasing

Posted: 03-Aug-2018 Tags: 2009 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota

Compare

Toyota Picnic 2.0A

\$19,800

\$10,400 /yr

18-May-2009

1,998 cc

128,000 km

Available

http://www.sgcarmart.com/used_cars/listing.php?RGD=2009&MOD=Toyota Picnic&RPG=20&VEH=...

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: /ehicle Details	0624E
/ehicle No.:	SJM6642X
/ehicle to be Exported:	No
ntended De-registration Date:	20 Aug 2018
/ehicle Make:	TOYOTA
/ehicle Model:	PICNIC AUTO W/O ROOF RACK
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1AZ5847468
Chassis No.:	JTEGH23B600026291
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$23,511.00
Original Registration Date:	13 Jan 2009
First Registration Date:	13 Jan 2009
ransfer Count:	2
Actual ARF Paid: ntended PARF Rebate Details	\$23,511.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jan 2019
ARF Rebate Amount:	\$11,755.00
ntended COE Rebate Details	
COE Expiry Date:	12 Jan 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$3,089.00
COE Rebate Amount:	\$122.00
Total Rebate Amount:	\$11,877.00

The information contained herein is correct as at 20 Aug 2018

OK

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP: 9748 9940 Shawn Tan

Vehicle No.: SJM 6642 X

Fax: 6346 7213

Email: shawn7530@hotmail.com

14 August 2018

4,554.45

Model: Toyota Picnic

QTY	DESCRIPTION		AMT S\$	
	<u>List Items</u>	1900021		92022 27
1	Rear windscreen moulding	12	\$	186.90 X
1	Rear tailgate	11	\$	1,306.90 ×
1	Rear tailgate inner lock		\$	341.90
1	Rear tailgate logo	rec	\$	67.40
1	Rear tailgate weatherstrip	11	\$	247.60 X
1	Rear tailgate "TOYOTA" emblem	u	\$	48.50
1	Rear tailgate "PICNIC" emblem	u	\$	48.50
	Rear taillamps	17	\$	587.00
2	Rear end panel	m	\$	781.50
1	Rear end panel inner garnish	Twy	\$	234.20
1	Rear bumper	80/DE	\$	795.00
	Rear bumper side bracket	34	\$	134.90
1 1	Rear bumper clip (1 set)	ren	\$	50.00
2	Rear bumper reflectors	11	\$	137.00
2	Rear bumper tow hook covers	11	\$	85.30 X
2	Rear bumper side retainers	nu	\$	134.90
1	Rear exhaust silencer	17	Ś	795.10X
2	Rear exhaust mountings	17	\$	90.00 🗴
2	near exhaust mountings		\$	6,072.60
		Less 25%	\$	1,518.15

1	Special Nett Items Rear windscreen sealant	1 7 Cre	\$ 100.00 X 380.00 20 0
1	Rear reverse sensor (1 set)	3123	\$ 480.00

<u>S/N.</u>	Labour Charges	ċ	80.00 20
1	To remove, replaced damaged lamps and check up rear wiring.	٠,	180.00 fv
2	To remove and refit inner garnishes.	2	150.00 50
3	To remove and refit rear reverse sensor.	\$	130.00 ₹0
4	To transfer rear tailgate mechanism and wiring assembly.	¢	180.00 X
5	To remove and refit rear windscreen glass.	ć	^ 150.00 ×
6	To remove, refit and replace exhaust silencer and mountings.	\$	200.00
7	To apply tuff kote.	\$	1,500.00 880
8	Panel beating.	Ś	1,400.00 1000
9	To respray painting on the affected areas.	\$	3,960.00
			4001.17

Signature: Date: Grand Total : \$ 8,994.45



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

فيلة		Affiliated to Federation Internati	onale Des Experts En Autom	obile
IRS	T CAPITAL INSUF	RANCE LTD	Ref : CS/FCI1801494	18/Uqd3n2
	OBINSON ROAD 01 CITY HOUSESI	INGAPORE 068877	Date: 04-09-2018 Code: FCI2	
١.	Carlotte St.	Policy Particulars	:- THIRD PARTY CLAI	M
	Insured Veh.	SHC 695J	Veh. Inspected	SJM 6642X
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18006093MFSH	Excess (\$)	0.00
	Assign From	LURENE	Assign Date	16/08/2018
2.		Vehicle Par	ticulars & Condition	
	Make & Model	TOYOTA PICNIC (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2009
E	Chassis No.	JTEGH23B600026291	Colour	SILVER
	Odometer	206389	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Cond	itions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
	L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
	R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
4.		The state of the s	tion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE F DETAILS.	REAR PORTION.	
5.		Gene	ral Information	with the second contract
	Accident Date	10/08/2018	Inspection Date	20/08/2018
	Survey held at	IMPERIUM AUTOMOTIVE		Tel.
		25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		
5a.			Remarks	
	BITHE INSPECTI	NSISTENT TO ACCIDENT REP ON WAS CONDUCTED ON A"V ICE TO YOUR INSTRUCTIONS	VITHOUT PREJUDICE" BA	SIS. SED REPAIRS.
5b.	100000000000000000000000000000000000000		te Days of Repair	
	ESTIMATED NOR	RMAL PERIOD FOR REPAIR:	5 Working Da	ys



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 6642X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	186.90	8
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,306.90	5
1	REAR TAILGATE INNER LOCK	NOT NECESSARY	341.90	27-
1	REAR TAILGATE LOGO	NECESSARY	67.40	67.40
1	REAR TAILGATE WEATHERSTRIP	NOT NECESSARY	247.60	-
1	REAR TAILGATE "TOYOTA" EMBLEM	NECESSARY	48.50	48.50
-1	REAR TAILGATE "PICNIC" EMBLEM	NECESSARY	48.50	48.50
2	REAR TAILLAMPS	NOT NECESSARY	587.00	974
1	REAR END PANEL	DENTED	781.50	781,50
1	REAR END PANEL INNER GARNISH	TWISTED	234.20	234.20
1	REAR BUMPER	DENTED / DEFORMED	795.00	795.00
1	REAR BUMPER SIDE BRACKET	BENT	134.90	134.90
1	SET REAR BUMPER CLIP	NECESSARY	50.00	50.00
2	REAR BUMPER REFLECTORS	NOT NECESSARY	137.00	
2	REAR BUMPER TOW HOOK COVERS	NOT NECESSARY	85.30	
2	REAR BUMPER SIDE RETAINERS	NECESSARY	134.90	134.90
1	REAR EXHAUST SILENCER	NOT NECESSARY	795.10	
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	90.00	
	LESS 25% DISCOUNT		-1,518.15	-573.73
			4,554.45	1,721.17
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	
1	SET REAR REVERSE SENSOR (SN)	CRACKED	380.00	200.00
	******	State (Control of the Control of the	480.00	200.00
	LABOUR			
	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	20.00
	TO REMOVE AND REFIT INNER GARNISHES.		180.00	
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	50.00

Report Ref No. CS/FCI18014948/Uqd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	
	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	150.00	15
	TO APPLY TUFF KOTE.		200.00	50.00
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR TAILGATE.		1,500.00	880.00
	TO RESPRAY PAINTING ON THE AFFECTED AREAS.		1,400.00	1,000.00
			3,960.00	2,080.00
	GRAND TOTAL		8,994.45	4,001.17

RECOMMENDED COST OF LUMP SUM REPAIRS		3,200.00
(TO ITS PRE-ACCIDENT CONDITION)	7.4 四层的设置的图像 图 图 图 图 图 图 图 图 图 图 图 图 图 图 图 图 图 图	TO THE PERSON

Report Ref No. CS/FCI18014948/Uqd3n2

CHUA KANG SENG

Licensed Appraiser