



联立机构(新)有限公司
LIANNEX CORPORATION (S) PTE LTD.

18, Sungei Kadut Way, Singapore 728789.
Tel: 6368 2668 Fax: 6367 8866 Email: liannexc@singnet.com.sg
Company Reg. No: 199304670R

15/8/2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

BY EMAIL ONLY
(motor.survey@axa.com.sg)

Attn : Motor claim Dept

Dear Sirs ,

OWN DAMAGE CLAIM
TRAFFIC ACCIDENT ON 11/8/2018 INVOLVING PC 5748 M AND TREES ALONG
JALAN AHMAD IBRAHIM TOWARDS AYE
POLICY HOLDER :- ATLANTIC TRAVEL PTE LTD
POLICY NO. :- VFX/PI748495
VEHICLE NO. : PC 5748 M

We append below our repair estimate for PC 5748 M (Isuzu LT434)

Repair estimate

Parts required :-

1 pc Front bumper assy.
1 pc Front bumper structural frame assy.
2 pcs Front bumper spot lamp
1 pc Front cross member
2 pcs Front headlamp
1 pc Front centre panel
1 pc Front centre panel chrome moulding
1 pc Front top panel
1 pc Front panel structural frame assy.
1 pc Front top visor panel
1 set Front top visor panel bracket
2 pcs Front wiper arm
2 pcs Front wiper blade
1 pc 2 pcs Front wiper arm cap
1 pc Front wiper motor
1 pc Front wiper linkage assy.
1 pc 2 pcs Front wiper nozzle
1 pc Front main windscreen glass
1 pc 2 pc Front electrical wing mirror assy.
1 PC Front visor panel
1 set Front visor panel bracket
1 pc Front top windscreen glass

Less 10% trade discount

Special net Items :-

1 pc Front main windscreen gum
b.c.f.

\$ 4600.00 Turn ✓
\$ 1400.00 PA ✓
\$ 560.00 ?
\$ 1100.00 PA ✓
\$ 1920.00 RH-scr / LH-? ✓
\$ 2100.00 DE ✓
\$ 310.00 DE ✓
\$ 3600.00 CR ✓
\$ 2400.00 PA ✓
\$ 2200.00 Turn ✓
\$ 320.00 PA ✓
\$ 560.00 SCR ✓
\$ 240.00 ~~SCR~~ X
\$ 52.00 mis - (1pc) RH / LH-X
\$ 410.00 X
\$ 480.00 X
\$ 20.00 cut (1pc) RH / LH X
\$ 7000.00 ?
\$ 5800.00 RH-CR / LH-repair ✓
\$ 2200.00 X
\$ 480.00 X
\$ 4200.00 ?
\$41952.00
\$ 4195.20
\$37756.80

\$ 500.00 200 Rec ✓
\$38256.80

...2/-

LIANNEX CORPORATION (S) PTE LTD
PC 5748 M

b.c.f.	\$38256.80
1 pc Front top windscreen gum	\$ 400.00 <i>200?</i>
1 pc Front number plate assy.	\$ 50.00 <i>800/35</i>
1 pc BRP bracket	\$ 120.00 <i>?</i>
2 pcs Front shock absorber	\$ 1082.00 <i>?</i>
Total parts cost	\$39908.80

Labour charges :-

a) To tow subject vehicle (two trips)	\$ 500.00 <i>? receipt</i>
b) To remove damaged front shock absorbers and refit new including carrying out front wheel alignment.	\$ 600.00 <i>300?</i>
c) To remove damaged front main windscreen glass and refit new.	\$ 600.00 <i>300?</i>
d) To remove damaged front top windscreen glass and refit new.	\$ 500.00 <i>300?</i>
e) To remove front dashboard panel so as to enable repair to be carried out and refit same.	\$ 500.00 <i>250?</i>
f) To check wiring system and adjust headlamp alignment.	\$ 150.00 <i>50</i>
g) To supply and spray insulation foam on all affected accident parts.	\$ 1500.00 <i>500</i>
h) To putty and spray painting on front bumper, front centre panel, front panel, front visor panel, wing mirror casing and all affected accident parts. (multi colour)	\$ 3800.00 <i>2000</i>
i) To cut off damaged front structural frames and weld new. To jack/knock/straighten all necessary parts including repairing and changing of all damaged parts and align same.	\$ 4500.00 <i>2000</i>
Total repair costs	\$48758.80

Note :- This estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress, insurer and/or their surveyor will be notified accordingly.

The subject vehicle is now lying at the abovementioned address.

Price quoted is subject to 7% GST.

Kindly contact our Miss Alice for the survey.

LIANNEX CORPORATION (S) PTE LTD


DAVID LIANG
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

RRM
Hp 90010068
10 days
P/P
16/08/18 @ 1600
EXCESS: 3000
Receipt
Resurvey 644 paint