

S. REC. BY:

REF: CS/FCI/18014964/Ksd3/12

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

aws

Lerene jaw

of

FCI

Date/Time: 16/8/18 @ 10:11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGP 45D

Insured:

SHC 0980K

at Workshop m/s

T & T Auto Services

Tel:

91459776

of

160 Sin Ming Drive #08-14

Policy No:

Claim No:

D18006019MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 07/08/2018

21/08/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

2:10pm @ 16/8/18

Person Contacted:

Vineent

Vehicle IN/OUT

OUT

Date/Time

Action/Instruction (✓) Estimate

SGP 45D-X

SHC 980K-CS/FCI/16024188/Kgh 3p2

14/12/2016

23/08/18 @ 14:49 p.m. revert pending estimate from repair to Lerene
via email.

(08/11/13) wef

REF: FCI

ASS. REC. BY:

ASSIGNMENT

From: Date: 21/08/2018

Estimated Cost:

On: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGP 45D

at Workshop m/s T&T Auto Services

of 160 Sin Ming Drive # 08-14

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 69K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SGP 45D Yr Regn: 07, 10

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Javar JTL c.c. 5000

Colour: M. Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 105304 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SA JAC22F4ALV03783

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 ER19

R: 275/40 ER19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 2 mm

L/Bal. 4 mm L/Bal. 2 mm

D.O.A. 7/8/18 D.O.I. 2/8/18

Survey held at

Des. of Damages: Frt ☒ Rear ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/8 File pass to Catherine, est not ready

29/08/18 Confirmed L/S \$ 5,350/- @ 4 days with Kenneth.

(\$ 5,152.00 Red - 49%)

RECEIVED 29 AUG 2018

Date/Time, File Pass to?

29/08/18

1) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 5,350.00 45)

170

50

50

19

289



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18014964/Ksd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 980K	Veh. Inspected	SGP 45D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006019MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	16/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/08/2018	Inspection Date	21/08/2018	
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	10-08-2018	Our Ref No. D18006019MFSH
Accident Date	07-08-2018	Claim Type. Third Party
Insured Vehicle	SHC0980K	Third Party Vehicle. SGP45D
Survey Location	160 SIN MING DRIVE #08-14SIN MING AUTOCITY	
Contact Person.	VINCENT TAN	
Contact No.	62666876/ 91459776	Fax No. 68666861
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	T & T AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8387C
Vehicle Details	
Vehicle No.:	SGP45D
Vehicle to be Exported:	No
Intended De-registration Date:	23 Aug 2018
Vehicle Make:	JAGUAR
Vehicle Model:	XJ 5.0L AT ABS D/AB 2WD 4DR GAS/D SR
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	10022302404508PN
Chassis No.:	SAJAC22F4ALV03783
Maximum Power Output:	283.0 kW (379 bhp)
Open Market Value:	\$88,548.00
Original Registration Date:	15 Jul 2010
First Registration Date:	15 Jul 2010
Transfer Count:	0
Actual ARF Paid:	\$88,548.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jul 2020
PARF Rebate Amount:	\$48,701.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$45,501.00
COE Rebate Amount:	\$8,601.00
Total Rebate Amount:	\$57,302.00

The information contained herein is correct as at 23 Aug 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 23 August 2018 2:49 PM
To: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'SUR'; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18006019MFSH/1

Dear Lurene,

Please be informed that we have inspected the vehicle SGP 45D on 21/08/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 16 August 2018 2:19 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006019MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 21/08/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 16 August 2018 10:10 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006019MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Ks

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

ESTIMATE

WONG WAI CHAN @MRS JESSIE PHUA
22 QUEEN ASTRID PARK
SINGAPORE 266827

DATE : 20/08/2018
VEHICLE NO : SGP 45 D
MAKE/MODEL : JAGUAR XJL
ACC DATE : 07/08/2018

*Not Wai Chan
Call 853504
Resurvey After Paint 4 days*

PARTICULAR AMOUNT S\$

LIST ITEMS:				
1	1	REAR BUMPER		<i>Ph</i> 2,250.00 <i>—</i>
2	1	REAR BUMPER REINFORCEMENT		<i>B</i> 1,382.00 <i>—</i>
3	1	REAR BUMPER CHROME GARNISH		<i>m</i> 386.00 <i>—</i>
4	2	REAR NUMBER PLATE LAMP	120.00	<i>cm</i> 260.00 <i>—</i>
5	2	REVERSE SENSOR - CENTRE	240.00	<i>shan</i> 480.00 <i>—</i>
6	1	REVERSE CAMERA		<i>ni</i> 1,220.00 <i>—</i>
7	1	END PANEL		<i>n</i> 1,902.00 <i>X</i>
				7,880.00
Less Discount:			10%	788.00
				7,092.00

SPECIAL NETT ITEMS:			
1	1	REAR NUMBER PLATE	<i>ni</i> 50.00 <i>45m</i>
2	12	REAR BUMPER CLIP	<i>m</i> 60.00 <i>—</i>
			110.00

LABOUR CHARGES:			
1	TO CHECK WIRING		50.00 <i>201</i>
2	TO TUFF KOTE		<i>nn</i> 250.00 <i>X</i>
3	TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING		150.00 <i>601</i>
4	TO REMOVE/REFIX REVERSE SENSOR		150.00 <i>801</i>
5	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS		1,400.00 <i>5001</i>
6	TO SPRAY PAINTING ON AFFECTED AREA		1,300.00 <i>6001</i>
			3,300.00

GRAND TOTAL: 10,502.00

Singapore Dollars: Ten Thousand Five Hundred And Two Only.


T & T Auto Services Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014964/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 980K	Veh. Inspected	SGP 45D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006019MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	16/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	JAGUAR XJL (A)	c.c	5000	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	SAJAC22F4ALV03783	Colour	METALLIC MAROON	
Odometer	105304	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 ZR19	PIRELLI	4 mm	
L/H Front Tyre	245/45 ZR19	PIRELLI	4 mm	
R/H Rear Tyre	275/40 ZR19	PIRELLI	2 mm	
L/H Rear Tyre	275/40 ZR19	PIRELLI	2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/08/2018	Inspection Date	21/08/2018	
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 45D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	2,250.00	2,250.00
1	REAR BUMPER REINFORCEMENT	BENT	1,382.00	1,382.00
1	REAR BUMPER CHROME GARNISH	NECESSARY	386.00	386.00
2	REAR NUMBER PLATE LAMP @\$120.00	CRACKED	260.00	260.00
2	REVERSE SENSOR-CENTRE @\$240.00	SHORTED	480.00	480.00
1	REVERSE CAMERA	DENTED	1,220.00	1,220.00
1	END PANEL	TO REPAIR SEE LABOUR	1,902.00	-
	LESS 10% DISCOUNT		-788.00	-597.80
			7,092.00	5,380.20
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	DENTED	50.00	45.00
12	REAR BUMPER CLIP (SN)	NECESSARY	60.00	60.00
			110.00	105.00
LABOUR				
	TO CHECK WIRING.	NOT NECESSARY	50.00	20.00
	TO TUFF KOTE.		250.00	-
	TO REMOVE/REFIX UPHOLSTERY,CUSHION SEAT & ROOF LINING.		150.00	60.00
	TO REMOVE/REFIX REVERSE SENSOR.		150.00	80.00
	TO PANEL BEATING,REMOVING & REPLACING OF NEW PARTS.INCLUSIVE OF THE REPAIR OF END PANEL.		1,400.00	500.00
	TO SPRAY PAINTING ON AFFECTED AREA.		1,300.00	600.00
			3,300.00	1,260.00
GRAND TOTAL			10,502.00	6,745.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,350.00

Report Ref No. CS/FCI18014964/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.