

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Date : 17/8/2018

M/S AIG

ESTIMATE REPAIR COST FOR SBJ168Z

S/N	QTY	DESCRIPTION			
1	1 PC	FRONT LH FENDER <i>3. d. 5. m</i>	\$	752.00	
2	1 PC	FRONT LH FENDER PROTECTOR <i>car</i>	\$	76.00	
3	1 PC	FRONT LH FENDER PROTECTOR CHROME <i>new</i>	\$	-	
4	1 PC	FRONT LH DOOR <i>r</i>	\$	1,895.00	+
5	1 PC	FRONT LH DOOR PROTECTOR <i>car</i>	\$	215.00	
6	1 PC	FRONT LH DOOR PROTECTOR CHROME <i>new</i>	\$	-	
7	1 PC	FRONT LH SIDE MIRROR <i>r</i>	\$	1,368.00	+
8	2 PCS	FRONT LH SIDE MIRROR SIGNAL LAMP <i>11</i>	\$	110.00	+
			\$	4,416.00	
			LESS 10%	\$ (441.60)	
			\$	3,974.40	
9		To spray paint.	\$	680.00	600
10		labour charge to renew damage parts	\$	580.00	400
11		CHECK WIRING	\$	50.00	20
12		To apply undercoating.	\$	80.00	30
			\$	5,364.40	

*not Allowed
Labor
2/5 3 day.
The photo after rep.
27/8/18*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: