



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : SJS6791S
Date of Accident : 16 August 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Soh Chye Seng

Date : 17 August 2018

Estimate To Repair SKR5962R - Hyundai ELANTRA 1.6 AT ABS D/AB 2WD 4D
Chassis No : KMHDH41CMFU434211

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper DIS	\$ 459.00
02	1 pc	left rear bumper side retainer 3P	\$ 26.00
03	10 ps	rear bumper clips @ \$4.50	\$ 45.00
04	1 pc	left rear bumper mudflap C47	\$ 24.00
05	1 pc	left rear bumper reflector 11	\$ 75.00
06	1 pc	left rear fender 500/500/500	\$ 1,768.00
07	1 pc	left rear fender inner liner 20.1	\$ 114.00
08	4 ps	left rear fender inner liner clips @ \$4.50	\$ 18.00
09	1 pc	left rear fender air vent 11	\$ 29.00
10	1 pc	rear windscreen glass weatherstrip	\$ 145.00
11	1 pc	left rear wheel bearing with hub 11	\$ 316.00
12	1 pc	left rear shock absorber 11	\$ 342.00
13	1 pc	rear axle beam 11	\$ 1,230.00
			\$ 4,591.00
		Less 20 %	\$ 918.20
			\$ 3,672.80
<u>SPECIAL NETT ITEMS</u>			
14	1 pc	rear windscreen sealant	\$ 60.00
15	1 pc	rear windscreen inner sponge seal	\$ 180.00
16	1 pc	left rear wheel rim C47	\$ 550.00
17	1 pc	left rear wheel tyre 80	\$ 350.00
			\$ 1,140.00
<u>LABOUR & MISC. CHARGES</u>			
01		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00
02		To rust-proofing of the affected areas.	\$ 180.00
03		To check steering geometry and computer wheel alignment.	\$ 120.00
04		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 1,380.00
05		To remove and refit rear windscreen glass.	\$ 180.00
06		Machine ti press in and out bearing	\$ 50.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00

not allowed
a/s 3250/2
take into the car
17/8/18
Sdy.

LKC
Maurice 17/08/18
@1130h

2599
2079.2

✓
✓
✓
✓
x
✓
✓
✓
✓
x
x
x

40
30
350
x

60
30
60
x
120
x
700



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SJS6791S
Date of Accident : 16 August 2018

Mr Soh Chye Seng

Date : 17 August 2018

Estimate To Repair SKR5962R - Hyundai ELANTRA 1.6 AT ABS D/AB 2WD 4D
Chassis No : KMHDH41CMFU434211

S/No	Quantity	Description	Amount
08		<u>LABOUR & MISC. CHARGES</u> Putty and spray painting of the affected portion.	\$ 950.00
			\$ 2,940.00
		Total	\$ 7,752.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2/8m @ 3250 x 5days

[Signature]

17/08/18

Carina Woon LCC

600

4069.2