

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0940/2018/PH  
**Date** : 17-Aug-18

**Vehicle IN workshop. Kindly arrange for survey.**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Wang Wei  
**Address** : 21 Canberra Drive  
#05-41  
Singapore 768076  
**Telephone** : HP +65 96162785  
**Type of Claim** : Own Damage claims  
**Policy No.** : 21004955291-01  
**Vehicle No** : **SKH 5019 S**  
**Model Code** : Audi A4 SEDAN 1.4  
**Model / Year** : Jun-17  
**Engine No** : CVN 038564  
**Chassis No** : WAUZZZF47HA161671  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 15-Aug-18  
**Place of Accident** : Upper Jurong Road & Benoi Road

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKH 5019 S.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and transfer both lhs doors multi-lock system and power window devices. Check function and renew if necessary.	S/N \$ 560.00 ✓	
3	To remove center console and dashboard assy for lhs door hinges renewal.	S/N \$ 3,200.00 ??	
4	To remove and reinstall front seat assy, back rest, ABCD pillar trims, carpets, roof liner, carpets, sill trims and etc. Disengage curtain airbags, safety belts.	S/N \$ 1,800.00 X.	
5	To dismantle front bumper, lhs front fender, lhs front door and lhs rear door. Repair lhs rear fender. Renew lhs front fender, lhs front door and lhs rear door. Reinstall all parts removed. ✓	\$ <del>3,600.00</del> 2000 .	
6	To respray lhs front fender, lhs front door, lhs wing mirror cover, lhs door hinges, lhs front door handle, lhs rear door, lhs fender. ✓	\$ <del>3,500.00</del> 2350	4 x 550 = 2200 Mirror : 100 Handle : 50
7	To carry out diagnostic check. ✓	S/N \$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 13,212.00</b>	<u>2350</u>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKH 5019 S.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - LH <i>dented</i>	\$ 665.00	✓
2	ATTACHMENT PARTS FOR FENDER ?	\$ 45.00	?
3	CLOSING ELEMENT - LH ?	\$ 44.00	?
4	BRACKET FOR FENDER - LH ?	\$ 31.00	?
5	BRACKET FOR DEFORMATION ELEMENT - LH <i>re</i>	\$ 43.00	✓
6	BRACKET FOR FENDER - LH & RH <i>re</i>	\$ 27.00	✓
7	BRACE - LH FRONT ?	\$ 103.00	?
8	COVER - LH ? <i>re</i>	\$ 27.00	✓
9	COVER - LH ? <i>re</i>	\$ 20.00	✓
10	DOOR - LH FRONT <i>Distorted</i>	\$ 2,048.00	✓
11	OUTER DOOR SEAL - LH <i>re</i>	\$ 176.00	✓
12	BONDING AGENT ?	\$ 43.00	?
13	CLEANING SOLUTION ?	\$ 64.00	?
14	ATTACHMENT PARTS FOR DOOR ?	\$ 462.00	?
15	DOOR CATCH ?	\$ 92.00	?
16	COVER DOOR CATCH ?	\$ 13.00	?
17	DOOR SEAL INNER ?	\$ 176.00	?
18	DOOR HINGE HALF - UPPER PART - LH UPPER ?	\$ 40.00	?
19	HINGE HALVES - LH UPPER ?	\$ 40.00	?
20	DOOR HINGE HALF - UPPER PART - LH LOWER ?	\$ 40.00	?
<b>SUB- TOTAL SPARE PARTS</b>		<b>\$ 4,199.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKH 5019 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	HEX COLLARED BOLT ?	TBC	?
22	WINDOW REGULATOR W/O MOTOR - LH <i>Nea</i>	\$ 242.00	X
23	WINDOW REGULATOR MOTOR - LH <i>Nea</i>	\$ 228.00	X
24	TRIM PLATE FOR DOOR HANDLE - PASSENGER DOOR <i>Nea</i>	\$ 22.00	X
25	DOOR HANDLE - EXTERIOR <i>ut</i>	\$ 33.00	✓
26	MOUNTIONG BAR - PASSENGER DOOR <i>Nea</i>	\$ 143.00	X
27	SENSOR FOR DOOR HANDLE - LH <i>Nea</i>	\$ 200.00	X
28	WING MIRROR WITH MOUNTING ADJUSTING UNIT - LH <i>Repd</i>	\$ 959.00	✓
29	MIRROR CAP <i>Missing</i>	\$ 217.00	✓
30	MIRROR GLASS(CONVEX) <i>Missing</i>	\$ 1,094.00	✓
31	TRIM STRIP FOR WINDOW GUIDE(HIGH CHROME)-LH <i>Nea</i>	\$ 202.00	X
32	WINDOW SLOT SEAL WITH TRIM STRIP - LH <i>? Nea</i>	\$ 265.00	X
33	WINDOW SLOT SEAL WITH TRIM STRIP - LH	\$ 317.00	X
34	DOOR - REAR LH <i>Dented</i>	\$ 1,928.00	✓
35	OUTER DOOR SEAL - LH <i>Nea</i>	\$ 176.00	✓
36	BONDING AGENT ?	\$ 43.00	?
37	CLEANING SOLUTION ?	\$ 64.00	?
38	SEALING STRIP(SELF ADHESIVE) ?	\$ 14.00	?
39	ATTACHMENT PARTS FOR DOOR ?	\$ 488.00	?
40	DOOR CATCH <i>Nea</i>	\$ 105.00	X
<b>SUB - TOTAL SPARE PARTS</b>		<b>\$ 6,740.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKH 5019 S.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	COVER DOOR CATCH <i>Not New</i>	\$ 12.00	*
42	DOOR SEAL - INNER <i>Not M</i>	\$ 192.00	*
43	SUNDRIES ?	\$ 500.00	^
<b>TOTAL SPARE PARTS</b>		<b>\$ 11,643.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 13,212.00</b>	
<b>GRAND TOTAL</b>		<b>\$ 24,855.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : *Adrian King -*  
Surveyed Date : *17/08/18*  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : *Not Authorised, 08 Days*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant