

ASS. REC. BY: Adrian King

REF:

CC3/A19/8015000/Avd3n2

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

2100495291-01

Claims No.

Sum Insured:

Excess:

600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

130K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

18/8

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKH5019S

Yr Regn: 2017 / June.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4

c.c 1395

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

29499

T/Radio: Insured / Std / NI / NA

Eng/No:

H

C/No:

WAU222F47HA161671

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 245/40R18

R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

15/8/18

D.O.I.

17/08/18

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

07 A19.

SKH 5019S - X

17/8/18

Revert via merimen

20/8/18

Rec approved \$12,875 from victor by merimen

20/8/18

Informed George c/A ex \$600 by email

21/8/18

Final fig \$12,800.48 (Rec 12,572.52, 50% confirmed by email)

RECEIVED 30 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

30/11 - typist

Report Format:

Merimen

Lump Sum / L.B.I. (\$)

12,800.48

Days Of Repair:

8

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

200

Transportation:

10

S + RS, SI

Photos

Others

TOTAL

210

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #07-16 Singapore 079120	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Mohd Zawaye, Norsazani	Date: 17 Aug 2018

Preliminary Advice

Vehicle No	: SKH5019S	Accident Date	: 15/08/2018
Make	: AUDI A4	Policy No.	: 2100495291-01
Assignment Date	: 17/08/2018	Excess	: S\$0.00
Date of Inspection	: 17/08/2018	Est. Duration of Repair	: 8.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,855.00
Revised Amount	:S\$	12,875.00
Check Items (Estimated)	:S\$	5,502.00
Total	:S\$	18,377.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	63,050.00
Salvage Value	:S\$	
Margin for Repair	:S\$	66,950.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 November 2018 3:30 PM
To: Boo seng yak; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SKH5019S - OD AIG - SURVEYED 17 AUG 18

Dear Mr Boo,

Confirm repair cost of \$12,800.48 before excess \$600 and GST @ 8 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Monday, 15 October 2018 10:10 AM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SKH5019S - OD AIG - SURVEYED 17 AUG 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$12,800.48 @ 8 days of repairs. Please take note of short labour charges.

Your early closure is well appreciated.

Best regards - jb

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 20 August 2018 12:05 PM
To: 'Claims Dept'; SUR
Subject: RE: SKH 5019 S (VEH IN)

Dear George,

As instructed by our client , please proceed to repair the insured vehicle **SKH 5019S (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Friday, 17 August 2018 3:06 PM
To: SUR <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: SKH 5019 S (VEH IN)

Daer all,

Survey was carried out on today morning .

Please assist in OD claims Approval for the above mentioned vehicle.

Thank you.

Best Regards,
George wong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with :

***SKH5019S (8380072927SG)**

OD

Aug 15 2018 7:00AM

[WANG WEI]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 20/08/2018 10:55 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12875.00) - SKH5019S - Claim Handler: Loo, Tong Shing

Approved:12875.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 20 August 2018 10:25 AM
To: 'Loo, Tong Shing'; SUR
Subject: RE: SKH5019S OD / 8380072927SG

Dear Tong Shing,

We are pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loo, Tong Shing <TongShing.Loo@aig.com>
Sent: Monday, 20 August 2018 9:33 AM
To: SUR <sur@lkkauto.com>
Subject: : SKH5019S OD / 8380072927SG



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ
เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면
첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-08-27 09:33 +08 to read your message.
After that, open the attachment.

[More Info](#)

: SKH5019S OD / 8380072927SG

From: Loo, Tong Shing

To: SUR

Cc:

Sent: 20/8/2018 9:33:10 AM

Hi LKK,

OI call up to check for the car status.

Would like to know is this case authorize to repair? W/s is pending authorization to activate replacement car for OI .

Thank you.

Loo Tong Shing

AIG

Express Claims Adjuster

Claims Operations | AIG Shared Services

TongShing.Loo@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9629D
Vehicle Details	
Vehicle No.:	SKH5019S
Vehicle to be Exported:	No
Intended De-registration Date:	17 Aug 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	CVN021890
Chassis No.:	WAUZZZF44HA056392
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,212.00
Original Registration Date:	28 Dec 2016
First Registration Date:	28 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$27,097.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2026
PARF Rebate Amount:	\$20,322.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,109.00
COE Rebate Amount:	\$42,728.00
Total Rebate Amount:	\$63,050.00

The information contained herein is correct as at 17 Aug 2018

OK



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : WANG WEI
Period of Insurance : 28 Dec 2017 To 27 Dec 2018
Engine No. : CVN021890
Chassis No. : WAUZZZF44HA056392

Vehicle No. : SKH5019S
Policy No. : 2100495291-01
Endorsement No. :
Issued Date : 27 Nov 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 35 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

WANG WEI - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125201

PREMIUM LEASING - DL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

86CD8K

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place
- Do not admit or discuss fault or blame with the other party(ies)
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.
8. The rental car will be delivered (within Singapore), and **MUST BE RETURNED BACK TO Audi Customer Service Centre** upon collection of your accident car.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7879629D



Name

WANG WEI

王伟

Race

CHINESE

Date of birth

26-10-1978

Sex

M

Country of birth

CHINA

S7879629D

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S7879629D

Name

WANG WEI

Birth Date 26 Oct 1978

Issue Date 02 Jul 2009



4307289

NRIC No. S7879629D



Date of issue

14-11-2008

21 CANBERRA DRIVE #05-41
SINGAPORE 768076

NRIC No: S7879629D

Date: 23/11/2015

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg 02 Jul 2009



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0940/2018/PH
Date : 17-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Wang Wei
Address : 21 Canberra Drive
#05-41
Singapore 768076
Telephone : HP +65 96162785
Type of Claim : Own Damage claims
Policy No. : 21004955291-01
Vehicle No : **SKH 5019 S**
Model Code : Audi A4 SEDAN 1.4
Model / Year : Jun-17
Engine No : CVN 038564
Chassis No : WAUZZZF47HA161671
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Aug-18
Place of Accident : Upper Jurong Road & Benoi Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKH 5019 S.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To remove and transfer both lhs doors multi-lock system and power window devices. Check function and renew if necessary.	S/N \$ 560.00 ✓	✓
3	To remove center console and dashboard assy for lhs door hinges renewal.	S/N \$ 3,200.00 ??	X
4	To remove and reinstall front seat assy, back rest, ABCD pillar trims, carpets, roof liner, carpets, sill trims and etc. Disengage curtain airbags, safety belts.	S/N \$ 1,800.00 X	
5	To dismantle front bumper, lhs front fender, lhs front door and lhs rear door. Repair lhs rear fender. Renew lhs front fender, lhs front door and lhs rear door. Reinstall all parts removed.	\$ 3,600.00	2000 + 2050
6	To respray lhs front fender, lhs front door, lhs wing mirror cover, lhs door hinges, lhs front door handle, lhs rear door, lhs fender.	\$ 3,500.00	2350 - 2900 4 x 550 = 2200 Mirror : 100 Handle : 50
7	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		\$ 13,212.00	2350

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 5019 S.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - LH <i>Dented</i>	\$ 665.00	✓ 532
2	ATTACHMENT PARTS FOR FENDER <i>7/16 new</i>	\$ 45.00	? } X
3	CLOSING ELEMENT - LH <i>7/16 new</i>	\$ 44.00	? } X
4	BRACKET FOR FENDER - LH <i>7/16 new</i>	\$ 31.00	? } X
5	BRACKET FOR DEFORMATION ELEMENT - LH <i>new</i>	\$ 43.00	✓ 34.16
6	BRACKET FOR FENDER - LH & RH <i>new</i>	\$ 27.00	✓ 21.60
7	BRACE - LH FRONT <i>7/16 new</i>	\$ 103.00	? X
8	COVER - LH <i>new</i>	\$ 27.00	✓ 21.04
9	COVER - LH <i>new</i>	\$ 20.00	✓ 15.36
10	DOOR - LH FRONT <i>Distorted</i>	\$ 2,048.00	✓ 1638.40
11	OUTER DOOR SEAL - LH <i>new</i>	\$ 176.00	✓ 140.40
12	BONDING AGENT <i>7/16 new</i>	\$ 43.00	? } X
13	CLEANING SOLUTION <i>7/16 new</i>	\$ 64.00	? } X
14	ATTACHMENT PARTS FOR DOOR <i>new</i>	\$ 462.00	? } X
15	DOOR CATCH <i>new</i>	\$ 92.00	? } X
16	COVER DOOR CATCH <i>new</i>	\$ 13.00	? } X
17	DOOR SEAL INNER <i>new</i>	\$ 176.00	? } X
18	DOOR HINGE HALF - UPPER PART - LH UPPER <i>7/16 new</i>	\$ 40.00	? } X
19	HINGE HALVES - LH UPPER <i>7/16 new</i>	\$ 40.00	? } X
20	DOOR HINGE HALF - UPPER PART - LH LOWER <i>7/16 new</i>	\$ 40.00	? } X
SUB- TOTAL SPARE PARTS		\$ 4,199.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 5019 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	HEX COLLARED BOLT <i>Not needed</i>	TBC	? <input checked="" type="checkbox"/>
22	WINDOW REGULATOR W/O MOTOR - LH <i>Not needed</i>	\$ 242.00	X
23	WINDOW REGULATOR MOTOR - LH <i>Not needed</i>	\$ 228.00	X
24	TRIM PLATE FOR DOOR HANDLE - PASSENGER DOOR <i>Not needed</i>	\$ 22.00	X
25	DOOR HANDLE - EXTERIOR <i>Not needed</i>	\$ 33.00	✓ 26.04
26	MOUNTIONG BAR - PASSENGER DOOR <i>Not needed</i>	\$ 143.00	X
27	SENSOR FOR DOOR HANDLE - LH <i>Not needed</i>	\$ 200.00	X
28	WING MIRROR WITH MOUNTING ADJUSTING UNIT - LH <i>Not needed</i>	\$ 959.00	✓ 765.00
29	MIRROR CAP <i>Missing</i>	\$ 217.00	✓ 173.60
30	MIRROR GLASS(CONVEX) <i>Missing</i>	\$ 1,094.00	✓ 875.00
31	TRIM STRIP FOR WINDOW GUIDE(HIGH CHROME)-LH <i>Not needed</i>	\$ 202.00	X 177.60
32	WINDOW SLOT SEAL WITH TRIM STRIP - LH <i>Not needed</i>	\$ 265.00	X
33	WINDOW SLOT SEAL WITH TRIM STRIP - LH <i>Not needed</i>	\$ 317.00	X
34	DOOR - REAR LH <i>Dented</i>	\$ 1,928.00	✓ 1542.40
35	OUTER DOOR SEAL - LH <i>Not needed</i>	\$ 176.00	✓ 140.40
36	BONDING AGENT <i>Not needed</i>	\$ 43.00	?
37	CLEANING SOLUTION <i>Not needed</i>	\$ 64.00	?
38	SEALING STRIP(SELF ADHESIVE) <i>Not needed</i>	\$ 14.00	?
39	ATTACHMENT PARTS FOR DOOR <i>Not needed</i>	\$ 488.00	?
40	DOOR CATCH <i>Not needed</i>	\$ 105.00	X
SUB - TOTAL SPARE PARTS		\$ 6,740.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 5019 S.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
41	COVER DOOR CATCH <i>Not New</i>	\$ 12.00	*
42	DOOR SEAL - INNER <i>Not New</i>	\$ 192.00	*
43	SUNDRIES <i>? New</i>	\$ 500.00	* 119.92
TOTAL SPARE PARTS		\$ 11,643.00	
TOTAL LABOUR CHARGES		\$ 13,212.00	
GRAND TOTAL		\$ 24,855.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

25,373

25267.96

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim -
Surveyed Date : 17/08/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 08 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 5019 S.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - LH <i>dented</i>	\$ 665.00	✓
2	ATTACHMENT PARTS FOR FENDER ?	\$ 45.00	?
3	CLOSING ELEMENT - LH ?	\$ 44.00	?
4	BRACKET FOR FENDER - LH ?	\$ 31.00	?
5	BRACKET FOR DEFORMATION ELEMENT - LH <i>re</i>	\$ 43.00	✓
6	BRACKET FOR FENDER - LH & RH <i>re</i>	\$ 27.00	✓
7	BRACE - LH FRONT ?	\$ 103.00	?
8	COVER - LH ? <i>re</i>	\$ 27.00	✓
9	COVER - LH ?	\$ 20.00	✓
10	DOOR - LH FRONT <i>Distorted</i>	\$ 2,048.00	✓
11	OUTER DOOR SEAL - LH <i>re</i>	\$ 176.00	✓
12	BONDING AGENT ?	\$ 43.00	?
13	CLEANING SOLUTION ?	\$ 64.00	?
14	ATTACHMENT PARTS FOR DOOR ?	\$ 462.00	?
15	DOOR CATCH ?	\$ 92.00	?
16	COVER DOOR CATCH ?	\$ 13.00	?
17	DOOR SEAL INNER ?	\$ 176.00	?
18	DOOR HINGE HALF - UPPER PART - LH UPPER ?	\$ 40.00	?
19	HINGE HALVES - LH UPPER ?	\$ 40.00	?
20	DOOR HINGE HALF - UPPER PART - LH LOWER ?	\$ 40.00	?
SUB- TOTAL SPARE PARTS		\$ 4,199.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 5019 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	HEX COLLARED BOLT ?	TBC	?
22	WINDOW REGULATOR W/O MOTOR - LH <i>Nea</i>	\$ 242.00	X
23	WINDOW REGULATOR MOTOR - LH <i>Nea</i>	\$ 228.00	X
24	TRIM PLATE FOR DOOR HANDLE - PASSENGER DOOR <i>Nea</i>	\$ 22.00	X
25	DOOR HANDLE - EXTERIOR <i>lt</i>	\$ 33.00	✓
26	MOUNTIONG BAR - PASSENGER DOOR <i>Nea</i>	\$ 143.00	X
27	SENSOR FOR DOOR HANDLE - LH <i>Nea</i>	\$ 200.00	X
28	WING MIRROR WITH MOUNTING ADJUSTING UNIT - LH <i>Nea</i>	\$ 959.00	✓
29	MIRROR CAP <i>Missing</i>	\$ 217.00	✓
30	MIRROR GLASS(CONVEX) <i>Missing</i>	\$ 1,094.00	✓
<i>add 23/8</i> 31	TRIM STRIP FOR WINDOW GUIDE(HIGH CHROME)-LH <i>Nea</i>	\$ (202.00)	X <i>\$ 222 fee ✓</i>
32	WINDOW SLOT SEAL WITH TRIM STRIP - LH <i>Nea</i>	\$ 265.00	X
33	WINDOW SLOT SEAL WITH TRIM STRIP - LH	\$ 317.00	X
34	DOOR - REAR LH <i>Dented</i>	\$ 1,928.00	✓
35	OUTER DOOR SEAL - LH <i>Nea</i>	\$ 176.00	✓
36	BONDING AGENT ?	\$ 43.00	?
37	CLEANING SOLUTION ?	\$ 64.00	?
38	SEALING STRIP(SELF ADHESIVE) ?	\$ 14.00	?
39	ATTACHMENT PARTS FOR DOOR ?	\$ 488.00	?
40	DOOR CATCH <i>Nea</i>	\$ 105.00	X
SUB - TOTAL SPARE PARTS		\$ 6,740.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 5019 S.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	COVER DOOR CATCH <i>Not New</i>	\$ 12.00	<i>X</i>
42	DOOR SEAL - INNER <i>Not New</i>	\$ 192.00	<i>X</i>
43	SUNDRIES <i>?</i>	\$ 500.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 11,643.00
TOTAL LABOUR CHARGES		:	\$ 13,212.00
GRAND TOTAL		:	\$ 24,855.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dep Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0940/2018/PH 23-Aug-18 CHANG 1 of 1 SKH 5019 S Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	PASSENGER DOOR HANDLE TRIM - LH	\$ 22.00	per / 17.00
2	DOOR HANDLE LIGHT - LH	\$ 64.00	car / 50.72
3	FRONT DOOR CORNER TRIM - LH	\$ 40.00	car / 31.44
4	FRONT DOOR WINDOW GUIDE - LH	\$ 392.00	sid / 313.60
GRAND TOTAL :		\$ 518.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Patel
23/08/18 @ 1610h

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0940/2018/PH
Date : 17-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

8 days - ok - jb - 15 Oct 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Wang Wei
Address : 21 Canberra Drive
#05-41
Singapore 768076
Telephone : HP +65 96162785
Type of Claim : Own Damage claims
Policy No. : 21004955291-01
Vehicle No : **SKH 5019 S**
Model Code : Audi A4 SEDAN 1.4
Model / Year : Jun-17
Engine No : CVN 038564
Chassis No : WAUZZZF47HA161671
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Aug-18
Place of Accident : Upper Jurong Road & Benoi Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKH 5019 S .

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To remove and transfer both lhs doors multi-lock system and power window devices. Check function and renew if necessary.	S/N \$ 560.00	\$ 560.00
3	To remove center console and dashboard assy for lhs door hinges renewal.	S/N \$ 3,200.00	
4	To remove and reinstall front seat assy, back rest, ABCD pillar trims, carpets, roof liner, carpets, sill trims and etc. Disengage curtain airbags, safety belts.	S/N \$ 1,800.00	
5	To dismantle front bumper, lhs front fender, lhs front door and lhs rear door. Repair lhs rear fender. Renew lhs front fender, lhs front door and lhs rear door. Reinstall all parts removed. <i>(Added \$250.00 repair rr fender)</i>	\$ 3,600.00	\$ 2,250.00
6	To respray lhs front fender, lhs front door, lhs wing mirror cover, lhs door hinges, lhs front door handle, lhs rear door, lhs fender. <i>(Added \$550.00 respray rr fender - short)</i>	\$ 3,500.00	\$ 2,900.00
7	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 13,212.00	\$ 6,262.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 5019 S.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - LH	\$ 665.00	\$ 532.00
2	ATTACHMENT PARTS FOR FENDER	\$ 45.00	
3	CLOSING ELEMENT - LH	\$ 44.00	
4	BRACKET FOR FENDER - LH	\$ 31.00	
5	BRACKET FOR DEFORMATION ELEMENT - LH	\$ 43.00	\$ 34.16
6	BRACKET FOR FENDER - LH & RH	\$ 27.00	\$ 21.60
7	BRACE - LH FRONT	\$ 103.00	
8	COVER - LH	\$ 27.00	\$ 21.04
9	COVER - LH	\$ 20.00	\$ 15.36
10	DOOR - LH FRONT	\$ 2,048.00	\$ 1,638.40
11	OUTER DOOR SEAL - LH	\$ 176.00	\$ 140.40
12	BONDING AGENT	\$ 43.00	
13	CLEANING SOLUTION	\$ 64.00	
14	ATTACHMENT PARTS FOR DOOR	\$ 462.00	
15	DOOR CATCH	\$ 92.00	
16	COVER DOOR CATCH	\$ 13.00	
17	DOOR SEAL INNER	\$ 176.00	
18	DOOR HINGE HALF - UPPER PART - LH UPPER	\$ 40.00	
19	HINGE HALVES - LH UPPER	\$ 40.00	
20	DOOR HINGE HALF - UPPER PART - LH LOWER	\$ 40.00	
SUB- TOTAL SPARE PARTS		\$ 4,199.00	\$ 2,402.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 5019 S

S/N	Parts Description	c/f	Damage Parts & Prices		REMARKS
			S/NETT		
				\$	2,402.96
21	HEX COLLARED BOLT	TBC			
22	WINDOW REGULATOR W/O MOTOR - LH		\$	242.00	
23	WINDOW REGULATOR MOTOR - LH		\$	228.00	
24	TRIM PLATE FOR DOOR HANDLE - PASSENGER DOOR		\$	22.00	
25	DOOR HANDLE - EXTERIOR		\$	33.00	\$ 26.24
26	MOUNTIONG BAR - PASSENGER DOOR		\$	143.00	
27	SENSOR FOR DOOR HANDLE - LH		\$	200.00	
28	WING MIRROR WITH MOUNTING ADJUSTING UNIT - LH		\$	959.00	\$ 767.20
29	MIRROR CAP		\$	217.00	\$ 173.60
30	MIRROR GLASS(CONVEX)		\$	1,094.00	\$ 875.20
31	TRIM STRIP FOR WINDOW GUIDE(HIGH CHROME)-LH		\$	202.00	\$ 177.60
32	WINDOW SLOT SEAL WITH TRIM STRIP - LH		\$	265.00	
33	WINDOW SLOT SEAL WITH TRIM STRIP - LH		\$	317.00	
34	DOOR - REAR LH		\$	1,928.00	\$ 1,542.40
35	OUTER DOOR SEAL - LH		\$	176.00	\$ 140.40
36	BONDING AGENT		\$	43.00	
37	CLEANING SOLUTION		\$	64.00	
38	SEALING STRIP(SELF ADHESIVE)		\$	14.00	
39	ATTACHMENT PARTS FOR DOOR		\$	488.00	
40	DOOR CATCH		\$	105.00	
SUB - TOTAL SPARE PARTS			\$	6,740.00	\$ 6,105.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 5019 S.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	6,105.60
41	COVER DOOR CATCH		\$ 12.00	
42	DOOR SEAL - INNER		\$ 192.00	
43	SUPPLEMENTARY		\$ 518.00	\$ 412.96
44	SUNDRIES		\$ 500.00	\$ 19.92
	TOTAL SPARE PARTS	:	\$ 12,161.00	\$ 6,538.48
	TOTAL LABOUR CHARGES	:	\$ 13,212.00	\$ 6,262.00
	GRAND TOTAL	:	\$ 25,373.00	\$ 12,800.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0940/2018/PH 23-Aug-18 CHANG 1 of 1 SKH 5019 S Audi A4 SEDAN 1.4 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	PASSENGER DOOR HANDLE TRIM - LH <i>2nd</i>	\$ 22.00	\$	17.20
2	DOOR HANDLE LIGHT - LH <i>2nd</i>	\$ 64.00	\$	50.72
3	FRONT DOOR CORNER TRIM - LH <i>could</i>	\$ 40.00	\$	31.44
4	FRONT DOOR WINDOW GUIDE - LH <i>2nd</i>	\$ 392.00	\$	313.60
GRAND TOTAL :		\$ 518.00	\$	412.96

For Premium Automobiles Pte Ltd

Adrian Ling,
AS

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKH 5019 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0940/2018/MAS

29 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SKH 5019 S, Audi A4 Sedan 1.4 TFSI

With reference to the above-mentioned vehicle, no. **SKH 5019 S**, claimant, **Mr. Wang Wei**, please find the related document per attached.

1. A copy of the Original invoice no. 85013169 – S\$13,054.51
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKH 5019 S

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Aug 2018 16:05		17 Aug 2018 15:48 Edit Adj Rpt	S\$12,800.48 Edit Estimates	S\$12,800.48 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured:	WANG WEI , ID: S7879629D, Tel: +6596162785, Email: WWANG9616@GMAIL.COM																							
Vehicle Reg. No.:	SKH5019S	Date of Loss:	15/08/2018 07:00 - :59 [19 Months and 18 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	OD / 8380072927SG	Policy/Cover Note No.:	2100495291-01 (Comprehensive)																					
		Excess:	S\$600.00																					
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911																							
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/08/2018]																							
Driver/Custodian:	WANG WEI (39 / Male) , NRIC: S7879629D, Tel: +6596162785																							
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail																				
<ul style="list-style-type: none"> AIG_SG (20/08/2018): Alert - Adj Mandate Approved (S\$12875.00) - SKH5019S - Claim Handler: Loo, Tong ... AIG_SG (20/08/2018): SKH5019S / OD / 15/08/2018 / Coverage & Excess update 																								
ALL ASSOCIATED TASKS																								
<div style="display: flex; justify-content: space-between;"> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents





































*SKH5019S (8380072927SG)

OD
















Aug 15 2018 7:00AM

[WANG WEI]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View Use Viewer		
Assessment Reports												1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	17/08/18 16:30	Adjuster Immediate Advice										 Load HTM					
Photos/Images												3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
2	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
3	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
4	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
5	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
6	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
7	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
8	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
9	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
10	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
11	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
12	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
13	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
14	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
15	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
16	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
17	20/08/18 08:37	General View										 Load JPG	<input checked="" type="checkbox"/>				
18	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
19	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
20	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
21	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
22	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
23	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
24	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
25	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
26	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
27	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
28	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
29	07/11/18 14:37	Reinspection Photo										 Load JPG	<input checked="" type="checkbox"/>				
Documentation												1 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	17/08/18 16:24	Singapore Accident Statement										 Load PDF					
2	17/08/18 16:25	Certificate of Insurance										 Load PDF					
3	17/08/18 16:25	Insured's Driving License										 Load PDF					
4	17/08/18 16:25	MARK ESTIMATE										 Load PDF					
5	03/12/18 13:52	WORKSHOP INVOICE										 Load PDF					
6	03/12/18 13:52	DISCHARGE VOUCHER										 Load PDF					
7	03/12/18 13:52	Supplementary										Load PDF					

Linked Accident Report Documents

			View	Use Viewer
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	15/08/18 14:35	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	15/08/18 14:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	15/08/18 14:27	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	15/08/18 14:27	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18015000/AVD3N2

Date: 03/12/2018

REFERENCE

Insured/Claimant: WANG WEI Policy No: 2100495291-01
Date of Loss: 15/08/2018 Nature of Claim: OD Claim No: 8380072927SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKH5019S Engine No: CVN021890
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Chassis No: WAUZZZF44HA056392
Reg. Date: 28/12/2016 (Man. Year: 2016) Odometer: 29499 km
Colour: Black
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$130,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,055.96	6,538.48	5,517.48	45.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,212.00	6,262.00	6,950.00	52.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,267.96	12,800.48	12,467.48	49.34
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	24,667.96	12,200.48	12,467.48	50.54
+ GST 7.00/7.00% (S\$)	1,726.76	854.03	872.73	50.54
Nett Amount (S\$)	26,394.72	13,054.51	13,340.21	50.54

INSPECTION

Date of Assignment: 17/08/2018

Date Inspected: 17/08/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-LH	Dented	665.00 FS	*532.00 FS
2	1		*ATTACHMENT PARTS FOR FENDER	Not Necessary	45.00 FS	*- FS
3	1		*CLOSING ELEMENT-LH	Not Necessary	44.00 FS	*- FS
4	1		*BRACKET FOR FENDER-LH	Not Necessary	31.00 FS	*- FS
5	1		*BRACKET FOR DEFORMATION ELEMENT-LH	Necessary	43.00 FS	*34.16 FS
6	2		*BRACKET FOR FENDER-LH & RH	Necessary	27.00 FS	*21.60 FS
7	1		*BRACKET-LH FRONT	Not Necessary	103.00 FS	*- FS
8	1		*COVER-LH	Necessary	27.00 FS	*21.04 FS
9	1		*COVER-LH	Necessary	20.00 FS	*15.36 FS
10	1		*DOOR-LH FRONT	Distorted	2,048.00 FS	*1,638.40 FS
11	1		*OUTER DOOR SEAL-LH	Necessary	176.00 FS	*140.40 FS
12	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
13	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
14	1		*ATTACHMENT PARTS FOR DOOR	Not Necessary	462.00 FS	*- FS
15	1		*DOOR CATCH	Not Necessary	92.00 FS	*- FS
16	1		*COVER DOOR CATCH	Not Necessary	13.00 FS	*- FS
17	1		*DOOR SEAL INNER	Not Necessary	176.00 FS	*- FS
18	1		*DOOR HINGE HALF-UPPER PART-LH UPPER	Not Necessary	40.00 FS	*- FS
19	1		*HINGE HALVES-LH UPPER	Not Necessary	40.00 FS	*- FS
20	1		*DOOR HINGE HALF-UPPER PART-LH LOWER	Not Necessary	40.00 FS	*- FS
21	1		*HEX COLLARED BOLT (NPA)	Not Necessary	0.00 FS	*- FS
22	1		*WINDOW REGULATOR W/O MOTOR-LH	Not Necessary	242.00 FS	*- FS
23	1		*WINDOW REGULATOR MOTOR-LH	Not Necessary	228.00 FS	*- FS
24	1		*TRIM PLATE FOR DOOR HANDLE-PASSENGER DOOR	Not Necessary	22.00 FS	*- FS
25	1		*DOOR HANDLE-EXTERIOR	Cut	33.00 FS	*26.24 FS
26	1		*MOUNTING BAR-PASSENGER DOOR	Not Necessary	143.00 FS	*- FS
27	1		*SENSOR FOR DOOR HANDLE-LH	Not Necessary	200.00 FS	*- FS
28	1		*WING MIRROR WITH MOUNTING ADJUSTING UNIT-LH	Damaged	959.00 FS	*767.20 FS
29	1		*MIRROR CAP	Missing	217.00 FS	*173.60 FS
30	1		*MIRROR GLASS (CONVEX)	Missing	1,094.00 FS	*875.20 FS
31	1		*TRIM STRIP FOR WINDOW GUIDE (HIGH CHROME)-LH	Cut	202.00 FS	*177.60 FS
32	1		*WINDOW SLOT SEAL WITH TRIM STRIP-LH	Not Necessary	265.00 FS	*- FS
33	1		*WINDOW SLOT SEAL WITH TRIM STRIP-LH	Not Necessary	317.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*DOOR-REAR LH	Dented	1,928.00 FS	*1,542.40 FS
35	1		*OUTER DOOR SEAL-LH	Necessary	176.00 FS	*140.40 FS
36	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
37	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
38	1		*SEALING STRIP (SELF ADHESIVE)	Not Necessary	14.00 FS	*- FS
39	1		*ATTACHMENT PARTS FOR DOOR	Not Necessary	488.00 FS	*- FS
40	1		*DOOR CATCH	Not Necessary	105.00 FS	*- FS
41	1		*COVER DOOR CATCH	Not Necessary	12.00 FS	*- FS
42	1		*DOOR SEAL-INNER	Not Necessary	192.00 FS	*- FS
43	1		*SUNDRIES	Necessary	500.00 FS	*19.92 FS
44	1		*PASSENGER DOOR HANDLE TRIM-LH	Damaged	17.20 FS	*17.20 FS
45	1		*DOOR HANDLE LIGHT-LH	Damaged	50.72 FS	*50.72 FS
46	1		*FRONT DOOR CORNER TRIM-LH	Cracked	31.44 FS	*31.44 FS
47	1		*FRONT DOOR WINDOW GUIDE-LH	Damaged	313.60 FS	*313.60 FS
F=Franchise part. S=SpcNett.					Total Parts (\$\$)	12,055.96 6,538.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH LHS DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.CHECK FUNCTION AND RENEW IF NECESSARY	New	560.00	560.00
3	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR LHS DOOR HINGES RENEWAL	New	3,200.00	-
4	TO REMOVE AND REINSTALL FRONT SEAT ASSY,BACK REST,ABCD PILLAR TRIMS,CARPETS,ROOF LINER,CARPETS,SILL TRIMS AND ETC.DISENGAGE CURTAIN AIRBAGS,SAFETY BELTS	New	1,800.00	-
5	TO DISMANTLE FRONT BUMPER,LHS FRONT FENDER,LHS FRONT DOOR AND LHS REAR DOOR.REPAIR LHS REAR FENDER.RENEW LHS FRONT FENDER,LHS FRONT DOOR AND LHS REAR DOOR.REINSTALL ALL PARTS REMOVED	New	3,600.00	2,250.00
6	TO RESPRAY LHS FRONT FENDER,LHS FRONT DOOR,LHS WING MIRROR COVER,LHS DOOR HINGES,LHS FRONT DOOR HANDLE,LHS REAR DOOR,LHS FENDER	New	3,500.00	2,900.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			13,212.00	6,262.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >