

000000

ASS. REC. BY: 11

REF CS3/SMO17021340 / Bsd3-1 range delays

Supervisor

ASSIGNMENT (Office)

From (Person)

Cinoh Puy Loong

SMO

Date/Time 17/08/2018

Estimated Cost

Bill to

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SJM 2045X

Insured

SLA 3399H

at Workshop m/s

A-TEC Automotive

Tel

6384 5206

of 8 kaki Bukit Ave 4 #05-27 Premier, 415875

Policy No

Claim No

CMTD1703961 / GPL

Sum Insured

Excess

D.O.A 7/11/2017

Make of Veh  
(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Estimate

Date/Time 10:10am @ 8/11/17

Person Contacted

Peggie

Vehicle (P.O.U.T)

Date/Time

Action/Instruction (X) Estimate

SJM2045X-CC4/AXA16017006 / 14yb3s2-D.O.A - 7/09/2016

SLA 3399H - x

Dismanthl Part: 09.11.2017

After repair: 10.11.2017

25.11.17 551pm Email to shen wong

1/5 \$ 2.650/- @ 6 days - checked by Simon  
( \$ 3,550/- Red - 57% )  
27/8/2018

RECEIVED 28 AUG 2018



## Nivitha (LKK Auto)

**From:** Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>  
**Sent:** Friday, 17 August 2018 12:22 PM  
**To:** Maia  
**Cc:** assignments@lkkauto.com; Catherine Chong (LKK Auto)  
**Subject:** RE: Please sent your client's survey report ;RE: ref : CMTD1703961 ; RE: IMMEDIATE ATTENTION!! - Our Ref: AS.172497.sa ; Your Vehicle SLA 3399H - ACCIDENT INVOLVING (OWNER) SJM 2045X & SLA 3399H & YN 5615Z ALONG TPE AFTER TAMPINES AVENUE 12 ON 7 NOVEMBER  
**Attachments:** RE: OFFER PLS!!! ;RE: ref : CMTD1703961 ; RE: IMMEDIATE ATTENTION!! - O... (8.48 MB)

### Without Prejudice

Dear Ms Maia,

Thank you for your enclosed email. We will revert to you as soon as possible once we receive the paper resurvey from M/s LKK.

By copy to M/s LKK,

Please obtain the enclosed scanned colour report and revert to us with the soft copy once ready, thank you.

Best Regards

**Gnoh Pau Loong**

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



Download now @

or

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

**From:** Gnoh, Pau Loong

**Sent:** Thursday, 28 June, 2018 5:00 PM

To: 'Maia' <maia@chiaarul.com>

Cc: assignments@lkkauto.com; 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>

**Subject:** Please sent your client's survey report ;RE: ref : CMTD1703961 ; RE: IMMEDIATE ATTENTION!! - Our Ref: AS.172497.sa ; Your Vehicle SLA 3399H - ACCIDENT INVOLVING (OWNER) SJM 2045X & SLA 3399H & YN 5615Z ALONG TPE AFTER TAMPINES AVENUE 12 ON 7 NOVEMBER 2017

**Importance:** High

Without Prejudice

Dear Ms Maia,

With reference to the captioned, when we received your initial LOD, there was no survey report, only the enclosed colour photos. We have written to Mr Alwyn to assist but till date, there is no survey report from your office.

Please expedite to provide the report to that we can move on for this matter.

In the meantime, please hold hands, thank you.

Best Regards

**Gnoh Pau Loong**

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

**From:** Maia [<mailto:maia@chiaarul.com>]

**Sent:** Wednesday, 27 June, 2018 4:47 PM

**To:** Ngo, Sau Wei Shawn <[Shawn.Ngo@sompo.com.sg](mailto:Shawn.Ngo@sompo.com.sg)>

**Cc:** Gnoh, Pau Loong <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>

**Subject:** ref : CMTD1703961 ; RE: IMMEDIATE ATTENTION!! - Our Ref: AS.172497.sa ; Your Vehicle SLA 3399H - ACCIDENT INVOLVING (OWNER) SJM 2045X & SLA 3399H & YN 5615Z ALONG TPE AFTER TAMPINES AVENUE 12 ON 7 NOVEMBER 2017

Dear Shawn,

We have emailed Mr Pau Loong on 6 March 2018 but did not hear from him since on your proposed offer.

Kindly revert back if you have an offer or we will proceed to issue the Writ of Summons.

Thank you.

Regards,

**Ms Marissa**

M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** Ngo, Sau Wei Shawn [<mailto:Shawn.Ngo@sompo.com.sg>]  
**Sent:** Thursday, February 22, 2018 12:30 PM

**To:** Maia

**Cc:** Gnoh, Pau Loong

**Subject:** RE: IMMEDIATE ATTENTION!! - Our Ref: AS.172497.sa ; Your Vehicle SLA 3399H - ACCIDENT INVOLVING (OWNER) SJM 2045X & SLA 3399H & YN 5615Z ALONG TPE AFTER TAMPINES AVENUE 12 ON 7 NOVEMBER 2017

WITHOUT PREJUDICE

Our ref : CMTD1703961

Dear Maia,

This matter is handle by my colleague, Pau Loong who is copied in this email.

Dear Paul Loong,

For your attention please....

Best Regards,

**Shawn Ngo**

Claims Division

D: 6329 5202 | T: 6461 6555 | F: 6221 3147

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

**From:** Maia [<mailto:maia@chiaarul.com>]

**Sent:** Thursday, February 22, 2018 10:43 AM

**To:** Ngo, Sau Wei Shawn

**Subject:** IMMEDIATE ATTENTION!! - Our Ref: AS.172497.sa ; Your Vehicle SLA 3399H - ACCIDENT INVOLVING (OWNER) SJM 2045X & SLA 3399H & YN 5615Z ALONG TPE AFTER TAMPINES AVENUE 12 ON 7 NOVEMBER 2017

**Importance:** High

Dear Shawn,

We refer to the above matter and to our letter of demand dated 20 December 2017.

We have yet to receive any acknowledgement/offers from your side.

Kindly revert on an urgent basis.

Regards,

**Ms Maia Sudi**

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

## Nivitha (LKK Auto)

---

**From:** Maia <maia@chiaarul.com>  
**Sent:** Friday, 17 August 2018 12:10 PM  
**To:** Gnoh, Pau Loong  
**Subject:** RE: OFFER PLS!!! ;RE: ref : CMTD1703961 ; RE: IMMEDIATE ATTENTION!! - Our Ref: AS.172497.sa ; Your Vehicle SLA 3399H - ACCIDENT INVOLVING (OWNER) SJM 2045X & SLA 3399H & YN 5615Z ALONG TPE AFTER TAMPINES AVENUE 12 ON 7 NOVEMBER  
**Attachments:** 20180817114945205.pdf  
**Importance:** High

Dear Pau Loong,

We refer to the above matter and to your email dated 28 June 2018.

We apologized for the oversight.

We wish to re-iterate that we have already forwarded the full survey report via our letter of demand. However, out of good will, we shall forward the survey report again.

Kindly let us have an offer on an urgent basis.

Regards,

**Ms Maia Sudi**

M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** Gnoh, Pau Loong [mailto:PauLoong.Gnoh@sompo.com.sg]  
**Sent:** Thursday, June 28, 2018 5:00 PM  
**To:** Maia  
**Cc:** assignments@lkkauto.com; Catherine Chong (LKK Auto)  
**Subject:** Please sent your client's survey report ;RE: ref : CMTD1703961 ; RE: IMMEDIATE ATTENTION!! - Our Ref: AS.172497.sa ; Your Vehicle SLA 3399H - ACCIDENT INVOLVING (OWNER) SJM 2045X & SLA 3399H & YN 5615Z ALONG TPE AFTER TAMPINES AVENUE 12 ON 7 NOVEMBER 2017  
**Importance:** High

Without Prejudice

Dear Ms Maia,





**SINCERE APPRAISAL SERVICES** Co.Reg no: 53159958B

60 Paya Lebar Road #07-41 Paya Lebar Square Singapore 409051

Tel : 6636 4628 Fax : 6636 4638 E-mail : sincereappraisal@gmail.com

## INVOICE

**Yap Pik Yee**  
**C/O A-Tec Automotive Pte Ltd**  
**8 Kaki Bukit Avenue 4**  
**#05-27 Premier**  
**Singapore 415875**

**Invoice No:** 171117-666  
**Our ref:** 666/TP/2017  
**Date:** 17/11/2017

**Claim Type:** Third Party  
**Vehicle Reg No:** SJM2045X  
**Vehicle Make/Model:** Nissan Latio 1.5

**Date of Loss:** 7/11/2017  
**Claimant:** Yap Pik Yee

Description	Amount (S\$)
1. Professional Fee (including Transport, Photographs and Miscellaneous charges)	632
<b>Total</b>	<b>632</b>

Singapore Dollar: Six hundred and thirty two dollars only.

Cheques should be crossed A/C PAYEE and made payable to Sincere Appraisal Services



**Sincere Appraisal Services**





# SINCERE APPRAISAL SERVICES

## VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 666/TP/2017

Date: 17/11/2017

### REFERENCE

Date of loss: 7/11/2017  
Claimant: Yap Pik Yee

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM2045X	Make &	Nissan
Reg date:	24/12/2008	Model	Latio 1.5
Colour:	Grey	Engine No:	HR15037117B
Type:	Motor Car	Chassis No:	JN1BAAC11Z0020415
Type of Claims:	Third Party	Odometer No:	123117km
		Engine Cap:	1498cc

### CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition: Good	Steering: Good	Engine Modification: Nil
Paint work: Good	Handbrake: Good	Pre-accident
	Footbrake: Good	Damage: Nil

### CONDITION OF TYRES

Front Left Size:	Bridgestone 185/65R15 70%	Front Right Size:	Bridgestone 185/65R15 70%
Rear Left Size:	Bridgestone 185/65R15 70%	Rear Right Size:	Bridgestone 185/65R15 70%

*The above percentages represent the remaining life of the tyre threads*

### COST OF REPAIRS


Parts	Repairer S\$	Adjuster S\$
	\$ 4,851.09	\$ 4,851.09
Labour	\$ 3,440.00	\$ 2,850.00
Calculated Cost (S\$) :	\$ 8,291.09	\$ 7,701.09

**Recommended Lump Sum Repair Cost (S\$) : \$ 6,200.00**

Date of Assignment: 7/11/2017  
Date Inspected: 7/11/2017  
Est. repair Period: 07 days

Inspected At: A-Tec Automotive Pte Ltd  
8 Kaki Bukit Avenue 4  
#05-27 Premier  
Singapore 415875

### POINT OF IMPACT



### BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle along TPE Expressway.

### GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the rear portion.

### SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$8,291.09. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$6,200.

We have not authorised the repair. Under normal circumstances, estimated **07** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.

  
  
**Dave Chang**  
Automotive Appraiser  
AUTO. ENG, CAE, CGI  
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

*Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.*

## ANNEX A

**REPAIR DETAILS**

## Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Rear bumper assy	warped/dented	\$ 656.90	\$ 551.40 <del>656.90</del> CuTV
2	2	Rear bumper side retainer	bent/necessary	\$ 66.40	\$ 66.40 NECV
3	2	Rear bumper bracket	bent/necessary	\$ 64.30	\$ 64.30 NECV
4	1	Rear bootlid assy	dented/bent	\$ 922.60	\$ 922.60 R X
5	1	Rear end lower panel	dented	\$ 486.60	\$ 486.60 R X
				\$ 2,196.80	\$ 2,196.80 712.10
Less 30%				\$ 659.04	\$ 659.04 213.60
				\$ 1,537.76	\$ 1,537.76 498.47
6	1	Rear bootlid lock solenoid switch	malfunction	\$ 221.30	\$ 221.30 BTV
7	1	Rear bootlid lock mechanism	bent/necessary	\$ 206.90	\$ 206.90 BTV
8	1	Rear bootlid lock catch	bent/necessary	\$ 65.60	\$ 65.60 NN X
9	1	Rear bootlid weatherstrip	warped	\$ 178.60	\$ 178.60
10	1	Rear bootlid inner board	necessary	\$ 278.80	\$ 278.80 NN X
11	1	Rear bootlid 'latio' emblem	necessary	\$ 36.40	\$ 36.40 NECV
12	1	Rear bootlid centre logo	necessary	\$ 38.20	\$ 38.20 NECV
13	1	Rear bootlid no plate lamp	necessary	\$ 64.40	\$ 64.40 X NN
14	1	Rear bootlid outer garnish	warped/bent	\$ 117.60	\$ 117.60 X NN
15	1	Rear left taillamp	cracked	\$ 476.40	\$ 476.40 CRV
16	1	Rear right taillamp X NC No picture	cracked	\$ 476.40	\$ 476.40 NC X
17	1	Rear end lower panel top garnish	cracked	\$ 116.20	\$ 116.20 CRV
18	1	Rear exhaust muffler assy	bent	\$ 595.40	\$ 595.40 NN X
19	2	Rear exhaust muffler rubber mounting	necessary	\$ 66.30	\$ 66.30 NN X
20	1	Rear bumper sponge	warped	\$ 76.30	\$ 76.30 CuTV
21	1	Rear bootlid lock cylinder	malfunction	\$ 88.90	\$ NN 88.90 X
				\$ 3,103.70	\$ 3,103.70
Less 10%				\$ 310.37	\$ 310.37
				\$ 2,793.33	\$ 2,793.33
<u>Special Nett Items</u>					
1	10	Rear bumper clips	necessary	\$ 50.00	\$ 30 50.00 NECV
2	4	Rear end lower panel top garnish clips	necessary	\$ 20.00	\$ 15 20.00 NECV
3	1	Rear end lower panel sealant	necessary	\$ 100.00	\$ 100.00 X NN
4	2	Rear bumper reverse sensor	malfunction	\$ 250.00	\$ 200.00 250.00
5	1	Rear no plate with garnish	necessary	\$ 80.00	\$ 80.00 X NN
6	4	Rear bootlid outer garnish clips	necessary	\$ 20.00	\$ 15 20.00 NECV
				\$ 520.00	\$ -520.00
<b>Total parts</b>				<b>\$ 4,851.09</b>	<b>\$ 4,851.09</b>

# ANNEX B

## REPAIR DETAILS

### Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten rear accident area and replace rear damaged parts.	\$ 1,200.00	\$ 1,000.00 600.00
2	To putty and spray painting rear portion.	\$ 1,200.00	\$ 1,000.00 600.00
3	To check rear lighting and wiring.	\$ 50.00	\$ 30.00
4	To remove and install rear bootlid lock mechanism.	\$ 80.00	\$ 60.00 X
5	To remove and install rear exhaust muffler.	\$ 100.00	\$ 80.00 NNX
6	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00	\$ 120.00 80.00
7	To apply anti rust proofing to rear affected area.	\$ 140.00	\$ 120.00 X
8	To remove and install rear bumper reverse sensor.	\$ 80.00	\$ 60.00
9	Towing service.	\$ 100.00	\$ 80.00 NNX
10	To repair, straighten and align both rear fender assy.	\$ 350.00	\$ 300.00 NNX
Total labour :		\$ 3,440.00	\$ 2,850.00

# ANNEX C

## REPAIR DETAILS

### Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 4,851.09	\$ 4,851.09
Total labour :	\$ 3,440.00	\$ 2,850.00
Total repair cost :	\$ 8,291.09	\$ 7,701.09

Adjusted Repair Cost (Lump Sum Repair)

\$ 6,200.00

45  
Repair days 6




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO17021340/Bsd3s2-1		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 07-09-2018		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLA 3399H	Veh. Inspected	SJM 2045X	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1703961/GPL	Excess (\$)	0.00	
Assign From	GNOH PAU LOONG	Assign Date	17/08/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN LATIO	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JN1BAAC11Z0020415	Colour	DARK GREY	
Odometer	123117	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	ECOPIA	3 mm	
L/H Front Tyre	185/65 R15	ECOPIA	3 mm	
R/H Rear Tyre	185/65 R15	BRIDGESTONE	3 mm	
L/H Rear Tyre	185/65 R15	BRIDGESTONE	3 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/11/2017	Inspection Date	08/11/2017	
Survey held at	A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 2045X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER ASSY	CUT	656.90	581.40
2	REAR BUMPER SIDE RETAINER	NECESSARY	66.40	66.40
2	REAR BUMPER BRACKET	NECESSARY	64.30	64.30
1	REAR BOOTLID ASSY	TO REPAIR SEE LABOUR	922.60	-
1	REAR END LOWER PANEL	TO REPAIR SEE LABOUR	486.60	-
	LESS 30% DISCOUNT		-659.04	-213.63
			1,537.76	498.47
<b><u>NETT ITEMS</u></b>				
1	REAR BOOTLID LOCK SOLENOID SWITCH (N)	BENT	221.30	221.30
1	REAR BOOTLID LOCK MECHANISM (N)	BENT	206.90	206.90
1	REAR BOOTLID LOCK CATCH (N)	NOT NECESSARY	65.60	-
1	REAR BOOTLID WEATHERSTRIP (N)	WARPED	178.60	178.60
1	REAR BOOTLID INNER BOARD (N)	NOT NECESSARY	278.80	-
1	REAR BOOTLID 'LATI' EMBLEM (N)	NECESSARY	36.40	36.40
1	REAR BOOTLID CENTRE LOGO (N)	NECESSARY	38.20	38.20
1	REAR BOOTLID NO PLATE LAMP (N)	NOT NECESSARY	64.40	-
1	REAR BOOTLID OUTER GARNISH (N)	NOT NECESSARY	117.60	-
1	REAR LEFT TAILLAMP (N)	CRACKED	476.40	476.40
1	REAR RIGHT TAILLAMP (CRACKED) (N)	NOT CONSISTENT WITH THE IMPACT	476.40	-
1	REAR END LOWER PANEL TOP GARNISH (N)	CRACKED	116.20	116.20
1	REAR EXHAUST MUFFLER ASSY (N)	NOT NECESSARY	595.40	-
2	REAR EXHAUST MUFFLER RUBBER MOUNTING (N)	NOT NECESSARY	66.30	-
1	REAR BUMPER SPONGE (N)	CUT	76.30	76.30
1	REAR BOOTLID LOCK CYLINDER (N)	NOT NECESSARY	88.90	-
	LESS 10% DISCOUNT		-310.37	-135.03
			2,793.33	1,215.27
<b><u>SPECIAL NETT ITEMS</u></b>				
10	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
4	REAR END LOWER PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	15.00
1	REAR END LOWER PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
2	REAR BUMPER REVERSE SENSOR (SN)		250.00	200.00

Report Ref No. CS3/SMO17021340/Bsd3s2-1





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NO PLATE WITH GARNISH (SN)	NOT NECESSARY	80.00	-
4	REAR BOOTLID OUTER GARNISH CLIPS (SN)	NECESSARY	20.00	15.00
			520.00	260.00
	<b>LABOUR</b>			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR ACCIDENT AREA AND REPLACE REAR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOTLID ASSY AND REAR END LOWER PANEL.		1,200.00	600.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		1,200.00	600.00
	TO CHECK REAR LIGHTING AND WIRING.		50.00	30.00
	TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER.	NOT NECESSARY	100.00	-
	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		140.00	80.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.	NOT NECESSARY	140.00	-
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.		80.00	60.00
	TOWING SERVICE.	NOT NECESSARY	100.00	-
	TO REPAIR, STRAIGHTEN AND ALIGN BOTH REAR FENDER ASSY.	NOT NECESSARY	350.00	-
			3,440.00	1,370.00
<b>GRAND TOTAL</b>			<b>8,291.09</b>	<b>3,343.74</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,650.00</b>

Report Ref No. CS3/SMO17021340/Bsd3s2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.