

振明摩哆

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
 Tel: 6747-4810 Fax: 6745-5018
 cmmotors@singnet.com.sg

Our Ref: CMM229/18/CIS
 Your Ref: To be advised

2-Oct-18

Great American Insurance Company
 3 Temasek Ave
 #16-01
 Centennial Tower
 Singapore 039190

Attn: Motor Claims Department

Dear Sir/Madam

Re: Final cost of repair to Toyota Hiace no: RU6857U

Date of accident: 09-08-2018



Parts supply:

1 pc Tailgate	S\$	950.00
1 pc Tailgate sticker - TOYOTA		30.00
1 pc Tailgate sticker - HIACE		30.00
1 pc Tailgate emblem		40.00
1 pc Taillamp R/h		95.00
1 pc Taillamp R/h lower corner panel		55.00
1 pc Taillamp R/h lower corner panel retainer		35.00
1 pc Rear end panel		180.00
1 pc Rear bumper		150.00
2 pcs Rear bumper retainer @\$35.00		35.00
2 pcs Rear bumper brackets @\$35.00		35.00
6 pcs Rear bumper clips @\$2.00		12.00
		1,647.00
	Add 10%:	164.70

S/Nett Item

1 pc Tailgate sticker - Certis CISCO (S/Nett)	100.00
1 pc Tailgate sticker - AUXILIARY POLICE (S/Nett)	100.00
1 pc Tailgate sticker - EMERGENCY DOOR (S/Nett)	20.00
1 pc Tailgate sticker - PULL TO OPEN (S/Nett)	20.00
1 pc Tailgate sticker - 60km/h (S/Nett)	10.00
1 pc Tailgate sticker - Green Disc (S/Nett)	10.00
1 pc Rear R/h body panel sticker - www.certissecurity.com (S/Nett)	50.00
1 pc Rear R/h body panel sticker - Certis CISCO (S/Nett)	100.00
1 pc Rear windscreen gum (S/Nett)	40.00
	2,261.70

CHIN MENG MOTORS

Jeremy Quek Yuan Ching
 Manager
 Head, Fleet Management
 Logistics Department
 Certis

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Re: Final cost of repair to Toyota Hiace no: RU6857U

Date of accident: 09-08-2018

Parts supply:

Balance b/f: S\$ 2,261.70

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc. 900.00

To respray affected part. 800.00

To remove & refit roof trimming, side trimmings to facilitate repair 80.00

To remove & refit rear windscreen 100.00

To check wirings. 20.00

4,161.70

Less excess: (500.00)

S\$ 3,661.70

Dollars: Three thousand six hundred sixty one and cents seventy only.

CHIN MENG MOTORS



Jeremy Quek Yuan Ching
Fleet Manager
Head, Fleet Management
Logistics Department
Certis