

2010/07/09

ASS. REC. BY: REF: CS/FCI18015021/T1vd3 | N2 Special instruction:

Surveyor: Tau Kich ASSIGNMENT (Office)

From (Person): Luene jaw of FCI Date/Time: 16/8/18 @ 6:23pm

Estimated Cost: Bill to:

OD / PWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 4029L Insured: SHC0770A

at Workshop m/s: Think one' Auto Tel: 68443300

of No. 18 Defu Ave 2

Policy No: Claim No: D18 006097 MFSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 13/08/2018
21/8/18 @ 2pm-3pm

CA / REV / REP. / REV 24 HRS Cup H.O.D. Endorsement:

Date/Time: 11:38am @ 17/8/18 Person Contacted: Karren Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>XD 4029L -x</u>
	<u>SHC0770A -CS3/FCI 16006603/71qh3e2</u> DoA: <u>7/1/2016</u>
<u>23/8/18</u>	<u>Email preli revised to FCI</u>
<u>31/8/18</u>	<u>@ 1138am Karen said vehicle has not send in for repair</u>

(08/11/13) Wef

ASS. REC. BY: *typist*

REF: FCI

ASSIGNMENT

From: _____ Date: 21/08/2018

Estimated Cost: _____

On WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XD 4029L

at Workshop m/s Think One Auto

of No. 18 Defu Lane 2

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

2pm - 3pm

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Cap

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: XD 4029L Yr Regn: 2019 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Nissan GK B45 c.c. 1307Y

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: — T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK B4 CA 00 286

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 11K22.5

R: 1- (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Horizon

Front R/Bal. 8 mm Rear R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. _____ D.O.I. 21/8/18 @ 230pm

Survey held at Think one.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/10/18 LS \$ 2150 confirmed by email (Ref 36, 20-40, 941)

RECEIVED 12 OCT 2018

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) 12/10 - typist

Report Format : CWS
Lump Sum / I.B.I. (\$) 2150/2

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
 Transportation: _____
 S + RS, SI _____
 Photos _____
 Others _____
 TOTAL 719

<u>170 + 420</u>
<u>50</u>
<u>50</u>
<u>29</u>
<u>719</u>

28x15 = 420



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015021/T1vd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 770A	Veh. Inspected	XD 4029L
Policy No.		Coverage (\$)	0.00
Claim No.	D18006097MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	17/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/08/2018	Inspection Date	21/08/2018
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18006097MFSH

Our ref: CS/FCI18015021/T1vd3

Date: 23/8/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. XD 4029L


We thank you for your instruction on 16/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/8/2018 at the premises of M/s THINK ONE AUTOCARE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$38,360.40
Revised Estimate Amount	: S\$2,694.50
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAL, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	14-08-2018	Our Ref No. D18006097MFSH
Accident Date	13-08-2018	Claim Type. Third Party
Insured Vehicle	SHC0770A	Third Party Vehicle. XD4029L
Survey Location	NO.18 DEFU AVENUE 2	
Contact Person.	KAREN TAN	
Contact No.	68443300/ 91288488	Fax No. 68424988
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	THINK ONE AUTOCARE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 12 October 2018 2:37 PM
To: Karen Tan
Cc: SUR
Subject: RE: XD4029L FINALISE PHOTO

Dear Karen,

Noted with thanks.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Karen Tan <karentan@thinkone.com.sg>
Sent: Friday, 12 October 2018 1:27 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: XD4029L FINALISE PHOTO
Importance: High

Hi Veron,

I shall agree and confirm with your offer.

Thank you.

Karen Tan

Claim Advisor

Think One Autocare Pte Ltd

No.18 Defu Avenue 2

Singapore 539522

HP : 9128 8488

DID : 6844 3300 FAX : 6842 4988

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Friday, 12 October, 2018 10:03 AM
To: Karen Tan <karentan@thinkone.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: XD4029L FINALISE PHOTO

Dear Karen,

WITHOUT PREJUDICE

Offer Lump Sum \$2150/- @ 3 working days.

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Karen Tan <karentan@thinkone.com.sg>

Sent: Thursday, 11 October 2018 3:39 PM

To: SUR <sur@lkkauto.com>

Subject: RE: XD4029L FINALISE PHOTO

Importance: High

Dear Sir/Mdm,

Please find as per attach

Thank you.

Karen Tan

Claim Advisor

Think One Autocare Pte Ltd

No.18 Defu Avenue 2

Singapore 539522

HP : 9128 8488

DID : 6844 3300 FAX : 6842 4988

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 23 August 2018 3:04 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006097MFSH/1, XD 4029L
Attachments: XD 4029L PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle XD 4029L
Date of survey: 21/8/2018
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 17 August 2018 11:44 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006097MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 16 August 2018 6:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006097MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.


Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

XD4029L UD Truck

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy (inner)	\$ 1,670.00 x nn
2	1	Front bumper assy (outer)	\$ 1,478.00 nt Rx
3	1	Front bumper top protector	\$ 258.00 x
4	1	Front bumper reinforcement	\$ 392.00 x
5	1	Front bumper reinforcement right side bracket	\$ 125.00 x } nn
6	1	Front bumper right bracket	\$ 51.00 x
7	1	Front bumper right side stay	\$ 129.00 nt ✓
8	1	Front grille assy	\$ 552.00 x
9	1	Front right corner panel	\$ 632.00 x
10	1	Front right headlamp	\$ 1,280.00 x
11	1	Front right headlamp bracket	\$ 220.00 x } x nn
12	1	Front right headlamp holder	\$ 65.00 x
13	1	Front right headlamp wire harness	\$ 650.00 x
14	1	Front right signal lamp	\$ 155.00 x
15	1	Front right step garnish (upper)	\$ 1,275.00 v
16	1	Front right step garnish (lower)	\$ 1,295.00 nt ✓
17	1	Front right foot step (upper)	\$ 393.00 x nn
18	1	Front right foot step (lower)	\$ 393.00 dd ✓
19	1	Front right step garnish bracket	\$ 95.00 x nn
20	1	Front right step garnish reflector	\$ 88.00 nt ✓
21	1	Front right door panel assy	\$ 3,675.00 x
22	2	Front right door hinges	\$ 265.00 x
23	1	Front right door lock	\$ 195.00 x
24	1	Front right door weatherstrip	\$ 388.00 x
25	1	Front right door inner insulation	\$ 260.00 x
26	1	Front right door inner rubber	\$ 128.00 x
27	1	Front right door regulator with motor	\$ 495.00 x } x nn
28	1	Front right fender	\$ 889.00 x
29	1	Front right fender inner shield	\$ 325.00 x
30	1	Front right support bracket	\$ 190.00 x
31	1	Front right leaf spring suspension assy	\$ 2,400.00 x
32	1	Front stabilizer bar	\$ 850.00 x
33	1	Front right shock absorber assy	\$ 650.00 x
34	1	Front right lower arm	\$ 750.00 x
			\$ 22,656.00
Less 10%			\$ 2,265.60
			<u>\$ 20,390.40</u>

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

XD4029L UD Truck

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	16	Front bumper clips	\$ 80.00x
2	1	Front bumper top protector sealant	\$ 80.00x
3	8	Front grille clips	\$ 50.00x
4	8	Front right door inner insulation clips	\$ 30.00x
5	8	Front right fender inner shield clips	\$ 40.00x
6	1	Front right door company sticker	\$ 250.00x
7	1	Front right wheel rim	\$ 1,200.00x
8	1	Front right tyre	\$ 600.00x
9	1	Front no plate	\$ 80.00x
			<u>\$ 2,410.00</u>
Total Parts			\$ 22,800.40

}
 x
 AM

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

XD4029L UD Truck

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front right damaged parts.	\$ 7,000.00 ⁵⁵⁰
2	To putty and spray painting front right affected portion.	\$ 7,000.00 ⁴⁰⁰
3	To remove and install front right door lock mechanism.	\$ 250.00 ^X
4	To check door central locking for function.	\$ 80.00 ^X
5	To apply anti rust proofing to front right affected area.	\$ 150.00 ^X
6	To transfer front right door glass to new door.	\$ 80.00 ^X
7	To check wiring and focus front headlamp.	\$ 50.00 ³⁰
8	To remove and install front right undercarriage parts.	\$ 650.00 ^X
9	Towing service.	\$ 300.00 ^X
		\$ 15,560.00

Total parts : \$ 22,800.40
Total labour : \$ 15,560.00
Total repair cost : \$ 38,360.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

62563561 /
 Taufik 97495749
 'WP' after
 Resurvey before paint.
 3 days
 sure lkk auto com.
 21/8/18 @ 2:30 pm.
 23/8/18.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015021/T1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-10-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 770A	Veh. Inspected	XD 4029L
Policy No.		Coverage (\$)	0.00
Claim No.	D18006097MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	16/08/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN GKB45	c.c	13074
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	GKB4CAB00286	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	11 R22.5	HORIZON	8 mm
L/H Front Tyre	11 R22.5	HORIZON	8 mm
R/H Rear Tyre	11 R22.5 (D)	HORIZON	8/8 mm
L/H Rear Tyre	11 R22.5 (D)	HORIZON	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/08/2018	Inspection Date	21/08/2018
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 4029L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER ASSY (INNER)	NOT NECESSARY	1,670.00	-
1	FRONT BUMPER ASSY (OUTER)	TO REPAIR SEE LABOUR	1,478.00	-
1	FRONT BUMPER TOP PROTECTOR	NOT NECESSARY	258.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	392.00	-
1	FRONT BUMPER REINFORCEMENT RIGHT SIDE BRACKET	NOT NECESSARY	125.00	-
1	FRONT BUMPER RIGHT BRACKET	NOT NECESSARY	51.00	-
1	FRONT BUMPER RIGHT SIDE STAY	CUT	129.00	129.00
1	FRONT GRILLE ASSY	NOT NECESSARY	552.00	-
1	FRONT RIGHT CORNER PANEL	NOT NECESSARY	632.00	-
1	FRONT RIGHT HEADLAMP	NOT NECESSARY	1,280.00	-
1	FRONT RIGHT HEADLAMP BRACKET	NOT NECESSARY	220.00	-
1	FRONT RIGHT HEADLAMP HOLDER	NOT NECESSARY	65.00	-
1	FRONT RIGHT HEADLAMP WIRE HARNESS	NOT NECESSARY	650.00	-
1	FRONT RIGHT SIGNAL LAMP	NOT NECESSARY	155.00	-
1	FRONT RIGHT STEP GARNISH (UPPER)	NOT NECESSARY	1,275.00	-
1	FRONT RIGHT STEP GARNISH (LOWER)	CUT	1,295.00	1,295.00
1	FRONT RIGHT FOOT STEP (UPPER)	NOT NECESSARY	393.00	-
1	FRONT RIGHT FOOT STEP (LOWER)	DENTED	393.00	393.00
1	FRONT RIGHT STEP GARNISH BRACKET	NOT NECESSARY	95.00	-
1	FRONT RIGHT STEP GARNISH REFLECTOR	CUT	88.00	88.00
1	FRONT RIGHT DOOR PANEL ASSY	NOT NECESSARY	3,675.00	-
2	FRONT RIGHT DOOR HINGES	NOT NECESSARY	265.00	-
1	FRONT RIGHT DOOR LOCK	NOT NECESSARY	195.00	-
1	FRONT RIGHT DOOR WEATHERSTRIP	NOT NECESSARY	388.00	-
1	FRONT RIGHT DOOR INNER INSULATION	NOT NECESSARY	260.00	-
1	FRONT RIGHT DOOR INNER RUBBER	NOT NECESSARY	128.00	-
1	FRONT RIGHT DOOR REGULATOR WITH MOTOR	NOT NECESSARY	495.00	-
1	FRONT RIGHT FENDER	NOT NECESSARY	889.00	-
1	FRONT RIGHT FENDER INNER SHIELD	NOT NECESSARY	325.00	-

Report Ref No. CS/FCI18015021/T1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RIGHT SUPPORT BRACKET	NOT NECESSARY	190.00	-
1	FRONT RIGHT LEAF SPRING SUSPENSION ASSY	NOT NECESSARY	2,400.00	-
1	FRONT STABILIZER BAR	NOT NECESSARY	850.00	-
1	FRONT RIGHT SHOCK ABSORBER ASSY	NOT NECESSARY	650.00	-
1	FRONT RIGHT LOWER ARM	NOT NECESSARY	750.00	-
	LESS 10% DISCOUNT		-2,265.60	-190.50
			20,390.40	1,714.50
	<u>SPECIAL NETT ITEMS</u>			
16	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	80.00	-
1	FRONT BUMPER TOP PROTECTOR SEALANT (SN)	NOT NECESSARY	80.00	-
8	FRONT GRILLE CLIPS (SN)	NOT NECESSARY	50.00	-
8	FRONT RIGHT DOOR INNER INSULATION CLIPS (SN)	NOT NECESSARY	30.00	-
8	FRONT RIGHT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	40.00	-
1	FRONT RIGHT DOOR COMPANY STICKER (SN)	NOT NECESSARY	250.00	-
1	FRONT RIGHT WHEEL RIM (SN)	NOT NECESSARY	1,200.00	-
1	FRONT RIGHT TYRE (SN)	NOT NECESSARY	600.00	-
1	FRONT NO PLATE (SN)	NOT NECESSARY	80.00	-
			2,410.00	-
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER ASSY (OUTER).		7,000.00	550.00
	TO PUTTY AND SPRAY PAINTING FRONT RIGHT AFFECTED PORTION.		7,000.00	400.00
	TO REMOVE AND INSTALL FRONT RIGHT DOOR LOCK MECHANISM.	NOT NECESSARY	250.00	-
	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION.	NOT NECESSARY	80.00	-
	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA.	NOT NECESSARY	150.00	-
	TO TRANSFER FRONT RIGHT DOOR GLASS TO NEW DOOR.	NOT NECESSARY	80.00	-
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		50.00	30.00
	TO REMOVE AND INSTALL FRONT RIGHT UNDERCARRIAGE PARTS.	NOT NECESSARY	650.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING SERVICE.	NOT NECESSARY	300.00	-
			15,560.00	980.00
	GRAND TOTAL		38,360.40	2,694.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,150.00

Report Ref No. CS/FCI18015021/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.