



HS MOTOR ENGINEERING

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 email: hsmotorengineering@gmail.com

DIRECT SETTLEMENT

Vehicle No : SKM 3767C
Make/Model : NISSAN JUKE
CHASIS NO : JNIFBAFL5Z0100071

WORKSHOP REPAIR ESTIMATES

Date : 14-Aug-18
Page 2 of 2

S/NO	QTY	List Items	UNIT PRICE (S\$)	AMOUNT (S\$)
<u>LABOUR</u>				
35		TO PANEL BEATING AND REPLACE PARTS	\$ 1,600.00	600
36		TO RESPRAY PAINTING TO AFFECTED PORTION	\$ 1,200.00	1,200 800
37		TO CHECK AND RECTIFY WIRING SYSTEM	\$ 180.00	30
38		TO REMOVE AND REFIX REAR EXHAUST PIPE	\$ 200.00	X
39		TO REMOVE AND TRANSFER REAR TAIL GATE COMPONENTS	\$ 180.00	X
LABOUR TOTAL SUM				\$ 3,360.00
PARTS AND LABOUR TOTAL SUM				\$ 14,271.50

4 Days.

Unpsum repair.

After repair photos.

Guo Qiang.

17/8/18.

[Signature]
5/9/18

Supplementary

- REAR BUMPER SLONGE / CMA \$189.50
- REAR BUMPER AIR VENTILATOR (LH & RH) / \$43.20 x 2
- REAR BUMPER LOWER SKIRT INNER GARNISH \$289.50
- REAR TEMPERATURE SENSOR / DM \$78.40