

Taufik

REF:

ATK

003/AG18015069/T1sd3er

ASSIGNMENT

From: 15082018

Estimated Cost:

00 / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLR 3033Z

at Workshop with:

Premium

of

24 Beni Sector.

Insured

Policy No.

Claims No.

Sum Insured

Excess:

\$800/-

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$110K

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Val No

SLR 3033Z

Vi Regn:

2017

Inf

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Audi Q2

999

Colour

Blue

AC

Insured / Std / NI / NA

Sp Reading

10994

T/Radio

Insured / Std / NI / NA

Engine

C/N

W44232 G46JH00/100

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A.

D.O.I.

18/8/18

Survey held at

Premium Beni

Des. of Damages: Frt / Rear / O/G / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

SLR 3033Z-X

20/08/18 @ 17:43 p.m. revised ZA to Chee Heng via memo.

20/08/18 @ 17:48 p.m. mandate requested authorize repair to Chee Heng via memo.

21/08/18 @ 11:30 a.m. mandate approved by Victor Koh via memo.

21/08/18 @ 16:54 p.m. revised authorised repair to Chee Sing via email.

26/11/18 Confirmed P/P \$16,482.56 @ 15 days with Taufik.

(± 36,110.44 Red 676)

RECEIVED 1 DEC 2018

Case/Time: File Pass to?

☐

Prel. Report

Days Of Repair:

13

11/2/18
4/1/18

☒

Final Report

Resurvey No. of Trip:

1

Case/Time: File Return to?

11

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Witness (\$

Survey Fee

200

Transportation

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

Report Format:

Lump Sum / L.B. to:

16,482.56 P/P

10

210

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 9421G |
| Vehicle Details | |
| Vehicle No.: | SLR3033Z |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 20 Aug 2018 |
| Vehicle Make: | AUDI |
| Vehicle Model: | Q2 1.0 TFSI S TRONIC |
| Primary Colour: | Silver |
| Manufacturing Year: | 2017 |
| Engine No.: | CHZ397700 |
| Chassis No.: | WAUZZZGA6JA001100 |
| Maximum Power Output: | 85.0 kW (113 bhp) |
| Open Market Value: | \$26,192.00 |
| Original Registration Date: | 08 Aug 2017 |
| First Registration Date: | 08 Aug 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$18,669.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 07 Aug 2027 |
| PARF Rebate Amount: | \$14,001.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 07 Aug 2027 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$44,002.00 |
| COE Rebate Amount: | \$39,448.00 |
| Total Rebate Amount: | \$53,449.00 |

The information contained herein is correct as at 20 Aug 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 26 November 2018 2:49 PM
To: 'Boo seng yak'
Cc: Adrian Ling (LKKAuto); SUR; 'Carrine Leong'; jiajee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLR3033Z - OD AIG - SURVEYED 16 AUG 18 - TAUFIKH

Dear Mr Boo,

Confirmed final fig \$ 16,482.56 @ 13 days of repairs before excess \$800/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Monday, 19 November 2018 4:21 PM

To: Adrian Ling <adrianling@lkkauto.com>; shirleyhiew@lkkauto.com; sur@lkkauto.com; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLR3033Z - OD AIG - SURVEYED 16 AUG 18 - TAUFIKH

Hi Adrian, Taufikh and all,

Revised estimate is attached, with photographs of checked item.

Please confirm repair cot of \$16,482.56 @ 13 days of repairs exclude 2 Sundays.

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 30 August 2018 1:55 PM
To: 'Koh, Victor-CK'
Cc: 'Fong, Andy-SY'; 'SUR'
Subject: RE: Re: Labour

Hi Victor,

We refer to your below email above matter were duly noted.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Koh, Victor-CK [mailto:Victor-CK.Koh@aig.com]
Sent: Thursday, 30 August 2018 1:26 PM
To: SUR <sur@lkkauto.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>
Subject: RE: Re: Labour

Hi,

Re-survey on the damage front bonnet, front LH inner fender and LH door pillar photos required.

Thanks & Regards

Victor Koh

AIG

Claims Technical Controller

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +65 6419 1785 | Fax +65 68357416

Victor-ck.koh@aig.com | www.aig.com

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]
Sent: Thursday, August 30, 2018 9:00 AM
To: Koh, Victor-CK
Subject: Fw: Re: Labour

This mail is associated with :
***SLR3033Z (3657937869SG)**
OD
Aug 14 2018 12:30PM
[WANG GE]
Premium Automobiles Pte Ltd

<-- Original Message -->

From: LKK_HQ

To: Andy-SY.Fong@AIG.com

CC: sur@lkkauto.com

Sent On: 29/08/2018 05:40 PM

Subject: Re: Labour

Hi Andy,

We refer to your below email above matter.

According to our surveyor, Taufikh mention the labour given is to replace front bumper and lower spoiler, front LH fender, front LH headlamp and front LH door.

It also include to repair and align the front bonnet, front LH inner fender and LH door pillar.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AIG_SG

To: LKK_HQ

CC: AIG_SG; Andy-SY.Fong@AIG.com

Sent On: 21/08/2018 11:31 AM

Subject: Labour

Hi,

Kindly break down why 4.5 days labour needed?

Regards

Victor Koh

This is an auto-generated email. Do not reply to this email.

Sent by : Hiew May Fung (LKK Auto Consultants Pte Ltd)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 21 August 2018 4:54 PM
To: 'PAL Claim'
Cc: Admin-D (LKKAuto)
Subject: RE: Request Certificate Insurance for vehicle no.SLR 3033Z

Dear Chee Sing,

As instructed by our client, please proceed to repair the insured vehicle **SLR 3033Z (Excess \$ 800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PAL Claim [mailto:claims@premiumauto.com.sg]
Sent: Monday, 20 August 2018 5:59 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: 'PAL Claim' <claims@premiumauto.com.sg>
Subject: RE: Request Certificate Insurance for vehicle no.SLR 3033Z

Dear Nivitha,

Kindly find attached is the document as per your request.

Best regards,
Chang Chee Sing
Estimator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Sent: Monday, 20 August 2018 4:02 PM
To: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: FW: Request Certificate Insurance for vehicle no.SLR 3033Z

Dear In-Charge,

Kindly assist.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Monday, 20 August 2018 1:12 PM
To: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: Request Certificate Insurance for vehicle no.SLR 3033Z

Dear In-charge,

Kindly provide Certificate Insurance for vehicle no. SLR 3033Z survey by Taufikh on 16.08.2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been checked for viruses by AVG antivirus software.
www.avg.com

View Received Message

This mail is associated with :

***SLR3033Z (3657937869SG)**

OD

Aug 14 2018 12:30PM

[WANG GE]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 21/08/2018 11:30 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$17347.00) - SLR3033Z - Claim Handler: Dally Amri, Mimi Zarina

Approved:17347.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loh, Chee-Heng

Date: 20 Aug 2018

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|--------------|
| Vehicle No | : SLR3033Z | Accident Date | : 14/08/2018 |
| Make | : AUDI Q2 | Policy No. | : |
| Assignment Date | : 20/08/2018 | Excess | : S\$0.00 |
| Date of Inspection | : 18/08/2018 | Est. Duration of Repair | : 9 days |
| Inspection At | : Premium Automobiles Pte Ltd (Benoi)
24 Benoi Sector
Singapore 629857 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 52,324.00 |
| Revised Amount | :S\$ | 17,347.00 |
| Check Items (Estimated) | :S\$ | 6,974.00 |
| Total | :S\$ | 24,321.00 |

Lump Sum Repair :S\$

Total Loss Consideration

| | | |
|--------------------|------|------------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 110,000.00 |
| COE / PARF Rebate | :S\$ | 53,449.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 56,551.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|----------------------------|
| Date Of Report | 14/08/2018 14:16 |
| Date Of Accident | 14/08/2018 12:30 |
| Exact Location Of Accident | 452 ALEXANDRA ROAD CARPARK |
| Country/State Of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLR3033Z |
| Insured/Policyholder | |
| Name Of Registered Owner | WANG GE |
| NRIC No | S7079421G |
| Email Address | GE.WANG@HPE.COM |
| Mobile Phone No | (LOCAL) +65-96968011 |
| Alternative Phone No | OFFICE-96968011 |

Vehicle Particulars

| | |
|--|------------------|
| Manufacturer | AUDI |
| Model | AUDI Q2 1.0 TFSI |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES |
| If No, Please state action to be taken | |

| | |
|------------------|-------------|
| Vehicle Category | PRIVATE CAR |
|------------------|-------------|

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | |
| Cover Note Number | |

Driver

| | |
|----------------------|-------------------------|
| Name of Driver | CHENG RU |
| NRIC No | S7079422E |
| Date Of Birth | 30/12/1996 |
| Occupation | INDOOR |
| Date Of Driving Pass | 30/12/1996 |
| Driving Experience | 21 YEARS AND 7 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-91732450 |
| Fax Number | |
| Contact Number | |
| Email Address | CHENGRU2004@HOTMAIL.COM |

| | |
|---|--------------------------|
| Address | 2 BISHAN ST 25
#19-01 |
| Postcode | S573973 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | SPOUSE |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|------------------------|
| Type Of Accident | COLLIDED INTO PROPERTY |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | |
| Was any other material or property damaged? | NO |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

I ACCIDENTALLY TURNED AND COLLIDED INTO THE PILLAR

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Lim Bo Guan
NRIC/Fin No: 4855256AM



Sketch Plan #2

SKETCH PLAN



A: SLR 3033 Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I Accidentally turned and collided into the pillar

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name: LYM BO SENG
NRIC/FIN No: 9155 25 8911





REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7079421G



Name
WANG GE
王 柯

Race
CHINESE

Date of birth
27-01-1970

Sex
M

Country of birth
CHINA

License Number
S7079421G

Valid Until
27 Jan 1970

Issue Date
01 Nov 2003





NRIC No. S7079421G



Date of issue
09-02-2007

2 BISHAN STREET 25 #18-01
SINGAPORE 570873

NRIC No. S7079421G

Date: 17/12/2011

No: 6907343

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

Valid Until: 30 Dec 1998

NP 428A

License No. S7079421G



REPUBLIC OF SINGAPORE DRIVING LICENCE

NAME: CHENG RU

DOB: 31 Jan 1970

Valid Until: 18 Jan 2004

IC01091130F



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7079422E

NAME: CHENG RU

程茹

RACE: CHINESE

DATE OF BIRTH: 31-07-1970

COUNTRY OF BIRTH: CHINA

SEX: F

S7079422E





YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 2 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

Valid Until: 30 Dec 1998

NP 426A

Licence No: S7079422E



4052225

NRIC No: S7079422E

Date of Issue: 20-08-2007

17 SHAN STREET 25 #15-01
SINGAPORE 573973

NRIC No: S7079422E Date: 17/12/2011 No: 6907140






CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : WANG GE
Period of Insurance : 08 Aug 2018 To 07 Aug 2019
Engine No. : CHZ397700
Chassis No. : WAUZZZGA6JA001100

Vehicle No. : SLR3033Z
Policy No. : 1700036655-01
Endorsement No. :
Issued Date : 20 Jun 2018

ABOUT THE COVER

Make/Model : AUDI Q2/ Q2 Sport 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

WANG GE - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add. 55, 56, Road 1 Singapore 408609 63662323

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1955 (Malaysia).

0904125208

PREMIUM LEASING - SLOH

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

80P2AM

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo





Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0932/2018/KS
Date : 15-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Wang Ge
Address : 2 Bishan Street 25
#19-01
Singapore 573973
Telephone : HP +65 96968011
Type of Claim : Own Damage Claim
Policy No. :
Vehicle No : **SLR 3033 Z**
Model Code : Audi Q2 1.0 TFSI
Model / Year : Aug-17
Engine No : CHZ 397700
Chassis No : WAUZZZGA6JA001100
Mileage : 10994
Date In : 13-Aug-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Aug-18
Place of Accident : 452 ALEXANDRA ROAD CARPARK

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495719
Revert, Not Author's
15/8/18 @ 5pm

Resurvey before part
sure@lkkauto.com

9 days.

25/8/18

Ex: to be advise

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLR 3033 Z

| S/N | Nature of Jobs | Estimated Charges | Remarks |
|--------------------------|--|-------------------------|---------|
| 1 | To remove and transfer wire harness for headlights, horns , fog lamps, outside temperature sensor and headlight washer assy. | S/N \$ 360.00 ✓ | |
| 2 | To remove and renew, aircon condensor, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas. | S/N \$ 1,000.00 ? X n/n | |
| 3 | To dislodge and reinstall lhs a-pillar, front door harness, multi-lock system and power window devices. Inspect for damage. | S/N \$ 780.00 ? X n/n | |
| 4 | To dislodge and reinstall center console and dashboard assy for A-Pillar renewal. | S/N \$ 3,200.00 X ✓ 280 | |
| 5 | To remove and reinstall lhs front seat assy, abcd pillar trims, sill trims, floor carpets, electronic components and fuse trays. | S/N \$ 1,800.00 X n/n | |
| 6 | To renew front windscreen. | S/N \$ 480.00 X n/n | |
| SUB-TOTAL LABOUR CHARGES | | : \$ 7,620.00 | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLR 3033 Z

| S/N | Nature of Jobs | Estimated Charges | Remarks |
|----------------------|---|--|-------------------------|
| 7 | <p>To dismantle front bumper, lhs front fender, bonnet and lhs front door. Cut out and reweld lhs fender support, closing element, and lhs A-pillar. Renew front lock carrier and align to position. Renew front bumper lhs front fender, headlight, bonnet and lhs front door. Re-organise front crash management components. Reinstall all parts removed.</p> | <p>2250.
\$ 12,250.00</p> | <p>500
3,000.00</p> |
| 8 | <p>To respray front bumper, lhs front fender, bonnet, lhs fender top support, lhs A-pillar, door entrances, lhs sill panel and lhs front door. To carry out joint sealer work and stone chip treatment.</p> | <p>2750.
\$ 6,200.00</p> | <p>550</p> |
| 9 | To carry out wheel alignment | S/N \$ 240.00 | ✓ |
| 10 | To carry out diagnostic check. | S/N \$ 384.00 | ✓ 192 |
| TOTAL LABOUR CHARGES | | : \$ 26,694.00 | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 3033 Z.

| S/N | Parts Description | Damage Parts & Prices | |
|------------------------------|----------------------------------|-----------------------|---------------|
| | | S/NETT | REMARKS |
| 1 | FRONT BUMPER | \$ 1,620.00 | de ✓ 1295.20 |
| 2 | FRONT BUMPER FIXING PARTS | \$ 297.00 | ? X n7 |
| 3 | FRONT BUMPER CENTER GRILLE | \$ 172.00 | X n7 |
| 4 | FRONT BUMPER SPOILER | \$ 259.00 | wt ✓ 207.20 |
| 5 | WHEEL SPOILER LH | \$ 30.00 | de ✓ ? X n7 |
| 6 | FRONT BUMPER AIR GUIDE GRILLE LH | \$ 29.00 | m7 ✓ 22.88 |
| 7 | FRONT BUMPER ADAPTOR LH / RH | 2 \$ 66.00 | de ✓ 52.72 |
| 8 | GUIDE SECTION LH | \$ 31.00 | ora ✓ 24.16 |
| 9 | FOAM FILLER PIECE | \$ 66.00 | ? X |
| 10 | BUMPER CARRIER | \$ 600.00 | ? X |
| 11 | RADIATOR GRILLE | \$ 1,215.00 | X |
| 12 | RADIATOR GRILLE STRIKER PLATE | \$ 108.00 | X |
| 13 | FRONT BUMPER TOP COVER | \$ 86.00 | X |
| 14 | "CAUTION" SIGN STICKER | \$ 12.00 | X |
| 15 | AIR CON STICKER | \$ 7.00 | X |
| 16 | WHEEL ARCH COVER LH / RH | 2 \$ 558.00 | ? de ✓ 445.60 |
| 17 | FRONT FENDER LH | \$ 1,011.00 | bt ✓ 808.80 |
| 18 | FRONT FENDER ATTACHMENT PARTS | \$ 34.00 | na ✓ X n7 |
| 19 | FRONT FENDER BRACKET LH | \$ 11.00 | bt ✓ 8.80 |
| 20 | FRONT FENDER BRACKET LH | \$ 41.00 | bt ✓ 32.72 |
| SUB-TOTAL SPARE PARTS | | \$ 6,212.00 | |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

6253

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 3033 Z.

| S/N | Parts Description | Damage Parts & Prices | |
|------------------------------|---|-----------------------|---------------|
| | | S/NETT | REMARKS |
| 21 | FRONT FENDER BRACKET LH | \$ 11.00 | bt - 8.80 |
| 22 | FRONT FENDER BRACE | \$ 28.00 | bt - 22.00 |
| 23 | FRONT FENDER CLOSING ELEMENT LH | \$ 29.00 | ent - 22.72 |
| 24 | FRONT FENDER INSULATION | \$ 66.00 | de - 52.80 |
| 25 | WHEEL HOUSING LINER LH | \$ 175.00 | de - 140.00 |
| 26 | WHEEL HOUSING LINER ATTACHMENT PARTS LH | \$ 49.00 | ne - 39.00 |
| 27 | LED HEADLIGHT LH | \$ 4,378.00 | Can - 3502.40 |
| 28 | LED HEADLIGHT POWER MODULE | \$ 665.00 | ? X nn |
| 29 | LED HEADLIGHT CONTROL UNIT | \$ 486.00 | ? 389.80 ds ✓ |
| 30 | LED HEADLIGHT HID BULB | \$ 625.00 | ? X nn |
| 31 | HEADLIGHT MOUNTING LH | \$ 103.00 | cu - 82.40 |
| 32 | LIFY CYLINDER LH | \$ 123.00 | ? X nn |
| 33 | BONNET | \$ 2,378.00 | X |
| 34 | BONNET ATTACHMENT PARTS | \$ 141.00 | X |
| 35 | BONNET STRIKER LH / RH | 2 \$ 192.00 | X |
| 36 | BONNET IMPACT PROTECTION LH | \$ 27.00 | X |
| 37 | BONNET IMPACT PROTECTION RH | \$ 27.00 | X |
| 38 | BONNET IMPACT PROTECTION CENTER | \$ 26.00 | X |
| 39 | BONNET LOCK WITH MICRO-SWITCH | \$ 353.00 | X |
| 40 | FRONT LOCK CARRIER | \$ 854.00 | ? X |
| SUB-TOTAL SPARE PARTS | | \$ 10,736.00 | |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 3033 Z.

| S/N | Parts Description | Damage Parts & Prices | |
|------------------------------|--------------------------------|-----------------------|----------|
| | | S/NETT | REMARKS |
| 41 | HORN BRACKET LH | \$ 30.00 X | } un |
| 42 | HORN LH | \$ 254.00 X | |
| 43 | WASH WATER RESERVOIR | \$ 149.00 ? X | |
| 44 | CONNECTING PLATE LH | \$ 65.00 X R | |
| 45 | CLOSING ELEMENT LH | \$ 26.00 X R | |
| 46 | SIDE MEMBER LH | \$ 359.00 X R | |
| 47 | A/B-PILLAR FRAME | \$ 1,603.00 X R | |
| 48 | FRONT WINDSCREEN | \$ 882.00 X | } un |
| 49 | RAIN SENSOR FOIL | \$ 127.00 X | |
| 50 | GLASS PRIMER | \$ 19.00 X | |
| 51 | FRONT DOOR LH | \$ 2,174.00 bf | 1,739.20 |
| 52 | FRONT DOOR CATCH LH | \$ 105.00 ? X un | |
| 53 | FRONT DOOR INNER SEAL LH | \$ 139 105.00 un | 111.20 |
| 54 | FRONT DOOR ATTACHMENT PARTS LH | \$ 81.00 ? X un | |
| 55 | FRONT DOOR COVER LH | \$ 226.00 un | 180.40 |
| 56 | WINDOW GUIDE | \$ 359.00 un | 286.20 |
| 57 | WINDOW REGULATOR GUIDE | \$ 113.00 ? X | } un |
| 58 | FRONT NO PLATE. | S/N \$ 25.00 X | |
| 59 | FRONT W/SCREEN SEALANT | S/N \$ 200.00 X | |
| 60 | ARYCLIX SEALER | S/N \$ 180.00 X | |
| SUB-TOTAL SPARE PARTS | | : \$ 7,082.00 | |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 3033 Z.

| S/N | Parts Description | Damage Parts & Prices | |
|----------------------|---------------------|-----------------------|-------------|
| | | S/NETT | REMARKS |
| 61 | CAVITY WAX | S/N \$ 140.00 X | } un X |
| 62 | STONE CHIP | S/N \$ 180.00 X | |
| 63 | METAL FILLER POWDER | S/N \$ 280.00 X | |
| 64 | SUNDRIES | \$ 1,000.00 ?X | |
| TOTAL SPARE PARTS | | : \$ 25,630.00 | 25705 |
| TOTAL LABOUR CHARGES | | : \$ 26,694.00 | |
| GRAND TOTAL | | : \$ 52,324.00 | \$ 2,593.00 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

52584-92

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd



Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

| AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dep
Tel: 6841 0055 / Fax: 6256 4315 | | Estimate No.
Date
Service Advisor
Pages
Regn No
Model No | PA/OD/0932/2018/KS
23-Aug-18
CHANG
1 of 1
SLR 3033 Z
Audi Q2 1.0 TFSI |
|---|---|---|--|
| Quantity | Description | Unit Price | Amount |
| <u>Parts</u> | | | |
| 1 | ^{burger} FRONT HEADLIGHT TRIM - LH | \$ 14.00 | ok / 10.48A |
| 2 | FRONT FENDER TRIM - LH | \$ 36.00 | DE / 28.16A |
| 3 | FRONT WHEEL ARCH TRIM CLIP SET | \$ 40.00 | aa / 31.68A |
| 4 | FRONT BUMPER GRILLE - LH | \$ 145.00 | 42 / 115.60A |
| GRAND TOTAL : | | \$ 235.00 | |

For Premium Automobiles Pte Ltd

Adrian Ling
KL



[Signature]
Authorised Signature

23/08/18 @ 1610

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0932/2018/KS
Date : 15-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
Your seveyor recommended 9 days
We took 13 days exclude 2 Sunday
jb - 19/11/18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Wang Ge
Address : 2 Bishan Street 25
#19-01
Singapore 573973
Telephone : HP +65 96968011
Type of Claim : Own Damage Claim
Policy No. :
Vehicle No : **SLR 3033 Z**
Model Code : Audi Q2 1.0 TFSI
Model / Year : Aug-17
Engine No : CHZ 397700
Chassis No : WAUZZZGA6JA001100
Mileage : 10994
Date In : 13-Aug-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Aug-18
Place of Accident : 452 ALEXANDRA ROAD CARPARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLR 3033 Z

| S/N | Nature of Jobs | | Estimated
Charges | | Remarks |
|--------------------------|--|--------|----------------------|----|---------|
| 1 | To remove and transfer wire harness for headlights, horns , fog lamps, outside temperature sensor and headlight washer assy. | S/N \$ | 360.00 | \$ | 360.00 |
| 2 | To remove and renew, aircon condensor, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas. | S/N \$ | 1,000.00 | | |
| 3 | To dislodge and reinstall lhs a-pillar, front door harness, multi-lock system and power window devices. Inspect for damage. | S/N \$ | 780.00 | | |
| 4 | To dislodge and reinstall center console and dashboard assy for A-Pillar renewal.
(R/L L/F door wiring harness P/W devices) | S/N \$ | 3,200.00 | \$ | 280.00 |
| 5 | To remove and reinstall lhs front seat assy, abcd pillar trims, sill trims, floor carpets, electronic components and fuse trays. | S/N \$ | 1,800.00 | | |
| 6 | To renew front windscreen. | S/N \$ | 480.00 | | |
| SUB-TOTAL LABOUR CHARGES | | : | \$ 7,620.00 | \$ | 640.00 |

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLR 3033 Z

| S/N | Nature of Jobs | Estimated Charges | Remarks |
|-----------------------------|--|---------------------|--------------------|
| | <i>c/f</i> | | \$ 640.00 |
| 7 | To dismantle front bumper, lhs front fender, bonnet and lhs front door. Cut out and reweld lhs fender support, closing element, and lhs A-pillar. Renew front lock carrier and align to position. Renew front bumper lhs front fender, headlight, bonnet and lhs front door. Re-organise front crash management components. Reinstall all parts removed. (Additional \$750/- for repair lhs fender top support and "A" pillar) | \$ 12,250.00 | \$ 3,000.00 |
| 8 | To respray front bumper, lhs front fender, bonnet, lhs fender top support, lhs A-pillar, door entrances, lhs sill panel and lhs front door. To carry out joint sealer work and stone chip treatment. | \$ 6,200.00 | \$ 2,750.00 |
| 9 | To carry out wheel alignment | S/N \$ 240.00 | \$ 240.00 |
| 10 | To carry out diagnostic check. | S/N \$ 384.00 | \$ 192.00 |
| TOTAL LABOUR CHARGES | | \$ 26,694.00 | \$ 6,822.00 |

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 3033 Z.

| S/N | Parts Description | <u>Damage Parts & Prices</u> | |
|------------------------------|----------------------------------|----------------------------------|--------------------|
| | | S/NETT | REMARKS |
| 1 | FRONT BUMPER | \$ 1,620.00 | \$ 1,295.20 |
| 2 | FRONT BUMPER FIXING PARTS | \$ 297.00 | |
| 3 | FRONT BUMPER CENTER GRILLE | \$ 172.00 | |
| 4 | FRONT BUMPER SPOILER | \$ 259.00 | \$ 207.20 |
| 5 | WHEEL SPOILER LH | \$ 30.00 | |
| 6 | FRONT BUMPER AIR GUIDE GRILLE LH | \$ 29.00 | \$ 22.88 |
| 7 | FRONT BUMPER ADAPTOR LH / RH | 2 \$ 66.00 | \$ 52.72 |
| 8 | GUIDE SECTION LH | \$ 31.00 | \$ 24.16 |
| 9 | FOAM FILLER PIECE | \$ 66.00 | |
| 10 | BUMPER CARRIER | \$ 600.00 | |
| 11 | RADIATOR GRILLE | \$ 1,215.00 | |
| 12 | RADIATOR GRILLE STRIKER PLATE | \$ 108.00 | |
| 13 | FRONT BUMPER TOP COVER | \$ 86.00 | |
| 14 | "CAUTION" SIGN STICKER | \$ 12.00 | |
| 15 | AIR CON STICKER | \$ 7.00 | |
| 16 | WHEEL ARCH COVER LH / RH | 2 \$ 558.00 | \$ 445.60 |
| 17 | FRONT FENDER LH | \$ 1,011.00 | \$ 808.80 |
| 18 | FRONT FENDER ATTACHMENT PARTS | \$ 34.00 | |
| 19 | FRONT FENDER BRACKET LH | \$ 11.00 | \$ 8.80 |
| 20 | FRONT FENDER BRACKET LH | \$ 41.00 | \$ 32.72 |
| SUB-TOTAL SPARE PARTS | | \$ 6,212.00 | \$ 2,898.08 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SLR 3033 Z.

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 3033 Z.

| S/N | Parts Description | | Damage Parts & Prices | | REMARKS |
|------------------------------|--------------------------------|-----|-----------------------|-----------|-----------------|
| | | | S/NETT | | |
| | | c/f | | \$ | 7,157.04 |
| 41 | HORN BRACKET LH | | \$ 30.00 | | |
| 42 | HORN LH | | \$ 254.00 | | |
| 43 | WASH WATER RESERVOIR | | \$ 149.00 | | |
| 44 | CONNECTING PLATE LH | | \$ 65.00 | | |
| 45 | CLOSING ELEMENT LH | | \$ 26.00 | | |
| 46 | SIDE MEMBER LH | | \$ 359.00 | | |
| 47 | A/B-PILLAR FRAME | | \$ 1,603.00 | | |
| 48 | FRONT WINDSCREEN | | \$ 882.00 | | |
| 49 | RAIN SENSOR FOIL | | \$ 127.00 | | |
| 50 | GLASS PRIMER | | \$ 19.00 | | |
| 51 | FRONT DOOR LH | | \$ 2,174.00 | \$ | 1,739.20 |
| 52 | FRONT DOOR CATCH LH | | \$ 105.00 | | |
| 53 | FRONT DOOR INNER SEAL LH | | \$ 139.00 | \$ | 111.20 |
| 54 | FRONT DOOR ATTACHMENT PARTS LH | | \$ 81.00 | | |
| 55 | FRONT DOOR COVER LH | | \$ 226.00 | \$ | 180.40 |
| 56 | WINDOW GUIDE | | \$ 359.00 | \$ | 286.80 |
| 57 | WINDOW REGULATOR GUIDE | | \$ 113.00 | | |
| 58 | FRONT NO PLATE. | S/N | \$ 25.00 | | |
| 59 | FRONT W/SCREEN SEALANT | S/N | \$ 200.00 | | |
| 60 | ARYCLIX SEALER | S/N | \$ 180.00 | | |
| SUB-TOTAL SPARE PARTS | | : | \$ 7,116.00 | \$ | 9,474.64 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 3033 Z.

| S/N | Parts Description | Damage Parts & Prices | |
|-----|----------------------|-----------------------|--------------|
| | | S/NETT | REMARKS |
| | | <i>c/f</i> | \$ 9,474.64 |
| 61 | CAVITY WAX | S/N \$ 140.00 | |
| 62 | STONE CHIP | S/N \$ 180.00 | |
| 63 | METAL FILLER POWDER | S/N \$ 280.00 | |
| 64 | SUPPLEMENTARY | \$ 235.00 | \$ 185.92 |
| 65 | SUNDRIES | \$ 1,000.00 | |
| | TOTAL SPARE PARTS | \$ 25,899.00 | \$ 9,660.56 |
| | TOTAL LABOUR CHARGES | \$ 26,694.00 | \$ 6,822.00 |
| | GRAND TOTAL | \$ 52,593.00 | \$ 16,482.56 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

| AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315 | | Estimate No.
Date
Service Advisor
Pages
Regn No
Model No | PA/OD/0932/2018/KS
23-Aug-18
CHANG
1 of 1
SLR 3033 Z
Audi Q2 1.0 TFSI |
|--|--------------------------------|---|--|
| Quantity | Description | Unit Price | Amount |
| Parts | | | |
| 1 | FRONT HEADLIGHT TRIM - LH | \$ 14.00 | \$ 10.48 |
| 2 | FRONT FENDER TRIM - LH | \$ 36.00 | \$ 28.16 |
| 3 | FRONT WHEEL ARCH TRIM CLIP SET | \$ 40.00 | \$ 31.68 |
| 4 | FRONT BUMPER GRILLE - LH | \$ 145.00 | \$ 115.60 |
| GRAND TOTAL : | | \$ 235.00 | \$ 185.92 |

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLR 3033 Z

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0932/2018/MAS

11 Dec 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLR 3033 Z, Audi Q2 1.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLR 3033 Z**, claimant, **Mr. Wang Ge**, please find the related document per attached.

1. A copy of the Original invoice no. 85013248 – S\$16,780.34
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLR 3033 Z

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6836 2222
Main Telefax: 6471 5755
Page 1 17:12

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6888 2222
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6755 2222
Telefax: 6471 1023

Customer Service
Service Appointment
24 Hour Breakdown Service
Email: customer.care@premiumcars.com.sg
6888 2222
9628 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

| | | |
|---|---|--|
| AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120 | Invoice: 85013248
Date : 06/12/2018
Order : SLR30332
Term : 30 | Account: 00006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 |
|---|---|--|

Regn No.: SLR30332 (V 34572) Regn Date: 08/08/2017 Mileage: 10994 WIP No.: 21088
Model: Q2 1.0 TFSI S tronic GABANG Chassis: WAUZZZGA6JA001100 Engine: CHZ 397700 Dept: U
VSS No.:
You have been assisted by :- UB-Jiayee (43)

| | | Details | Qty | Unit Price | Amount |
|-------------|----------|--|---------|------------|----------|
| D | EXC | M: 8888
Insurance Excess/Liability | -888.00 | 1.00 | -888.00 |
| S | BODYWORK | M:
TO REMOVE,CHECK AND REINSTALL FRONT WIRE
HARNESS FOR HEADLIGHTS,HORNS, FOG LAMPS,
OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT
WASHER ASSY | 368.00 | 1.00 | 368.00 |
| S | BODYWORK | M:
TO DISLODGE AND REINSTALL LHS A PILLAR,FRONT
DOOR HARNESS,MULTI LOCK SYSTEM AND POWER WINDOW
DEVICES. INSPECT FOR DAMAGE | 288.00 | 1.00 | 288.00 |
| S | BODYWORK | M:
TO DISMANTLE FRONT BUMPER,LHS FRONT FENDER,BONNET
AND LHS FRONT DOOR.CUT OUT AND REWELD LHS FENDER S
CLOSING ELEMENT,AND LHS A PILLAR.REALIGN FRONT LOC
CARRIER TO POSITION.RENEW FRONT BUMPER,LHS FRONT F
HEADLIGHT AND LHS FRONT DOOR.REORGANISE FRONT CRAS
MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED | 3000.00 | 1.00 | 3,000.00 |
| Sub-Total | | | | | |
| 7% GST | | | | | |
| Grand Total | | | | | |



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6856 2221
Fax: 6475 1733
Page 2 17:12

Alexandra Service Centre:
281 Alexandra Road
Singapore 159938
Telephone: 6888 2223
Telefax: 6475 1023

Ubi Service Centre:
100 Woodlands
Singapore 738602
Telephone: 6885 1184
Telefax: 6885 1184

Customer Service:
Service Appointment:
Hour Breakdown Service:
Email:
6866 2323
6828 1231
customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

| | | |
|---|---|--|
| AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120 | Invoice: 85813248
Date : 06/12/2018
Order : SLR30337
Term : 30 | Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 |
|---|---|--|

Regn No.: SLR30337 (V 34572) Regn Date: 08/08/2017 Mileage: 10994 WIP No.: 21088
Model: Q2 1.0 TFSI S tronic 88KW Chassis: WAUZZZGA6JAN01100 Engine: CHZ 397700 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (43)

| | | Details | Qty | Unit Price | Amount |
|-------------|-------------|---|---------|------------|----------|
| S | BODYWORK | M:
TO RESPRAY FRONT BUMPER, LHS FRONT FENDER,
BONNET, LHS FENDER TOP SUPPORT AND LHS FRONT
DOOR. TO CARRY OUT OINT SEALER WORK AND STONE
CHIP TREATMENT | 2750.00 | 1.00 | 2,750.00 |
| S | BODYWORK | M:
TO CARRY OUT WHEEL ALIGNMENT | 240.00 | 1.00 | 240.00 |
| S | BODYWORK | M:
TO CARRY OUT DIAGNOSTIC CHECK | 192.00 | 1.00 | 192.00 |
| X | A81A807409 | (AIR) (SK) ADAPTER (21/ | 1.00 | 30.20 | 24.16 |
| X | A81A821471 | (AIR) (SK) BRACKET (21/ | 1.00 | 11.00 | 8.80 |
| X | A81A821467 | (AIR) (SK) BRACKET (21/ | 1.00 | 40.90 | 32.72 |
| X | A81A821469 | (AIR) (SK) BRACKET (21/ | 1.00 | 11.00 | 8.80 |
| X | A81A821135 | (AIR) (SK) SUPPORT (21/ | 1.00 | 27.50 | 22.00 |
| X | A81A821111 | 006419/ (V) (G) PLATE (2 | 1.00 | 28.40 | 22.72 |
| X | A81A831721A | 006419/ (VOR) (SK) DOOR | 1.00 | 139.00 | 111.20 |
| X | A81A807410 | 006419/ (VOR) (BER) AD | 1.00 | 35.70 | 28.56 |
| X | A81A941773A | (AIR) (SK) HEADLIGHT (2 | 1.00 | 4378.00 | 3,502.40 |
| Sub-Total | | | | | |
| 7% GST | | | | | |
| Grand Total | | | | | |



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159958
Main Telephone: 6894 2223
Main Telefax: 6471 3733
Page 3 17:12

Alexandra Service Centre
281 Alexandra Road
Singapore 159958
Telephone: 6894 2223
Telefax: 6471 3733

UBi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6744 3333
Telefax: 6744 3333

Customer Service
Service Appointment
400 000 000
400 000 000
Email: customer.care@premiumauts.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

| | | |
|---|---|--|
| AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120 | Invoice: 85013248
Date : 06/12/2018
Order : SLR30332
Term : 30 | Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 |
|---|---|--|

Regn No.: SLR30332 (V 34572) Regn Date: 08/08/2017 Mileage: 10994 WIP No.: 21088
Model: Q2 1.0 TFSI S tronic GABANG Chassis: WAUZZZ6A6JA001100 Engine: CHZ 397700 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (43)

| | | Details | | Qty | Unit Price | Amount |
|---|----------------|------------------------|-----------|-------|------------|----------|
| X | A01A021105 | FENDER | Less 020% | 1.00 | 1011.00 | 808.80 |
| X | A01A021171B | (AIR) (SK) WHEEL HOU(| Less 020% | 1.00 | 175.00 | 140.00 |
| X | A01A007107 GRU | (AIR) (SK) COVER(21/00 | Less 020% | 1.00 | 746.50 | 597.20 |
| X | A01A007108 GRU | (AIR) (SK) COVER(21/00 | Less 020% | 1.00 | 746.50 | 597.20 |
| X | A01A007110 4W3 | (AIR) (SK) SPOILER(21/ | Less 020% | 1.00 | 259.00 | 207.20 |
| X | A01A031051A | DOOR | Less 020% | 1.00 | 2174.00 | 1,739.20 |
| X | A01A053716 4W3 | (AIR) (SK) COVER(21/00 | Less 020% | 1.00 | 278.50 | 222.80 |
| X | A01A090629 | PARTS KIT | Less 020% | 1.00 | 48.80 | 39.04 |
| X | A01A005607B | MOUNTING | Less 020% | 1.00 | 103.00 | 82.40 |
| X | A01A007151 989 | COVER | Less 020% | 1.00 | 28.60 | 22.88 |
| X | A01A007663 GRU | CONN PIECE | Less 020% | 1.00 | 126.00 | 100.80 |
| X | A01A021169 | (AIR) (GER) COVER(21/0 | Less 020% | 1.00 | 35.20 | 28.16 |
| X | A01A021653 | (AIR) (GER) COVER(21/0 | Less 020% | 1.00 | 13.10 | 10.48 |
| X | A191053506C | BROWMET | Less 020% | 18.00 | 2.20 | 31.68 |
| X | A01A007183 | (AIR) (GER) GUIDE(21/0 | Less 020% | 1.00 | 30.20 | 24.16 |
| X | A01A037439A | CHANNEL | Less 020% | 1.00 | 358.50 | 286.80 |
| X | A01A007671 4W3 | (AIR) (SK) GRILL(21/00 | Less 020% | 1.00 | 144.50 | 115.60 |
| X | A01A998473 | (A) (SK) LED(06/09/201 | Less 020% | 1.00 | 486.00 | 388.80 |

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119908
Main Telephone: 6886 2223
Main Telefax: 6471 3753
Page 4 17:12

Alexandra Service Centre
281 Alexandra Road
Singapore 119908
Telephone: 6886 2223
Telefax: 6471 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408663
Telephone: 6886 2223
Telefax: 6471 1033

Customer Service
Service Appointment
Labour Breakdown Service
Email: customer.care@premiumauto.com.sg
6886 2323
6828 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

| | | |
|---|---|--|
| AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120 | Invoice: 85013248
Date : 06/12/2018
Order : SLR3033Z
Term : 30 | Account: 00006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 |
|---|---|--|

Regn No.: SLR3033Z (V 34572) Regn Dates: 08/08/2017 Mileage: 10994 WIP No.: 21088
Model: Q2 1.0 TFSI S tronic GABANG Chassis: WAUZZZ66AJA001100 Engine: CHZ 397700 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (43)

| | | Details | Qty | Unit Price | Amount |
|---|----------------|--------------------------|------|------------|--------|
| X | AB1AB37477 | (A) (SK) SEAL (20/08/20) | 1.00 | 66.00 | 52.00 |
| X | AB1AB53959 4M3 | (AIR) (SK) COVER (21/08) | 1.00 | 225.50 | 180.40 |
| X | AB1AB53717 4M3 | (AIR) (SK) COVER (21/08) | 1.00 | 278.50 | 222.80 |

| | | | |
|-----------|----------|-------------|-----------|
| Parts | 9,660.56 | Sub-Total | 15,682.56 |
| Labour | 0.00 | 7% GST | 1,097.78 |
| Sublet | 6,822.00 | Grand Total | 16,780.34 |
| Menus | 0.00 | | |
| Lubricant | 0.00 | | |



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLR 3033 Z

Norah Khai
6768 9828
6841 1183

Body Repair
PA/OD/0932/2018/KS
7TH September 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q2 1.0 TFSI S TRONIC
Vehicle Chassis No. : WAUZZZGA6JA001100
Vehicle Regn No. : **SLR 3033 Z**
Vehicle Mileage : 10994 KM
Vehicle Owner : Mr. Wang Ge
Certificate No : 1700036655-01
Policy Excess : S\$ 856.00 (Inclusive GST)
Accident Date : 14th August 2018
Place : 452 Alexandra Road Carpark
Repair Cost : \$ 16,780.34
WIP No. : 21088
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 7/9/18

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7079421G




Name: WANG GE
王 柯

Race: CHINESE
Date of birth: 27-01-1970
Country of birth: CHINA

Sex: M
Size: 170.79421G

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7079421G
Name: WANG GE

Birth Date: 27 Jan 1970
Issue Date: 01 Nov 2003



00056502G

4001644



NRIC No: S7079421G



Date of issue: 09-02-2007
2 BISHAN STREET 25 #19-01
SINGAPORE 573973

NRIC No: S7079421G Date: 17/12/2011 No: 8907141

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

| Class | Motor Cars and Motor Tractors the weight of which unladen does not exceed 3500 kilograms | PASS DATE |
|---------|--|-------------|
| Class 3 | Motor Cars and Motor Tractors the weight of which unladen does not exceed 3500 kilograms | 30 Dec 1996 |

NP 428A

Licence No: S7079421G



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7079422E

Name:

CHENG RU

Birth Date: 31 Jul 1970

Issue Date: 19 Jan 2004



001891270F

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7079422E



Name:

CHENG RU

程 茹

Race:

CHINESE

Date of birth:

31-07-1970

Country of birth:

CHINA

Sex:

F

S7079422E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

30 Dec 1996



Licence No: S7079422E

NP 428A



4032225



NRIC No: S7079422E

Date of issue:

20-04-2007

2 BISHAN STREET 25 #19-01
SINGAPORE 573973

NRIC No: S7079422E

Date: 17/12/2011

No: 6907140



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : WANG GE
Period of Insurance : 08 Aug 2018 To 07 Aug 2019
Engine No. : CHZ397700
Chassis No. : WAUZZZGA6JA001100

Vehicle No. : SLR3033Z
Policy No. : 1700036655-01
Endorsement No. :
Issued Date : 20 Jun 2018

ABOUT THE COVER

Make/Model : AUDI Q2/ Q2 Sport 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

*You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 188) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

WANG GE - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63962323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125208

PREMIUM LEASING - SLOH

261 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. N. K.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSPEAM

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---|---|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 19 Aug 2018 | | 20 Aug 2018
16:20
Edit Adj Rpt | S\$16,482.56
Edit Estimates | S\$16,482.56
View Rpt | | Pending for Survey Report
Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|-----------|---|------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: WANG GE , ID: S7079421G | | | | | | | | | |
| Vehicle Reg. No.: SLR3033Z | | Date of Loss: 14/08/2018 12:00 - :59
[12 Months and 6 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: OD / 3657937869SG | | Policy/Cover Note No.: (Comprehensive) | | | | | | | |
| | | Excess: S\$800.00 | | | | | | | |
| Repairer: Premium Automobiles Pte Ltd (Benoi) 24 Benoi Sector, 629857 Pioneer - Tel: 67689911 / 63882323 | | | | | | | | | |
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Daily Amri, Mimi Zarina]
MimiZarina.DailyAmri@aig.com | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/08/2018] | | | | | | | | | |
| Driver/Custodian: CHENG RU (21 / Female), NRIC: S7079422E, Tel: +6591732450 | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG (21/08/2018): Labour AIG_SG (21/08/2018): Alert - Adj Mandate Approved (S\$17347.00) - SLR3033Z - Claim Handler: Daily Amri... | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SLR3033Z (3657937869SG)
OD
Aug 14 2018 12:30PM
[WANG GE]
Premium Automobiles Pte Ltd

| | | | | | | | | | | | | | | | | | | | | | | | |
|--------------------|-----------------|--|-----------------------------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|------------|--|--|-------------------------------------|--|--|-------------------------------------|--|--|
| Upload Documents | | | Upload Photos | | | Compose New Letter | | | Upload Video | | | Upload Audio | | | View | | | View in Browser | | | | | |
| Assessment Reports | | | | | | | | | | | | | | | 1 per page | | | ☒ | | | | | |
| No | Finalized On | | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | | | Thumbnail | | | Print | | | | | |
| 1 | 20/08/18 17:43 | | Adjuster Immediate Advice | | | | | | | | | | | | | | | Load HTM | | | | | |
| Photos/Images | | | | | | | | | | | | | | | 3 per page | | | ☒ | | | | | |
| No | Relabel/Reorder | | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | | | Thumbnail | | | Print | | | | | |
| 1 | 20/08/18 17:47 | | Odometer Reading | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 2 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 3 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 4 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 5 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 6 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 7 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 8 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 9 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 10 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 11 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 12 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 13 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 14 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 15 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 16 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 17 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 18 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 19 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 20 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 21 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 22 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 23 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 24 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 25 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 26 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 27 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 28 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 29 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 30 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 31 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 32 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 33 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 34 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |
| 35 | 20/08/18 17:47 | | General View | | | | | | | | | | | | | | | Load JPG | | | ☒ | | |

| Assessment Reports | | | 1 per page | ☒ |
|--------------------|-----------------|-----------------------------------|---|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 36 | 20/08/18 17:47 | General View |  | ☒ |
| 37 | 20/08/18 17:47 | General View |  | ☒ |
| 38 | 20/08/18 17:47 | General View |  | ☒ |
| 39 | 20/08/18 17:47 | General View |  | ☒ |
| 40 | 20/08/18 17:47 | Chassis Number |  | ☒ |
| 41 | 20/08/18 17:47 | General View |  | ☒ |
| 42 | 20/08/18 17:47 | General View |  | ☒ |
| 43 | 20/08/18 17:47 | General View |  | ☒ |
| 44 | 20/08/18 17:47 | General View |  | ☒ |
| 45 | 20/08/18 17:47 | General View |  | ☒ |
| 46 | 20/08/18 17:47 | General View |  | ☒ |
| 47 | 20/08/18 17:47 | General View |  | ☒ |
| 48 | 20/08/18 17:47 | General View |  | ☒ |
| 49 | 20/08/18 17:47 | General View |  | ☒ |
| 50 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 51 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 52 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 53 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 54 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 55 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 56 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 57 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 58 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 59 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 60 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 61 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 62 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 63 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 64 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 65 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 66 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 67 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 68 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| 69 | 26/11/18 14:29 | Dismantled Parts |  | ☒ |
| Documentation | | | 1 per page | ☒ |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 20/08/18 16:57 | INSURANCE CERT & IC DRIVING |  | |
| 2 | 20/08/18 16:57 | ESTIMATE |  | |
| 3 | 26/11/18 14:30 | ESTIMATE MARKED.pdf |  | |
| 4 | 26/11/18 14:30 | SUPPLEMENTARY.pdf |  | |
| 5 | 18/12/18 10:43 | Workshop Invoice |  | |
| 6 | 18/12/18 10:43 | Discharge Voucher |  | |
| 7 | 18/12/18 10:46 | Supplementary |  | |

Linked Accident Report Documents

| Assessment Reports | | | 1 per page | ☒ |
|--------------------|----------------|-----------------------------------|---|-------------------------------------|
| No | Finalized On | Premium Automobiles Pte Ltd (UBI) | Thumbnail | Print |
| 1 | 14/08/18 15:25 | Accident Statement |  | |

| Assessment Reports | | | 1 per page | ☒ |
|--------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | Premium Automobiles Pte Ltd (UBI) | Thumbnail | Print |
| Photos/Images | | | 3 per page | ☒ |
| No | Finalized On | Premium Automobiles Pte Ltd (UBI) | Thumbnail | Print |
| 1 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 2 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 3 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 4 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 5 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 6 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 7 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 8 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 9 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 10 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 11 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 12 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| 13 | 14/08/18 15:24 | Accident Photo |  Load JPG | ☒ |
| Documentation | | | 1 per page | ☒ |
| No | Finalized On | Premium Automobiles Pte Ltd (UBI) | Thumbnail | Print |
| 1 | 14/08/18 15:17 | Sketch Plan |  Load JPG | ☒ |
| 2 | 14/08/18 15:17 | Sketch Plan #2 |  Load JPG | ☒ |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: ☐ Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18015069/T1SD3E2

Date: 18/12/2018

REFERENCE

Insured/Claimant: WANG GE Policy No:
Date of Loss: 14/08/2018 Nature of Claim: OD Claim No: 3657937869SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR3033Z**
Make & Model: AUDI Q2, 999cc TFSI S-TRONIC (A) Engine No: CHZ397700
Reg. Date: 08/08/2017 (Man. Year: 2017) Chassis No: WAUZZZGA6JA001100
Colour: Silver Odometer: 10994 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$110,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|------------------|------------------|------------------|--------------|
| Parts | 25,890.92 | 9,660.56 | 16,230.36 | 62.69 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 26,694.00 | 6,822.00 | 19,872.00 | 74.44 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 52,584.92 | 16,482.56 | 36,102.36 | 68.66 |
| - Excess (S\$) | 800.00 | 800.00 | 0.00 | 0.00 |
| (S\$) | 51,784.92 | 15,682.56 | 36,102.36 | 69.72 |
| + GST 7.00/7.00% (S\$) | 3,624.94 | 1,097.78 | 2,527.16 | 69.72 |
| Nett Amount (S\$) | 55,409.86 | 16,780.34 | 38,629.52 | 69.72 |

INSPECTION

Date of Assignment: 20/08/2018
Date Inspected: 18/08/2018 Inspected At: Premium Automobiles Pte Ltd (Benoi)
24 Benoi Sector
Singapore 629857
Estimated Period of Repair: 13.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 1,620.00 FS | *1,295.20 FS |
| 2 | 1 | | *FRONT BUMPER FIXING PARTS | Not Necessary | 297.00 FS | *- FS |
| 3 | 1 | | *FRONT BUMPER CENTER GRILLE | Not Necessary | 172.00 FS | *- FS |
| 4 | 1 | | *FRONT BUMPER SPOILER | Cut | 259.00 FS | *207.20 FS |
| 5 | 1 | | *WHEEL SPOILER LH | Not Necessary | 30.00 FS | *- FS |
| 6 | 1 | | *FRONT BUMPER AIR GUIDE GRILLE LH | Missing | 29.00 FS | *22.88 FS |
| 7 | 2 | | *FRONT BUMPER ADAPTOR LH/RH | Necessary | 66.00 FS | *52.72 FS |
| 8 | 1 | | *GUIDE SECTION LH | Cracked | 31.00 FS | *24.16 FS |
| 9 | 1 | | *FOAM FILLER PIECE | Not Necessary | 66.00 FS | *- FS |
| 10 | 1 | | *BUMPER CARRIER | Not Necessary | 600.00 FS | *- FS |
| 11 | 1 | | *RADIATOR GRILLE | Not Necessary | 1,215.00 FS | *- FS |
| 12 | 1 | | *RADIATOR GRILLE STRIKER PLATE | Not Necessary | 108.00 FS | *- FS |
| 13 | 1 | | *FRONT BUMPER TOP COVER | Not Necessary | 86.00 FS | *- FS |
| 14 | 1 | | *CAUTION SIGN STICKER | Not Necessary | 12.00 FS | *- FS |
| 15 | 1 | | *AIR CON STICKER | Not Necessary | 7.00 FS | *- FS |
| 16 | 2 | | *WHEEL ARCH COVER LH / RH | Deformed | 558.00 FS | *445.60 FS |
| 17 | 1 | | *FRONT FENDER LH | Bent | 1,011.00 FS | *808.80 FS |
| 18 | 1 | | *FRONT FENDER ATTACHMENT PARTS | Not Necessary | 34.00 FS | *- FS |
| 19 | 1 | | *FRONT FENDER BRACKET LH | Bent | 11.00 FS | *8.80 FS |
| 20 | 1 | | *FRONT FENDER BRACKET LH | Bent | 41.00 FS | *32.72 FS |
| 21 | 1 | | *FRONT FENDER BRACKET LH | Bent | 11.00 FS | *8.80 FS |
| 22 | 1 | | *FRONT FENDER BRACE | Bent | 28.00 FS | *22.00 FS |
| 23 | 1 | | *FRONT FENDER CLOSING ELEMENT LH | Cut | 29.00 FS | *22.72 FS |
| 24 | 1 | | *FRONT FENDER INSULATION | Deformed | 66.00 FS | *52.80 FS |
| 25 | 1 | | *WHEEL HOUSING LINER LH | Deformed | 175.00 FS | *140.00 FS |
| 26 | 1 | | *WHEEL HOUSING LINER ATTACHMENT PARTS LH | Necessary | 49.00 FS | *39.04 FS |
| 27 | 1 | | *LED HEADLIGHT LH | Cracked | 4,378.00 FS | *3,502.40 FS |
| 28 | 1 | | *LED HEADLIGHT POWER MODULE | Not Necessary | 665.00 FS | *- FS |
| 29 | 1 | | *LED HEADLIGHT CONTROL UNIT | Distorted | 486.00 FS | *388.80 FS |
| 30 | 1 | | *LED HEADLIGHT HID BULB | Not Necessary | 625.00 FS | *- FS |
| 31 | 1 | | *HEADLIGHT MOUNTING LH | Cracked | 103.00 FS | *82.40 FS |
| 32 | 1 | | *LIFT CYLINDER LH | Not Necessary | 123.00 FS | *- FS |
| 33 | 1 | | *BONNET | Not Necessary | 2,378.00 FS | *- FS |
| 34 | 1 | | *BONNET ATTACHMENT PARTS | Not Necessary | 141.00 FS | *- FS |
| 35 | 2 | | *BONNET STRIKER LH/RH | Not Necessary | 192.00 FS | *- FS |
| 36 | 1 | | *BONNET IMPACT PROTECTION LH | Not Necessary | 27.00 FS | *- FS |
| 37 | 1 | | *BONNET IMPACT PROTECTION RH | Not Necessary | 27.00 FS | *- FS |
| 38 | 1 | | *BONNET IMPACT PROTECTION CENTER | Not Necessary | 26.00 FS | *- FS |
| 39 | 1 | | *BONNET LOCK WITH MICRO - SWITCH | Not Necessary | 353.00 FS | *- FS |
| 40 | 1 | | *FRONT LOCK CARRIER | Not Necessary | 854.00 FS | *- FS |
| 41 | 1 | | *HORN BRACKET LH | Not Necessary | 30.00 FS | *- FS |
| 42 | 1 | | *HORN LH | Not Necessary | 254.00 FS | *- FS |
| 43 | 1 | | *WASH WATER RESERVOIR | Not Necessary | 149.00 FS | *- FS |
| 44 | 1 | | *CONNECTING PLATE LH | Repair | 65.00 FS | *- FS |
| 45 | 1 | | *CLOSING ELEMENT LH | Repair | 26.00 FS | *- FS |
| 46 | 1 | | *SIDE MEMBER LH | Repair | 359.00 FS | *- FS |
| 47 | 1 | | *A/B-PILLAR FRAME | Repair | 1,603.00 FS | *- FS |
| 48 | 1 | | *FRONT WINDSCREEN | Not Necessary | 882.00 FS | *- FS |
| 49 | 1 | | *RAIN SENSOR FOIL | Not Necessary | 127.00 FS | *- FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|---------------|-------------|--------------|
| 50 | 1 | | *GLASS PRIMER | Not Necessary | 19.00 FS | *- FS |
| 51 | 1 | | *FRONT DOOR LH | Bent | 2,174.00 FS | *1,739.20 FS |
| 52 | 1 | | *FRONT DOOR CATCH LH | Not Necessary | 105.00 FS | *- FS |
| 53 | 1 | | *FRONT DOOR INNER SEAL LH | Necessary | 139.00 FS | *111.20 FS |
| 54 | 1 | | *FRONT DOOR ATTACHMENT PARTS LH | Not Necessary | 81.00 FS | *- FS |
| 55 | 1 | | *FRONT DOOR COVER LH | Necessary | 226.00 FS | *180.40 FS |
| 56 | 1 | | *WINDOW GUIDE | Necessary | 359.00 FS | *286.80 FS |
| 57 | 1 | | *WINDOW REGULATOR GUIDE | Not Necessary | 113.00 FS | *- FS |
| 58 | 1 | | *FRONT NO PLATE | Not Necessary | 25.00 FS | *- FS |
| 59 | 1 | | *FRONT W/SCREEN SEALANT | Not Necessary | 200.00 FS | *- FS |
| 60 | 1 | | *ACYCLIX SEALER | Not Necessary | 180.00 FS | *- FS |
| 61 | 1 | | *CAVITY WAX | Not Necessary | 140.00 FS | *- FS |
| 62 | 1 | | *STONE CHIP | Not Necessary | 180.00 FS | *- FS |
| 63 | 1 | | *METAL FILLER POWDER | Not Necessary | 280.00 FS | *- FS |
| 64 | 1 | | *SUNDRIES | Not Necessary | 1,000.00 FS | *- FS |
| 65 | 1 | | *FRONT BUMPER TRIM - LH | Cut | 10.48 FS | *10.48 FS |
| 66 | 1 | | *FRONT FENDER TRIM - LH | Deformed | 28.16 FS | *28.16 FS |
| 67 | 1 | | *SET FRONT WHEEL ARCH TRIM CLIP | Necessary | 31.68 FS | *31.68 FS |
| 68 | 1 | | *FRONT BUMPER GRILLE - LH | Missing | 115.60 FS | *115.60 FS |

F=Franchise part. S=SpcNett.

| | | |
|---------------------------|------------------|-----------------|
| Total Parts (\$\$) | 25,890.92 | 9,660.56 |
|---------------------------|------------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|------------|----------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE AND TRANSFER WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY | New | 360.00 | 360.00 |
| 2 | TO REMOVE AND RENEW, AIRCON CONDENSOR, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, TO CARRY OUT VACUUM AND REGAS | New | 1,000.00 | 0.00 |
| 3 | TO DISLODGE AND REINSTALL LHS A-PILLAR, FRONT DOOR HARNESS, MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGE | New | 780.00 | 0.00 |
| 4 | TO DISLODGE AND REINSTALL CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL | New | 3,200.00 | 280.00 |
| 5 | TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS | New | 1,800.00 | 0.00 |
| 6 | TO RENEW FRONT WINDSCREEN | New | 480.00 | 0.00 |
| 7 | TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR. CUT OUT AND REWELD LHS FENDER SUPPORT, CLOSING ELEMENT, AND LHS A-PILLAR. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER LHS FRONT FENDER, HEADLIGHT, BONNET AND LHS FRONT DOOR. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 12,250.00 | 3,000.00 |
| 8 | TO CARRY OUT WHEEL ALIGNMENT | New | 240.00 | 240.00 |
| 9 | TO CARRY OUT DIAGNOSTIC CHECK | New | 384.00 | 192.00 |
| 10 | TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FENDER TOP SUPPORT, LHS A-PILLAR, DOOR ENTRANCES, LHS SILL PANELS AND LHS FRONT DOOR. TO CARRY OUT JOINT SEALER WORK AND STONE CHIP TREATMENT | New | 6,200.00 | 2,750.00 |
| Gross Labour Cost (S\$) | | | 26,694.00 | 6,822.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >