

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

INDIA

Owner : Tan Chian Teck David

Accident Date : 14 Aug 2018

Vehicle No : FU 5006 U

Vehicle Model : Honda TA200

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fender	\$ 50.00
1	Front sport rim	\$ 350.00
1	Front rim shaft	\$ 55.00
2	Fork inner tubes	\$ 370.00
2	Fork outer tubes	\$ 210.00
1	Handle bar	\$ 75.00
1	Handle bar end	\$ 30.00
1	Side mirror	\$ 65.00
1	Clutch lever	\$ 18.00
1	Front footrest	\$ 48.00
1	Front footrest bracket	\$ 35.00
1	Gear pedal	\$ 34.00
1	Rear footrest	\$ 65.00
1	Exhaust pipe	\$ 585.00
2	Rear signals	\$ 90.00
1	Rear fender	\$ 98.00
		\$ 2,178.00
Less 10%		\$ 217.80
		\$ 1,960.20

not Adhered
2 km
n/s 600k
32y.

17/8/18
take photo after repair

382
102
343.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Special Nett Items

- | | |
|---|-----------------------|
| 1 | Number plate (1 set) |
| 2 | Fork oils |
| 2 | Fork oil seals |
| 1 | Steering cone (1 set) |
| 1 | Rear box |
| 1 | Rear box bracket |

\$	17	28.00	g
\$	17	30.00	g
\$	17	56.00	g
\$	17	75.00	X
\$	247	280.00	200
\$	2	100.00	X
\$		569.00	

S/No. **Labour**

- | | |
|---|--|
| 1 | To provide towing service. |
| 2 | To check wiring and reset headlamp focusing. |
| 3 | To provide labour. |

\$	17	45.00	X
\$	17	80.00	X
\$	220	380.00	
\$		505.00	

763.8

Grand Total

\$	3,034.20
----	----------

Dollars: Seven Thousand Five Hundred Fifty-Three And Thirty Cents Only.



EROFIA MOTOR TRADING PTE LTD