

155/2010

INS. CASE OWNER:

CC 4/AIG1801 5075, Kabb⁵²

LKK:

IDAC:

Surveyor:

Kenneth.

DOI:

ASSIGNMENT

20/8/18

Date / Time:

20/8/18

Registered in Merimen:

20/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBO 9277P

Name of Insured:

EXIM 1 MFR ENTERPRISE

Insured Tel No.:

HP:

Claim No.:

5 W 2424 57454

Policy No.:

1800071870

Make / Model:

T040TA

Excess Sec II :SS

D.O.A.:

16/8/18

Place of Accident:

MARPLESON RD OPP SPC

Is driver the owner?

(YES ☒ NO ☐)

Nature of Accident:

If NO, Driver Name / Age:

MOTAMED ASRI BIN ZAHMOL

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

% Final ? Yes / No

SMC 45452

INSRS:
WSP:
Tel:
Liability:
RMKS:Accord
AutoINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

21/8/18
TH

SMC 45452 - X

GBO 9277P - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

EMAIL 11.3.19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: WSC

Repair Cost:

PIP

SS5,850.61

(7

days) Reduction:

48 %

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 27-3-19

Confirm with CENA

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 21

If NO or B 28, Ass. Lia :

Repair Cost:

W/LA

SS6,260.15

OLD REPAIR ENDED TP.

Loss of Rental (LOR):

SS 1,000.00

(10

days) x +100

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4350

Total:

SS 7,262.15

Global Sum SS:

FINAL PAYMENT

Date/Time: 27-3-19

Confirm with: CENA

Email ☒Call ☐

Payee 1:

SS 7,262.15

Name 1:

ACCORD AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF:

AIG/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC 45452

Yr Regn:

18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS Rph

c.c 15.9d

Colour:

M. Grey

AC: Insured / Std / NI / NA

Sp. Reading

3221

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JNNY BRABI 7E 0032394

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

16/8/18

D.O.I.

20/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/8

File pass to Catherine, est not ready

PIP: +5.350.61 (RED: +5.461.68 48%)

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + R.S. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18015075/Kub3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 20-08-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 9277P	Veh. Inspected	SMC 4545Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/08/2018	Inspection Date	20/08/2018
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Notarized

ESTIMATE

ALG Asia Pacific Insurance Pte Ltd

78 Shenton Way,

ALG Building #09-16

Singapore 079120

Attn: Motor Claims Department

Repair B4 paint

Date: 20/08/2018

Vehicle No: SMC4545Z

Veh Make/Model: Nissan Sylphy 1.6 CVT

YOM: 2018

Chassis No: MNTBBAB17Z0032394

Date of Accident: 16/08/2018

No	Qty	Description	Amount S
<u>Nett Items:-</u>			
1	1	Rear bootlid <i>1163.80</i>	S <i>R1</i> 1,163.80
2	1	Rear bootlid "SYLPHY" emblem	S <i>RM</i> 88.50
3	1	Rear bootlid logo	S <i>RM</i> 46.90
4	1	Rear bootlid chrome <i>185.70</i>	S <i>CMR</i> 185.70
5	2	Rear bootlid number plate lamp	S <i>RM</i> 156.80
6	1	Rear bootlid reflector (LH)	S <i>RM</i> 141.60
7	1	Rear bootlid reflector (RH)	S <i>CMR</i> 141.60
8	1	Rear bootlid inner trim board	S <i>RM</i> 138.80
9	10	Rear bootlid inner trim board clip	S <i>RM</i> 64.00
10	2	Rear bootlid hinge	S <i>RM</i> 116.80
11	1	Rear bootlid lock	S <i>RM</i> 64.50
12	1	Rear bootlid weatherstrip	S <i>RM</i> 85.30
13	1	LH tail lamp <i>365</i>	S <i>RM</i> 365.00
14	1	RH tail lamp	S <i>RM</i> 365.00
15	1	Rear LH fender	S <i>R</i> 1,387.40
16	1	Rear LH fender splash shield	S <i>RM</i> 34.20
17	10	Rear LH fender splash shield clip	S <i>RM</i> 44.00
18	1	Rear RH fender	S <i>R</i> 1,387.40
19	1	Rear RH fender splash shield	S <i>RM</i> 34.20
20	10	Rear RH fender splash shield clip	S <i>RM</i> 44.00
21	1	Rear bumper <i>607</i>	S <i>R1</i> 607.00
22	1	Rear bumper reflector (LH)	S <i>RM</i> 55.00
23	1	Rear bumper reflector (RH)	S <i>RM</i> 55.00
24	2	Rear bumper side retainer	S <i>RM</i> 67.20
25	10	Rear bumper clip	S <i>RM</i> 4.00
26	1	Rear bumper sponge	S <i>OL</i> <i>CMR</i> 255.24
27	2	Rear bumper reinforcement bracket	S <i>OL</i> <i>R1</i> 44.60
28	1	End panel <i>428.40</i>	S <i>R1</i> 428.40
29	1	End panel top garnish	S <i>RM</i> 91.70
30	6	End panel top garnish clip	S <i>RM</i> 26.40
Total - Nett Item			S 7,745.10
Less 10%			S 774.51
Total			S 6,970.59

4009.90
3602.91

10 Ang Mo Kio Industrial Park 2A

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

AIG Asia Pacific Insurance Pte Ltd

ALG Building #09-16

Attn: Motor Claims Department

Date : 20/08/2018
Vehicle No : SMC4545Z
Vch Make/Model : Nissan Sylphy 1.6 CVT
YOM : 2018
Chassis No : MNTBBAB17Z0032394
Date of Accident : 16/08/2018

450a
200a
x
x
~~20~~
231.70

90d
80d
60d
20d
20d
5d
~~60d~~
1910

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledgement:

Acknowledged by Reparer

3608.91
331.70
1910.00

5850.61 ✓ o/c

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Notarized

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way,

AIG Building #09-16

Singapore 079120

Attn: Motor Claims Department

Repair B4 paint

6 days

Date :

20/08/2018

Vehicle No :

SMC4545Z

Veh Make/Model :

Nissan Sylphy 1.6 CVT

YOM :

2018

Chassis No :

MNTBBAB17Z0032394

Date of Accident :

16/08/2018

No	Qty	Description	Amount S
		Nett Items:-	
1	1	Rear bootlid	\$ <i>R</i> 1,163.80 ✓
2	1	Rear bootlid "SYLPHY" emblem	\$ <i>M</i> 88.50 ✓
3	1	Rear bootlid logo	\$ <i>M</i> 46.90 ✓
4	1	Rear bootlid chrome	\$ <i>CMR</i> 185.70 ✓
5	2	Rear bootlid number plate lamp	\$ 156.80 ?
6	1	Rear bootlid reflector (LH)	\$ <i>Set</i> 141.60 ✓
7	1	Rear bootlid reflector (RH)	\$ 141.60 ?
8	1	Rear bootlid inner trim board	\$ 138.80 ?
9	10	Rear bootlid inner trim board clip	\$ 64.00 ?
10	2	Rear bootlid hinge	\$ <i>R</i> 116.80 X
11	1	Rear bootlid lock	\$ <i>D.R</i> 64.50 ✓
12	1	Rear bootlid weatherstrip	\$ <i>D.R M</i> 85.30 ✓
13	1	LH tail lamp	\$ 365.00 ?
14	1	RH tail lamp	\$ 365.00 ?
15	1	Rear LH fender	\$ <i>R</i> 1,387.40 X
16	1	Rear LH fender splash shield	\$ <i>Sm</i> 34.20 X
17	10	Rear LH fender splash shield clip	\$ <i>nn</i> 44.00 X
18	1	Rear RH fender	\$ <i>R</i> 1,387.40 X
19	1	Rear RH fender splash shield	\$ <i>Sm</i> 34.20 ✓
20	10	Rear RH fender splash shield clip	\$ <i>nn</i> 44.00 X
21	1	Rear bumper	\$ <i>R</i> 607.00 ✓
22	1	Rear bumper reflector (LH)	\$ 55.00 ?
23	1	Rear bumper reflector (RH)	\$ 55.00 ?
24	2	Rear bumper side retainer	\$ <i>0.50.1</i> 67.20 ✓
25	10	Rear bumper clip	\$ <i>M</i> 4.00 ✓
26	3	Rear bumper sponge	\$ 255.30 ?
27	2	Rear bumper reinforcement bracket	\$ 99.60 ?
28	1	End panel	\$ <i>R</i> 428.40 ✓
29	1	End panel top garnish	\$ <i>D.1</i> 91.70 ✓
30	6	End panel top garnish clip	\$ <i>M</i> 26.40 ✓
Total - Nett Item			\$ 7,745.10
Less 10%			\$ 774.51
Total			\$ 6,970.59

10 Ang Mo Kio Industrial Park 2A

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

AIG Asia Pacific Insurance Pte Ltd

Singapore 079120

Date : 20/08/2018
Vehicle No : SMC4545Z
Veh Make/Model : Nissan Sylphy 1.6 CVT
YOM : 2018
Chassis No : MNTBBAB17Z0032394
Date of Accident : 16/08/2018

45m
200m
x
?
?

90d
80d
60d
20d
20d
5d
60d

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

- Pre repair inspection request - SMC4545Z VS GBD9277P (OI) DOA 16/08/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi
Sent: 20/8/2018 9:54:55 AM
Attachments:  tmp664F.TIF

Hi,

Please refer to the enclosed request from Accord Auto Services Pte Ltd.

Claim no : 5202434574SG003
Case Owner : WAN NUR SALIHA BINTE SYED YUSOFF

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: claims@mycarworkshop.com.sg [mailto:claims@mycarworkshop.com.sg]
Sent: Monday, August 20, 2018 9:49 AM
To: Mithoosingh, Aashweenjeetkaur
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi; claims@mycarworkshop.com.sg
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBD9277P AND SMC4545Z ON 16/08/2018

Hi,

We would be appointing Kenneth Kong - LKK Auto Consultants Pte Ltd to conduct PRS.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

From: Mithoosingh, Aashweenjeetkaur
Sent: Mon, 20 Aug 2018 01:40:21 +0000
To: claims@mycarworkshop.com.sg
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBD9277P AND SMC4545Z ON 16/08/2018

Without Prejudice

Your Reference : SMC4545Z
Our Reference : 5202434574SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

12.22pm @ 20/8/18
person @ Jessy
vehicle in
sure Kenneth

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ACCORD AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#03-11 AMK AUTOPOINT

SINGAPORE 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516

Email: claims@mycarworkshop.com.sg

Date: 17/08/2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
AIG Building #09-16
Singapore 079120
Att: Accident Claims Department

Fax: 6415 3727

Dear Sir/Mdm,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We have been appointed by GOH LEE KHENG PHILIP to repair his motor vehicle no. SMC4545Z.

Please provide us the LO surveyor name list and advise liability.

Please be informed that the said vehicle can be inspected at:

Accord Auto Services Pte Ltd
10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint
Singapore 568047

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, we will commence repairs thereafter without further reference to you.

Yours faithfully,



Jessy See 17 AUG 2018

NB: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 6271 5133/6271 7433 FAX: 6274 5715
GST Regn No: 201113141K

22 February 2019

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING VEHICLE: SMC4545Z and GBD9277P on 16.8.2018 Along Macpherson Road.

We are the authorized repair workshop for the owner of motor vehicle no: **SMC4545Z** which was involved in the captioned accident with your insured vehicle: **GBD9277P**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01) Cost Of Repair	\$	5,850.61
02) 7% GST	\$	409.54
03) Loss Of Rental 14 days @ \$180 (*Including 2 non working days on 19.8.2018, 22.8.2018 & 26.8.2018 and 2 days Pre-repair)	\$	2,520.00
04) GIA/LTA Search Fee	\$	2.00
		<u>8,782.15</u>

We enclosed herewith the following documents to support the claims:-

- | | |
|-----------------------------------|-------------------------|
| a) GIA Report | d) Letter Of Authority |
| b) Repair Statement AMK503 | e) GIA/LTA Search Fee |
| c) Insured NRIC & Driving Licence | f) Rental Car Agreement |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours faithfully

ACCORD
AUTO SERVICES PTE LTD

Celia Lai
Accord Auto Services Pte Ltd
Tel: 6271 7433 / 9274 0999
email: avclaims@mycarworkshop.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Aug 2018 Edit Reg		20 Aug 2018 00:00 Edit Adj Rpt	S\$5,850.61 Edit Estimates	S\$5,850.61 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	EXIM & MFR ENTERPRISE , Co. Reg. No.: 28993500L		
Main Claimant:	GOH LEE KHENG PHILIP , ID: S0150350B		
Vehicle Reg. No.:	SMC4545Z	Date of Loss:	16/08/2018 17:00 - :59 [1 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5202434574SG	Policy/Cover Note No.:	1800071890 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD9277P	Policy No. (Claimant):	1800077955
		Excess:	
Repairer:	Accord Auto Services Pte Ltd (Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-80, 159723 Bukit Merah - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/08/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SMC4545Z (5202434574SG)**
[GBD9277P]

TP
GOH LEE KHENG PHILIP
Aug 16 2018 5:00PM
[EXIM & MFR ENTERPRISE]
Accord Auto Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Letters/Correspondences										1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown							1	Edit			
										3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print		
1	11/03/19 15:58	General View							1	Load JPG	☒		
2	11/03/19 15:58	General View							1	Load JPG	☒		
3	11/03/19 15:58	General View							1	Load JPG	☒		
4	11/03/19 15:58	General View							1	Load JPG	☒		
5	11/03/19 15:58	General View							1	Load JPG	☒		
6	11/03/19 15:58	General View							1	Load JPG	☒		
7	11/03/19 15:58	General View							1	Load JPG	☒		
8	11/03/19 15:58	General View							1	Load JPG	☒		
9	11/03/19 15:58	General View							1	Load JPG	☒		
10	11/03/19 15:58	General View							1	Load JPG	☒		
11	11/03/19 15:58	General View							1	Load JPG	☒		
12	11/03/19 15:58	General View							1	Load JPG	☒		
13	11/03/19 15:58	General View							1	Load JPG	☒		
14	11/03/19 15:58	General View							1	Load JPG	☒		
15	11/03/19 15:58	General View							1	Load JPG	☒		
16	11/03/19 15:58	General View							1	Load JPG	☒		
17	11/03/19 15:58	General View							1	Load JPG	☒		
18	11/03/19 15:58	General View							1	Load JPG	☒		
19	11/03/19 15:58	General View							1	Load JPG	☒		
20	11/03/19 15:58	General View							1	Load JPG	☒		
21	11/03/19 15:58	General View							1	Load JPG	☒		
22	11/03/19 15:58	General View							1	Load JPG	☒		
23	11/03/19 15:58	General View							1	Load JPG	☒		
24	11/03/19 15:58	General View							1	Load JPG	☒		
25	11/03/19 15:58	Reinspection Photo							1	Load JPG	☒		
26	11/03/19 15:58	Reinspection Photo							1	Load JPG	☒		
27	11/03/19 15:58	Reinspection Photo							1	Load JPG	☒		
28	11/03/19 15:58	Reinspection Photo							1	Load JPG	☒		
29	11/03/19 15:58	Reinspection Photo							1	Load JPG	☒		
30	11/03/19 15:58	Reinspection Photo							1	Load JPG	☒		
31	11/03/19 15:58	Reinspection Photo							1	Load JPG	☒		
32	11/03/19 15:58	Reinspection Photo							1	Load JPG	☒		

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
34	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
35	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
36	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
37	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
38	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
39	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
40	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
41	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
42	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
43	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
44	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
45	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
46	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
47	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
48	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
49	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
50	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
51	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
52	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
53	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
54	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
55	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
56	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
57	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
58	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
59	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
60	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
61	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
62	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
63	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
64	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
65	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
66	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
67	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
68	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
69	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
70	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
71	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
72	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
73	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
74	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
75	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
76	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
77	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
78	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
79	11/03/19 15:58	Reinspection Photo	 Load JPG	☒
80	11/03/19 15:58	Reinspection Photo	Load JPG	☒

Documents Checklist

Reset Save Print

There are no document checklists configured.

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBD9277P (Insd veh)	Model:	NISSAN SYLPHY 1.6 (A)
	SMC4545Z (TP veh)		
Date of Accident:	16/08/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		12,138.82
Final Repair Cost	:	\$		6,260.15
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		1,000.00 10 days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		
	:	\$		
Final Settlement Sum	:	\$		7,262.15

Is Third Party Workshop GIA Registered?	[] YES	[X] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:	Agreed Liability ____ 100 ____ (%)		
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Accord Auto Services Pte Ltd	: \$	7,262.15
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

02 May
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18015075/KEB3S2
Date: 02/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800071890
Claimant Vehicle No: SMC4545Z Insured Vehicle No: GBD9277P
Date of Loss: 16/08/2018 Nature of Claim: TP Claim No: 5202434574SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC4545Z Engine No: HR16928555C
Make & Model: NISSAN SYLPHY, 1.6 (A) Chassis No: MNTBBAB17Z0032394
Reg. Date: 30/06/2018 (Man. Year: 2018) Odometer: 3221 km
Colour: Metallic Grey
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R16 Rear Tyre Size: 195/60R16
Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9 mm
Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,234.69	3,940.61	4,294.08	52.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	1,910.00	1,200.00	38.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,344.69	5,850.61	5,494.08	48.43
+ GST 7.00/7.00% (S\$)	794.13	409.54	384.59	48.43
Nett Amount (S\$)	12,138.82	6,260.15	5,878.67	48.43
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,262.15		

INSPECTION

Date of Assignment: 20/08/2018
Date Inspected: 20/08/2018 Inspected At: Accord Auto Services Pte Ltd (Bukit Merah)
BLK 1009 BUKIT MERAH LANE 3, #01-80
Singapore 159723
Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOTLID	Bent	1,163.80 FN	*1,163.80 FN
2	1	*REAR BOOTLID SYLPHY EMBLEM	Necessary	88.50 FN	*88.50 FN
3	1	*REAR BOOTLID LOGO	Necessary	46.90 FN	*46.90 FN
4	1	*REAR BOOTLID CHROME	Cracked	185.70 FN	*185.70 FN
5	2	*REAR BOOTLID NUMBER PLATE LAMP	Serviceable	156.80 FN	*- FN
6	1	*REAR BOOTLID REFLECTOR (LH)	Scratched	141.60 FN	*141.60 FN
7	1	*REAR BOOTLID REFLECTOR (RH)	Cracked	141.60 FN	*141.60 FN
8	1	*REAR BOOTLID INNER TRIM BOARD	Serviceable	138.80 FN	*- FN
9	10	*REAR BOOTLID INNER TRIM BOARD CLIP	Not Necessary	64.00 FN	*- FN
10	2	*REAR BOOTLID HINGE	Repair	116.80 FN	*- FN
11	1	*REAR BOOTLID LOCK	Distorted	64.50 FN	*64.50 FN
12	1	*REAR BOOTLID WEATHERSTRIP	Distorted / Dented	85.30 FN	*85.30 FN
13	1	*LH TAILLAMP	Mtg Cracked	365.00 FN	*365.00 FN
14	1	*RH TAILLAMP	Mtg Cracked	365.00 FN	*365.00 FN
15	1	*REAR LH FENDER	Repair	1,387.40 FN	*- FN
16	1	*REAR LH FENDER SPLASH SHIELD	Serviceable	34.20 FN	*- FN
17	10	*REAR LH FENDER SPLASH SHIELD CLIP	Not Necessary	44.00 FN	*- FN
18	1	*REAR RH FENDER	Repair	1,387.40 FN	*- FN
19	1	*REAR RH FENDER SPLASH SHIELD	Serviceable	34.20 FN	*- FN
20	10	*REAR RH FENDER SPLASH SHIELD CLIP	Not Necessary	44.00 FN	*- FN
21	1	*REAR BUMPER	Bent	607.00 FN	*607.00 FN
22	1	*REAR BUMPER REFLECTOR (LH)	Serviceable	55.00 FN	*- FN
23	1	*REAR BUMPER REFLECTOR (RH)	Serviceable	55.00 FN	*- FN
24	1	*REAR BUMPER SIDE RETAINER	O/s Distorted	67.20 FN	*33.60 FN
25	10	*REAR BUMPER CLIP	Necessary	40.00 FN	*40.00 FN
26	1	*REAR BUMPER SPONGE	O/s Cracked	255.30 FN	*85.10 FN
27	1	*REAR BUMPER REINFORCEMENT BRACKET	O/s Bent	99.60 FN	*49.80 FN
28	1	*END PANEL	Bent	428.40 FN	*428.40 FN
29	1	*END PANEL TOP GARNISH	Distorted	91.70 FN	*91.70 FN
30	6	*END PANEL TOP GARNISH CLIP	Necessary	26.40 FN	*26.40 FN
31	1	*REAR NUMBER PLATE WITH HOLDER	Dented	55.00 FS	*45.00 FS
32	1	*SET REAR REVERSE SENSOR	Dented / Shorted	380.00 FS	*200.00 FS
33	1	*REAR BOOTLID COMPARTMENT WATERPROOF SEALANT	Not Necessary	150.00 FS	*- FS
34	1	*REAR BUMPER LOW SPOILER	Serviceable	560.00 FS	*- FS
35	1	*ANTENNA ASSY	Cracked	86.70 FS	*86.70 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	9,012.80	4,341.60
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	778.11	400.99
Total Parts (\$\$)	8,234.69	3,940.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON ALL AFFECTED AREA.	New	1,200.00	900.00
2	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.	New	1,400.00	800.00
3	TO APPLY ANTI RUST TREATMENT.	New	150.00	60.00
4	TO CHECK WIRING SYSTEM & LIGHT.	New	80.00	20.00
5	TO CHECK AND TEST REAR BOOTLID WATER LEAKING.	New	60.00	20.00
6	TO REMOVE AND REPLACE REVERSE SENSOR.	New	120.00	50.00
7	TO REMOVE AND REPLACE REINSTALL INTERIOR UPHOLSETRY.	New	100.00	60.00
Gross Labour Cost (S\$)			3,110.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >