



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZ1007 / INDIA INTERNATIONAL
Chassis No: MRHFC1660GT000131
License No: SLG8283T
Mileage: 33012
Engine No: L15B71624957

Document No: SVO18051543
Printed By: ARYCHUA
Order Date: 4. September 2018
Order Time: 8:21:33 AM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 71165) OWNER: LAU LENG CHAI OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 13/08/2018@08.55AM SURVEYED BY: ADRIAN LING (LKKAUTO)16.16PM REF NO: TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH: SHC1412C (HYUNDAI/I40/BLUE TAXI)							
54600	ACE GT - RECOAT REAR BUMPER only	1	230.00		230.00	16.10	246.10	
	SUM EXCESS:				230.00	16.10	246.10	
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47	
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30	
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.60	25	5.70	0.40	6.10	
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22	
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22	
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	25	28.65	2.01	30.66	
	SUM PARTS:				535.49	37.48	572.97	
BOSUN	0672 SUNDRIES	1	20.00		20.00	1.40	21.40	
BA02R	EXT-YJ REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	140.00		140.00	9.80	149.80	
BP02R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)	1	450.00		450.00	31.50	481.50	
BKRP02S	EXT-YJ STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	560.00		560.00	39.20	599.20	
	SUM LABOUR:				1,170.00	81.90	1,251.90	
	TOTAL SGD				1,935.49	135.48	2,070.97	
	Total Payable (SGD)						2,070.97	

GST Amount is calculated from individual line(s)



INVOICE

BILL TO :

Name : Francis Lau
Contact Number : 9187 8252
Vehicle Make/Model/Colour : Honda civic grey
Vehicle Registration Number : SLG 8283 T

DATE : 28/09/2018

INVOICE : 1809043

Payment Mode : nets

DESCRIPTION	UNIT	QTY	AMOUNT (\$)
MS REAR Bumper GOLD	230.00	1.00	230.00

Total \$ 230.00

Balance Due : \$ 230.00

Warranty number TR220163906

Notes for new application / Re-application / Rejuvenate

Keep the surface dry. Dab the surface dry with a lightly damp Microfiber towel. Wash with quality shampoo and dry with clean chamois/Microfiber towel. Remove any contaminants promptly with proper method. Maintain the Nano-fiairs by applying Ceramic Pro SPORT once every 3 month or surface is losing its hydrophobic. Contact us immediately to avoid unnecessary cost for re-application if there are contaminants that cannot be cleaned off with shampoo. Do not use Shampoo for the Next 3 days. Apply a Layer of Ceramic PRO SPORT after the 3rd day of treatment.

9 Yishun Industrial Street 1 #01-69/70 North Spring Bizhub Singapore 768163