

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLG8283T

Chassis No : MRHFC1660GT000131

Model : CIVIC 1.5 TURBO VTIS YM2016

Owner's Name : LAU LENG CHAI

Ins Policy No. : SD16V13853/VPC2/R00

Date of Accident : 13/8/2018

Document No. : SQT18003430 Page 1

Date : 17. Aug 2018

Customer No. : WZ1007

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15B71624957

Date | Time : 17. Aug 2018 8:21:33 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71165)						
	OWNER: LAU LENG CHAI						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 13/08/2018@08.55AM						
	SURVEYED BY: (LKKAUTO)10.30AM						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH: SHC1412C (HYUNDAI/I40/BLUE TAXI)						
54600	ACE GT - RECOAT REAR BUMPER	1	643.74		643.74	45.06	688.80
			Sum G/L Account		<u>643.74</u>	<u>45.06</u>	<u>688.80</u>
91505-TM8-003	CLIPBUMPER <i>Mer</i>	14	2.00	25	✓ 21.00	1.47	22.47
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>del</i>	1	617.20	25	✓ 462.90	32.40	495.30
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER ?	1	173.00	25	? 129.75	9.08	138.83
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE <i>del</i>	1	7.60	25	✓ 5.70	0.40	6.10
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>Mer</i>	1	11.50	25	✓ 8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE <i>Mer</i>	1	11.50	25	✓ 8.62	0.60	9.22
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE <i>Mer</i>	1	2.20	25	X 1.65	0.12	1.77
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE <i>Mer</i>	1	2.20	25	X 1.65	0.12	1.77
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER <i>del</i>	1	38.20	25	✓ 28.65	2.01	30.66
33500-TEA-T01	TAILLIGHT ASSYR. <i>Mer</i>	1	253.80	25	X 190.35	13.32	203.67
33550-TEA-T01	TAILLIGHT ASSYL. <i>Mer</i>	1	273.10	25	X 204.82	14.34	219.16
33550-TEA-T01	TAILLIGHT ASSYL. <i>Mer</i>	1	273.10	25	X 204.82	14.34	219.16
			Sum Item		<u>1268.53</u>	<u>88.80</u>	<u>1,357.33</u>
BOSUN	SUNDRIES	1	40.00		40.00 20	2.80	42.80
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00		140.00 X	9.80	149.80
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	160.00		160.00 140.	11.20	171.20

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SLG8283T
Chassis No : MRHFC1660GT000131
Model : CIVIC 1.5 TURBO VTIS YM2016
Owner's Name : LAU LENG CHAI
Ins Policy No. : SD16V13853/PC2/R00
Date of Accident : 13/8/2018

Document No. : SQT18003430 Page 2
Date : 17. Aug 2018
Customer No. : WZI007
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B71624957
Date | Time : 17. Aug 2018 8:21:33 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	900.00	450	900.00	63.00	963.00
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1680.00	560	1680.00	117.60	1797.60
Sum Labor					<u>2920.00</u>	<u>204.40</u>	<u>3,124.40</u>

Survey By

Date & Time

Excess

Status

Signature

Adrian Wj
04/09/18.
Not Authorised
SLG.

03 Days.

Total Amount 4,832.27 338.26 5,170.53

Total (Inclusive of GST) 5,170.53

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 3/9/2018 12:09:50 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)