



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJU3488C

Mr Lee Chee Khen

121 Meyer Road
#06-10
Singapore 437932

Mobile: 98193123

Vehicle & Document Information

WIP No **26195**
Reg No/Reg Date **SJU3488C / 19/10/2009**
Date In/Mileage **/ 0**
Chassis No **WDD2120472A077594**
Engine No **27186030003501**
Make/Model **MB/E 250 CGI SEDAN (W212)**
Colour/Trim **027 775 Iridium sil/ 042 201 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	16/08/2018/ 20:05		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request				
M BPNSUN POLICY NO/ACC DATE : 2100169353 // 15/08/2018 DRIVE IN/EXCESS : 16/08/2018 // TP VEH NO SGF2381Y AXA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				960 1200.00
A BPIRES RESPRAY FRONT BUMPER, BONNET, RIGHT FRONT FENDER, RIGHT 'A' PILLAR AND RIGHT WING MIRROR.				2400 3000.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	380.00
A BPILAB TO CHECK LIGHTINGS AND WIRINGS				120.00
M RIGHT WING MIRROR UNDER COVER	1.00	108.91	00.00	108.91
M RIGHT WING MIRROR HOUSING	1.00	356.98	00.00	356.98

ESTIMATE

Rasul
Hp 90010068
6 days
11/09/18 @ 1600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by
Acknowledged by Repairer
Signature:
Date:

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

7% GST on **5165.89** **Nett 5,165.89**
361.61
Total Payable 5,527.50

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg