



Feida Bus Consortium Pte Ltd

06 Sungei Kadut Way Singapore 728786

Tel: 6655 6665 Fax: 6655 6659

Date of Estimate: 22.08.2018
 Vehicle No: CB8803B
 Owner: GOH TRANSPORT SERVICES CO. PTE LTD
 Date of Accident: 14.08.2018
 Make & Model: YOTONG ZK6107H AUTO 45 SEATER
 Chassis No : E1024349

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

ESTIMATE FOR ACCIDENT VEHICLE NOS CB8803B

LABOUR

1	Panel beating for replace and repair affected parts	\$3,200.00	2,000
2	Spraypainting on affected area	\$1,600.00	1,400
3	Wiring charges & testing commissioning	\$200.00	160
4	Apply putty and anti-corrosion to affected parts	\$600.00	300
SUB TOTAL (LABOUR)		\$5,600.00	

PARTS

1	1 Rear engine hood (repair)	\$0.00	
2	1 Rear bumper	\$2,780.00	BD
3	1 Rear bumper bracket	\$480.00	?
4	1 Rear tail lamp panel R/H	\$3,650.00	BD
5	1 Rear tail lamp R/H	\$780.00	?
6	1 Rear tail lamp panel reflector	\$312.00	?
7	1 Rear engine support panel	\$2,800.00	?
SUB TOTAL		\$10,802.00	
LESS 5 %		\$540.10	
DISCOUNTED SUB TOTAL		\$10,261.90	

S. NETT ITEM

1	1 Logo for rear hood	\$480.00	X m
---	----------------------	----------	-----

NA2 LKK
 30/8/18 1245
 L/S
 6 Days
 67418434

SUB TOTAL	\$480.00
LESS 0 %	\$0.00
DISCOUNTED SUB TOTAL	\$480.00
S.NET ITEM	\$480.00
SUB TOTAL (PARTS)	\$10,261.90
SUB TOTAL (LABOUR)	\$5,600.00
ESTIMATED GRAND TOTAL	\$15,861.90

Na2@lkkauto.com

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE OF REPAIRS, WE WOULD INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

APPROVING OFFICER SIGNATURE & COMPANY'S CHOP