

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0936/2018/CCS
Date : 15-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.
Your insured vehicle no: SHD 9369 L

AXA Insurance Singapore Pte Ltd

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Dept
Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Lim Ek Chow
Address : 27 Yio Chu Kang Road
#05-07
Singapore 545542
Telephone : HP +65 97623538
Type of Claim : Third Party Claims
Policy No. : 1800024297
Vehicle No : **SKM 2899 L**
Model Code : Audi Q2 1.0 TFSI
Model / Year : Mar-18
Engine No : CHZ 553766
Chassis No : WAUZZZGA9JA030672
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Aug-18
Place of Accident : Junction of Tampines Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKM 2899 L.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	/
2	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,450.00	600
3	To respray front bumper and bonnet.	\$ 1,700.00	1200
TOTAL LABOUR CHARGES - FRONT		: \$ 4,510.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKM 2899 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>X repair</i>	\$ 1,619.00	
2	FRONT BUMPER FIXING PARTS <i>X nn</i>	\$ 297.00	
3	FRONT BUMPER GRILLE - LOWER CTR <i>scr ?</i>	\$ 172.00	
4	FRONT BUMPER GRILLE - RH <i>scr</i>	\$ 145.00	
5	FRONT BUMPER GRILLE END CAP - RH <i>scr</i>	\$ 29.00	
6	FRONT BUMPER SPOILER <i>scr</i>	\$ 259.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER <i>?</i>	\$ 134.00	
8	FRONT WHEEL SPOILER - RH <i>?</i>	\$ 30.00	
9	FRONT BUMPER ADAPTER - LH/RH <i>X nn</i>	2 \$ 72.00	
10	RADIATOR GRILLE <i>scr</i>	\$ 1,215.00	
11	RADIATOR GRILLE STRIKER PLATE <i>?</i>	\$ 108.00	
12	FRONT BUMPER FOAM <i>?</i>	\$ 66.00	
13	FRONT REINFORCEMENT BEAM <i>?</i>	\$ 600.00	
14	FRONT REINFORCEMENT BEAM BOLT SET <i>?</i>	\$ 31.00	
15	FRONT BUMPER GUIDE - LH/RH <i>X</i>	2 \$ 62.00	
16	BONNET <i>X repair</i>	\$ 2,378.00	
17	BONNET ATTACHMENT PARTS <i>X</i>	\$ 141.00	
18	BONNET IMPACT PROTECTION - CENTER <i>X</i>	\$ 26.00	<i>nn</i>
19	BONNET IMPACT PROTECTION - LH/RH <i>X</i>	2 \$ 54.00	
20	BONNET BUNGS <i>X</i>	2 \$ 36.00	
SUB-TOTAL PARTS CHARGES - FRONT		\$ 7,474.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKM 2899 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	BONNET STOP BUFFER <i>X NN.</i>	2 \$	9.00
22	HEADLIGHT MOUNTING - RH <i>?</i>	\$	103.00
23	LED HEADLIGHT - RH <i>?</i>	\$	4,378.00
24	HEADLIGHT WASHER CYLINDER - RH <i>X NN</i>	\$	123.00
25	FRONT WHEEL ARCH TRIM - LH/RH <i>1 Spec.</i>	2 \$	557.00
26	WHEEL ARCH TRIM CLIP SET <i>1</i>	\$	45.00
27	FRONT NO. PLATE <i>1 BT</i>	S/N \$	25.00
TOTAL PARTS CHARGES - FRONT		:	\$ 12,714.00
TOTAL LABOUR CHARGES - FRONT		:	\$ 4,510.00
GRAND TOTAL PARTS AND LABOUR - FRONT		:	\$ 17,224.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKM 2899 L.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	/
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00	/
3	To dismantle and renew rear bumper and rear lid. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,100.00	1200
4	To respray rear bumper and rear lid.	\$ 1,700.00	1300
5	To renew rear windscreen.	S/N \$ 480.00	/
6	To remove and renew rear exhaust silencer. Align to position.	S/N \$ 480.00	?
7	To re-apply rear windscreen solar film.	S/N \$ 400.00	/
8	To carry out diagnostic check.	S/N \$ 384.00	/
TOTAL LABOUR CHARGES - REAR		: \$ 6,304.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKM 2899 L.

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER / u	\$ 1,016.00	
2	REAR BUMPER FIXING PARTS ?	\$ 66.00	
3	REAR BUMPER SPOILER / hot	\$ 247.00	
4	REAR BUMPER TOW EYE COVER X	\$ 20.00	
5	REAR BUMPER LIGHT REFLECTOR - LH/RH X {nn	2 \$ 52.00	
6	REAR REINFORCEMENT BEAM ?	\$ 480.00	
7	REAR BUMPER HOLDING STRAP - LH/RH / MBL	2 \$ 22.00	
8	REAR BUMPER GUIDE - LH/RH X nn	2 \$ 92.00	
9	REAR PARKING AID SENSOR - OUTER X	2 \$ 211.00	
10	REAR PARKING AID SENSOR - INNER X {nn	2 \$ 211.00	
11	REAR PARKIND AID SEAL / MBL	\$ 14.00	
12	REAR LID / RT	\$ 2,106.00	
13	REAR LID ATTACHMENT PARTS / MBL	\$ 103.00	
14	REAR LID SEAL / MBL	\$ 101.00	
15	REAR LID LOCK X	\$ 188.00	
16	REAR LID LOCK COVER X {nn	\$ 10.00	
17	REAR LID PUSH BUTTON X	\$ 159.00	
18	REAR LID LICENCE PLATE TRIM / Scar	\$ 204.00	
19	REAR LID AUDI LOGO / {MBL	\$ 108.00	
20	REAR LID ' Q2 ' INSCRIPTION /	\$ 83.00	
SUB-TOTAL PARTS CHARGES - REAR		\$ 5,493.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKM 2899 L.

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	REAR LID ' TFSI ' INSCRIPTION /	\$ 83.00	
22	REAR WINDSCREEN /	\$ 679.00	
23	GLASS PRIMER /	\$ 37.00	
24	REAR WHEEL ARCH TRIM - LH/RH /	2 \$ 298.00	
25	WHEEL ARCH TRIM CLIP SET /	\$ 30.00	
26	REAR LID SPOILER FIXING PARTS ?	\$ 117.00	
27	REAR SILENCER ?	\$ 633.00	
28	REAR SILENCER DUAL CLIP ?	\$ 53.00	
29	REAR SILENCER RETAINER ?	2 \$ 72.00	
30	REAR WINDSCREEN SEALANT / MC	S/N \$ 200.00	
31	REAR NO. PLATE X NN.	S/N \$ 25.00	
32	SUNDRIES ?	\$ 300.00	
TOTAL PARTS CHARGES - REAR		: \$ 8,020.00	
TOTAL LABOUR CHARGES - REAR		: \$ 6,304.00	
GRAND TOTAL PARTS AND LABOUR - REAR		: \$ 14,324.00	
GRAND TOTAL - FRONT & REAR		: \$ 31,548.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Gano Corp.*
Surveyed Date : *21/8/18*
Authorised Date :
Excess Cost : *refe print photos.*
Liability :
Remarks : *8 Days.*

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant