

Tamper

REJ

AXA

AXA

OE 2021 July
2006 July

Form
Estimated Cost
ID / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No.
At Workshop only
at
Insured
Policy No.
Claims No.
Gum Insured
Excess
(Client's Record)
Make of Veh.

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$28K.
IDAC Accident Report: Consistent? Yes or No
GIA / PR Seen: Consistent? Yes or No
Est. Repairs: 5 days Res: Yes or No
Lump Sum: 20 % 3 Val: Yes or No
CA / REV / REP. / 24 HRS WP

Date: Person Contacted

Vehicle: IN / OUT

Date / Time Action / Instruction

Vehicle No. SMA 8821K
Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or

Make: Honda Integra cc 1998
Colour: Red A/C: Insured / Std / Nil / NA
Sp. Reading: 197361 TP/Date: Insured / Std / Nil / NA

Engin: JHMD1545065201094
C/Nr:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / ☒ Rrim / ☐ STD A/Rim or

Tyre Size: F: 225/45K12
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / ☒ YOKO or

Front: 6 mm Rear: 6 mm
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A: 19/8/18 @ 1455

Survey held at: 27A Jang Port Rd #01-27

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S
The UIC / Chassis frame / Body Structure affected due to collision.

456.16

Date/Time: File Photo: ☐ Prel. Report
☐ Final Report

Date/Time: File Report: ☐

at

Report Format:

Lump Sum / LB / ☐

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transport:

Add Fee: ☐ Site Trip: \$

☐ Interview: \$

☐ Test Drive: \$

☐ Wheel Lock: \$

1 - 3 - 5 - 7

1 Hour

1 Day

TOTAL

L/S: 42,60.00 (Ref: 42,208.16 / 50.67 %)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18015087/T1fb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 20-08-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SCL 8969D	Veh. Inspected	SMA 8821K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/08/2018
2. Vehicle Particulars & Condition			
Make & Model		Color	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Crash	
Odometer	-	Stolen	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Pressure	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/08/2018	Report Date	17/08/2018
Survey held at	HUP HUP WORKSHOP PTE LTD 27-A JURONG PORT ROAD #01-29 SINGAPORE 619101		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

QUOTATION

合合車廠私人有限公司

HUP HUP WORKSHOP PTE. LTD.

27-A, JURONG PORT ROAD, #01-29, SINGAPORE 619101

TEL: 6265 5270, 6261 3407, 6265 1966 FAX: 6261 8456

Business Regn. / GST Regn. No. 19-8004325-G

Date: 15/08/2018

M/s AXA INSURANCE PTE LTD

VEHICLE NO. SMA 8821K

MAKE Honda Integra

Our Ref: HHW/TP 2395/2018

Your Ref:

- | | |
|------|------------------------------|
| 1 pc | Tail lamp LH |
| 1 pc | Tail lamp bracket lower LH |
| 1 pc | End panel |
| 1 pc | Rear bumper |
| 1 pc | Rear bumper side retainer LH |

CR 440.60
 NR 48.00
 RS 453.70
 DE 718.70

RE 36.70

1697.70

339.54

1358.16 NW

7 200.00 SN

- | | |
|-------|-------------------------|
| 1 set | Reverse sensor & fixing |
|-------|-------------------------|

Labour charge to cut, weld, replace rear end panel; repair, straighten rear LH fender, rear LH fender inner panel, tail lamp panel and dismantle, align, adjust and replace parts.

500 2000
 1000.00

Spray paint on rear end panel - inside/outside, rear LH fender, tail lamp panel, rear bumper, reverse sensor.

500 2000
 1000.00

3558.16

Spiker ?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]

office - 62563561
 Tanjil 97495747
 ur

17/8/18 R 1455

Resurvey after repair

05 days

sur@lkkauto.com

N.B.: Estimate does not include 7% GST

QUOTATION

合合車廠私人有限公司 HUP HUP WORKSHOP PTE. LTD.

27-A, JURONG PORT ROAD, #01-29, SINGAPORE 619101

TEL: 6265 5270, 6261 3407, 6265 1966 FAX: 6261 8456

Business Regn. / GST Regn. No. 19-8004325-G

Date: 27/08/2018

M/s AXA INSURANCE PTE LTD

VEHICLE NO. SMA 8821K

MAKE Honda Integra

Our Ref: HHW/TP 2395/2018


Your Ref:

SUPPLEMENTARY

Supply and affix sticker wrap on rear bumper and rear LH fender (from front LH windscreen glass to the end of rear LH fender).

500.
800.00

合合車廠私人有限公司
HUP HUP WORKSHOP PTE. LTD.



Authorized Signatory

N.B.: Estimate does not include 7% GST

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7472E
Vehicle Details	
Vehicle No.:	SMA8821K
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	INTEGRA 2.0A
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	K20A35800792
Chassis No.:	JHMDC54506S201094
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$21,887.00
Original Registration Date:	21 Jul 2006
First Registration Date:	21 Jul 2006
Transfer Count:	4
Actual ARF Paid:	\$24,076.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jul 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$25,815.00
COE Rebate Amount:	\$13,658.00
Total Rebate Amount:	\$13,658.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Nov 2018

OK

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Wednesday, 9 January 2019 6:14 PM
To: 'HUPHUP WORKSHOP'
Subject: RE: VEHICLE NO: SMA 8821K HONDA INTEGRA (TP CLAIM)
Attachments: DV SMA 8821K.pdf

Importance: High

Without Prejudice

LKK Ref: CC4/ASM18015087/T1fB3
Your Ref: SMA 8821K(DOA: 08/08/2018)

Dear Ms Wong,

We refer to the above matter

We confirmed settlement as below:

1. Cost of Repair (w/GST)	S\$ 2,300.50
2. Loss of Use (\$80.00 x 7 days)	S\$ 560.00
3. LTA search fee	S\$ 7.49
	<u>S\$ 2,867.99</u>

Please duly sign the DV attached and return for payment processing.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

From: HUPHUP WORKSHOP <hupwshop@hotmail.com>
Sent: Wednesday, 9 January 2019 5:52 PM
To: Poh Kin (LKKAuto)
Subject: RE: VEHICLE NO: SMA 8821K HONDA INTEGRA (TP CLAIM)
Attachments: SKM_224e19010918070.pdf

Categories: clear

Hi Poh Kin,

Please see attachment of LOD, REPAIR BILL, LETTER OF AUTHORISATION TO ACT & SEARCH FEE.

We await for your Discharge Voucher.

Thanks & Best regards
Wong (Ms)
Hup Hup Workshop
Tel: 6265 1966



Virus-free. www.avg.com

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Thursday, 6 December 2018 11:55 AM
To: 'HUPHUP WORKSHOP'; Taufikh (LKKAUTO)
Subject: RE: VEHICLE NO: SMA 8821K HONDA INTEGRA

Importance: High

Without Prejudice

LKK Ref: CC4/ASM18015087/T1fB3
Your Ref: SMA 8821K(DOA: 08/08/2018)

Dear Ms Wong,

We refer to the above matter and our tele conversation.

As spoken, We had confirmed COR at **L/S \$2,150.00 with 5 repair days.**

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act) to us (LKK) for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: HUPHUP WORKSHOP [mailto:hupwshop@hotmail.com]
Sent: Monday, 12 November 2018 10:26 AM
To: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Subject: RE: VEHICLE NO: SMA 8821K HONDA INTEGRA

Poh Kin (LKKAuto)

From: Poh Yueh Loong <loong72188@gmail.com>
Sent: Monday, 27 August 2018 7:01 PM
To: Poh Kin (LKKAuto)
Cc: hupwshop@hotmail.com; jooguanseng@yahoo.com.sg
Subject: Fwd: Fw: ROAD TRAFFIC ACCIDENT INVOLVING SCL 8969D AND SMA 8821K ON 08.08.2018

Categories: clear

Dear Mr Chong,

I was the driver of the car (SMA8821K) on the day the accident occurred on 08.08.2018 at about 0700hrs. I would like to inform that the accident report made by the opposite party (SCL8969D) was untrue as neither did I swerve back into her lane nor did I make an e-brake that caused the accident. Please refer to the CCTV recordings I attached in this mail which will prove my claims



2018-08-08_06-54-13-Normal.avi



2018-08-08_06-54-13-Normal_Rear.avi



2018-08-08_06-54-39-Shock.avi



2018-08-08_06-54-39-Shock_Rear.avi

Thank you.

Regards,
Mr Poh

----- Forwarded message -----

From: HUPHUP WORKSHOP <hupwshop@hotmail.com>
Date: Thu, Aug 23, 2018 at 11:37 AM
Subject: Fw: ROAD TRAFFIC ACCIDENT INVOLVING SCL 8969D AND SMA 8821K ON 08.08.2018
To: loong72188@gmail.com <loong72188@gmail.com>

Hi Mr Poh,

Forwarded the e-mail from the other party.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Thursday, 23 August 2018 9:44 AM
To: 'hupwshop@hotmail.com'
Cc: Hsiao Tong (LKKAUTO)
Subject: ROAD TRAFFIC ACCIDENT INVOLVING SCL 8969D AND SMA 8821K ON 08.08.2018
Attachments: OI sketch plan+ statement.pdf
Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/ASM18015087/T1fb3
Your Ref: SMA 8821K

Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING SCL 8969D AND SMA 8821K ALONG ON 08.08.2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is unclear for the above mentioned case. There is no conclusive evidence yet to substantiate either party's version. Below is a copy of our insured's accident report statement for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request the CCTV footage / accident scene photos / evidence in order to seek further instruction from our principal.

Thank you.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

<< Re:Re-Seek Mandate Approval < S8M00SAT >

Type

🔗 Question

Message

PLS PROCEED

11/30/2018

Reply

◀ Re-Seek Mandate Approval < S8M00SAT >

Type

🔗 Question

Message

Dear Stacey, we refer to the above matter and we hereby re seek mandate approval as per surveyor had finalize check items and one supplementary added, resurvey photo uploaded in Smart Claim. Revise Immediate Advice (with mandate) have been uploaded in SMART CLAIM. We hereby seek your approval to offer Third Party repairer M/s "Hup Hup Workshop Pte Ltd " is as follows: - 1)COR(w/gst): \$2,300.50 + 2) Loss of Use (7days x \$80.00): \$ 560.00 +3)LTA search: \$7.49=Total: \$2,867.99. **5days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your kind attention/instruction. PohKin - 28/11/2018

Reply



Pls proceed DS as proposed

Type

🔔 Question

Message

Reply



<S8M00SAT> IA with mandate uploaded

Type

🔔 Question

Message

Liability: Insured collided to rear of third party vehicle. Front to rear collision. Liability is down against our insured. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. Propose settlement amount is between \$ 2,118.49 to \$2,599.99. All the relevant documents had been uploaded in SMART CLAIM. For your kind attention and instruction, Thank you-Pohkin 30/08/2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 30/08/2018

Survey Details:

Date of loss	8-Aug-18
Date of appointment	17-Aug-18
Date of survey	17-Aug-18
Location of survey	HUP HUP WORKSHOP PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SMA 8821K
Make and Model	HONDA INTEGRA 2.0A - 1998cc
Date of registration	21/7/2006
Excess	
Market Value	\$28,000
Part Rebate	\$15,035
Nett Loss	\$12,965

Repair details:

Initial Estimate	\$ 3,558.16
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 604.32
Check items (estimate)	\$ 590.88
Labour	\$ 1,000.00
Total	\$ 2,195.20
Lump Sum(if applicable)	\$ -

Number of days for repair	5
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Estimate for Rental: \$120 x 6 days = \$720.00

Mandate:

Liability(TP)	100%	100%
Check item	with check item	no check item
Proposed repair cost(w/gst)	(\$1,750.00 + 7% GST) \$1,872.50	(\$1,300.00 + 7% GST) \$1,391.00
Loss of use	\$-	\$-
Loss of rental (estimate)	\$ 720.00	\$ 720.00
Loss of income	\$-	\$-
LTA search fees	\$ 7.49	\$7.49
Others	-	\$-
Proposed Total	\$2,599.99	\$2,118.49

合合車廠私人有限公司
HUP HUP WORKSHOP PTE. LTD.

27-A, JURONG PORT ROAD, #01-29, SINGAPORE 619101

TEL: 6265 5270, 6261 3407, 6265 1966 FAX: 6261 8456

Email: hupwshop@hotmail.com

Business Regn. / GST Regn. No. 19-8004325-G

Your Ref: CC4/ASM18015087/T1f83

Our Ref : HHW/TP 2395/2018 (SMA 8821K)

Date: 09/01/2019

LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park
Ubi Avenue 1, #02-25
Singapore 408933

Attn: Mr Chong Poh Kin
(Case Handler)

Dear Sirs,

RE: ACCIDENT INVOLVING SMA 8821K & SCL 8969D ON 08/08/2018


Our client Mr Poh Yueh Loong, owner of SMA 8821K is claiming against
Your insured (SCL 8969D) for the following:-

Cost Of Repair	\$ 2,300.50
Loss Of use (7 Days @ \$ 80 Per Day)	\$ 560.00
Search Fee	\$ 7.49

\$ 2,867.99
=====

We shall appreciate your payment in return.

Yours sincerely,



TEY HANG LIANG
MANAGING DIRECTOR

Enclosed: Repair Bill, Letter Of Authority & Indemnity, LTA Search Fee.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

30th August 2018

HONG YUN XIN
49 Hindhede Walk,
#03-04,
Singapore 587976.

Attn: Madam Lim Ah Chek

Dear Sir/Madam,

OUR REF : CC4/ASM18015087/T1fb3
YOUR REF : SCL 8969D
ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SCL 8969D AND SMA 8821K
ALONG PIE ON 08.08.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party Property Damage claim against your policy.

We have received a claim from M/s Hup Hup Workshop Pte Ltd, acting on behalf of the owner of SMA 8821K against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had collided into the rear of Third Party vehicle SMA 8821K. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to pohkin@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2132 or email us at pohkin@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Poh Kip, Chong

Case Handler

DID: 6841 2132

FAX: 6741 4108

Email: pohkin@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

Date: 30/08/2018

To: M/s Hup Hup Workshop Pte Ltd
27A Jurong Port Road
#01-29
Singapore 619101

LETTER OF AUTHORITY & INDEMNITY

I/We POH YUEH LOONG Nric No./ Co Registration
No. S 8827472E of (address) HDB BUKIT BATOK, 265 BUKIT BATOK EAST AVENUE 4,
#10-401
the registered owner (or his/her/their/agent) of motor vehicle registration no. SMA 8821K S 650265
hereby authorise M/s Hup Hup Workshop Pte Ltd ("the Repairer") to commence repairs
to my/our vehicle and to forward the claim for inter alia the costs of repairs to the
owner/insured of the Third Party responsible for the said accident on (date) 08/08/2018
involving motor vehicle nos SMA 8821K & SCL 8969D along PIE TOWARDS CHANGI
I further authorise M/s Hup Hup Workshop Pte Ltd to sign and execute all documents in
my name including but not limited to the Discharge Voucher in connection with the claim
against the Third Party

However, if the third party rejects liability for whatever reasons and/or if the
claim is reverted to my/our insurers and my/our insurers do not settle the repair costs and
disbursements under my/our own insurance policy, I/we will be fully responsible for the
repair costs, rental (if any) and survey fees.

My/our vehicle is repaired by the Repairer on my/our own free will and without
any threat, inducement and/or promise.

In the event that the Repairer is compelled to enforce this undertaking, I/we agree
that I/we shall pay for the legal costs incurred by the Repairer on a solicitor and client full
indemnity basis.


Signature/ Co. Stamp



DISCHARGE VOUCHER

REPAIR BILL

合合車廠私人有限公司
HUP HUP WORKSHOP PTE. LTD.

27-A, JURONG PORT ROAD, #01-29, SINGAPORE 619101

TEL: 6265 5270, 6261 3407, 6265 1966 FAX: 6261 8456

Email: hupwshop@hotmail.com

Business Regn. / GST Regn. No. 19-8004325-G

No. TP/1529

Date: 07/01/2019

M/s. AXA INSURANCE PTE LTD

Vehicle No. SMA 8821K


Make Honda Integra

Your Ref:

Our Ref: HHW/TP 2395/2018

1 set	<p>To Supply Spare Parts.</p> <p>Reverse sensor & fixing.</p> <p>Labour charge to cut, weld, replace rear end panel; repair, straighten rear LH fender, rear LH fender inner panel, tail lamp panel and dismantle, align, adjust and replace parts.</p> <p>Spray paint on rear end panel-inside/outside, rear LH fender, tail lamp panel, rear bumper, reverse sensor.</p> <p>Supply and affix sticker wrap on rear bumper and rear LH fender (from front LH windscreen glass to the end of rear LH fender).</p>		
		LUMP SUM	\$ 2150.00
		Add GST 7%	\$ 150.50
			<u>\$ 2300.50</u>
	(D/S: TWO THOUSAND THREE HUNDRED AND CENTS FIFTY ONLY)		

for HUP HUP WORKSHOP PTE. LTD.





Thank you

Phee Lay San has successfully logged out.

Your last login date and time was 13 Aug 2018, 09:52:45.

To return to ONE MOTORING, please [click here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount (\$)	Log Date/Time
1	Vehicle	SCL8969D	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	13 Aug 2018 / 09:54:09

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SCL 8969D (Insd veh)	Model:	HONDA INTEGRA
	SMA 8821K (TP veh)		
Date of Accident:	08/08/2018		

Global Sum Settlement	: [] Yes	[X] No
Repair Estimate	: \$	4,663.23
Final Repair Cost	: \$	2,300.50
Loss of Use	: \$	560.00
		7days at \$80.00 per day
Rental (if any)	: \$	
		days
LTA / GIA Search Fee	: \$	7.49

Others:	: \$	0.00
---------	------	------

	: \$	
Final Settlement Sum	: \$	2,867.99

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____100____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____(%)	Assessed Liability (*): _____(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	HUP HUP WORKSHOP PTE.LTD.	: \$ 2,867.99

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

24/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18015087/T1fb3q2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: STACEY NG

Date : 24-01-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SCL 8969D	Veh. Inspected	SMA 8821K
Policy No.	GA218393/1	Coverage (\$)	0.00
Claim No.	S8M00SAT	Excess (\$)	0.00
Assign From		Assign Date	17/08/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA INTEGRA	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JHMDC54506S201094	Colour	RED
Odometer	197361	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/45 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	08/08/2018	Inspection Date	17/08/2018
Survey held at	HUP HUP WORKSHOP PTE LTD 27-A JURONG PORT ROAD #01-29 SINGAPORE 619101		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 8821K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL LAMP (LH) (CONSISTENT)	CRACKED	440.60	440.60
1	TAIL LAMP BRACKET LOWER LH (CONSISTENT)	NECESSARY	48.00	48.00
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	453.70	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	718.70	718.70
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	NECESSARY	36.70	36.70
	LESS 20% DISCOUNT		-339.54	-248.80
			1,358.16	995.20
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR & FIXING (SN) (CONSISTENT)	NOT WORKING	200.00	200.00
			200.00	200.00
	LABOUR			
	LABOUR CHARGE TO CUT,WELD, REPLACE REAR END PANEL,REPAIR,STRAIGHTEN REAR LH FENDER, REAR LH FENDER INNER PANEL, TAIL LAMP PANEL AND DISMANTLE, ALIGN,ADJUST AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF END PANEL.		1,000.00	500.00
	SPRAY PAINT ON REAR END PANEL-INSIDE/OUTSIDE REAR LH FENDER, TAIL LAMP PANEL,REAR BUMPER, REVERSE SENSOR.		1,000.00	500.00
	SUPPLY AND REFIX STICKER WRAP ON REAR BUMPER AND REAR LH FENDER (FROM FRONT LH WINDSCREEN GLASS TO THE END OF REAR LH FENDER), (ADDITIONAL)		800.00	500.00
			2,800.00	1,500.00
	GRAND TOTAL		4,358.16	2,695.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,150.00

Report Ref No. CC4/ASM18015087/T1fb3q2

MOHAMAD TAUFIKH**M.MATAI, AMSAE-A**

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SIMMODSAT
Reference	CC4/A9M1B015087/TIR3q2
Loss Date	8 August 2018
Request Date	16 August 2018
Due Date	

Vendor Name LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss Third Party Vehicle Damage

Services Pending verification - Direct Settlement

Actions

Next Step: Wait for Approve Invoice

0.0.0 Invoice

Vehicle Information	
Incident Vehicle Registration #	SMA8821K
Make	TPVD HONDA
Model	INTEGRA 2.0
Service Address	

...

Primary Contact/Insured
HONG YUN XIN
49 HINDHEDE WALK, #03-04, SPRINGDALE CONDO, S87976, Singapore
RACH.HONG21@GMAIL.COM

Claim Handler

NG Stacy
6568804351
stacey.ng@axa.com.sg















Additional Instructions








- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type Document SubType

Upload Documents

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
LKXInvoice1 (4).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	28 January 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 LIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 Immediate Advice Review (with mandated dated 28.11.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	28 November 2018
 TP supplementary-Marked.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	28 November 2018
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 November 2018
 LKK RESURVEY PHOTO-AFTER REPAIR.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 November 2018
 Immediate Advice (with mandated dated 30.08.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	30 August 2018
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 August 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Letter to OI.pdf	Letters and Correspondence	Policy Holders / Insured	LINK AUTO CONSULTANTS PTE LTD (TP)	30 August 2018
 TP Video footage SMA 8821K FRONT.mp4	Evidence	Videos	LINK AUTO CONSULTANTS PTE LTD (TP)	28 August 2018
 TP Video footage SMA 8821K REAR.mp4	Evidence	Videos	LINK AUTO CONSULTANTS PTE LTD (TP)	28 August 2018
 TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LINK AUTO CONSULTANTS PTE LTD (TP)	21 August 2018
 SMA8821K TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	16 August 2018
 SCL8969D INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	16 August 2018
 TP PRI FROM WORKSHOP.mng	Letters and Correspondence	Workshop	DHAKAL Raghav	16 August 2018