

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5642D**

**AAD1808-015**

*Not Authorized  
11 Sep 83300*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHC 5642D**  
VF1ABL15AUC280338  
RENAULT  
LATITUDE  
2.8.2018  
**AXA**

| PART |   |                                 | LIST                       |
|------|---|---------------------------------|----------------------------|
| 1    | 1 | BUMPER COVER FRT                | \$ <i>Bar</i> 1,259.42 ✓   |
| 2    | 1 | BUMPER SPOILER FRT              | \$ <i>Sm</i> 181.75 X      |
| 3    | 1 | BUMPER ABSORBER FRT             | \$ <i>Sm</i> 394.68 X      |
| 4    | 1 | BUMPER RETAINER FRT LH          | \$ <i>D.S</i> 151.41 ✓     |
| 5    | 1 | BUMPER SUPPORT FRT              | \$ <i>Sm</i> 123.88 X      |
| 6    | 1 | BUMPER RETAINER FRT RH          | \$ <i>Sm</i> 150.77 X      |
| 7    | 1 | BUMPER SUPPORT FRT              | \$ <i>Sm</i> 123.88 X      |
| 8    | 1 | BUMPER UNDERTRAY FRT            | \$ <i>Sm</i> 472.83 X      |
| 9    | 1 | BUMPER GRILLE LOWER FRT         | \$ <i>Sm</i> 266.80 X      |
| 10   | 1 | BUMPER FOG LAMP GRILLE LH       | \$ <i>nd</i> 207.21 ✓      |
| 11   | 1 | BUMPER FOG LAMP GRILLE RH       | \$ <i>Sm</i> 207.21        |
| 12   | 1 | BUMPER BEAM FRT                 | \$ <i>R</i> 914.08         |
| 13   | 1 | TOW COVER FRT                   | \$ <i>Sm</i> 28.61         |
| 14   | 1 | RADIATOR GRILLE                 | \$ <i>Sm</i> 1,707.78      |
| 15   | 1 | RADIATOR GRILLE BADGE 'RENAULT' | \$ <i>Sm</i> 225.36 X      |
| 16   | 1 | RADIATOR GRILLE FRAME           | \$ <i>Sm</i> 1,353.75      |
| 17   | 1 | FRAME FULL SUPPORT PANEL        | \$ <i>Sm</i> 615.90        |
| 18   | 1 | FRAME FULL SUPPORT BRACKET      | \$ <i>R</i> 89.79          |
| 19   | 1 | FRONT BRACE PANEL               | \$ <i>R</i> 177.22         |
| 20   | 1 | HORN                            | \$ <i>Sm</i> 314.17        |
| 21   | 1 | HORN BRACKET                    | \$ <i>R</i> 40.45          |
| 22   | 1 | HEADLAMP LH                     | \$ <i>mgcna</i> 1,184.43 ✓ |
| 23   | 1 | HEADLAMP RH                     | \$ <i>Sm</i> 1,184.43 X    |
| 24   | 1 | HEADLAMP PANEL FRT LH           | \$ <i>R</i> 152.15 X       |
| 25   | 1 | HEADLAMP PANEL FRT RH           | \$ <i>R</i> 152.15 X       |
| 26   | 1 | BONNET                          | \$ <i>R</i> 1,941.63 X     |
| 27   | 1 | BONNET INSULATOR                | \$ <i>Sm</i> 405.73 X      |
| 28   | 1 | BONNET STRUT LH                 | \$ <i>Sm</i> 88.61 X       |

**Trans-cab Auto Services Pte Ltd**

**AAD1808-015**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5642D**

|    |   |                                       |    |    |          |
|----|---|---------------------------------------|----|----|----------|
| 29 | 1 | BONNET STRUT RH                       | \$ | Su | 88.61 X  |
| 30 | 1 | BONNET HINGE LH                       | \$ | R  | 348.31 X |
| 31 | 1 | BONNET HINGE RH                       | \$ | R  | 348.31 X |
| 32 | 1 | BONNET LOCK                           | \$ | R  | 305.48 X |
| 33 | 1 | BONNET CABLE                          | \$ | Su | 119.19 X |
| 34 | 1 | BONNET CABLE COVER                    | \$ | Su | 161.03 X |
| 35 | 1 | BONNET SEAL OUTER                     | \$ | Su | 92.36 X  |
| 36 | 1 | BONNET SEAL INNER                     | \$ | Su | 157.28 X |
| 37 | 1 | FENDER PANEL FRT LH                   | \$ | R  | 783.83 ✓ |
| 38 | 1 | WHEELARCH FRT LH                      | \$ | Su | 278.84 ? |
| 39 | 1 | FENDER BRACKET LOWER LH               | \$ | Su | 15.79    |
| 40 | 1 | FENDER INSULATOR LH                   | \$ | Su | 130.84   |
| 41 | 1 | FENDER INSULATOR RH                   | \$ | Su | 130.84   |
| 42 | 1 | WIPER RESERVOIR                       | \$ | Su | 348.25   |
| 43 | 1 | WIPER RESERVOIR NECK                  | \$ | Su | 136.11   |
| 44 | 1 | WIPER RESERVOIR MOTOR                 | \$ | Su | 270.06   |
| 45 | 1 | AIR CLEANER LOWER                     | \$ | Su | 271.26   |
| 46 | 1 | AIR CLEANER HOSE                      | \$ | Su | 76.14    |
| 47 | 1 | BASE BATTERY TRAY                     | \$ | Su | 363.40   |
| 48 | 1 | AIR CLEANER BOX                       | \$ | Su | 464.20   |
| 49 | 1 | TURBO DUCT                            | \$ | Su | 1,027.80 |
| 50 | 1 | A/C HEATER VALVE                      | \$ | Su | 484.50   |
| 51 | 1 | SUBFRAME OUTER FRT                    | \$ | Su | 2,652.45 |
| 52 | 1 | SUBFRAME BRACKET OUTER LH             | \$ | Su | 92.36    |
| 53 | 1 | ENGINE UNDERTRAY                      | \$ | Su | 564.98   |
| 54 | 1 | A/C CONDENSER                         | \$ | Su | 2,020.37 |
| 55 | 1 | A/C CONDENSER GARNISH LH UPPER        | \$ | Su | 39.67    |
| 56 | 1 | A/C CONDENSER GARNISH RH UPPER        | \$ | Su | 39.67    |
| 57 | 1 | A/C CONDENSER GARNISH LH              | \$ | Su | 58.81    |
| 58 | 1 | A/C CONDENSER GARNISH RH              | \$ | Su | 59.60    |
| 59 | 1 | A/C PIPE CONDENSER TO COMPRESSOR      | \$ | Su | 208.39   |
| 60 | 1 | A/C PIPE CONDENSER TO EXPENSION VALVE | \$ | Su | 658.72   |
| 61 | 1 | A/C PIPE COMPRESSOR                   | \$ | Su | 334.29   |
| 62 | 1 | A/C PIPE                              | \$ | Su | 658.72   |
| 63 | 1 | A/C COMRPRESSOR                       | \$ | Su | 2,684.61 |
| 77 | 1 | AIR COOLER                            | \$ | Su | 792.60   |
| 78 | 1 | AIR INTERCOOLER HOSE (LONG)           | \$ | Su | 1,014.13 |
| 79 | 1 | AIR INTERCOOLER HOSE (Short)          | \$ | Su | 375.14   |

**Trans-cab Auto Services Pte Ltd**

**AAD1808-015**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5642D**

|     |   |                                   |    |    |          |   |
|-----|---|-----------------------------------|----|----|----------|---|
| 80  | 1 | TRANSMISSION COOLER               | \$ | Su | 1,219.30 | } |
| 81  | 1 | TRANSMISSION COOLER PAD           | \$ | Ju | 17.96    |   |
| 82  | 1 | RADIATOR                          | \$ | Ju | 1,202.20 |   |
| 83  | 2 | RADIATOR STUD UPPER               | \$ | Su | 14.41    |   |
| 84  | 2 | RADIATOR BUSH UPPER               | \$ | Su | 50.12    |   |
| 85  | 2 | RADIATOR MTG LOWER                | \$ | Su | 55.85    |   |
| 86  | 1 | RADIATOR FAN COWLING              | \$ | Su | 820.54   |   |
| 87  | 1 | RADIATOR FAN MOTOR LH             | \$ | Su | 967.36   |   |
| 88  | 1 | RADIATOR FAN MOTOR RH             | \$ | Su | 1,479.46 |   |
| 89  | 1 | RADIATOR TANK                     | \$ | Su | 324.62   |   |
| 90  | 1 | RADIATOR HOSE UPPER               | \$ | Su | 240.56   |   |
| 91  | 1 | RADIATOR HOSE LOWER               | \$ | Su | 491.18   |   |
| 92  | 1 | RADIATOR TANK HOSE                | \$ | Su | 61.18    |   |
| 93  | 1 | AUTO COMPUTER                     | \$ | Su | 5,032.17 |   |
| 94  | 1 | INJECTION COMPUTER                | \$ | Su | 4,706.30 |   |
| 95  | 1 | RHD HYDRAULIC POWER(ROCK&PINION)  | \$ | N  | 5,154.52 |   |
| 96  | 1 | STEERING PUMP ELECTRIC L70Y       | \$ | Su | 2,306.90 |   |
| 97  | 1 | STEERING PINION RACK L70Y         | \$ | N  | 4,413.11 |   |
| 98  | 1 | DOOR PANEL FRT LH                 | \$ | N  | 2,844.66 |   |
| 99  | 1 | LOWER ARM LH L70Y                 | \$ | Su | 685.76   |   |
| 100 | 1 | KUNCKLE ARM LH L70Y               | \$ | Su | 846.98   |   |
| 101 | 1 | ABSORBER FRT LH L70Y              | \$ | Su | 360.54   |   |
| 102 | 1 | AIR CLEANER BOX                   | \$ | Su | 464.20   |   |
| 103 | 1 | AIR CLEANER HOSE                  | \$ | Su | 175.85   |   |
| 104 | 1 | DOOR HARNESS WIRE LH              | \$ | Su | 2,670.00 |   |
| 105 | 1 | DOOR MIRROR ASSY LH               | \$ | N  | 1,483.40 |   |
| 106 | 1 | WHEEL HOUSING COMPLETE SET FRT LH | \$ | Su | 5,487.04 |   |

|              |    |                  |
|--------------|----|------------------|
|              | \$ | <b>70,862.14</b> |
| <b>TOTAL</b> | \$ | <b>7,086.21</b>  |
| <b>10%</b>   | \$ | <b>63,775.92</b> |

**Special Nett**

|   |    |    |         |
|---|----|----|---------|
|   | \$ | Nu | 52.00 X |
| 1 | \$ | Nu | 66.00 X |
| 2 | \$ | Nu | 12.00   |

**Trans-cab Auto Services Pte Ltd**

**AAD1808-015**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5642D**

|                    |      |                                 |           |    |                  |   |  |
|--------------------|------|---------------------------------|-----------|----|------------------|---|--|
| 3                  | 1    | BUMPER BRACKET CLIP FRT LH      | \$        | na | 10.50            | } |  |
| 4                  | 1    | BUMPER SUPPORT CLIP FRT LH      | \$        | na | 12.00            |   |  |
| 5                  | 1    | BUMPER BRACKET CLIP FRT RH      | \$        | na | 12.00            |   |  |
| 6                  | 1    | BUMPER SUPPORT CLIP FRT RH      | \$        | na | 14.50            |   |  |
| 7                  | 1    | TOW COVER FRT                   | \$        | na | 16.00            |   |  |
| 8                  | 1SET | RADAIOR GRILLE SCREW            | \$        | na | 69.00            |   |  |
| 9                  | 1SET | BUMPER GRILLE LOWER CLIP        | \$        | na | 70.00            |   |  |
| 10                 | 1SET | FRAME FULL SUPPORT PANEL CLIP   | \$        | na | 20.00            |   |  |
| 11                 | 2    | FRAME FULL SUPPORT PANEL NUT    | \$        | na | 30.00            |   |  |
| 12                 | 2    | FRAME FULL SUPPORT PANEL STUD   | \$        | na | 100.00           |   |  |
| 13                 | 1    | Windscreen moulding             | \$        | na | 80.00            |   |  |
| 14                 | 1SET | Front licence plate with holder | \$        | na | 330.00           |   |  |
| 15                 | 1    | Front left tyre                 | \$        | sm | 380.00           |   |  |
| 16                 | 1    | Front left tyre rim             | \$        | sm | 80.00            |   |  |
| 17                 | 1    | FRONT DOOR STICKER 'Trans-cab'  | \$        | na | 50.00            |   |  |
| 18                 | 1    | FRONT DOOR STICKER 'Chassis'    | \$        | na | 50.00            |   |  |
| <b>TOTAL</b>       |      |                                 | <b>\$</b> |    | <b>1,404.00</b>  |   |  |
| <b>TOTAL PARTS</b> |      |                                 | <b>\$</b> |    | <b>65,179.92</b> |   |  |

**LABOUR**

|   |    |          |          |
|---|----|----------|----------|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 5,400.00 | 4000     |
| Towing Fees.  | \$ | na       | 120.00 X |
| To apply paint protection system (PPS) maintain and enhancement   | \$ | na       | 380.00 X |
| Putty and spray painting of the affected portion.   | \$ | 6,000.00 | 4400     |
| To rust-proofing of the affected areas.   | \$ | 170.00   | 300      |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | na       | 380.00 X |

**Trans-cab Auto Services Pte Ltd**

AAD1808-015

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5642D**

|   |    |    |        |     |
|---|----|----|--------|-----|
| To check steering geometry and computer wheel alignment   | \$ | na | 170.00 | X   |
| To transfer of tire, rim and on wheel balancing.  | \$ | na | 380.00 | X   |
| To Check Electrical Lighting Concerned.   | \$ |    | 380.00 | 2ol |
| To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack. | \$ | na | 440.00 | X   |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                                     | \$ | na | 440.00 | X   |
| To lift-up engine with gear box and refit.  | \$ | na | 480.00 | X   |
| To remove and renew power steering pump, oil cooler pipe and final checking and testing.                            | \$ | na | 380.00 | X   |
| To remove and refit air bag system and reset.   | \$ | na | 380.00 | X   |
| To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.                        | \$ | na | 170.00 | X   |
| To vacuum, replace, refix and recharge air condenser  | \$ | na | 170.00 | X   |
| To replace, refix and top up coolant for radiator   | \$ | na | 170.00 | X   |
| To vacuum, replace, refix and recharge Air Intercooler  | \$ | na | 300.00 | X   |

**Trans-cab Auto Services Pte Ltd**

**AAD1808-015**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5642D**

To Transfer Of Fender Fittings, Attachments And  
Perform Water Seepage Test.

\$

*na* 300.00 X

**TOTAL** \$

16,610.00

**Over All Total** \$

**81,789.92**

**Repair Days (LUMP SUM)**

**20 DAYS**

*2 days*

86,676.27#

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date: