

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5642D

AAD1808-015

*Not Authorized
11 Sep 833001*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5642D
VF1ABL15AUC280338
RENAULT
LATITUDE
2.8.2018
AXA

PART

LIST

QTY	PART	UNIT	PRICE	LIST	STATUS
1	BUMPER COVER FRT		\$	1,259.42	✓
2	BUMPER SPOILER FRT		\$	181.75	X
3	BUMPER ABSORBER FRT		\$	394.68	X
4	BUMPER RETAINER FRT LH		\$	151.41	✓
5	BUMPER SUPPORT FRT		\$	123.88	X
6	BUMPER RETAINER FRT RH		\$	150.77	X
7	BUMPER SUPPORT FRT		\$	123.88	X
8	BUMPER UNDERTRAY FRT		\$	472.83	X
9	BUMPER GRILLE LOWER FRT		\$	266.80	X
10	BUMPER FOG LAMP GRILLE LH		\$	207.21	✓
11	BUMPER FOG LAMP GRILLE RH		\$	207.21	} X
12	BUMPER BEAM FRT		\$	914.08	
13	TOW COVER FRT		\$	28.61	
14	RADIATOR GRILLE		\$	1,707.78	
15	RADIATOR GRILLE BADGE 'RENAULT'		\$	225.36	
16	RADIATOR GRILLE FRAME		\$	1,353.75	
17	FRAME FULL SUPPORT PANEL		\$	615.90	
18	FRAME FULL SUPPORT BRACKET		\$	89.79	
19	FRONT BRACE PANEL		\$	177.22	
20	HORN		\$	314.17	
21	HORN BRACKET		\$	40.45	
22	HEADLAMP LH		\$	1,184.43	✓
23	HEADLAMP RH		\$	1,184.43	X
24	HEADLAMP PANEL FRT LH		\$	152.15	X
25	HEADLAMP PANEL FRT RH		\$	152.15	X
26	BONNET		\$	1,941.63	X
27	BONNET INSULATOR		\$	405.73	X
28	BONNET STRUT LH		\$	88.61	X

Trans-cab Auto Services Pte Ltd

AAD1808-015

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5642D

29	1	BONNET STRUT RH	\$	Su	88.61	X
30	1	BONNET HINGE LH	\$	R	348.31	X
31	1	BONNET HINGE RH	\$	R	348.31	X
32	1	BONNET LOCK	\$	R	305.48	X
33	1	BONNET CABLE	\$	Su	119.19	X
34	1	BONNET CABLE COVER	\$	Su	161.03	X
35	1	BONNET SEAL OUTER	\$	Su	92.36	X
36	1	BONNET SEAL INNER	\$	Su	157.28	X
37	1	FENDER PANEL FRT LH	\$	R	783.83	✓
38	1	WHEELARCH FRT LH	\$	Su	278.84	?
39	1	FENDER BRACKET LOWER LH	\$	Su	15.79	
40	1	FENDER INSULATOR LH	\$	Su	130.84	
41	1	FENDER INSULATOR RH	\$	Su	130.84	
42	1	WIPER RESERVOIR	\$	Su	348.25	
43	1	WIPER RESERVOIR NECK	\$	Su	136.11	
44	1	WIPER RESERVOIR MOTOR	\$	Su	270.06	
45	1	AIR CLEANER LOWER	\$	Su	271.26	
46	1	AIR CLEANER HOSE	\$	Su	76.14	
47	1	BASE BATTERY TRAY	\$	Su	363.40	
48	1	AIR CLEANER BOX	\$	Su	464.20	
49	1	TURBO DUCT	\$	Su	1,027.80	
50	1	A/C HEATER VALVE	\$	Su	484.50	
51	1	SUBFRAME OUTER FRT	\$	Su	2,652.45	
52	1	SUBFRAME BRACKET OUTER LH	\$	Su	92.36	
53	1	ENGINE UNDERTRAY	\$	Su	564.98	
54	1	A/C CONDENSER	\$	Su	2,020.37	
55	1	A/C CONDENSER GARNISH LH UPPER	\$	Su	39.67	
56	1	A/C CONDENSER GARNISH RH UPPER	\$	Su	39.67	
57	1	A/C CONDENSER GARNISH LH	\$	Su	58.81	
58	1	A/C CONDENSER GARNISH RH	\$	Su	59.60	
59	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Su	208.39	
60	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Su	658.72	
61	1	A/C PIPE COMPRESSOR	\$	Su	334.29	
62	1	A/C PIPE	\$	Su	658.72	
63	1	A/C COMRPRESSOR	\$	Su	2,684.61	
77	1	AIR COOLER	\$	Su	792.60	
78	1	AIR INTERCOOLER HOSE (LONG)	\$	Su	1,014.13	
79	1	AIR INTERCOOLER HOSE (Short)	\$	Su	375.14	

Trans-cab Auto Services Pte Ltd

AAD1808-015

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5642D

80	1	TRANSMISSION COOLER	\$	Su	1,219.30	}
81	1	TRANSMISSION COOLER PAD	\$	Ju	17.96	
82	1	RADIATOR	\$	Ju	1,202.20	
83	2	RADIATOR STUD UPPER	\$	Su	14.41	
84	2	RADIATOR BUSH UPPER	\$	Su	50.12	
85	2	RADIATOR MTG LOWER	\$	Su	55.85	
86	1	RADIATOR FAN COWLING	\$	Su	820.54	
87	1	RADIATOR FAN MOTOR LH	\$	Su	967.36	
88	1	RADIATOR FAN MOTOR RH	\$	Su	1,479.46	
89	1	RADIATOR TANK	\$	Su	324.62	
90	1	RADIATOR HOSE UPPER	\$	Su	240.56	
91	1	RADIATOR HOSE LOWER	\$	Su	491.18	
92	1	RADIATOR TANK HOSE	\$	Su	61.18	
93	1	AUTO COMPUTER	\$	Su	5,032.17	
94	1	INJECTION COMPUTER	\$	Su	4,706.30	
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	N	5,154.52	
96	1	STEERING PUMP ELECTRIC L70Y	\$	Su	2,306.90	
97	1	STEERING PINION RACK L70Y	\$	N	4,413.11	
98	1	DOOR PANEL FRT LH	\$	N	2,844.66	
99	1	LOWER ARM LH L70Y	\$	Su	685.76	
100	1	KUNCKLE ARM LH L70Y	\$	Su	846.98	
101	1	ABSORBER FRT LH L70Y	\$	Su	360.54	
102	1	AIR CLEANER BOX	\$	Su	464.20	
103	1	AIR CLEANER HOSE	\$	Su	175.85	
104	1	DOOR HARNESS WIRE LH	\$	Su	2,670.00	
105	1	DOOR MIRROR ASSY LH	\$	N	1,483.40	
106	1	WHEEL HOUSING COMPLETE SET FRT LH	\$	Su	5,487.04	

	\$	70,862.14
TOTAL	\$	7,086.21
10%	\$	63,775.92

Special Nett

	\$	Nu	52.00	X
1	\$	Nu	66.00	X
2	\$	Nu	12.00	✓

Trans-cab Auto Services Pte Ltd

AAD1808-015

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5642D

3	1	BUMPER BRACKET CLIP FRT LH	\$	na	10.50	}	
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	12.00		
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00		
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	14.50		
7	1	TOW COVER FRT	\$	na	16.00		
8	1SET	RADAIOR GRILLE SCREW	\$	na	69.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	70.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	20.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	30.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	100.00		
13	1	Windscreen moulding	\$	na	80.00		
14	1SET	Front licence plate with holder	\$	na	330.00		
15	1	Front left tyre	\$	sm	380.00		
16	1	Front left tyre rim	\$	sm	80.00		
17	1	FRONT DOOR STICKER 'Trans-cab'	\$	na	50.00		
18	1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00		
TOTAL			\$		1,404.00		
TOTAL PARTS			\$		65,179.92		

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	5,400.00	4000
Towing Fees.	\$	na 120.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	4800
To rust-proofing of the affected areas.	\$	170.00	300
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1808-015

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5642D

To check steering geometry and computer wheel alignment	\$	na	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	380.00	X
To Check Electrical Lighting Concerned.	\$		380.00	2ol
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na	440.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na	440.00	X
To lift-up engine with gear box and refit.	\$	na	480.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	na	380.00	X
To remove and refit air bag system and reset.	\$	na	380.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	na	170.00	X
To vacuum, replace, refix and recharge air condenser	\$	na	170.00	X
To replace, refix and top up coolant for radiator	\$	na	170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	na	300.00	X

Trans-cab Auto Services Pte Ltd

AAD1808-015

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5642D

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$

na 300.00 X

TOTAL \$

16,610.00

Over All Total \$

81,789.92

Repair Days (LUMP SUM)

20 DAYS

2 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: