



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR GBA7999T*M

Cycle & Carriage Industries Pte Ltd

239 Alexandra Rd
Singapore 159930

Work: 64733122

Vehicle & Document Information

WIP No 26030
Reg No/Reg Date GBA7999T*M / 12/09/2017
Date In/Mileage / 0
Chassis No WDF44760323329501
Engine No 65195034182914
Make/Model MBCV/VITO 114KA/ L4X2 3200 AUT
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	16/08/2018/ 12:23	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPN SUN POLICY NO/ACC DATE :B28674301MKF // 08-08-2018 DRIVE IN:10-08-2018 // TP CAR NO:SLT5618M (AXA INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	✓ 380.00
A BPILAB RENEW REAR WINDSHIELD			0.07	✓ 560.00
S BPN SUB SUPPLY 1PC REAR WINDSHIELD SOLAR FILM PURCHASE ORDER NO:				? 300.00
S BPN SUB SUPPLY REAR DISPLAY STICKER PURCHASE ORDER NO:				✓ 380.00
A BPILAB REMOVE & REPLACE REAR BUMPER, REAR BOOT LID & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				1920 2880.00
A BPIRES RESPRAY REAR BUMPER & REAR BOOT LID				1000 1500.00
M REAR BOOT LID	1.00	1987.90	00.00	bt ✓ 1987.90
M REAR BOOT LID SEAL	1.00	5.63	00.00	nl ✓ 5.63
M REAR WINDSHIELD	1.00	745.02	00.00	nl ✓ 745.02
M GLAZING REPAIR KIT	2.00	154.72	00.00	nl ✓ 309.44
M VITO EMBLEM	1.00	44.41	00.00	nl ✓ 44.41
M BLUETEC EMBLEM	1.00	56.23	00.00	nl ✓ 56.23
M REAR STAR EMBLEM	1.00	38.67	00.00	nl ✓ 38.67
M 114 CDI EMBLEM	1.00	52.55	00.00	nl ✓ 52.55
M 3RD BRAKE LAMP	1.00	179.21	00.00	nl ✓ 179.21
M REAR BUMPER	1.00	1166.34	00.00	de ✓ 1166.34
M RH/R BUMPER SIDE AREA COVER	1.00	132.12	00.00	de ✓ 132.12
M LH/R BUMPER SIDE BRACKET	1.00	65.26	00.00	? 65.26

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

ESTIMATE FOR GBA7999T*M

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Cycle & Carriage Industries Pte Ltd
239 Alexandra Rd
Singapore 159930

Work: 64733122

WIP No: 26030
Reg No/Reg Date: GBA7999T*M / 12/09/2017
Date In/Mileage: / 0
Chassis No: WDF44760323329501
Engine No: 65195034182914
Make/Model: MBCV/VITO 114KA/ L4X2 3200 AUT
Colour/Trim: 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	16/08/2018/ 12:23	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RH/R BUMPER SIDE BRACKET	1.00	65.26	00.00	65.26
M RH/R BUMPER REFLECTOR	1.00	26.23	00.00	26.23
M LH/R BUMPER REFLECTOR	1.00	26.23	00.00	26.23
M CT/R BUMPER REINFORCEMENT	1.00	185.96	00.00	185.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749
'wp'
17/8/18 @ 1545
5 days
sur@lkkauto.com
Reply before part

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Authorized signatory and company stamp

Nett 11,086.46
7% GST on 11086.46 776.05
Total Payable 11,862.51

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388