



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR GBA7999T*M

Cycle & Carriage Industries Pte Ltd

239 Alexandra Rd
Singapore 159930

Work: 64733122

Vehicle & Document Information

WIP No 26030
Reg No/Reg Date GBA7999T*M / 12/09/2017
Date In/Mileage 0 / 0
Chassis No WDF44760323329501
Engine No 65195034182914
Make/Model MBCV/VITO 114KA/ L4X2 3200 AUT
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	16/08/2018/ 12:23	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : B28674301MKF // 08-08-2018 DRIVE IN: 10-08-2018 // TP CAR NO: SLT5618M (AXA INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB RENEW REAR WINDSHIELD			0.07	560.00
S BPNSUB SUPPLY 1PC REAR WINDSHIELD SOLAR FILM PURCHASE ORDER NO:				300.00
S BPNSUB SUPPLY REAR DISPLAY STICKER PURCHASE ORDER NO:				380.00
A BPILAB REMOVE & REPLACE REAR BUMPER, REAR BOOT LID & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH				2880.00
A BPIRES RESPRAY REAR BUMPER & REAR BOOT LID				1500.00
M REAR BOOT LID	1.00	1987.90	00.00	1987.90
M REAR BOOT LID SEAL	1.00	5.63	00.00	5.63
M REAR WINDSHIELD	1.00	745.02	00.00	745.02
M GLAZING REPAIR KIT	2.00	154.72	00.00	309.44
M VITO EMBLEM	1.00	44.41	00.00	44.41
M BLUETEC EMBLEM	1.00	56.23	00.00	56.23
M REAR STAR EMBLEM	1.00	38.67	00.00	38.67
M 114 CDI EMBLEM	1.00	52.55	00.00	52.55
M 3RD BRAKE LAMP	1.00	179.21	00.00	179.21
M REAR BUMPER	1.00	1166.34	00.00	1166.34
M RH/R BUMPER SIDE AREA COVER	1.00	132.12	00.00	132.12
M LH/R BUMPER SIDE BRACKET	1.00	65.26	00.00	65.26

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR GBA7999T*M

Cycle & Carriage Industries Pte Ltd
239 Alexandra Rd
Singapore 159930

Work: 64733122

Vehicle & Document Information

WIP No **26030**
Reg No/Reg Date **GBA7999T*M / 12/09/2017**
Date In/Mileage **0**
Chassis No **WDF44760323329501**
Engine No **65195034182914**
Make/Model **MBCV/VITO 114KA/ L4X2 3200 AUT**
Colour/Trim **914 Arctic White / NA NOT APPLICABLE**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	16/08/2018/ 12:23	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RH/R BUMPER SIDE BRACKET	1.00	65.26	00.00	65.26
M RH/R BUMPER REFLECTOR	1.00	26.23	00.00	26.23
M LH/R BUMPER REFLECTOR	1.00	26.23	00.00	26.23
M CT/R BUMPER REINFORCEMENT	1.00	185.96	00.00	185.96

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **11,086.46**
7% GST on **11086.46** **776.05**

Authorized signatory and company stamp

Total Payable 11,862.51

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg