



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR LIM BOON PENG (LIN WENPING) BLK 98 ALJUNIED CRES #12-409 SINGAPORE 380098 Contact No Mobile: 96545475	Cust No/Name	/MR LIM BOON PENG (LIN WENPING)
	Reg No/Reg Date	SLQ8832G / 26/07/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH005605
	Engine No	3A92UGA8076
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	17/08/2018/ 10:05	COC	442 / CocoLu	29875

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER				✓ 550.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER				420 500.00
M SUNDRY FRT NUMBER PLATE WITH FRAME				56 50.00
M SUNDRY APPLY LTA RESEAL NUMBER PLATE				✓ 80.00
M SUNDRY Sundry				✓ 20.00
M FACE,FR BUMPER	1.00	696.00	00.00	46 696.00
M GRILLE,FR UNDER	1.00	163.00	00.00	? 163.00
M GRILLE,RADIATOR	1.00	548.00	00.00	out 548.00
M MARK,THREE-DIA	1.00	51.00	00.00	art 51.00

SURVEYOR NAME: Tanfan 97495745SURVEYOR SIGNATURE: [Signature]DATE: 8/10/18 @ 11:5pmREMARKS: Resurvey before paint.
03 days
serve 11km to work.**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

	Nett	2,658.00
7% GST on	2658.00	186.06
Total Payable		2,844.06

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.