



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR LIM BOON PENG (LIN WENPING) BLK 98 ALJUNIED CRES #12-409 SINGAPORE 380098 Contact No Mobile: 96545475	Cust No/Name	/MR LIM BOON PENG (LIN WENPING)
	Reg No/Reg Date	SLQ8832G / 26/07/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH005605
	Engine No	3A92UGA8076
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	17/08/2018/ 10:05	COC	442 / CocoLu	29875		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							550.00
RENEW FRT BUMPER							
E PNT98000							500.00
SPRAY PAINT FOR FRT BUMPER							
M SUNDRY							50.00
FRT NUMBER PLATE WITH FRAME							
M SUNDRY							80.00
APPLY LTA RESEAL NUMBER PLATE							
M SUNDRY							20.00
Sundry							
M FACE,FR BUMPER				1.00	696.00	00.00	696.00
M GRILLE,FR UNDER				1.00	163.00	00.00	163.00
M GRILLE,RADIATOR				1.00	548.00	00.00	548.00
M MARK,THREE-DIA				1.00	51.00	00.00	51.00

Estimate

Confirm & accepted by

Nett	2,658.00
7% GST on	186.06
Total Payable	2,844.06

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.