

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [mailto:shupe@lkkauto.com]
Sent: Tuesday, August 21, 2018 5:17 PM
To: Joel Goh
Cc: Admin A; Hsiao Tong (LKKAuto)
Subject: Direct Settlement - Accident Involving GY3874K (OI : EQI - TBA) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upp3) on 17.08.2018

WITHOUT PREJUDICE

Dear Joel,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLE 8227S at M/s Fastech Auto Pte Ltd.

Enclosed for your perusal is:
- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,
Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 29 January 2019 11:36 AM
To: 'Joel Goh'
Cc: Admin A
Subject: <SEEK MANDATE> Direct Settlement - Accident Involving GY3874K (OI : EQI - DM18HO02178-JG) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Attachments: LKK Survey Report & Photos.pdf; TP LOD_SLE8227S.pdf

Your ref : **DM18HO02178-JG**
Our ref : CC6/EQI18015105/Upb3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING GY3874K(EQ-OI) AND SLE8227S(TP) ON 17/08/2018

We refer to the above matter.

This is a head-to-rear collision. Third party video footage had been submitted to your good office on 05/09/2018. Liability is not in our insured's driver's favour.
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "**Fastech Auto Pte Ltd**" at **\$28,052.00(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 93,475.00	\$ 26,750.00
2. Loss of Rental (13days x \$100.00)	\$ 1,300.00	\$ 1,300.00 (13days x \$100.00)
3. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 94,777.00	<u>\$ 28,052.00</u>

**15days recommendation for repair.

Market Value	: \$ 75,500.00 (est)
LTA Rebate	: \$ 50,034.00 (est)
Nett Value	: <u>\$ 25,466.00 (est)</u>

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Hsiao Tong (LKKAuto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Wednesday, 27 February 2019 3:57 PM
To: Hsiao Tong (LKKAuto)
Cc: Admin A
Subject: RE: <SEEK MANDATE> Direct Settlement - Accident Involving GY3874K (OI : EQI - DM18HO02178-JG) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Dear Hsiao Tong

My apologies for the late response.
Please proceed to resolve this matter up to S\$28,052.00

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Tuesday, January 29, 2019 11:36 AM
To: Joel Goh
Cc: Admin A
Subject: <SEEK MANDATE> Direct Settlement - Accident Involving GY3874K (OI : EQI - DM18HO02178-JG) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Your ref : **DM18HO02178-JG**
Our ref : CC6/EQI18015105/Upb3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING GY3874K(EQ-OI) AND SLE8227S(TP) ON 17/08/2018

We refer to the above matter.

This is a head-to-rear collision. Third party video footage had been submitted to your good office on 05/09/2018. Liability is not in our insured's driver's favour.
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "**Fastech Auto Pte Ltd**" at **S\$28,052.00(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 93,475.00	\$ 26,750.00
2. Loss of Rental (13days x \$100.00)	\$ 1,300.00	\$ 1,300.00 (13days x \$100.00)
3. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 94,777.00	\$ 28,052.00

**15days recommendation for repair.

Market Value	: \$ 75,500.00 (est)
LTA Rebate	: \$ 50,034.00 (est)
Nett Value	: \$ 25,466.00 (est)

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>

Sent: Wednesday, 9 January 2019 11:14 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GY3874K (OI : EQ) - DM18HO02178-JG) AND SLE8227S (TP : LKK REF - CC6/EQ18015105/Upb3) on 17.08.2018

Dear Hsiao Tong

After reviewing this matter, our management has decided to allow this claim.

Please proceed with direct settlement and keep us updated.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg



Handwritten mark resembling a stylized 'S' or signature.

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Joel Goh

Sent: Wednesday, January 2, 2019 11:02 AM

To: 'Hsiao Tong (LKKAuto)'

Cc: Admin A

Subject: RE: Direct Settlement - Accident Involving GY3874K (OI : EQI - DM18HO02178-JG) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Dear Hsiao Tong

We have repudiated the claim however insured has appealed and our management is in the midst of reviewing this matter.

Best Regards,

Joel Goh

Executive | Claims




EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg



Handwritten mark resembling a stylized 'S' or signature.

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Wednesday, January 2, 2019 10:50 AM

To: Joel Goh

Cc: Admin A

Subject: RE: Direct Settlement - Accident Involving GY3874K (OI : EQI - DM18HO02178-JG) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Hi Joel,

Further to your below email.

Kindly let us have your instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>

Sent: Thursday, 22 November 2018 6:09 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GY3874K (OI : EQI - DM18HO02178-JG) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Dear Hsiao Tong

We are still in the midst of seeking approval to repudiate this claim.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify th

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Thursday, November 22, 2018 4:52 PM

To: Joel Goh

Cc: Admin A

Subject: RE: Direct Settlement - Accident Involving GY3874K (OI : EQI - DM18HO02178-JG) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Hi Joel,

Further to the below email.

Kindly advise if we may proceed DS.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Friday, 9 November 2018 10:24 AM

To: 'Joel Goh' <joel.goh@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GY3874K (OI : EQI - DM18HO02178-JG) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Hi Joel,

Contents noted.

We await your further instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>

Sent: Friday, 9 November 2018 9:35 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GY3874K (OI : EQI - DM18HO02178-JG) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Dear Hsiao Tong

Please put this direct settlement on hold.

There is a potential breach of the policy T&C

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]
Sent: Thursday, October 18, 2018 8:27 AM
To: Joel Goh
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving GY3874K (OI : EQI - TBA) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Dear Sirs/ Mdm,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 5 September 2018 4:10 PM
To: 'Joel Goh' <joel.goh@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GY3874K (OI : EQI - TBA) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Hi Joel,

Attached is a copy of third party video for your reference.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>

Sent: Thursday, 23 August 2018 9:17 AM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GY3874K (OI : EQI - TBA) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

Dear Shu Pei

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

A handwritten mark consisting of a circle with a horizontal line extending to the right, and a small 'S' above it.

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Tuesday, August 21, 2018 5:17 PM

To: Joel Goh

Cc: Admin A; Hsiao Tong (LKKAuto)

Subject: Direct Settlement - Accident Involving GY3874K (OI : EQI - TBA) AND SLE8227S (TP : LKK REF - CC6/EQI18015105/Upb3) on 17.08.2018

WITHOUT PREJUDICE

Dear Joel,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLE 8227S at M/s Fastech Auto Pte Ltd.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeilkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Monday, 11 March 2019 11:36 AM
To: Hsiao Tong (LKKAuto)
Subject: RE: Your Ref: SLE 8227S *Our Ref: CC6/EQ18015105/Upb3 [ACCIDENT INVOLVING GY 3874K(EQ) & SLE 8227S ON 12/08/2018]

Without Prejudice

Dear Hsiao Tong,

We are pleased to accept your offer of global sum of \$28,000.00(all-in) for my client's vehicle property claim.

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Sunday, March 10, 2019 8:09 PM
To: Jason Fastech Auto <jason@fastechauto.com.sg>
Subject: Re: Your Ref: SLE 8227S *Our Ref: CC6/EQ18015105/Upb3 [ACCIDENT INVOLVING GY 3874K(EQ) & SLE 8227S ON 12/08/2018]

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$28,000.00(all-in).

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Wednesday, 5 September 2018 3:54 PM
To: Hsiao Tong (LKKAuto)
Subject: RE: Your Ref: SLE 8227S *Our Ref: CC6/EQ118015105/Upb3 [ACCIDENT INVOLVING GY 3874K(EQ) & SLE 8227S ON 12/08/2018]

Without Prejudice

Dear Hsiao Tong,

As requested.

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]
Sent: Wednesday, September 5, 2018 3:37 PM
To: Jason Fastech Auto (jason@fastechauto.com.sg) <jason@fastechauto.com.sg>
Subject: Your Ref: SLE 8227S *Our Ref: CC6/EQ118015105/Upb3 [ACCIDENT INVOLVING GY 3874K(EQ) & SLE 8227S ON 12/08/2018]

Your Ref: **SLE 8227S**
Our Ref: CC6/EQ118015105/Upb3

ACCIDENT INVOLVING GY 3874K(EQ) & SLE 8227S ON 12/08/2018

We refer to the above matter.

We would like to request a copy of your client's video footage as stated in his accident report for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ18015105/Upb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 25-04-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 3874K	Veh. Inspected	SLE 8227S
Policy No.	DMCPHQ18-001335	Coverage (\$)	0.00
Claim No.	DM18HO02178-JG	Excess (\$)	0.00
Assign From		Assign Date	20/08/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11200812	Colour	WHITE
Odometer	044232	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	DUNLOP	6 mm
L/H Front Tyre	215/60R16	DUNLOP	6 mm
R/H Rear Tyre	215/60R16	DUNLOP	6 mm
L/H Rear Tyre	215/60R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND FRONT O/S PORTION. THE UNDERCARRIAGE AND CHASSIS FRAME AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/08/2018	Inspection Date	20/08/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 8227S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	BONNET HINGES @ \$85.00	TO REPAIR SEE LABOUR	170.00	-
1	BONNET INSULATOR	TORN	211.30	211.30
1	SET BONNET INSULATOR CLIPS	NOT NECESSARY	35.00	-
1	BONNET LOCK	NOT NECESSARY	135.50	-
2	BONNET RUBBERS @ \$32.00	NOT NECESSARY	64.00	-
1	BONNET	BUCKLED	915.00	892.30
1	FRONT BUMPER	DISTORTED	950.00	801.70
1	FRONT BUMPER REINFORCEMENT	DENTED	480.00	321.00
2	FRONT BUMPER SIDE RETAINERS @ \$65.00	BENT	130.00	90.00
2	FRONT BUMPER BRACKETS @ \$115.00	NO SUCH PARTS	230.00	-
1	FRONT BUMPER CENTRE GRILLE	CRACKED	285.00	149.00
1	FRONT BUMPER LOWER SPOILER	DEFORMED	525.00	391.10
1	FRONT BUMPER UNDER COVER	TORN	480.00	165.20
1	SET FRONT BUMPER UNDER COVER CLIPS	NECESSARY	35.00	35.00
1	FRONT BUMPER TOW COVER	NOT NECESSARY	45.00	-
2	FRONT BUMPER FOG LAMP COVERS @ \$180.00	O/S TWISTED	360.00	98.00
2	FRONT BUMPER FOG LAMPS @ \$445.00	NOT NECESSARY	890.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	40.00	40.00
1	FRONT GRILLE	CRACKED	525.00	389.50
1	FRONT GRILLE OUTER GARNISH	CRACKED	548.00	385.00
1	FRONT GRILLE 'H' LOGO	SCRATCHED	38.80	38.80
2	HEADLAMPS @ \$2250.00	O/S BROKEN	4,500.00	1,759.00
2	HEADLAMP LOWER BRACKETS @ \$85.00	O/S CRACKED	170.00	85.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	745.11	-
1	FRONT SUPPORT PANEL TOP GARNISH	TORN	322.30	166.30
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	NECESSARY	50.00	50.00
2	FRONT FENDERS @ \$688.00	N/S TO REPAIR SEE LABOUR / O/S BUCKLED	1,376.00	580.00
2	FRONT FENDER INNER SHIELDS @ \$166.50	O/S TORN	333.00	166.50

Report Ref No. CC6/EQ118015105/Upb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT FENDER OUTER PROTECTORS @ \$295.00	DEFORMED / TORN	590.00	420.00
1	AIRCON CONDENSER	NOT NECESSARY	1,568.00	-
2	AIRCON CONDENSER SIDE GARNISH @ \$148.00	NOT NECESSARY	296.00	-
1	RADIATOR	NOT NECESSARY	1,817.50	-
1	RADIATOR FAN COWLING	NOT NECESSARY	288.30	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	488.20	-
1	RADIATOR FAN BLADE	NOT NECESSARY	101.50	-
1	FRONT FENDER INNER PANEL O/S	BADLY DENTED	525.30	525.30
1	FRONT WHEEL HOUSING PANEL O/S	TO REPAIR SEE LABOUR	988.20	-
1	FUSE BOX	NOT NECESSARY	2,665.00	-
1	FUSE BOX BRACKET	NOT NECESSARY	89.60	-
1	WIPER GARNISH	DEFORMED	166.30	166.30
1	BATTERY TRAY	NOT NECESSARY	180.20	-
1	WASHER TANK	NOT NECESSARY	305.00	-
1	FRONT DOOR 'A' PILLAR OUTER	TO REPAIR SEE LABOUR	899.20	-
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	866.30	-
1	FRONT WINDSCREEN	NOT NECESSARY	1,488.20	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	122.30	-
1	ENGINE MOUNTING N/S	NOT NECESSARY	188.20	-
1	ENGINE MOUNTING O/S	NOT NECESSARY	195.30	-
1	FRONT LOWER ARM O/S	BUCKLED	488.20	392.30
1	FRONT KNUCKLE ARM O/S	BENT	499.50	388.50
1	FRONT KNUCKLE ARM BEARING O/S	NECESSARY	250.00	185.20
1	FRONT DRIVESHAFT O/S	SERVICEABLE	1,150.20	-
1	FRONT ENGINE CROSS MEMBER	BENT / CRACKED	1,660.80	1,660.80
1	STEERING RACK ASSY	BENT / JAMMED	2,715.00	2,445.90
1	SRS AIR BAG IMPACT SENSOR	ACTIVATED	150.00	150.00
1	SRS AIR BAG STEERING WHEEL	ACTIVATED	2,448.00	1,805.00
1	SRS STEERING WHEEL SPIRAL SENSOR	ACTIVATED	399.00	268.90
1	PASSENGER AIR BAG	ACTIVATED	2,880.00	2,436.80
1	INSTRUMENT DASHBOARD ASSY	BURST	1,466.20	892.50

Report Ref No. CC6/EQ118015105/Upb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DRIVER SEAT BELT	ACTIVATED	980.00	780.00
1	PASSENGER SEAT BELT	ACTIVATED	980.00	780.00
1	SRS AIR BAG CONTROL UNIT	ACTIVATED	1,450.00	980.00
1	ROOF LINING	TORN	1,800.00	1,445.30
1	CURTAIN AIR BAG O/S	ACTIVATED	1,660.00	1,400.50
1	FRONT MUDFLAP O/S	NOT FITTED	105.30	-
2	ROCKER PANEL GARNISHES @ \$899.20	GRAZED / DISTORTED	1,798.40	1,290.40
1	ROCKER PANEL O/S	TO REPAIR SEE LABOUR	850.50	-
1	STABILIZER BAR	SERVICEABLE	366.30	-
1	FRONT LINKAGE O/S	TWISTED	166.00	166.00
1	REAR WINDSCREEN	SMASHED	1,488.20	1,488.20
1	REAR WINDSCREEN MOULDING	NECESSARY	121.30	121.30
1	TAILGATE	BADLY DENTED	1,100.90	953.00
1	TAILGATE OUTER GARNISH	BENT / CRACKED	399.20	399.20
1	TAILGATE 'H' LOGO	NECESSARY	35.80	35.80
2	TAILGATE REFLECTORS @ \$460.50	N/S CRACKED	921.00	260.50
1	TAILGATE INNER LOCK	JAMMED	198.50	198.50
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	321.70	321.70
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	40.00	40.00
2	TAILGATE DAMPERS @ \$299.10	NOT NECESSARY	598.20	-
1	TAILGATE WEATHERSTRIP	TWISTED	135.70	135.70
1	TAILGATE KEYLESS SENSOR	CRACKED	180.00	180.00
1	REAR BUMPER	DISTORTED	762.70	762.70
2	REAR BUMPER SIDES @ \$285.10	N/S DISTORTED	570.20	285.10
2	REAR BUMPER SIDES RETAINERS @ \$35.20	BENT	70.40	70.40
2	REAR BUMPER REFLECTORS @ \$85.00	NOT NECESSARY	170.00	-
1	REAR BUMPER DIFFUSER	DISTORTED	348.20	348.20
1	SET REAR BUMPER DIFFUSER CLIPS	NECESSARY	50.00	50.00
2	TAILLAMPS @ \$485.20	N/S BROKEN	970.40	460.50
2	TAILLAMP HOUSING PANELS @ \$195.00	TO REPAIR SEE LABOUR	390.00	-

Report Ref No. CC6/EQ118015105/Upb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL	BADLY DENTED	514.00	514.00
1	REAR END PANEL TOP GARNISH	TWISTED	184.00	184.00
1	REAR FLOOR PANEL	BADLY DENTED / BUCKLED	912.00	912.00
1	REAR FLOOR PANEL TOOLS SPONGE	TORN	685.00	485.00
1	REAR FLOOR PANEL TOP BOARD	WARPED	499.20	316.00
2	REAR FENDERS @ \$885.10	N/S BADLY DENTED	1,770.20	825.10
2	REAR FENDER INNER TRIM BOARDS @ \$645.30	DEFORMED / TORN	1,290.60	900.00
2	REAR FENDER OUTER PROTECTORS @ \$288.60	N/S TORN	577.20	288.60
1	REAR EXHAUST	NOT NECESSARY	899.20	-
2	REAR EXHAUST MOUNTINGS @ \$45.00	NOT NECESSARY	90.00	-
2	REAR SHOCK ABSORBER @ \$305.00	NOT NECESSARY	610.00	-
2	REAR WHEEL HUB BEARING @ \$450.00	NOT NECESSARY	900.00	-
1	REAR AXLE BEAM	NOT NECESSARY	1,885.00	-
	LESS 20% DISCOUNT		-	-7,185.98
			72,369.81	28,743.92
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	30.00
1	REAR WINDSCREEN SOLAR FILM (SN)	NECESSARY	280.00	150.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR REVERSE CAMERA (SN)	SHORTED	380.00	300.00
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
2	FRONT SPORT RIMS @ \$800.00 (SN)	O/S DENTED	1,600.00	480.00
2	FRONT TYRES @ \$250.00 (LOCAL PURCHASE) (@ \$200.00 DISC 60%) (SN)	O/S CUT	500.00	120.00
1	REAR SPORT RIM (SN)	DENTED	800.00	480.00
1	REAR TYRE O/S (LOCAL PURCHASE) (@ \$200.00 DISC 60%) (SN)	CUT	250.00	120.00
			4,290.00	2,000.00
	<u>LABOUR</u>			
	TOWING CHARGE.		150.00	60.00

Report Ref No. CC6/EQ118015105/Upb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REAR REVERSE SENSOR.		80.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM.		100.00	60.00
	TO TRANSFER TAILGATE COMPONENTS.		100.00	60.00
	TO SPRAY RUST PROOFING.		280.00	150.00
	TO REFILL AIRCON GAS.		150.00	100.00
	TO DISMANTLE & REFIX FRONT WINDSCREEN.	NOT NECESSARY	150.00	-
	TO MOUNT VEHICLE ON CAR-O-LINER.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE.		500.00	350.00
	TO DISMANTLE & REFIX PETROL TANK.		100.00	60.00
	TO DISMANTLE & REPLACING DASHBOARD.		380.00	260.00
	TO DISMANTLE & REPLACING AIR BAG, SEAT BELT.		300.00	200.00
	TO RESET AIR BAG SYSTEM & REPROGRAMME.		500.00	300.00
	TO DISMANTLE & REPLACING ROOF LINING.		200.00	120.00
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF BONNET HINGES, FRONT SUPPORT PANEL, N/S FRONT FENDERS, FRONT WHEEL HOUSING PANEL O/S, FRONT DOOR 'A' PILLAR OUTER, FRONT DOOR O/S, ROCKER PANEL O/S AND TAILLAMP HOUSING PANELS.		3,800.00	2,400.00
	TO PUTTY & SPRAY PAINTING.		3,000.00	1,800.00
			10,700.00	6,260.00
GRAND TOTAL			87,359.81	37,003.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				25,000.00

Report Ref No. CC6/EQ18015105/Upb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.