

FASTECH AUTO PTE LTD

1 Kakit Bukit Ave 6
#01-46,48,50 Autobay
SINGAPORE 417883

VEHICLE NO: SGJ 768H

QTY	PARTICULAR
1 PCS	BONNET 3966.12
1 PCS	BONNET LOCK
2 PCS	BONNET HINGES @\$300.00
1 PCS	FRONT BUMPER 1645.30
2 PCS	FRONT BUMPER SIDE HOLDERS @\$285.00
1 SET	FRONT BUMPER CLIPS
2 PCS	FRONT BUMPER SENSORS @\$205.00
1 PCS	FRONT BUMPER CENTRE GRILLE
1 PCS	FRONT BUMPER REINFORCEMENT
1 PCS	FRONT GRILLE
1 PCS	FRONT GRILLE LOGO
1 PCS	HEADLAMP LED N/S 4159.50
2 PCS	HEADLAMP BALLASTS @\$880.00 485 x 2 = 970

LABOUR CHARGES:

TO CHECK WIRING
TO DISMANTLE & REFIX PDC SENSOR
TO REFILL AIR CON GAS
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

TOTAL

not allowed
2/2/11 11734.32
4/2/11
20/8/18

20/8/18	\$6,088.10	✓
11	\$266.50	X
11	\$600.00	X
20/10/11	\$2,266.00	✓
11	\$570.00	X
11	\$60.00	✓
11	\$410.00	X
11	\$269.30	X
11	\$899.10	X
20/10/11	\$1,215.00	✓
11	\$105.00	X
5/2/11	\$4,859.10	✓
shhd	\$1,760.00	✓
	\$19,368.10	

	\$50.00	20
	\$80.00	50
11	\$150.00	X
	\$80.00	50
	\$680.00	400
	\$900.00	400
	\$21,308.10	400
		920

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1201582
1/2
10814.32
11734.32