

CASE OWNER: Nurshah

CC 6, ALG 180 15713, Ufa39

LKK:  
IDAC:

Surveyor:

MARUW

ASSIGNMENT  
DOI: 20/8/18

Registered in Merimen:

20/8/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SMD 3781J  
 Name of Insured : LYNN SUZANNO Goh Yan Ahn  
 Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_  
 Excess Sec II :SS \_\_\_\_\_ D.O.A: 19/08/2018  
 Is driver the owner? ( YES / NO ) \_\_\_\_\_ Nature of Accident : \_\_\_\_\_  
 If NO, Driver Name / Age : ISAAC GUEAN Yan Minke  
 Driver Tel No. : 90257844 (V/L: YES / NO)

Claim No. : 0204735228 SG  
 Policy No. : 2100449503  
 Make / Model : Mazda CX-5  
 Place of Accident : Chemping Ave 4  
 OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
 Insured Liability : % Final ? Yes / No

SLX 1402 Z



INSRS: \_\_\_\_\_  
 WSP: Hup Motor  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	<u>5/28/8/2018 email</u>
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorization To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

RECEIVED 06 SEP 2018

A before print photo ✓

<b>PRELIMINARY ADVICE</b>	Date/Time: <u>21/8/2018</u>	Sent By: <u>HMK</u>
<b>FINALIZATION</b>	Date/Time: _____	Confirm with: _____
Repair Cost:	SS <u>6,616.24</u> ( <u>6</u> days) Reduction: <u>45.5</u> %	Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>	Date/Time: <u>31/8/2018</u>	Confirm with <u>David Ag</u>
Final Liability:	% <u>100</u> (Agreed / Assessed) BOLA S/N No. : <u>2.1</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Repair Cost:	SS <u>6,616.24</u>	
Loss of Rental (LOR):	SS <u>300.00</u> ( <u>8</u> days) <u>\$100.00</u>	
Loss of Use (LOU):	SS <u>-</u> ( <u>5</u> x days)	
Loss of Income (LOI):	SS <u>-</u> ( <u>5</u> x days)	
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]	
GIA/LTA Search:	SS <u>4.00</u>	
Medical:	SS <u>-</u>	
Disbursement:	SS <u>-</u> (e.g. Tow/ Independent)	
Legal Cost:	SS <u>-</u>	
<b>Total:</b>	SS <u>7,420.24</u>	Global Sum SS: _____
<b>FINAL PAYMENT</b>	Date/Time: _____	Confirm with: _____
Payee 1:	SS <u>7,420.24</u>	Name 1: <u>Hup Motor Trading &amp; Service</u>
Payee 2 (Strike if I.A.):	SS _____	Name 2: _____
Payee 3 (Strike if I.A.):	SS _____	Name 3: _____

Front to rear

5/9/2018

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: \$2000+\$20.00

ahya

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLX14022  
 at Workshop m/s: mp motor  
 of: 15MD3781J  
 Insured: 5 JS 88/85  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

N/S	O/S

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 QA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 6 days Res.: Yes or No  
 Lum Sum: 218% % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 9 3/81  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SLX14022 Yr Regn: 3 1/8  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CAI  
 Make: Honda verel c.c. 1496  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 6015 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: RU11232714  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: order / Jammed / Leaked / Burnt or  
 Brake: order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 215 / 60R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 9 mm R/Bal. 9 mm  
 L/Bal. 9 mm L/Bal. 9 mm  
 D.O.A. 19/8/18 D.O.I. 20/8/18  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	£150.99
	<u>RTA 45583</u>	

Date/Time, File Pass to?  : Prell. Report  : Final Report

1) Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$) \_\_\_\_\_ )

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_ )  : S + RS \_\_\_\_\_ \$

: Interview (\$ \_\_\_\_\_ )  : Photos

: Tech. Invs (\$ \_\_\_\_\_ )  : Others

: Weekend (\$ \_\_\_\_\_ )

TOTAL \_\_\_\_\_

p/p 6.16.24 (Red 5.534.24 / 45.5)

7/18 6616:24 not allowed  
 take ph. screenshot  
 6dy  
 29/8/18

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk. 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupnotice@gmail.com Reg. No. 37809100W

Our Ref: TF 2921/08/18 Your Ref: \_\_\_\_\_ Date: 20th AUG 2018

**MH KOH GIN THIAM**  
 BLK 230J, #08-673  
 TAMPINES STREET 21, 3 (523230)

SLX1402S

Estimate cost of repair to HONDA VEZEL 1.5i (A) CVT 5door - SLI 1402 S

1 pc tail gate door	30/6/20		\$ 957.00	---
1 pc tail gate door 'VEZEL' emblem	neu		58.50	---
1 pc tail gate door 'H' logo emblem	neu		25.90	---
1 pc tail gate door 'HYBRID' emblem	neu		58.30	X
2 pcs rear windscreen glass o/s & n/s seal	neu @ \$ 74.10		148.20	---
1 pc rear windscreen glass top seal	neu		66.00	---
1 pc rear windscreen glass lower seal	neu		68.00	---
1 pc rear windscreen glass damper	1pc		45.00	---
1 pc rear windscreen glass sealant	neu		60.00	POS.N
1 pc rear licence lamp garnish	11		238.70	X
2 pcs rear o/s & n/s licence lamp assy	11 @ \$ 38.50		77.00	X
12 pcs rear licence lamp garnish clips	11 @ \$ 6.90		82.80	X
12 pcs rear licence lamp garnish clips stopper	@ \$ 8.50 11		102.00	X
1 pc trim board cover	20/7/18		184.40	---
12 pcs trim board cover clips	neu @ \$ 5.90		70.80	---
1 pc tail gate door handle	7/18/1		147.30	---
1 pc tail gate door inner lock	7/18/1		180.60	---
1 pc tail gate door lock striker	11		23.80	X
1 pc key less sensor (outer)	11		137.10	X
1 pc key less sensor (inner)	11		107.30	X
1 pc tail gate door weatherstrip	7/18/1		119.90	---
2 pcs tail gate door o/s & n/s reflector	@ \$ 272.30 o/s/n		544.60	1/2 C
2 pcs o/s & n/s tail lamp assy	@ \$ 463.90 o/s/n		927.80	1/2 C
1 pc rear number plate & holder	neu		50.00	---
1 pc rear bumper	5/18		528.00	---
6 pcs rear bumper top clips	@ \$ 3.90 neu		23.40	---
5 pcs rear bumper lower clips	@ \$ 3.90 neu		19.50	---
1 pc rear bumper reinforcement (Top)	neu		143.60	X
1 set rear bumper reverse sensor	shhd		287.80	20/05/18
2 pcs rear bumper o/s & n/s side pad	@ \$ 148.50 o/s/n		297.00	1/2 C
2 pcs rear bumper o/s & n/s side retainer	@ \$ 20.40 o/s/n		40.80	1/2 C
2 pcs rear bumper o/s & n/s top retainer	@ \$ 18.50 o/s/n		37.00	1/2 C
4 pcs rear bumper o/s & n/s side pad clips	@ \$ 5.90 11		23.60	X
2 pcs rear bumper o/s & n/s reflector	@ \$ 151.80 11		303.60	X
1 pc rear end panel	30/4/18		470.30	---
1 pc rear end panel top garnish	neu		95.70	---
5 pcs rear end panel top garnish clips	@ \$ 5.80 11		29.00	X
1 pc rear floor board panel	neu		709.50	X
1 pc rear floor board panel under cover garnish	neu		156.80	X
8 pcs rear floor board panel under cover clips	@ \$ 3.90 11		31.20	X
1 pc spare tyre cover board	neu		264.80	X
1 pc tool set sponge	neu		204.80	---
16 pcs rear o/s & n/s fender wheel guard clips	@ \$ 8.50 11		136.00	X
1 pc rear o/s fender wheel guard	7/18/1		134.10	---
1 pc rear floor board panel insulator	neu		68.80	X
1 pc rear o/s fender	neu		709.80	X
1 pc rear floor board panel insulator	11		68.40	X
			<b>\$ 9,263.80</b>	

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2921/08/18 Your Ref: \_\_\_\_\_ Date: 20th AUG 2018

MR KOH GIN THIAM.,	Balance B/Y.....	9,263.80
	Less 20%	1,852.76
		<u>7,411.04</u>
To wiring check up & transfer affected wiring system into new door & necessary parts.		60.00 30
To transfer rear windscreen glass & necessary parts into new door.		150.00 120
To transfer tail gate door inner lock, trim board cover, hinge, shock absorber, spoiler, third brake light, wiper motor, arm, garnish, reverse camera & necessary parts into new door.		160.00 60
To remove & refix rear cushion seat, carpet, floor mat, garnish, floor board cover, spare tyre, tool set & necessary parts.		120.00 80
To jack, straighten & knocking out rear exhaust & tail pipe. ✓		120.00 2
To respray Tuff-Kote on all affected accident parts.		120.00 60
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear o/s & n/s fender & necessary parts, to weld, renew & align above parts.		1,800.00 1000
To putty & respray painting (Pearl Colour) on all affected accident parts.		1,900.00 1100
		<u>11,841.04</u>

Dollars : Eleven Thousand One Hundred Eighty Four And Cents Four Only.

HUP MOTOR TRADING & SERVICE

\_\_\_\_\_

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

r-4521,  
202  
3616.80.  
s.v-240  
labour-2450  
6306.80  
supp 309.44  
6616.24

↓

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2921/08/18 Your Ref: \_\_\_\_\_ Date: 23rd AUG 2018

MR KOH GIN THIAM  
BLK 230J, #08-673  
TAMPINES STREET 21  
SINGAPORE 523230



Supplementary Bill for MONDA VEZEL 1.5X (A) CVT 5door - SLX 1402 #

1 pc rear o/s fender inner garnish shield	<i>Return</i>	\$ 327.30 /
8 pcs rear o/s fender inner garnish clips	@ \$ 6.50 <i>rev</i>	52.00 /
1 pc o/s tail lamp clip stopper	<i>rev</i>	7.50 /
		<hr/>
		\$ 386.80
	Less 20%	\$ 77.36
		<hr/>
		\$ 309.44 /
		*****

Dollars : Three Hundred Nine Dollars And Cents Forty Four Only.

HUP MOTOR TRADING & SERVICE

-----  
*J*

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
 Owner ID: 9319I

### Vehicle Details

Vehicle No.: SLX1402Z  
 Vehicle to be Exported: No  
 Intended De-registration Date: 20 Aug 2018  
 Vehicle Make: HONDA  
 Vehicle Model: VEZEL 1.5X CVT  
 Primary Colour: Red  
 Manufacturing Year: 2017  
 Engine No.: L15B4432719  
 Chassis No.: RU11232714  
 Maximum Power Output: 96.0 kW (128 bhp)  
 Open Market Value: \$20,893.00  
 Original Registration Date: 16 Mar 2018  
 First Registration Date: 16 Mar 2018  
 Transfer Count: 0  
 Actual ARF Paid: \$11,251.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 15 Mar 2028  
 PARF Rebate Amount: \$8,438.00

### Intended COE Rebate Details

COE Expiry Date: 15 Mar 2028  
 COE Category: A - Car up to 1600cc & 97kW (130bhp)  
 COE Period(Years): 10  
 QP Paid: \$38,830.00  
 COE Rebate Amount: \$37,145.00  
**Total Rebate Amount: \$45,583.00**

The information contained herein is correct as at 20 Aug 2018

OK



**CONNECTING CAR BUYERS & SELLERS.**  
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertise Login Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



\$2000 Downpayment Monthly  
From \$488 Onwards. Lowest  
3.68%APR @GV Cars Financing  
GV Credit Pte Ltd StarAd

click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

Browse by Category

« Back ( 1 2 ) Next »

Sort by Date Posted 20 results/page

22 vehicles

Honda Vezel

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>								
Honda Vezel		Any	Any	2018	Any	Any	Any	Available
	Honda Vezel Hybrid 1.5A	\$91,800	\$8,510 /yr	27-Jun-2018	1,496 cc	-	SUV	Available
<b>Fuel Type:</b> Petrol-Electric								
Almost New 2018 New Facelifted Honda Vezel Hybrid. Best Fuel Consumption SUV In Town. 10% Down Payment, 10 Years Repayment, In House Loan Or Balloon Scheme Available. Make And Assemble In Japan. 3 Yea...								
Trust Motoring Posted: 20-Aug-2018 Tags: 2018 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda								
	Honda Vezel 1.5A X	\$96,988	\$9,510 /yr	16-Mar-2018	1,496 cc	64 km	SUV	Available
Down Payment 10% Easy Approval Available! 2018 Model, High Trade In Your Existing Car, Warranty 5 Years Or 100,000km, Flexible Loan Package Available 8 Years, Call Us For More Details.								
Vincar Pte Ltd Posted: 20-Aug-2018 Tags: 2018 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda								
	Honda Vezel 1.5A X	\$95,900	\$9,060 /yr	27-Jun-2018	1,496 cc	2,500 km	SUV	Available
Look No Further, Best Value For Your Money. Direct Owner's White, Jun 2018' Honda Vezel 1.5X CVT With Black Leather Upholstery Owned By 1 Private Owner. Comes With City Brake Assist. Selling Due To Up...								
Posted: 19-Aug-2018 Tags: 2018 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda								
	Honda Vezel 1.5A X Honda Sensing	\$99,800	\$9,540 /yr	25-May-2018	1,496 cc	10 km	SUV	Available
Grab Driver Welcome 100% Loan Available, 2018 New Model Vezel, Vitas Ready, Deliver Immediate, High Accessories With GPS, IRoad Recording Camera, High Trade In Your Existing Car, 5 Years Or 130,000km W...								
HTS Motor Posted: 19-Aug-2018 Tags: 2018 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda								
Car Buying	Car Selling	Car Ownership						
Car Aftermarket	On The Move	Lifestyle		<ul style="list-style-type: none"> <li>Buy Types Online</li> <li>Latest Special Offers from Tunepai!</li> </ul>				
	Honda Vezel 1.5A X Honda Sensing	\$88,800	\$8,700 /yr	23-Feb-2018	1,496 cc	4,000 km	SUV	Available
Special 1.98% Interest Rate! No Gimmicks, Act Fast! 3 Years Warranty By Hitachi, 3 Free Servicing Package. 1 Owner. Face-lifted Unit With Honda Sensing Technology, Pearl White Paintwork With Black Lea...								
Auto Zoom Enterprise Pte Ltd Posted: 18-Aug-2018 Tags: 2018 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda								
	Honda Vezel 1.5A X Honda Sensing	\$91,800	\$8,710 /yr	14-Jun-2018	1,496 cc	12 km	SUV	Available
Brand New Condition, 3 Year Hitachi Warranty.								
Posted: 18-Aug-2018 Tags: 2018 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda								

Compare

NOT ALLOWED  
 take ph. before  
 6dy  
 20/8/18

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2921/08/18 Your Ref: \_\_\_\_\_ Date: 20th AUG 2018

MR KOH GIN THIAM  
 BLK 230J, #08-673  
 TAMPINES STREET 21, S (523230)

### Estimate cost of repair to HONDA VEZEL 1.5X (A) CVT 5door - SLX 1402 #

1 pc tail gate door	<i>30dy</i>		\$ 957.00	—
1 pc tail gate door 'VEZEL' emblem	<i>nu</i>		58.50	—
1 pc tail gate door 'H' logo emblem	<i>nu</i>		25.90	—
1 pc tail gate door 'HYBRID' emblem	<i>nu</i>		58.30	X
2 pcs rear windscreen glass o/s & n/s seal	<i>nu</i>	@ \$ 74.10	148.20	—
1 pc rear windscreen glass top seal			66.00	—
1 pc rear windscreen glass lower seal	<i>nu</i>		68.00	—
1 pc rear windscreen glass damper	<i>17</i>		45.00	—
1 pc rear windscreen glass sealant	<i>nu</i>		60.00	<i>POS.N</i>
1 pc rear licence lamp garnish			238.70	?
2 pcs rear o/s & n/s licence lamp assy	<i>17</i>	@ \$ 38.50	77.00	X
12 pcs rear licence lamp garnish clips	<i>17</i>	@ \$ 6.90	82.80	X
12 pcs rear licence lamp garnish clips stopper		@ \$ 8.50	102.00	X
1 pc trim board cover			184.40	?
12 pcs trim board cover clips		@ \$ 5.90	70.80	?
1 pc tail gate door handle			147.30	?
1 pc tail gate door inner lock			180.60	—
1 pc tail gate door lock stricker			23.80	X
1 pc key less sensor (outer)	<i>17</i>		137.10	?
1 pc key less sensor (inner)			107.30	?
1 pc tail gate door weatherstrip			119.90	?
2 pcs tail gate door o/s & n/s reflector		@ \$ 272.30	544.60	<i>12C</i>
2 pcs o/s & n/s tail lamp assy		@ \$ 463.90	927.80	<i>12C</i>
1 pc rear number plate & holder			50.00	—
1 pc rear bumper			528.00	—
6 pcs rear bumper top clips		@ \$ 3.90	23.40	—
5 pcs rear bumper lower clips		@ \$ 3.90	19.50	—
1 pc rear bumper reinforcement (Top)			143.60	—
1 set rear bumper reverse sensor			287.80	<i>2005.N</i>
2 pcs rear bumper o/s & n/s side pad		@ \$ 148.50	297.00	<i>12C</i>
2 pcs rear bumper o/s & n/s side retainer		@ \$ 20.40	40.80	<i>12C</i>
2 pcs rear bumper o/s & n/s top retainer		@ \$ 18.50	37.00	?
4 pcs rear bumper o/s & n/s side pad clips		@ \$ 5.90	23.60	?
2 pcs rear bumper o/s & n/s reflector		@ \$ 151.80	303.60	?
1 pc rear end panel			470.30	?
1 pc rear end panel top garnish			95.70	?
5 pcs rear end panel top garnish clips		@ \$ 5.80	29.00	?
1 pc rear floor board panel			709.50	X
1 pc rear floor board panel under cover garnish			156.80	?
8 pcs rear floor board panel under cover clips		@ \$ 3.90	31.20	?
1 pc spare tyre cover board			264.80	?
1 pc tool set sponge			204.80	?
16 pcs rear o/s & n/s fender wheel guard clips		@ \$ 8.50	136.00	?
1 pc rear o/s fender wheel guard			134.10	?
1 pc rear floor board panel insulator			68.80	?
1 pc rear o/s fender			709.80	X
1 pc rear floor board panel insulator			68.40	—
			<b>\$ 9,263.80</b>	

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2921/08/18 Your Ref: \_\_\_\_\_ Date: 20th AUG 2018

MR KOH GIN THIAM.,

Balance B/W.....\$ 9,263.80

Less 20% \$ 1,852.76

To wiring check up & transfer affected wiring system into new door & necessary parts.	\$ 7,411.04 60.00 30
To transfer rear windscreen glass & necessary parts into new door.	150.00 120
To transfer tail gate door inner lock, trim board cover, hinge, shock absorber, spoiler, third brake light, wiper motor, arm, garnish, reverse camera & necessary parts into new door.	160.00 60
To remove & refix rear cushion seat, carpet, floor mat, garnish, floor board cover, spare tyre, tool set & necessary parts.	120.00 80
To jack, straighten & knocking out rear exhaust & tail pipe. u1	120.00 x
To respray Tuff-Kote on all affected accident parts.	120.00 60
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear o/s & n/s fender & necessary parts, to weld, renew & align above parts.	1,800.00 ?
To putty & respray painting (Pearl Colour) on all affected accident parts.	1,900.00 100
	<u>\$ 11,841.04</u>

Dollars : Eleven Thousand One Hundred Eighty Four And Cents Four Only.

HUP MOTOR TRADING & SERVICE

\_\_\_\_\_

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Poh Kin (LKKAuto)**

---

**From:** David Ang <hupmotor@gmail.com>  
**Sent:** Friday, 31 August 2018 3:49 PM  
**To:** Poh Kin (LKKAuto)  
**Cc:** Admin A  
**Subject:** Re: Offer OUR REF : CC6/AIG18015113/Ufa3; Your Ref: TP2921/08/18  
**Attachments:** SLX 1402 Z (DV).pdf

Dear Poh Kin,

As requested, we attach the discharge voucher (chop & signed) for your reference & attention, Please let us have the settlement soonest, we will forwards the original D/V to you by mail,

On 31 August 2018 at 15:23, Poh Kin (LKKAuto) <[pohkin@lkkauto.com](mailto:pohkin@lkkauto.com)> wrote:

**WITHOUT PREJUDICE**

Our Ref: CC6/AIG18015113/Ufa3

Your Ref: TP2921/08/18

Dear Mr David,

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SMD 3781J AND SLX 1402Z ON 19/08/2018**

We refer to the above matter and our tele conversation on even date.

We hereby confirmed settlement as below:

1. Cost of Repair	S\$ 6,616.24
2. Loss of Rental (\$100.00 x 8 days)	S\$ 800.00
3. GIA searches	<u>S\$ 4.00</u>
	<b><u>S\$ 7,420.24</u></b>

Please duly sign the **DV** enclosed and return for payment processing.

## Poh Kin (LKKAuto)

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Friday, 31 August 2018 3:23 PM  
**To:** 'David Ang'  
**Cc:** Admin A  
**Subject:** RE: Offer OUR REF : CC6/AIG18015113/Ufa3; Your Ref: TP2921/08/18  
**Attachments:** DV SLX 1402Z.pdf

**Importance:** High

### WITHOUT PREJUDICE

Our Ref: CC6/AIG18015113/Ufa3  
Your Ref: TP2921/08/18

Dear Mr David,

### **ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SMD 3781J AND SLX 1402Z ON 19/08/2018**

We refer to the above matter and our tele conversation on even date.

We hereby confirmed settlement as below:

1. Cost of Repair	S\$ 6,616.24
2. Loss of Rental (\$100.00 x 8 days)	S\$ 800.00
3. GIA searches	<u>S\$ 4.00</u>
	<b><u>S\$ 7,420.24</u></b>

Please duly sign the DV enclosed and return for payment processing.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

## Poh Kin (LKKAuto)

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Friday, 31 August 2018 2:02 PM  
**To:** 'David Ang'  
**Cc:** Hsiao Tong (LKKAuto); Admin A  
**Subject:** RE: Offer OUR REF : CC6/AIG18015113/Ufa3; Your Ref: TP2921/08/18  
**Importance:** High

### WITHOUT PREJUDICE

Our Ref: CC6/AIG18015113/Ufa3  
Your Ref: TP2921/08/18

Dear Mr David,

### **ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SMD 3781J AND SLX 1402Z ON 19/08/2018**

We refer to the above matter and your letter of demand dated 29<sup>th</sup> August 2018.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

1. Cost of Repair	S\$ 6,616.24
2. Loss of Use (\$90.00 x 8 days)	S\$ 720.00
3. GIA searches	<u>S\$ 4.00</u>
	<b><u>S\$ 7,340.24</u></b>

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Poh Kin (LKKAuto)**

---

**From:** Tan Glenn <isaac.glenn.tan@gmail.com>  
**Sent:** Thursday, 23 August 2018 2:04 PM  
**To:** Poh Kin (LKKAuto)  
**Cc:** Admin A; Hsiao Tong (LKKAuto); Tony Tan; lynnsuegoh@yahoo.com.sg  
**Subject:** Re: ROAD TRAFFIC ACCIDENT INVOLVING SMD 3781J AND SLX 1402Z ALONG TAMPINES AVENUE 4ON 19.08.2018

Hi Mr Chong,

Please find attached the document as requested. Kindly let us know if this is sufficient. Thank you.

Regards,  
Isaac

**Retain Registered Vehicle No. (Acknowledgement)  
Business Transaction Details**

(LKI)  
bst1066

Business Transaction Ref. No: 20180816103938508945

Business Transaction Date: 16 Aug 2018

Business Transaction Time: 10:39:38

**Vehicle No. Details**

Retained Vehicle No.: SJS8819J

Retained Vehicle No. Expiry Date: 29 Aug 2018

Re-assigned Vehicle No.: SMD3781J

Chassis No.: JM6KE1032G0356303

Engine No.: PY30469416

Motor No.: -

Vehicle Make: MAZDA

Vehicle Model: CX-5 SKYACTIV-G 2.5 SP.6EAT 2WD LED S/R

**Message**

Vehicle No. retained successfully.

Please note that \$100.00 will be deducted from the motor dealer's GIRO account.

The number plates on the existing vehicle must be changed by 19 Aug 2018 to display the newly assigned vehicle registration number. Failure to comply with this requirement is an offence under the Road Traffic Act.

SJS8819J is not transferable and must be used to register a vehicle by 29 Aug 2018 or \$1,200.00 will be deducted from the motor dealer's GIRO account after the validity period.

OK

## Print Sent Message

This mail is associated with :

**\*SLX1402Z (9016341772SG)**  
**[SMD3781J]**

TP  
 KOH GIN THIAM  
 Aug 19 2018 9:00AM

Hup Motor Trading & Service

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 23/08/2018 14:24 PM.  
**To** AIG\_SG; NoorMariesa.AbuKassim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com; Darshene.Supramaniam@aig.com; Aashweenjeetkaur.Mithoosingh@aig.com; Syazairdina.Azlan@aig.com; ShengYang.Lim@aig.com  
**CC** pohkin@lkkauto.com; chewht@lkkauto.com; Bernard-JQ.Ler@aig.com  
**Subject** Re: No Policy Found (9016341772SG)

Our Ref: CC6/AIG18015113/Ufa3  
 Your Ref: TBA(OI veh no. SMD 3781)

Dear Sir/Madam,

**RE: No Policy Found**

We refer to the above matter.

Please be informed that we managed to speak to Insured Driver Mr Isaac, OID mention he has changed vehicle number and yet to inform M/s AIG.

Attached herewith a copy of document from OID for your kind attention.

Kindly let us have your advice/ instruction.

In the meantime, Kindly assist upload OI GIA report in merimen.

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AIG\_SG

To: NoorMariesa.AbuKassim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com;

Aashweenjeetkaur.Mithoosingh@aig.com; Syazairdina.Azlan@aig.com; ShengYang.Lim@aig.com; LKK\_HQ

CC: pohkin@lkkauto.com; chewht@lkkauto.com; Bernard-JQ.Ler@aig.com

Sent On: 21/08/2018 03:04 PM

Subject: Re: No Policy Found

Hi

Thank you for the OI GIA report. But, we are requesting for LTA notification letter.

Kindly assist to get LTA notification letter from insured for us to proceed.

OI name : Lynn Suzanne Goh Yan Cheng

OI contact no. : 92700468

Thanks and regards,

# 哈 汽 車 貿 易 服 務

**HUP MOTOR TRADING & SERVICE** Email : hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: http://hupmotor.com.sg Reg. No. 378091/00W

Our Ref: TF 2921/08/18

Your Ref: \_\_\_\_\_

Date: 29th AUG 2018

 The Claim's Manager  
Motor Claims Dept.  
AIG ASIA PACIFIC INSURANCE PTE. LTD.  
78, Shenton Way, #07-16, Chartis Bldg.  
Singapore 079120

Dear Sirs,

RE : ACCIDENT ON 19/08/18 ALONG TAMPINES AVE 4 Slip Rd into TAMPINES AVE 5  
INVOLVING : SLX 1402 Z & YOUR INSURED : SMD 3781 J

We act for Mr Koh Gin Thiam., (S1309319/I)  
Who is the registered owner of Veh. No : SLX 1402 Z Which was involved  
in the above accident with Veh. No : SMA 3781 J Which we understand  
is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and  
we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am,  
therefore, seeking compensation from you for my financial losses as  
itemised below : -

Cost of repair	\$ 6,616.24
Car rental for 8 days ( 1 day X \$ 100.00 )	800.00
LTA Search Fee & GIA-RMC Search Fee	4.00
Survey Fee	0.00

\$ 7,420.24  
=====

We have enclosed copies of relevant documents to support my client's  
claim, There was no receipt enclosed, as my client's did not pay us  
any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully,

HUP MOTOR TRADING & SERVICE

  
-----  
Mr David Ang B. Y.

Encl : Final Bill, Car Rental Bill, LTA Search Fee, Owner Authorisation  
Letter, GIA Report, Survey Report & Ins. Cert.

 Remark : Kindly acknowledge receipt.

Car rental total 8 days, Due to 22/8 & 26/8 was holiday, Not working day,

**Poh Kin (LKKAuto)**

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Thursday, 23 August 2018 1:52 PM  
**To:** 'ISAAC.GLENN.TAN@GMAIL.COM'  
**Cc:** Hsiao Tong (LKKAuto); Admin A  
**Subject:** ROAD TRAFFIC ACCIDENT INVOLVING SMD 3781J AND SLX 1402Z ALONG TAMPINES AVENUE 4 ON 19.08.2018

**Importance:** High

Our Ref: CC6/AIG18015113/Ufb3  
Your Veh: SMD 3781J

23<sup>rd</sup> August 2018

**LYNN SUZANNE GOH YAN CHENG**  
33 Jalan Grisek,  
Singapore 419481.

Attn: Mr Isaac Glenn Tan MingKu

Dear Sir,

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SMD 3781J AND SLX 1402Z ALONG TAMPINES AVENUE 4 ON 19.08.2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

As spoken over the phone, kindly furnish us a copy of the **LTA notification letter of change vehicle number** for our necessary action.

Your prompt reply will be very much appreciated.

Please call us if you have further queries.

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK  
Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.

## AUTHORIZATION TO ACT

I, KOH GIN THIAM ("the third party claimant") NRIC : (S1309319/I) of BLK 230J, #08-673, Tampines Street 21, S (523230) (address), owner of SLX 1402 & (vehicle no.) hereby authorize Hup Motor Trading & Service, ("The workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my Vehicle No. SLX 1402 & that was damaged pursuant to the accident which occurred on 19/08/18 (date) along Slip Road Of Tampines Avenue 4 into Tampines Avenue 5 (location) involving Vehicle No/s SMD 3784 J ("The accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 28th day of AUGUST (month) 20 18 (year)

  
Mr Koh Gin Thiam (S1309319/I)  
Signed by "the third party claimant"

**HUP MOTOR TRADING & SERVICE**

  
Signed by "the workshop"

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **Hup Motor Trading & Services** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$6,616.24** (Repair Cost), **S\$800.00** (Loss of Use/Rental), **S\$4.00** (Disbursement) for vehicle no. **SLX 1402Z** that was damaged pursuant to the accident which occurred on **19/08/2018** (date) along **slip road of Tampines Avenue 4 towards Tampines Avenue 5** (location) involving vehicle no/s **SMD 3781J**. This is pursuant to the inspection conducted on **20/08/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **Koh Gin Thiam** ("the third party claimant") of vehicle no. **SLX 1402Z** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLX 1402Z** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 31<sup>st</sup> (day) of August (month) 2018 (year)

CKS 

Signed by appointed surveyor

**HUP MOTOR TRADING & SERVICE**



Signed by "the workshop" (with chop)

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2921/08/18 Your Ref: \_\_\_\_\_ Date: 29th AUG 2018

MR KOH GIN THIAM  
BLK 230J, #08-673  
TAMPINES STREET 21,  
SINGAPORE 523230

### Cost of repair to HONDA VEZEL 1.5X (A) CVT 5door - SLX 1402 &

1 pc tail gate door		\$	957.00
1 pc tail gate door 'VEZEL' emblem			58.50
1 pc tail gate door 'H' emblem			25.90
2 pcs rear windscreen glass o/s & n/s seal	@ \$ 74.10		148.20
1 pc rear windscreen glass top seal			66.00
1 pc rear windscreen glass lower seal			68.00
1 pc rear windscreen glass damper			45.00
1 pc trim board cover			184.40
12 pcs trim board cover clips	@ \$ 5.90		70.80
1 pc tail gate door handle			147.30
1 pc tail gate door inner lock			180.60
1 pc tail gate door weatherstrip			119.90
1 pc tail gate door o/s reflector			272.30
1 pc o/s tail lamp assy			463.90
1 pc o/s tail lamp clips stopper			7.50
1 pc rear number plate & holder (Matt Chrome)			50.00
1 pc rear bumper			528.00
6 pcs rear bumper top clips	@ \$ 3.90		23.40
5 pcs rear bumper low clips	@ \$ 3.90		19.50
1 pc rear bumper o/s side pad			148.50
1 pc rear bumper o/s side retainer			20.40
1 pc rear bumper o/s top retainer			18.50
1 pc rear end panel			470.30
1 pc rear end panel top garnish			95.70
1 pc tool set sponge			204.80
1 pc rear o/s fender wheel guard			134.10
1 pc rear o/s fender inner shield garnish			327.30
8 pcs rear o/s fender inner shield clips	@ \$ 6.50		52.00
		\$	4,907.80
	Less 20%	\$	981.58
		\$	3,926.24
1 pc rear windscreen glass sealant			40.00 S.N
1 set rear bumper reverse sensor			200.00 S.N
To wiring check up & transfer affected wiring system.			30.00
To transfer rear windscreen glass & necessary parts into new door.			120.00
		\$	4,316.24
	Balance C/P.....		

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2921/08/18 Your Ref: \_\_\_\_\_ Date: 29th AUG 2018

MR KOH GIN THIAM.,

Balance B/P..... \$ 4,316.24

To transfer tail gate door inner trim board, garnish, inner lock, shock absorber shaft, hinge, third brake light, wiper motor, spoiler, reverse camera & necessary parts. 60.00

To remove & refix rear cushion seat, carpet, floor mat, garnish, floor board cover, tool set, spare tyre & necessary parts. 80.00

To respray Tuff-Kote on all affected accident parts. 60.00

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s fender, rear floor board panel & necessary parts, to weld, renew & align above parts. 1,000.00

To putty & respray painting for Pearl Colour on all affected accident parts. 1,100.00

\$ 6,616.24

\*\*\*\*\*

Dollars : Six Thousand Six Hundred Sixteen And Cents Twenty Four Only.

HUP MOTOR TRADING & SERVICE

.....  




專營達善必甲出租  
汽車修理  
汽車保險賠償服務  
嘉寶多授權服務中心

# 國家汽車服務

## NATIONAL AUTOMOBILE SERVICE

Block 5033, Ang Mo Kio Industrial Park 2, #01-279  
(off Ang Mo Kio Avenue 3) Singapore 569536  
TEL: 6482 5577 (3 Lines) FAX: 6482 5000  
TOWING SERVICE: 6858 4067 (After 10.30pm)  
Reg. No: 062389/00M



TRUCK RENTAL  
MOTOR REPAIR  
INSURANCE CLAIMS  
AGENCY  
AUTHORISED CASTROL  
SERVICE CENTRE

### 车辆出租合同 VEHICLE RENTAL AGREEMENT

Date: 20th AUGUST 2018

Owner: NATIONAL AUTOMOBILE SERVICE ("the owner")

Hirer: MR KOH GIN THIAM (Owner of SLX 1402 Z)

Address: BLK 230J, #08-673, Tampines Street 21, S (523230)

NRIC / Co. Reg. No: S1309319I

Tel: \_\_\_\_\_ Fax: \_\_\_\_\_ H/P: 90264774

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: <b>SLX 5130 A TOYOTA ALTIS 1.6 (A)</b> <b>SALOON</b>		Agreement No.: 56620-G	
Driver's Particulars			
Name: <b>MR KOH GIN THIAM</b>		Odometer: <b>22342 (Full Tank Fuel)</b>	
Address: <b>AS ABOVE</b>		Date & Time Out: <b>20/08/18 (11:55hrs)</b>	
		Date & Time In: <b>28/08/18 (12:30hrs)</b>	
I/C No: <b>S1309319I</b>	Dr/Licence No: <b>S1309319I</b>	Hour @\$	
Date of Issue: <b>05/06/03</b>	Occupation: <b>SELF-EMPLOYED</b>	<b>8</b> Days @\$ <b>100-00</b>	<b>\$ 800-00</b>
YOD : <b>19/08/89</b>	Tools: <b>One Set</b>	Wks @\$	
Date of Birth: <b>02/08/58</b>	Spare Tyre: <b>One</b>	Mths @\$	

**Third Party Claim**

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive), Hirer unconditionally agrees to pay Owner ~~\$5,500~~ comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

**Own Vehicle Damage**

Hirer is responsible for the first \$ ~~3,500~~ excess for collision/damage to first party, (i.e.) NATIONAL AUTOMOBILE SERVICE (including windscreen) plus loss of earnings while damaged vehicle is under repair.

**Authorised Driver**

Hirer shall pay additional excess of S\$1500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

**Driver Not Cover By Insurance**

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable) :	NIL
Sub-Total :	\$ 800-00
Balance To Pay :	\$ 800-00

PETROL/DIESEL AT YOUR OWN EXPENSE  
FOR LOCAL USE ONLY

NATIONAL AUTOMOBILE SERVICE

Authorised Signature

Hirer's Signature



國家汽車服務  
NATIONAL AUTOMOBILE SERVICE

Block 5033, Ang Mo Kio Industrial Park 2 #01-279  
Singapore 696536. Tel: 6482 5577 (3 Lines) Fax: 6482 5000

正式收據  
OFFICIAL RECEIPT

DATE: 30/8/18

錢收到  
RECEIVED FROM: Koh Gin Thiam

銀額  
AMOUNT: Eight Hundred only

BEING PAYMENT OF: 車費  
(SUBJECT TO CHEQUE CLEARANCE)

此收據必須俟支票過帳之後始屬有效。

rental of SLK 5130 A  
from 20/8/18 to 28/8/18

\$ 800.-  
CASH/CHEQUE  
現銀/支票

NATIONAL AUTOMOBILE SERVICE



RECORDS MANAGEMENT CENTRE

# GENERAL INSURANCE ASSOCIATION OF SINGAPORE

## RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-18-127346

Date of Request: 20/08/2018

Your Ref No: Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 20/08/2018  
Enquiry By David Ang Beng Yeow  
TP Vehicle No. SJS8819J  
Accident Date 19/08/2018

#### Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJS8819J	AIG Asia Pacific Insurance Pte. Ltd.	26/01/2018-25/01/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL  
INSURANCE  
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF  
SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-133236

Date of Request: 29/08/2018

Your Ref No: Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 29/08/2018  
Enquiry By David Ang Beng Yeow  
TP Vehicle No. SMD3781J  
Accident Date 19/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

GIRO  Cash  Cheque

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018 <a href="#">Edit Reg</a>		20 Aug 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$6,616.24</b> <a href="#">Edit Estimates</a>	<b>S\$6,616.24</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by adjuster]							
Insured:	<b>Lynn Suzanne Goh Yan Cheng</b> , ID: S1589536E, Tel: +6599999999								
Main Claimant:	<b>KOH GIN THIAM</b> , ID: S1309319I								
Vehicle Reg. No.:	<b>SLX1402Z</b>	Date of Loss:	19/08/2018 09:00 - :59 [5 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 0204735228SG</b>	Policy/Cover Note No.:	2100449503 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SMD3781J</b>	Policy No. (Claimant):	VA1/GA334327						
		Excess:							
Repairer:	<b>Hup Motor Trading &amp; Service (HQ)</b> Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 30/08/2018]								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>AIG_SG (21/08/2018): Re: No Policy Found</li> <li>AIG_SG (21/08/2018): No Policy Found</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLX1402Z (0204735228SG)**  
**[SMD3781J]**  
**TP**  
**KOH GIN THIAM**  
**Aug 19 2018 9:00AM**  
**[Lynn Suzanne Goh Yan Cheng]**  
**Hup Motor Trading & Service**

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <span style="float: right;">View in Browser</span>	
<b>Letters/Correspondences</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	<b>Third Party Express Settlement - Payment Breakdown</b>							Edit		
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	20/08/18 19:29	<b>Chassis Number</b>							Load JPG	<input checked="" type="checkbox"/>	
2	20/08/18 19:29	<b>Odometer Reading</b>							Load JPG	<input checked="" type="checkbox"/>	
3	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
4	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
5	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
6	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
7	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
8	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
9	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
10	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
11	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
12	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
13	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
14	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
15	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
16	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
17	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
18	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
19	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
20	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
21	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
22	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
23	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
24	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
25	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
26	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
27	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
28	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
29	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
30	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
31	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
32	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
33	20/08/18 19:30	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
34	20/08/18 19:30	<b>General View</b>							Load JPG		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
				<input checked="" type="checkbox"/>
35	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
36	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
37	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
38	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
39	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
40	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
41	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
42	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
43	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
44	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
45	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
46	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
47	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
48	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
49	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
50	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
51	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
52	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
53	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
54	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
55	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
56	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
57	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
58	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
59	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
60	20/08/18 19:30	General View		Load JPG <input checked="" type="checkbox"/>
61	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
62	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
63	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
64	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
65	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
66	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
67	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
68	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
69	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
70	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
71	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
72	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
73	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
74	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
75	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
76	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
77	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
78	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
79	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
80	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
81	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
82	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
83	29/08/18 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	29/08/18 08:37	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
85	29/08/18 08:37	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
86	29/08/18 08:37	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
87	29/08/18 08:37	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
88	29/08/18 08:37	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
89	29/08/18 08:37	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
90	29/08/18 08:37	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
91	29/08/18 08:37	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
92	29/08/18 08:37	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>

  

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/08/18 17:25	<b>TP GIA REPORT</b>	 Load PDF	
2	21/08/18 13:18	<b>copy of OI GIA Report provide by TP repairer</b>	 Load PDF	
3	21/08/18 14:34	<b>OI GIA REPORT</b>	 Load PDF	
4	21/08/18 22:07	<b>TP ESTIMATE - MARKED</b>	 Load PDF	
5	23/08/18 14:15	<b>Document from OI</b>	 Load JPG	<input checked="" type="checkbox"/>
6	30/08/18 09:21	<b>Supplementary</b>	 Load PDF	
7	30/08/18 15:32	<b>LETTER TO OI</b>	 Load PDF	
8	19/09/18 13:33	<b>WORKSHOP INVOICE</b>	 Load PDF	
9	19/09/18 13:33	<b>AUTHORISATION TO ACT FORM</b>	 Load PDF	
10	19/09/18 13:33	<b>Release Voucher</b>	 Load PDF	
11	19/09/18 13:33	<b>RENTAL RECEIPT</b>	 Load PDF	
12	19/09/18 13:33	<b>GIA SEARCH</b>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SMD3781J (Insd veh)	Model:	HONDA VEZEL 1.5 X CVT (A)
	SLX1402Z (TP veh)		
Date of Accident:	19/08/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$		12,150.48
Final Repair Cost	: \$		6,616.24
Loss of Use	: \$		_____ days at \$0.00 per day
Rental (if any)	: \$		800.00    8 days
LTA / GIA Search Fee	: \$		4.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		7,420.24
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO    (Kindly indicate below)			
<b>A) For Non GIA Registered Workshop:</b>		Agreed Liability ____100____(%)	
<b>B) For GIA Registered Workshop:</b>		BOLA Applicable: Yes/ No    BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Hup Motor Trading & Service	: \$	7,420.24
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

19 Sep  
2018

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG18015113/UFA3Q2  
**Date:** 19/09/2018

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100449503
<b>Claimant Vehicle No :</b> SLX1402Z	<b>Insured Vehicle No :</b>	SMD3781J
Date of Loss: 19/08/2018	Nature of Claim:	TP
		Claim No: 0204735228SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLX1402Z</b>	Engine No:	L15B4432719
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11232714
Reg. Date:	16/03/2018 (Man. Year: 2017)	Odometer:	6015 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,720.48	4,166.24	3,554.24	46.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	2,450.00	1,980.00	44.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>12,150.48</b>	<b>6,616.24</b>	<b>5,534.24</b>	<b>45.55</b>
	+ Car Rental (8.0 x S\$100.00/day) (S\$)	800.00		
	+ Doc/Search Fee (S\$)	4.00		
	<b>Nett Liability (S\$)</b>	<b>7,420.24</b>		

#### INSPECTION

Date of Assignment:	20/08/2018	
Date Inspected:	20/08/2018	Inspected At: Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	6.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** Chong Poh Kin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE DOOR	Badly Dented	957.00 FL	*957.00 FL
2	1		*TAIL GATE DOOR VEZEL EMBLEM	Necessary	58.50 FL	*58.50 FL
3	1		*TAIL GATE DOOR H LOGO EMBLEM	Necessary	25.90 FL	*25.90 FL
4	1		*TAIL GATE DOOR HYBRID EMBLEM	Not fitted	58.30 FL	*- FL
5	2		*REAR WINDSCREEN GLASS O/S & N/S SEAL	Necessary	148.20 FL	*148.20 FL
6	1		*REAR WINDSCREEN GLASS TOP SEAL	Necessary	66.00 FL	*66.00 FL
7	1		*REAR WINDSCREEN GLASS LOWER SEAL	Necessary	68.00 FL	*68.00 FL
8	1		*REAR WINDSCREEN GLASS DAMPER	Necessary	45.00 FL	*45.00 FL
9	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	48.00 FS	*40.00 FS
10	1		*REAR LICENCE LAMP GARNISH	Not Necessary	238.70 FL	*- FL
11	2		*REAR O/S & N/S LICENCE LAMP ASSY	Not Necessary	77.00 FL	*- FL
12	12		*REAR LICENCE LAMP GARNISH CLIPS	Not Necessary	82.80 FL	*- FL
13	12		*REAR LICENCE LAMP GARNISH CLIPS STOPPER	Not Necessary	102.00 FL	*- FL
14	1		*TRIM BOARD COVER	Deformed / Torn	184.40 FL	*184.40 FL
15	12		*TRIM BOARD COVER CLIPS	Necessary	70.80 FL	*70.80 FL
16	1		*TAIL GATE DOOR HANDLE	Twisted	147.30 FL	*147.30 FL
17	1		*TAIL GATE DOOR INNER LOCK	Twisted	180.60 FL	*180.60 FL
18	1		*TAIL GATE DOOR LOCK STRICKER	Not Necessary	23.80 FL	*- FL
19	1		*KEY LESS SENSOR (OUTER)	Not Necessary	137.10 FL	*- FL
20	1		*KEY LESS SENSOR (INNER)	Not Necessary	107.30 FL	*- FL
21	1		*TAIL GATE DOOR WEATHERSTRIP	Twisted	119.90 FL	*119.90 FL
22	1		*TAIL GATE DOOR O/S & N/S REFLECTER	O/S Cracked	544.60 FL	*272.30 FL
23	1		*O/S & N/S TAIL LAMP ASSY	O/S Cracked	927.80 FL	*463.90 FL
24	1		*REAR NUMBER PLATE & HOLDER	Cracked	50.00 FL	*50.00 FL
25	1		*REAR BUMPER	Dented	528.00 FL	*528.00 FL
26	6		*REAR BUMPER TOP CLIPS	Necessary	23.40 FL	*23.40 FL
27	5		*REAR BUMPER LOWER CLIPS	Necessary	19.50 FL	*19.50 FL
28	1		*REAR BUMPER REINFORCEMENT (TOP)	No such part	143.60 FL	*- FL
29	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	230.24 FS	*200.00 FS
30	1		*REAR BUMPER O/S & N/S SIDE PAD	O/S Dented	297.00 FL	*148.50 FL
31	1		*REAR BUMPER O/S & N/S SIDE RETAINER	O/S Bent	40.80 FL	*20.40 FL
32	1		*REAR BUMPER O/S & N/S TOP RETAINER	O/S Bent	37.00 FL	*18.50 FL
33	4		*REAR BUMPER O/S & N/S SIDE PAD CLIPS	Not Necessary	23.60 FL	*- FL
34	2		*REAR BUMPER O/S & N/S REFLECTOR	Not Necessary	303.60 FL	*- FL
35	1		*REAR END PANEL	Badly Dented	470.30 FL	*470.30 FL
36	1		*REAR END PANEL TOP GARNISH	Twisted	95.70 FL	*95.70 FL
37	5		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	29.00 FL	*- FL
38	1		*REAR FLOOR BOARD PANEL	Repair	709.50 FL	*- FL
39	1		*REAR FLOOR BOARD PANEL UNDER COVER GARNISH	Not Necessary	156.80 FL	*- FL
40	8		*REAR FLOOR BOARD PANEL UNDER COVER CLIPS	Not Necessary	31.20 FL	*- FL
41	1		*SPARE TYRE COVER BOARD	Not Necessary	264.10 FL	*- FL
42	1		*TOOL SET SPONGE	Torn	204.80 FL	*204.80 FL
43	16		*REAR O/S & N/S FENDER WHEEL GUARD CLIPS	Not Necessary	136.00 FL	*- FL
44	1		*REAR O/S FENDER WHEEL GUARD	Torn	134.10 FL	*134.10 FL
45	1		*REAR FLOOR BOARD PANEL INSULATOR	Not Necessary	68.80 FL	*- FL
46	1		*REAR O/S FENDER	Repair	709.80 FL	*- FL
47	1		*REAR FLOOR BOARD PANEL INSULATORS	Not Necessary	68.40 FL	*- FL
48	1		*REAR O/S FENDER INNER GARNISH SHIELD	Deformed / Torn	327.30 FL	*327.30 FL
49	8		*REAR O/S FENDER INNER GARNISH CLIPS	Necessary	52.00 FL	*52.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
50	1		*O/S TAIL LAMP CLIP STOPPER	Necessary	7.50 FL	*7.50 FL	
					<b>Sub Total (S\$)</b>	<b>9,581.04</b>	<b>5,147.80</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>1,860.56</b>	<b>981.56</b>
					<b>Total Parts (S\$)</b>	<b>7,720.48</b>	<b>4,166.24</b>

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO WIRING CHECK UP & TRANSFER AFFECTED WIRING SYSTEM INTO NEW DOOR & NECESSARY PARTS	New	60.00	30.00
2	TO TRANSFER REAR WINDSCREEN GLASS & NECESSARY PARTS INTO NEW DOOR	New	150.00	120.00
3	TO TRANSFER TAIL GATE DOOR INNER LOCK ,TRIM BOARD COVER ,HINGE,SHOCK ABSORBER ,SPOILER ,THIRD BRAKE LIGHT ,WIPER MOTOR ,ARM,GARNISH ,REVERSE CAMERA & NECESSARY PARTS INTO NEW DOOR	New	160.00	60.00
4	TO REMOVE & REFIX REAR CUSHION SEAT, CARPET ,FLOOR MAT ,GARNISH ,FLOOR BOARD COVER ,SPARE TYRE ,TOOL SET & NECESSARY PARTS	New	120.00	80.00
5	TO JACK ,STRAIGHTEN & KNOCKING OUT REAR EXHAUST & TAIL PIPE	New	120.00	0.00
6	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	120.00	60.00
7	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT REAR FLOOR BOARD PANEL ,REAR O/S & N/S FENDER & NECESSARY PARTS,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,800.00	1,000.00
8	TO PUTTY & RESPRAY PAINTING (PEARL COLOUR) ON ALL AFFECTED ACCIDENT PARTS	New	1,900.00	1,100.00
<b>Gross Labour Cost (S\$)</b>			<b>4,430.00</b>	<b>2,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >