

not followed
 the ph. before
 6dy.
 20/8/18

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2924/08/18 Your Ref: _____ Date: 20th AUG 2018

MR KOH GIN THIAM
 BLK 230J, #08-673
 TAMPINES STREET 21, S (523230)

Estimate cost of repair to HONDA VEZEL 1.5X (A) CVT 5door - SLX 1402 Z

1 pc	tail gate door	30dy		\$	957.00	—
1 pc	tail gate door 'VEZEL' emblem	nu			58.50	—
1 pc	tail gate door 'H' logo emblem	nu			25.90	—
1 pc	tail gate door 'HYBRID' emblem	nz			58.30	X
2 pcs	rear windscreen glass o/s & n/s seal	nu @ \$	74.10		148.20	—
1 pc	rear windscreen glass top seal	nu			66.00	✓
1 pc	rear windscreen glass lower seal	nu			68.00	✓
1 pc	rear windscreen glass damper	11			45.00	✓
1 pc	rear windscreen glass sealant	nu			60.00	405.N
1 pc	rear licence lamp garnish				238.70	?
2 pcs	rear o/s & n/s licence lamp assy	11 @ \$	38.50		77.00	X
12 pcs	rear licence lamp garnish clips	11 @ \$	6.90		82.80	X
12 pcs	rear licence lamp garnish clips stopper	@ \$	8.50	11	102.00	X
1 pc	trim board cover				184.40	?
12 pcs	trim board cover clips	@ \$	5.90		70.80	?
1 pc	tail gate door handle				147.30	?
1 pc	tail gate door inner lock			7w1	180.60	—
1 pc	tail gate door lock stricker			11	23.80	X
1 pc	key less sensor (outer)				137.10	?
1 pc	key less sensor (inner)				107.30	?
1 pc	tail gate door weatherstrip			7w1	119.90	?
2 pcs	tail gate door o/s & n/s reflector	@ \$	272.30	o/sen	544.60	12C
2 pcs	o/s & n/s tail lamp assy	@ \$	463.90	o/sen	927.80	12C
1 pc	rear number plate & holder			cm	50.00	—
1 pc	rear bumper			TD	528.00	—
6 pcs	rear bumper top clips	@ \$	3.90	nu	23.40	—
5 pcs	rear bumper lower clips	@ \$	3.90	nu	19.50	—
1 pc	rear bumper reinforcement (Top)				143.60	?
1 set	rear bumper reverse sensor				287.80	2005.N
2 pcs	rear bumper o/s & n/s side pad	@ \$	148.50	o/sen	297.00	12C
2 pcs	rear bumper o/s & n/s side retainer	@ \$	20.40	o/sen	40.80	12C
2 pcs	rear bumper o/s & n/s top retainer	@ \$	18.50		37.00	?
4 pcs	rear bumper o/s & n/s side pad clips	@ \$	5.90		23.60	?
2 pcs	rear bumper o/s & n/s reflector	@ \$	151.80		303.60	?
1 pc	rear end panel				470.30	?
1 pc	rear end panel top garnish				95.70	?
5 pcs	rear end panel top garnish clips	@ \$	5.80		29.00	?
1 pc	rear floor board panel				709.50	X
1 pc	rear floor board panel under cover garnish				156.80	?
8 pcs	rear floor board panel under cover clips	@ \$	3.90		31.20	?
1 pc	spare tyre cover board				264.10	?
1 pc	tool set sponge				204.80	?
16 pcs	rear o/s & n/s fender wheel guard clips	@ \$	8.50		136.00	?
1 pc	rear o/s fender wheel guard				134.10	?
1 pc	rear floor board panel insulator				68.80	?
1 pc	rear o/s fender				709.80	X
1 pc	rear floor board panel insulator				68.40	—
					\$ 9,263.80	

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2921/08/18 Your Ref: _____ Date: 20th AUG 2018

MR KOH GIN THIAM.,

Balance B/F.....\$ 9,263.80
Less 20% \$ 1,852.76

	\$ 7,411.04
To wiring check up & transfer affected wiring system into new door & necessary parts.	60.00 30
To transfer rear windscreen glass & necessary parts into new door.	150.00 120
To transfer tail gate door inner lock, trim board cover, hinge, shock absorber, spoiler, third brake light, wiper motor, arm, garnish, reverse camera & necessary parts into new door.	160.00 60
To remove & refix rear cushion seat, carpet, floor mat, garnish, floor board cover, spare tyre, tool set & necessary parts.	120.00 80
To jack, straighten & knocking out rear exhaust & tail pipe. u1	120.00 x
To respray Tuff-Kote on all affected accident parts.	120.00 60
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear o/s & n/s fender & necessary parts, to weld, renew & align above parts.	1,800.00 ?
To putty & respray painting (Pearl Colour) on all affected accident parts.	1,900.00 100
	<u>\$ 11,841.04</u> =====

Dollars : Eleven Thousand One Hundred Eighty Four And Cents Four Only.

HUP MOTOR TRADING & SERVICE
.....
[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: