

22/03/2002

ASS. REC. BY:

REF:

CS3/LPC/8015141/Ntd36

Special Instruction:

Surveyor:

Naz

ASSIGNMENT (Office)

From (Person):

Gerald Poh

of

Lpc

Date/Time:

22/8/18 @ 8.45am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 6431 U

Insured:

GV 3601 Y

at Workshop m/s

Hwa Peng Auto

Tel:

9688 5655

of

Blk 70, Woodlands Ind. Park E

Policy No:

Claim No:

18/18/18/VCOS/020842

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/08/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10.14am @ 20/8/18

Person Contacted:

Francis

Vehicle IN

(OUT)

Date/Time	Action/Instruction (X) Estimate
	GBF 6431 U - X
	GV 3601 Y - X
24/8-	dismantle

REF:

Surveyor: N/A

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GRF 64314

Yr Regn:

1

Type M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA DYNA

C.C

Colour

SILVER

A/C: Insured / Std / NI /

Sp. Reading

56,967

T/Radio: Insured / Std / NI /

Eng/No:

C/No:

KDX231-8025091

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Use / Jammed / Leaked / Burnt or

Brake: In Use / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 / 70 R15 - C

R:

195 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXTREK (F) BS (R)

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23/8/18 @ 050

Survey held at

HWA PENG AUTO SERVICE

Des. of Damages: Frnt / Rev / O/S / N/S / U/C / Rooftop or

N/S FET

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

12/9- Submit PRS Report first then follow up paper survey

RECEIVED 25 SEP 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 25/9 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

1

Survey Fee:

150

Transportation:

Add Fee:

☐

Site Insp

(\$

) S + RS. SI

☐

Interview

(\$

) Photos

☐

Tech. Invs

(\$

) Others

☐

Weekend

(\$

)

Report Format :

TP-PRS

Lump Sum / I.B.I. (\$

TOTAL

150

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 20 August 2018 8:45 AM
To: admin-d@lkkauto.com
Cc: MT_Claim_SG; Chris Tan
Subject: FW: Our Ref: 18/18/18/VC05/020842 RE: PRS for GBF 6431 U involving vehicle GV 3601 Y (your insured) on 14 August 2018 at Tampines Stret 91 open carpark (Oref: LCH.my/W1HP-80740.18)

Our Ref : 18/18/18/VC05/020842

Dear Nivitha,

Please proceed to arrange the pre-repair survey.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Cheong Hoh Lee [mailto:mail@cheonghoh.sg]

Sent: Friday, 17 August, 2018 5:59 PM

To: ONG LI LI

Cc: MT_Claim_SG; Catherine Chong (LKK Auto); assignments@lkkauto.com

Subject: Re: Our Ref: 18/18/18/VC05/020842 RE: PRS for GBF 6431 U involving vehicle GV 3601 Y (your insured) on 14 August 2018 at Tampines Stret 91 open carpark (Oref: LCH.my/W1HP-80740.18)

We refer to the above matter and to your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your aforesaid letter.

We are further instructed to append below our client's 10 proposed surveyors as follows :-

- (1) Jeffery Ong Leng Kiat
- (2) Fong Kok Heng
- (3) Chang Fuh Keong
- (4) T Rajan
- (5) Ng Soon Chuan Louis
- (6) Ng Soon Aik Francis
- (7) Jayson Liaw Leong San
- (8) Lee Kok Weng
- (9) Loi Boon Juan
- (10) How Andrew

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey ("PRS") of our client's vehicle no. GBF 6431 U at our client's repairer workshop as follows :-

Hwa Peng Auto Service (1996)
Blk 70 Woodlands Industrial Park E

Singapore 757836

Person to contact : Francis (mobile no. 9688 5655)

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

On Aug 17, 2018, at 3:56 PM, ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	

9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Cheong Hoh Lee [<mailto:mail@cheonghoh.sg>]
Sent: Friday, 17 August, 2018 3:50 PM
To: MT_Claim_SG; GERALD POH WEE BIN
Subject: Re: PRS for GBF 6431 U involving vehicle GV 3601 Y (your insured) on 14 August 2018 at Tampines Stret 91 open carpark (Oref: LCH.my/W1HP-80740.18)

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC18015141/Ntd3		
300 BEACH ROAD		Date : 20-08-2018		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code : LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GV 3601Y	Veh. Inspected	GBF 6431U	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VC05/020842	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	20/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/08/2018	Inspection Date	23/08/2018	
Survey held at	HWA PENG AUTO SERVICE (1996) 70 WOODLAND INDUSTRIAL PARK E SINGAPORE 757836			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC18015141/Ntd3e2 Date: 25-09-2018 Code: LPC2		
				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GV 3601Y	Veh. Inspected	GBF 6431U	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VC05/020842	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	20/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	KDY2318025091	Colour	SILVER	
Odometer	56967 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/70 R15C	MAXTREK	5 mm	
L/H Front Tyre	195/70 R15C	MAXTREK	5 mm	
R/H Rear Tyre	145 R13	BRIDGESTONE	6 mm	
L/H Rear Tyre	145 R13	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
5. General Information				
Accident Date	14/08/2018	Inspect Date / Time	23/08/2018 (05:07 PM)	
Survey held at	HWA PENG AUTO SERVICE (1996) 70 WOODLAND INDUSTRIAL PARK E SINGAPORE 757836			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC18015141/Ntd3e2

Inspected By

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.